

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Merced Streams Group

| | Spring (March - May) | Summer ** (June - August) | Fall (September - November) | Winter ** (December - February) |
|----------------------------------|-------------------------|------------------------------|--------------------------------|------------------------------------|
| * Overall LMA Rating (Fall Only) | | | | |

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

| |
|--|
| |
| |
| |
| |
| |
| |
| |

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Merced Streams Group**

| | | | |
|------------------------------------|--|-------------|-------------------|
| Waterway | | Bank | Unit Miles |
| Unit No. 01 Black Rascal Diversion | | Right | 1.64 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2010 - 5/26/2010 | | | |
| DWR Inspector | Herman Phillips | | | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------------|--|--|--|-------|------------|--------------------------|-----------------|
| Unit No. 01 Black Rascal Diversion | | | | Right | 1.64 | 05/26/2010 05/26/2010 | Herman Phillips |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|------------|------------|-----------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 1.31 | 1.64 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | 37.332740 ° -120.395045 ° | 37.341433 ° -120.398815 ° | 1 Y |

| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------------|-------|------------|--------------------------|-----------------|
| Unit No. 01 Black Rascal Diversion | Right | 1.64 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|--|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 1.31 |
| End Levee Mile | 1.64 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |
| <p>This photo was added to show the split unit 1 Black Rascal Slough with Fairfield Canal continues downstream to L/M 1.64</p> | |
| <p>phillips_s_20100601_064.jpg</p> | |



| | |
|---|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 1.31 |
| End Levee Mile | 1.64 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |
| <p>Levee mile 1.38 berries on shoulder.waterside.</p> | |
| <p>phillips_s_20100601_065.jpg</p> | |



| | |
|---|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 1.31 |
| End Levee Mile | 1.64 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |
| <p>Tree growth and wild growth water ward District states that this is not Black Rascal but instead Murphy's canal.</p> | |
| <p>phillips_s_20100601_066.jpg</p> | |



| | | | |
|---|---|---|---|
| <p>* Location LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> | <p>C : Corrected W : Watch/Monitor</p> |
|---|---|---|---|

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Merced Streams Group**

| | | | |
|------------------------------------|--|-------------|-------------------|
| Waterway | | Bank | Unit Miles |
| Unit No. 02 Black Rascal Diversion | | Left | 1.88 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2010 - 5/26/2010 | | | |
| DWR Inspector | Herman Phillips | | | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------------|--|--|--|------|------------|--------------------------|-----------------|
| Unit No. 02 Black Rascal Diversion | | | | Left | 1.88 | 05/26/2010 05/26/2010 | Herman Phillips |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|----------------|------------|-----------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.69 | 0.75 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | 37.331242 ° -120.394545 ° | 37.325337 ° -120.393400 ° | 1 |
| 2 | 0.69 | 0.82 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.331163 ° -120.394637 ° | 37.329660 ° -120.395797 ° | 9 |
| 3 | 0.70 | 0.97 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.331107 ° -120.394673 ° | 37.327500 ° -120.396098 ° | 8 |
| 4 | 0.72 | 0.72 | Earthen Levee | Animal Control | CR | M | Exterminate rodents and backfill and compact or grout burrows. | 37.330913 ° -120.394893 ° | 37.330913 ° -120.394893 ° | 2 |
| 5 | 0.96 | 1.12 | Earthen Levee | Vegetation | LS | M | Control annual grass and weeds on the levee slopes and easements. | 37.327655 ° -120.396175 ° | 37.325408 ° -120.393197 ° | 3 Y |

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------------|------|------------|--------------------------|-----------------|
| Unit No. 02 Black Rascal Diversion | Left | 1.88 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 5 |
| Start Levee Mile | 0.96 |
| End Levee Mile | 1.12 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

View looking downstream of unit 2 L/M 0.00 standing on land side. There is growth on crown road way you can see where District made a couple of passes. These grasses aren't tall, you can still view the levee.

phillips_s_20100601_062.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 5 |
| Start Levee Mile | 0.96 |
| End Levee Mile | 1.12 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

Looking at water side of levee the weeds are not blocking the view of levee. Looking downstream from L/M 0.00.

phillips_s_20100601_063.jpg



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Merced Streams Group**

| | | | |
|-----------------------------------|--|-------------|-------------------|
| Waterway | | Bank | Unit Miles |
| Unit No. 03 Owens Creek Diversion | | Right | 1.44 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2010 - 5/26/2010 | | | |
| DWR Inspector | Herman Phillips | | | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|--|--|--|-------|------------|--------------------------|-----------------|
| Unit No. 03 Owens Creek Diversion | | | | Right | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|--------------------|------------|-----------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.00 | 0.39 | Earthen Levee | Vegetation | CR | M | Control annual grass and weeds on the levee slopes and easements. | ° | ° | 3 |
| 2 | 0.02 | 0.39 | Earthen Levee | Vegetation | LS | M | Control annual grass and weeds on the levee slopes and easements. | ° | ° | 4 |
| 3 | 0.02 | 0.39 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | ° | ° | 5 |
| 4 | 0.26 | 0.26 | Earthen Levee | Trim / Thin Trees | LS | M | Trim trees to at least five feet above ground level. | ° | ° | 9 |
| 5 | 0.70 | 1.44 | Earthen Levee | Animal Control | WS | M | No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: The maintaining Agency has done an excellent job of mowing the levee both unit 3 and 4, the channel has been dredged removing the tule growth. It looks good. | 37.267302 ° -120.287190 ° | 37.273742 ° -120.277737 ° | 6 |
| 6 | 0.73 | 0.95 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.267585 ° -120.286860 ° | 37.270175 ° -120.284772 ° | 969 |
| 7 | 1.00 | 1.00 | Supplemental | DWR Erosion Survey | WS | U | Inspector Comments: 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U3RM1] | 37.270800 ° -120.284180 ° | 37.270800 ° -120.284180 ° | 1 Y |
| 8 | 1.07 | 1.28 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.271402 ° -120.283263 ° | 37.273045 ° -120.280272 ° | 970 |
| 9 | 1.19 | 1.27 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.272388 ° -120.281348 ° | 37.272840 ° -120.280295 ° | 7 |
| 10 | 1.24 | 1.28 | Earthen Levee | Animal Control | CR | M | Exterminate rodents and backfill and compact or grout burrows. | 37.272533 ° -120.280605 ° | 37.273045 ° -120.280272 ° | 971 |
| 11 | 1.24 | 1.25 | Earthen Levee | Animal Control | CR | M | Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: This Unit is maintained as far as the vegetation is concerned however there is a problem with the rodents. The District should have bait stations through out the area where rodents are present. | 37.272537 ° -120.280500 ° | 37.272560 ° -120.280447 ° | 8 |
| 12 | 1.25 | 1.25 | Supplemental | DWR Erosion Survey | WS | M | Inspector Comments: 2009: Scouring possible created by velocity and effects resulting from channel confinement of the bridge upstream; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0013U3RM1.25] | 37.272630 ° -120.280390 ° | 37.272630 ° -120.280390 ° | 2 Y |

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|-------|------------|--------------------------|-----------------|
| Unit No. 03 Owens Creek Diversion | Right | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|--|--------------------|
| Levee Mile Report Line | 7 |
| Start Levee Mile | 1.00 |
| End Levee Mile | 1.00 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U3RM1] | |
| SJR2009_LM1.0a.JPG | |



| | |
|--|--------------------|
| Levee Mile Report Line | 7 |
| Start Levee Mile | 1.00 |
| End Levee Mile | 1.00 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U3RM1] | |
| SJR2009_LM1.0b.JPG | |



| | |
|--|--------------------|
| Levee Mile Report Line | 7 |
| Start Levee Mile | 1.00 |
| End Levee Mile | 1.00 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U3RM1] | |
| SJR2009_LM1.0c.JPG | |



| | | | |
|--|--|--|------------------------------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected W : Watch/Monitor |
|--|--|--|------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|-------|------------|--------------------------|-----------------|
| Unit No. 03 Owens Creek Diversion | Right | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|---|--------------------|
| Levee Mile Report Line | 12 |
| Start Levee Mile | 1.25 |
| End Levee Mile | 1.25 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: bank erosion scour that is immediately downstream of Mission Ave. bridge; noticeable terracetting damage from livestock traversing the slope; site is recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0013U3RM1.25]</p> <p>SJR2009_S17 LM1.25 082508b.JPG</p> | |



| | |
|---|--------------------|
| Levee Mile Report Line | 12 |
| Start Levee Mile | 1.25 |
| End Levee Mile | 1.25 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: bank erosion scour that is immediately downstream of Mission Ave. bridge; noticeable terracetting damage from livestock traversing the slope; site is recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0013U3RM1.25]</p> <p>SJR2009_S17 LM1.25 082508e.JPG</p> | |



| | |
|---|--------------------|
| Levee Mile Report Line | 12 |
| Start Levee Mile | 1.25 |
| End Levee Mile | 1.25 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: bank erosion scour that is immediately downstream of Mission Ave. bridge; noticeable terracetting damage from livestock traversing the slope; site is recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0013U3RM1.25]</p> <p>SJR2009_S17 LM1.25 082508c.JPG</p> | |



| | | | |
|---|---|---|--|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> | <p>C : Corrected W : Watch/Monitor</p> |
|---|---|---|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|-------|------------|--------------------------|-----------------|
| Unit No. 03 Owens Creek Diversion | Right | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|---|--------------------|
| Levee Mile Report Line | 12 |
| Start Levee Mile | 1.25 |
| End Levee Mile | 1.25 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: bank erosion scour that is immediately downstream of Mission Ave. bridge; noticeable terracetting damage from livestock traversing the slope; site is recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0013U3RM1.25]</p> <p>SJR2009_S17 LM1.25 082508a.JPG</p> | |



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Merced Streams Group**

| Waterway | | Bank | Unit Miles |
|-----------------------------------|--|------|------------|
| Unit No. 04 Owens Creek Diversion | | Left | 1.44 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2010 - 5/26/2010 | | | |
| DWR Inspector | Herman Phillips | | | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|------|------------|--------------------------|-----------------|
| Unit No. 04 Owens Creek Diversion | Left | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|--------------------|------------|-----------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.13 | 1.03 | Earthen Levee | Animal Control | LS | M | No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: I did not see any rodent during my inspection of unit 4 I did see rodent holes that appeared to be active. 2010 INSPECTION there were active rodent holes in levee slopes and crown no bait stations in infected areas. | 37.272967 ° -120.280055 ° | 37.262870 ° -120.287862 ° | 1 |
| 2 | 0.13 | 1.03 | Earthen Levee | Animal Control | WS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.272967 ° -120.280057 ° | 37.262877 ° -120.287860 ° | 2 |
| 3 | 0.15 | 0.28 | Supplemental | DWR Erosion Survey | WS | M | Inspector Comments: 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U4RM0.21] | 37.272283 ° -120.280869 ° | 37.272283 ° -120.280869 ° | 3 Y |
| 4 | 0.42 | 0.43 | Supplemental | DWR Erosion Survey | WS | U | Inspector Comments: 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; terracetting damage from livestock traversing; there is a wooden platform installed on site; landside ground is same heights as levee crown; previously rated "M" [2009 | 37.270630 ° -120.283970 ° | 37.270630 ° -120.283970 ° | 4 Y |
| 5 | 0.47 | 0.47 | Earthen Levee | Animal Control | CR | M | Exterminate rodents and backfill and compact or grout burrows. | 37.270030 ° -120.284472 ° | 37.270030 ° -120.284472 ° | 968 |
| 6 | 0.61 | 0.63 | Earthen Levee | Animal Control | CR | M | Exterminate rodents and backfill and compact or grout burrows. | 37.268428 ° -120.285887 ° | 37.268142 ° -120.286112 ° | 6 |
| 7 | 0.72 | 0.79 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.267060 ° -120.286882 ° | 37.266215 ° -120.287595 ° | 969 |
| 8 | 0.84 | 1.02 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.265647 ° -120.287998 ° | 37.263080 ° -120.287820 ° | 970 |
| 9 | 1.16 | 1.41 | Earthen Levee | Animal Control | WS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.261007 ° -120.288170 ° | 37.257498 ° -120.288100 ° | 11 |
| 10 | 1.16 | 1.41 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 37.261005 ° -120.288168 ° | 37.257502 ° -120.288102 ° | 10 |

| | | | |
|---|---|---|--|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> | <p>C : Corrected W : Watch/Monitor</p> |
|---|---|---|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|------|------------|--------------------------|-----------------|
| Unit No. 04 Owens Creek Diversion | Left | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|---|--------------------|
| Levee Mile Report Line | 3 |
| Start Levee Mile | 0.15 |
| End Levee Mile | 0.28 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U4RM0.21] | |
| SJR2009_LM0.21a.JPG | |



| | |
|---|--------------------|
| Levee Mile Report Line | 3 |
| Start Levee Mile | 0.15 |
| End Levee Mile | 0.28 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "U" [2009 SiteID:NA0013U4RM0.21] | |
| SJR2009_LM0.21b.JPG | |



| | |
|---|--------------------|
| Levee Mile Report Line | 4 |
| Start Levee Mile | 0.42 |
| End Levee Mile | 0.43 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; terracing damage from livestock traversing; there is a wooden platform installed on site; landside ground is same heights as levee crown; previously rated "M" [2009 SiteID:NA0013U4RM0.42] | |
| SJR2009_LM0.42a.JPG | |



| | | | |
|--|--|--|------------------------------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected W : Watch/Monitor |
|--|--|--|------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Merced Streams Group

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------------|------|------------|--------------------------|-----------------|
| Unit No. 04 Owens Creek Diversion | Left | 1.44 | 05/26/2010 05/26/2010 | Herman Phillips |

| | |
|---|--------------------|
| Levee Mile Report Line | 4 |
| Start Levee Mile | 0.42 |
| End Levee Mile | 0.43 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; terracetting damage from livestock traversing; there is a wooden platform installed on site; landside ground is same heights as levee crown; previously rated "M" [2009 SiteID:NA0013U4RM0.42]</p> | |
| <p>SJR2009_LM0.42b.JPG</p> | |



| | |
|---|--------------------|
| Levee Mile Report Line | 4 |
| Start Levee Mile | 0.42 |
| End Levee Mile | 0.43 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; terracetting damage from livestock traversing; there is a wooden platform installed on site; landside ground is same heights as levee crown; previously rated "M" [2009 SiteID:NA0013U4RM0.42]</p> | |
| <p>SJR2009_LM0.42c.JPG</p> | |



| | |
|---|--------------------|
| Levee Mile Report Line | 4 |
| Start Levee Mile | 0.42 |
| End Levee Mile | 0.43 |
| Location | Water Side |
| Category | Supplemental |
| Item | DWR Erosion Survey |
| <p>2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; terracetting damage from livestock traversing; there is a wooden platform installed on site; landside ground is same heights as levee crown; previously rated "M" [2009 SiteID:NA0013U4RM0.42]</p> | |
| <p>SJR2009_LM0.42d.JPG</p> | |



| | | | |
|---|---|---|---|
| <p>* Location LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> | <p>C : Corrected W : Watch/Monitor</p> |
|---|---|---|---|