

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Comment Code					
Inspector Comment					
This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Comment Code					
Inspector Comment					
District maintains supply of sand bags and gets other supplies from other districts.					

No Photos

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Comment Code					
Inspector Comment					
MBK Engineering mailed a copy of the O/M Manual to the RD President in spring of 2017.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.20	Rating **	M	Issue No.	4 (cont)
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.346500 °	38.337197 °
				-121.539146 °	-121.564147 °
DWR ID	DWR_RD0755_01_f_2014_4				

Photo 2 of 2 : SP_2020_RD0755_177_4_20200330_00070.jpg



View a couple animal holes on the landside slope (Spring 2020).

LM Start	0.21	Rating **	M	Issue No.	10
LM End	0.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.346428 °	38.346428 °
				-121.539400 °	-121.539400 °
DWR ID	DWR_RD0755_01_s_2019_10				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
There is a 2" seperation between roadway and levee on the landside shoulder.					

Photo 1 of 1 : SP_2020_RD0755_177_10_20200304_00001.jpg



View looking upstream at small slip on the landside shoulder (Spring 2019).

LM Start	0.24	Rating **	C	Issue No.	21
LM End	0.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.346275 °	38.346275 °
				-121.539838 °	-121.539838 °
DWR ID	DWR_RD0755_01_f_2016_21				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trim trees to at least five feet above the ground.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.28	Rating **	U	Issue No.	18
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.346249 °	38.346331 °
				-121.540542 °	-121.540664 °
DWR ID	DWR_RD0755_01_s_2020_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 27 feet in length. Site ID No:327 Site Designation:LMA-154 3/25/2020 Field Notes: Erosion is significant. At least 1' into waterside slope. No riprap present.					

LM Start	0.28	Rating **	U	Issue No.	18 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2020_RD0755_177_18_20200330_00064.jpg



View looking upstream and slightly down at erosion into the waterside slope (Spring 2020).

Photo 2 of 2 : SP_2020_RD0755_177_18_20200330_00065.jpg



View looking upstream and slightly up at erosion into the waterside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.33	Rating **	M	Issue No.	19
LM End	1.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346043 °	38.336409 °
				-121.541483 °	-121.564813 °
DWR ID	DWR_RD0755_01_f_2016_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The tall weeds on the waterside slope should be removed/managed to allow inspection. Large cactus (Century Plants) at LM 1.07 should also be removed.					

Photo 1 of 1 : SP_2020_RD0755_177_19_20200304_00008.jpg



View looking downstream at thick vegetation on the waterside slope (Fall 2019).

LM Start	0.40	Rating **	M	Issue No.	48
LM End	0.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345665 °	38.345648 °
				-121.542708 °	-121.542863 °
DWR ID	DWR_RD0755_01_f_2019_48				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.43	Rating **	M	Issue No.	47
LM End	0.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345633 °	38.345633 °
				-121.543278 °	-121.543278 °
DWR ID	DWR_RD0755_01_f_2019_47				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.50	Rating **	M	Issue No.	17
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.345652 °	38.345618 °	
			-121.544482 °	-121.545122 °	
DWR ID	DWR_RD0755_01_f_2018_17				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	M	Issue No.	26
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.345103 °	38.345103 °	
			-121.547918 °	-121.547918 °	
DWR ID	DWR_RD0755_01_f_2018_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	C	Issue No.	27
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.345070 °	38.345070 °	
			-121.547985 °	-121.547985 °	
DWR ID	DWR_RD0755_01_f_2018_27				
Comment Code					
GA : Garbage					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	51	
LM End	0.70	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °	
				-121.548050 °	-121.548050 °	
DWR ID	18852					
Comment Code						
Inspector Comment						
DS_ID:18852 FS_ID:17145 EP_NO: 11222 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system. FIELD_STRUCT_DESC: *ABANDONED* 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. (Retention of a 12-inch drainage pipe sleeved through a 24-inch pipe through the levee, 8 feet below the crown, authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005, 12-inch inner pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.89)]. FS Date: 8/6/2013						

LM Start	0.70	Rating **	A/W	Issue No.	51 (cont)
LM End	0.70	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2020_17145_29292.jpg



WS view: pipe and siphon breaker on levee slope

Photo 2 of 3 : UCIP_SP_2020_17145_29293.jpg



WS view: 16-inch pipe sleeved through 24-inch pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	51 (cont)
LM End	0.70	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °
				-121.548050 °	-121.548050 °
DWR ID	18852				

Photo 3 of 3 : UCIP_SP_2020_17145_29295.jpg



WS view: 16-inch drainage pipe on levee slope.

LM Start	0.79	Rating **	M	Issue No.	45
LM End	0.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.344612 °	38.344612 °
				-121.549752 °	-121.549752 °
DWR ID	DWR_RD0755_01_f_2019_45				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.99	Rating **	C	Issue No.	29
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343835 °	38.343835 °
				-121.553162 °	-121.553162 °
DWR ID	DWR_RD0755_01_f_2018_29				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0755 Randall

View of tree at the top of the waterside shoulder (Spring 2019).

No Photos

View looking downstream at tree on the waterside slope (Spring 2020).

Page 9 of 15

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	LMA-155				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length. Site ID No:328 Site Designation:LMA-155 3/25/2020 Field Notes: Erosion is into berm and not prism. A boat survey would get a better look. Monitor.					

Photo 1 of 3 : SP_2020_RD0755_177_22_20200304_00010.jpg



LM Start	1.23	Rating **	A/W	Issue No.	22 (cont)
LM End	1.29	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP_2020_RD0755_177_22_20200304_00011.jpg

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22 (cont)
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	LMA-155				

Photo 3 of 3 : SP_2020_RD0755_177_22_20200304_00012.jpg



LM Start	1.26	Rating **	C	Issue No.	42
LM End	1.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.342632 °	38.342632 °
				-121.558008 °	-121.558008 °
DWR ID	DWR_RD0755_01_f_2019_42				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.32	Rating **	M	Issue No.	40
LM End	1.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.342274 °	38.341170 °
				-121.559014 °	-121.560208 °
DWR ID	DWR_RD0755_01_f_2019_40				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD0755_177_40_20200330_00071.jpg



View looking downstream at vegetation on the landside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.39	Rating **	M	Issue No.	41
LM End	1.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.341510 °	38.341510 °
				-121.559892 °	-121.559892 °
DWR ID	DWR_RD0755_01_f_2019_41				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.42	Rating **	M	Issue No.	34
LM End	1.42	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.341205 °	38.341205 °
				-121.560122 °	-121.560122 °
DWR ID	DWR_RD0755_01_s_2019_34				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Multiple rodent holes are on the crown, including one that was 2' deep.					

Photo 1 of 2 : SP_2020_RD0755_177_34_20200304_00023.jpg



View of 2 foot deep rodent hole on the landside of the crown (Spring 2019).

LM Start	1.42	Rating **	M	Issue No.	34 (cont)
LM End	1.42	Issue Type +	Ma	Location *	CR

Photo 2 of 2 : SP_2020_RD0755_177_34_20200304_00024.jpg



Measuring tape showing rodent hole as being 2 feet deep on the landside of the crown (Spring 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.45	Rating **	M	Issue No.	39
LM End	1.45	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.340948 °	38.340948 °
				-121.560482 °	-121.560482 °
DWR ID	DWR_RD0755_01_s_2020_39				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.45	Rating **	C	Issue No.	38
LM End	1.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.340907 °	38.340577 °
				-121.560505 °	-121.560800 °
DWR ID	DWR_RD0755_01_f_2019_38				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	1.53	Rating **	U	Issue No.	36
LM End	1.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339867 °	38.339867 °
				-121.561397 °	-121.561397 °
DWR ID	DWR_RD0755_01_f_2019_36				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD0755_177_36_20200304_00026.jpg



View looking downstream at thick trees on the waterside slope (Fall 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.61	Rating **	U	Issue No.	37
LM End	1.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339030 °	38.339030 °
				-121.562232 °	-121.562232 °
DWR ID	DWR_RD0755_01_f_2019_37				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD0755_177_37_20200330_00072.jpg



View looking downstream of tree branches directly on waterside slope (Spring 2020).

LM Start	1.73	Rating **	A/W	Issue No.	24
LM End	1.81	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.337758 °	38.336789 °
				-121.563856 °	-121.564739 °
DWR ID	LMA-156				
Comment Code					
Inspector Comment					
Planned For Repair.					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 424 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos.					
Site location T06N R04E Section 29.					
Site ID No:329					
Site Designation:LMA-156					
Repair Type: Erosion					
Rating:Serious					
Field Date:7/13/2017					
Notes: Crown is a paved road. Large LS berm on part. Good visibility here. Serious because erosion cut into prism significantly for a long distance and soils are very sandy here and WS slope is very steep.					

Photo 1 of 3 : SP_2020_RD0755_177_24_20200304_00014.jpg



* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/25/2020 03/25/2020	David Julian

LM Start	1.73	Rating **	A/W	Issue No.	24 (cont)
LM End	1.81	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		38.337758 °	38.336789 °	
			-121.563856 °	-121.564739 °	
DWR ID	LMA-156				

Photo 2 of 3 : SP_2020_RD0755_177_24_20200304_00015.jpg



LM Start	1.73	Rating **	A/W	Issue No.	24 (cont)
LM End	1.81	Issue Type +	Ma	Location *	

Photo 3 of 3 : SP_2020_RD0755_177_24_20200304_00016.jpg



LM Start	1.81	Rating **	M	Issue No.	12
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.336812 °	38.336812 °
				-121.564551 °	-121.564551 °
DWR ID	DWR_RD0755_01_s_2020_12				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---