

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Comment Code					
Inspector Comment					
This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Comment Code					
Inspector Comment					
District maintains supply of sand bags and gets other supplies from other districts.					

No Photos

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Comment Code					
Inspector Comment					
MBK Engineering mailed a copy of the O/M Manual to the RD President in spring of 2017.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

### Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	<b>0.07</b>	Rating **	M	Issue No.	<b>42</b>
LM End	<b>0.15</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.347353 °	38.346886 °	
			-121.537034 °	-121.538322 °	
DWR ID	DWR_RD0755_01_s_2021_42				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	<b>0.18</b>	Rating **	M	Issue No.	<b>51</b>
LM End	<b>1.82</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.346675 °	38.336686 °	
			-121.538850 °	-121.564620 °	
DWR ID	DWR_RD0755_01_f_2021_51				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	<b>0.18</b>	Rating **	M	Issue No.	<b>39</b>
LM End	<b>1.49</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.346608 °	38.340374 °	
			-121.538843 °	-121.560885 °	
DWR ID	DWR_RD0755_01_s_2022_39				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	0.20	Rating **	M	Issue No.	4
LM End	0.92	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.346500 °	38.344130 °
				-121.539146 °	-121.552038 °
DWR ID	DWR_RD0755_01_f_2014_4				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Evidence of active rodents on landside slope. LMA has started baiting.					

Photo 1 of 2 : SP\_2022\_RD0755\_177\_4\_20220307\_00001.jpg



View looking downstream at fresh animal hole on the landside slope (Spring 2020).

LM Start	<b>0.20</b>	Rating **	M	Issue No.	<b>4 (cont)</b>
LM End	<b>0.92</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2022\_RD0755\_177\_4\_20220307\_00002.jpg



View a couple animal holes on the landside slope (Spring 2020).

LM Start	0.21	Rating **	M	Issue No.	10	
LM End	0.21	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			38.346428 °		38.346428 °
				-121.539400 °		-121.539400 °
DWR ID	DWR_RD0755_01_s_2019_10					
Comment Code						
S1 : Repair slope instability.						
Inspector Comment						
There is a 2" seperation between roadway and levee on the landside shoulder.						

Photo 1 of 1 : SP\_2022\_RD0755\_177\_10\_20220307\_00003.jpg



View looking upstream at small slip on the landside shoulder (Spring 2019).

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	0.28	Rating **	U	Issue No.	18
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.346249 °	38.346331 °
				-121.540542 °	-121.540664 °
DWR ID	DWR_RD0755_01_s_2020_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 27 feet in length. Site ID No:327 Site Designation:LMA-154 3/25/2020 Field Notes: Erosion is significant. At least 1' into waterside slope. No riprap present.					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_18\_20220307\_00005.jpg



View looking upstream and slightly up at erosion into the waterside slope (Spring 2020).

LM Start	0.50	Rating **	M	Issue No.	17
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345652 °	38.345618 °
				-121.544482 °	-121.545122 °
DWR ID	DWR_RD0755_01_f_2018_17				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	0.58	Rating **	M	Issue No.	43
LM End	0.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345510 °	38.345510 °
				-121.545929 °	-121.545929 °
DWR ID	DWR_RD0755_01_f_2021_43				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	M	Issue No.	26
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345103 °	38.345103 °
				-121.547918 °	-121.547918 °
DWR ID	DWR_RD0755_01_f _ 2018_26				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	0.70	Rating **	M	Issue No.	21
LM End	0.70	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °
				-121.548050 °	-121.548050 °
DWR ID	18852				
Comment Code					
Inspector Comment					
FS_ID:57038 DS_ID:18852 EP_NO: 11222 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 05/26/2020 Record updated from No Action Needed to Non-Urgent. No permit has been identified authorizing pipe. Pipe was running during site visit pumping water to the waterside. (O.Yakimov - DWR UCIP) 08/06/2013 It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system. FIELD_STRUCT_DESC: 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. Air vent installed on the pipe on WS slope. Concrete headwall on LS. (12-inch pipe sleeved through 24-inch pipe-inch pipe [HLM 0.71] authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005 (HLM 0.71), referenced as 12-inch pipe through 24-inch pipe. USACE Sacramento O&M Manual, Unit 111, May 1959, Revised 29 December 2016, (RM 35.89), listed as 24-inch pipe]. FS Date: 5/26/2020 3:00:07 PM					

LM Start	<b>0.70</b>	Rating **	M	Issue No.	<b>21 (cont)</b>
LM End	<b>0.70</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_SP\_2022\_57038\_84440.jpg



Top of Levee: View of levee crown looking downstream

Photo 2 of 3 : UCIP\_SP\_2022\_57038\_84442.jpg



Water-Side: View of levee slope looking from crown

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

# Reclamation District No. 0755 Randall



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

### Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.01	Rating **	M	Issue No.	59
LM End	1.01	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.343726 °	38.343726 °
				-121.553526 °	-121.553526 °
DWR ID	DWR_RD0755_01_f _ 2021_59				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_59\_20220307\_00022.jpg



View of animal holes in the landside slope (Fall 2021).

LM Start	1.06	Rating **	M	Issue No.	31
LM End	1.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343542 °	38.343542 °
				-121.554487 °	-121.554487 °
DWR ID	DWR_RD0755_01_s_2019_31				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees are blocking visibility down waterside slope.					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_31\_20220307\_00011.jpg



View of tree at the top of the waterside shoulder (Spring 2019).

LM Start	1.10	Rating **	M	Issue No.	47
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343422 °	38.343422 °
				-121.555217 °	-121.555217 °
DWR ID	DWR_RD0755_01_s_2021_47				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

### Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.17	Rating **	M	Issue No.	58
LM End	1.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.343087 °	38.343087 °
				-121.556488 °	-121.556488 °
DWR ID	DWR_RD0755_01_f_2021_58				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					


Photo 1 of 1 : SP\_2022\_RD0755\_177\_58\_20220307\_00021.jpg



View of animal hole in the landside slope (Fall 2021).

LM Start	1.18	Rating **	U	Issue No.	28
LM End	1.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343072 °	38.343072 °
				-121.556532 °	-121.556532 °
DWR ID	DWR_RD0755_01_f_2019_28				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_28\_20220307\_00010.jpg



View looking downstream at tree on the waterside slope (Fall 2021).

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	LMA-155				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length. Site ID No:328 Site Designation:LMA-155 6/18/2020 Field Notes: Erosion is into berm and not prism.					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_22\_20220307\_00007.jpg



LM Start	1.24	Rating **	M	Issue No.	57
LM End	1.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.342816 °	38.342816 °
				-121.557659 °	-121.557659 °
DWR ID	DWR_RD0755_01_f_2021_57				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.26	Rating **	M	Issue No.	56
LM End	1.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.342692 °	38.342692 °
				-121.558053 °	-121.558053 °
DWR ID	DWR_RD0755_01_f_2021_56				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.28	Rating **	M	Issue No.	48
LM End	1.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.342602 °	38.342602 °
				-121.558360 °	-121.558360 °
DWR ID	DWR_RD0755_01_s_2021_48				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.29	Rating **	U	Issue No.	55
LM End	1.29	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.342526 °	38.342526 °
				-121.558481 °	-121.558481 °
DWR ID	DWR_RD0755_01_f_2021_55				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Multiple fresh rodent holes.					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_55\_20220307\_00020.jpg



View of animal holes in the landside slope (Fall 2021).

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

### Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.39	Rating **	M	Issue No.	41
LM End	1.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.341510 °	38.341510 °
				-121.559892 °	-121.559892 °
DWR ID	DWR_RD0755_01_f_2019_41				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.49	Rating **	M	Issue No.	52
LM End	1.49	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.340326 °	38.340326 °
				-121.560948 °	-121.560948 °
DWR ID	DWR_RD0755_01_f_2021_52				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_52\_20220311\_00079.jpg



View of animal hole in the landside slope (Spring 2022).

LM Start	1.55	Rating **	U	Issue No.	36
LM End	1.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339689 °	38.339689 °
				-121.561576 °	-121.561576 °
DWR ID	DWR_RD0755_01_f_2019_36				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_36\_20220307\_00014.jpg



View looking downstream at thick trees on the waterside slope (Fall 2019).

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.57	Rating **	M	Issue No.	49
LM End	1.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.339484 °	38.337683 °
				-121.561739 °	-121.563707 °
DWR ID	DWR_RD0755_01_f _ 2021_49				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	1.61	Rating **	U	Issue No.	37
LM End	1.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339030 °	38.339030 °
				-121.562232 °	-121.562232 °
DWR ID	DWR_RD0755_01_f _ 2019_37				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2022\_RD0755\_177\_37\_20220307\_00015.jpg



View looking downstream at thick tree on the waterside slope (Spring 2021).

LM Start	1.73	Rating **	M	Issue No.	40
LM End	1.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.337682 °	38.337682 °
				-121.563707 °	-121.563707 °
DWR ID	DWR_RD0755_01_f_2021_40				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side    N/A : Not Applicable		A : Acceptable		Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable		Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable		En : Enforcement	
		N : Not Inspected/Rated			
		C : Corrected			
		A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

### Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/11/2022 03/11/2022	David Julian

LM Start	1.81	Rating **	M	Issue No.	12
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.336812 °	38.336812 °
				-121.564551 °	-121.564551 °
DWR ID	DWR_RD0755_01_s_2020_12				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---