

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0785_01_s_2013_3				
Comment Code					
Inspector Comment					
LMA has emergency supplies and equipment at the firehouse.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0785_01_s_2013_7				
Comment Code					
Inspector Comment					
LMA is current with flood fight training.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0785_01_s_2012_10				
Comment Code					
Inspector Comment					
LMA has the O&M Manual at the firehouse.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	0.11	Rating **	U	Issue No.	9	
LM End	0.11	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.660211 °		38.660211 °
				-121.611748 °		-121.611748 °
DWR ID	DWR_RD0785_01_f_2017_9					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Runoff erosion on landside slope that has gotten worse.						

LM Start	0.11	Rating **	U	Issue No.	9 (cont)
LM End	0.11	Issue Type +	Ma	Location *	LS

Photo 1 of 5 : FA_2018_RD0785_185_9_20181105_00047.jpg



Updated view of erosion on the landside slope. Fall 2018.

Photo 2 of 5 : FA_2018_RD0785_185_9_20181105_00048.jpg



Additional view of erosion on the landside slope. Fall 2018.

LM Start	0.11	Rating **	U	Issue No.	9 (cont)
LM End	0.11	Issue Type +	Ma	Location *	LS

Photo 3 of 5 : FA_2018_RD0785_185_9_20180904_00006.jpg



View of runoff on the landside slope. Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	0.11	Rating **	U	Issue No.	9 (cont)	
LM End	0.11	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.660211 °	38.660211 °	
				-121.611748 °	-121.611748 °	
DWR ID	DWR_RD0785_01_f_2017_9					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Runoff erosion on landside slope that has gotten worse.						

Photo 4 of 5 : FA_2018_RD0785_185_9_20180904_00007.jpg



Additional view of runoff on the landside slope. Spring 2018.

LM Start	0.11	Rating **	U	Issue No.	9 (cont)
LM End	0.11	Issue Type +	Ma	Location *	LS

Photo 5 of 5 : FA_2018_RD0785_185_9_20180904_00008.jpg



View of runoff erosion on the landside slope. Fall 2017.

LM Start	0.21	Rating **	M	Issue No.	16
LM End	1.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.659340 °	38.646093 °
				-121.610405 °	-121.598518 °
DWR ID	DWR_RD0785_01_f_2013_16				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 2 : FA_2018_RD0785_185_16_20180904_00013.jpg



Brush and other vegetation partially blocks visibility or access to the levee slope. Fall 2013

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	0.21	Rating **	M	Issue No.	16 (cont)	
LM End	1.35	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.659340 °		38.646093 °
				-121.610405 °		-121.598518 °
DWR ID	DWR_RD0785_01_f_2013_16					
Comment Code						
V2 : Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comment						

Photo 2 of 2 : FA_2018_RD0785_185_16_20180904_00014.jpg



Brush and other vegetation partially blocks visibility. Spring 2014

LM Start	0.24	Rating **	M	Issue No.	24
LM End	0.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.658998 °	38.658998 °
				-121.610081 °	-121.610081 °
DWR ID	DWR_RD0785_01_s_2017_24				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff erosion on waterside slope.					

Photo 1 of 1 : FA_2018_RD0785_185_24_20180904_00017.jpg



Runoff erosion on waterside levee slope. Spring 2017.

LM Start	0.28	Rating **	N	Issue No.	36
LM End	0.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.658537 °	38.658537 °
				-121.609675 °	-121.609675 °
DWR ID	DWR_RD0785_01_s_2017_36				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : FA_2018_RD0785_185_36_20180904_00023.jpg



View of stump on landside levee slope. Spring 2017.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	0.28	Rating **	A/W	Issue No.	1
LM End	0.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.658467°	38.658467°
				-121.609573°	-121.609573°
DWR ID	DWR_RD0785_01_s_2012_1				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	0.40	Rating **	A/W	Issue No.	2
LM End	0.44	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.657168°	38.656697°
				-121.608270°	-121.607845°
DWR ID	DWR_RD0785_01_s_2012_2				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	0.45	Rating **	A/W	Issue No.	50
LM End	0.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.656502 °	38.656440 °
				-121.607623 °	-121.607571 °
DWR ID	DWR_RD0785_01_s_2018_50				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	0.85	Rating **	A/W	Issue No.	5
LM End	0.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.651863 °	38.650777 °
				-121.604158 °	-121.603182 °
DWR ID	DWR_RD0785_01_s_2012_5				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	0.86	Rating **	M	Issue No.	18
LM End	0.86	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.651790 °	38.651790 °
				-121.604014 °	-121.604014 °
DWR ID	DWR_RD0785_01_s_2018_18				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree on the waterside slope.					

No Photos

LM Start	0.99	Rating **	N	Issue No.	28
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.650055 °	38.650055 °
				-121.602752 °	-121.602752 °
DWR ID	DWR_RD0785_01_f_2016_28				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : FA_2018_RD0785_185_28_20180904_00019.jpg



Two tree stumps near levee toe on landside. Fall 2016.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	1.07	Rating **	C	Issue No.	48
LM End	1.07	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.649392°	38.649392°
				-121.601636°	-121.601636°
DWR ID	DWR_RD0785_01_s_2012_48				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

No Photos

LM Start	1.19	Rating **	M	Issue No.	44
LM End	1.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.647965 °	38.647753 °
				-121.600228 °	-121.599963 °
DWR ID	DWR_RD0785_01_f_2016_44				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	1.30	Rating **	A/W	Issue No.	6
LM End	1.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.646712 °	38.646712 °
				-121.599095 °	-121.599095 °
DWR ID	DWR_RD0785_01_s_2012_6				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_RD0785_185_6_20180904_00004.jpg



View of elderberry trees on LS slope. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	1.31	Rating **	M	Issue No.	13
LM End	1.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.646652 °	38.646652 °
				-121.598907 °	-121.598907 °
DWR ID	DWR_RD0785_01_s_2013_13				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Footpath on the waterside slope.					

LM Start	1.31	Rating **	M	Issue No.	13 (cont)
LM End	1.31	Issue Type +	Ma	Location *	WS

Photo 1 of 4 : FA_2018_RD0785_185_13_20180904_00009.jpg



Updated view of slope stability on the waterside slope. Spring 2018.

Photo 2 of 4 : FA_2018_RD0785_185_13_20180904_00010.jpg



Updated view of the slope stability site. Fall 2016.

LM Start	1.31	Rating **	M	Issue No.	13 (cont)
LM End	1.31	Issue Type +	Ma	Location *	WS

Photo 3 of 4 : FA_2018_RD0785_185_13_20180904_00011.jpg



Updated view of the slope stability site. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	1.31	Rating **	M	Issue No.	13 (cont)
LM End	1.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.646652 °	38.646652 °
				-121.598907 °	-121.598907 °
DWR ID	DWR_RD0785_01_s_2013_13				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Footpath on the waterside slope.					

Photo 4 of 4 : FA_2018_RD0785_185_13_20180904_00012.jpg



View of the slope stability on the waterward side of the levee. Fall 2015.

LM Start	1.51	Rating **	M	Issue No.	55
LM End	1.51	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.644349 °	38.644349 °
				-121.596506 °	-121.596506 °
DWR ID	DWR_RD0785_01_f_2017_55				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff on waterside slope.					

Photo 1 of 1 : FA_2018_RD0785_185_55_20180904_00032.jpg



View of the runoff erosion on the waterside slope. Fall 2017.

LM Start	1.61	Rating **	C	Issue No.	22
LM End	1.62	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.643359 °	38.643229 °
				-121.595237 °	-121.595011 °
DWR ID	DWR_RD0785_01_s_2016_22				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trees still need trimming.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.26	11/05/2018 11/05/2018	Zach Jojola

LM Start	1.66	Rating **	C	Issue No.	25
LM End	1.66	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.642942 °	38.642942 °
				-121.594523 °	-121.594523 °
DWR ID	DWR_RD0785_01_f_2017_25				
Comment Code					
PR : Prunings					
Inspector Comment					
Pruning pile on waterside slope.					

No Photos

LM Start	1.68	Rating **	N	Issue No.	356
LM End	1.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.642650 °	38.642650 °
				-121.594168 °	-121.594168 °
DWR ID	DWR_RD0785_01_s_2015_356				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	2.23	Rating **	A/W	Issue No.	19
LM End	2.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.642908 °	38.642908 °
				-121.584647 °	-121.584647 °
DWR ID	DWR_RD0785_01_s_2018_19				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Runoff erosion on waterside slope. Recommend monitoring.					

Photo 1 of 1 : FA_2018_RD0785_185_19_20180904_00015.jpg



View of runoff erosion on the waterside slope. Fall 2017.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0785 Driver

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	3.31	10/24/2018 10/24/2018	Zach Jojola

LM Start	1.52	Rating **	M	Issue No.	24
LM End	1.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.621694 °	38.621694 °
				-121.607610 °	-121.607610 °
DWR ID	DWR_RD0785_02_s_2017_24				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Footpath for environmental access site. There is a noticeable dip on the waterside slope.					

Photo 1 of 1 : FA_2018_RD0785_186_24_20180904_00004.jpg



View of slope stability on waterside levee slope. Spring 2017.

LM Start	1.76	Rating **	A/W	Issue No.	8
LM End	1.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.618651 °	38.618651 °
				-121.605307 °	-121.605307 °
DWR ID	DWR_RD0785_02_s_2018_8				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Beginning of small rill on the waterside slope. Recommend monitoring.					

No Photos

LM Start	3.26	Rating **	A/W	Issue No.	5
LM End	3.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Cracking			38.600148 °	38.600148 °
				-121.590880 °	-121.590880 °
DWR ID	DWR_RD0785_02_f_2018_5				
Comment Code					
CR1 : Monitor and have inspected by geotechnical engineer.					
Inspector Comment					
Cracking on the waterside shoulder. Approximately 50' long. Recommend monitoring.					

Photo 1 of 1 : FA_2018_RD0785_186_5_20181025_00008.jpg



View of cracks on the waterside shoulder. Fall 2018.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement