

Flood Control Project Maintenance Levee Inspections

Fall 2021 Levee Maintenance Deficiency Summary Report

Sacramento River Basin

RD0827	Overall LMA Rating	Total LMA Miles						
Reclamation District No. 0827 Elkhorn	A	4.12						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments	0.01		0.01	0.24%	0.04	0.17		
Animal Control	0.01		0.01	0.24%				
Erosion / Bank Caving	0.01		0.01	0.24%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.06			
<i>LMA Totals:</i>	0.03	0.00	0.03	0.73%	0.10	0.17	0.00	0.00
Unit No. 01 Sacramento River RB	Overall Unit Rating	Total Unit Miles						
RD0827	A	1.34						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.04	0.17		
Erosion / Bank Caving	0.01		0.01	0.75%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.02			
<i>Unit Totals:</i>	0.01	0.00	0.01	0.75%	0.06	0.17	0.00	0.00
Unit No. 02 Yolo Bypass LB	Overall Unit Rating	Total Unit Miles						
RD0827	A	2.78						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments	0.01		0.01	0.36%				
Animal Control	0.01		0.01	0.36%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.04			
<i>Unit Totals:</i>	0.02	0.00	0.02	0.72%	0.04	0.00	0.00	0.00

Flood Control Project Maintenance Levee Inspections LMA District Cover Sheet

Reclamation District No. 0827 Elkhorn

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			A	

**** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.**

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet**

Reclamation District No. 0827 Elkhorn

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.34
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/20/2021 - 4/20/2021		10/27/2021 - 10/27/2021	
DWR Inspector	Zach Jojola		Zach Jojola	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	10/27/2021 10/27/2021	Zach Jojola

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_RD0827_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 827 has a copy of the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD0827_01_f_2020_7				
Comment Code					
Inspector Comment					
RD 827 shares a maintained stockpile of Flood Response Material with RD 785.					

No Photos

LM Start		Rating **	A	Issue No.	9		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD0827_01_s_2020_9						
Comment Code							
Inspector Comment							
RD 827 works jointly with RD 785 on Flood Preparedness and Training.							

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	10/27/2021 10/27/2021	Zach Jojola

LM Start	0.00	Rating **	M	Issue No.	31	
LM End	0.00	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.661210 °	38.661210 °	
				-121.613030 °	-121.613030 °	
DWR ID	21163					
Comment Code						
Inspector Comment						
DS_ID:21163 FS_ID:39703 EP_NO: N/A Repair Type: Non-Urgent EVAL Issue: Crossing Status: Not Found UCIP Comments: No pipe was found only what appears to be an abandoned pump house on landward side. Need to contact owner to determine status of crossing. FIELD_STRUCT_DESC: 30-inch steel pipe through the levee, 9.1 feet below the crown. Pump in pump house on landward side not waterward side as mentioned in desk study. (USACE-1955). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (RM 69.50). FS Date: 3/18/2014						

No Photos

LM Start	0.00	Rating **	U	Issue No.	30
LM End	0.16	Issue Type +	En	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.675168 °	38.673575 °
				-121.630530 °	-121.628398 °
DWR ID	DWR_RD0827_01_s_2020_30				
Comment Code					
EQ : Equipment					
Inspector Comment					
Sierra Railroad has placed track and rail cars on the crown that prevent vehicle access. They have constructed a new ramp and berm to access the portion of levee that does not have track on the crown.					

Photo 1 of 1 : FA_2021_RD0827_187_30_20210907_00006.jpg



View of ramp to adjacent waterside berm. Fall 2020.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	10/27/2021 10/27/2021	Zach Jojola

LM Start	0.03	Rating **	U	Issue No.	20
LM End	0.03	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.674912 °	38.674912 °
				-121.630133 °	-121.630133 °
DWR ID	DWR_RD0827_01_f_2019_20				
Comment Code					
BU : Building					
Inspector Comment					
Sacramento River Train has constructed their office and a ticket booth on the waterside shoulder and crown.					

Photo 1 of 1 : FA_2021_RD0827_187_20_20210907_00003.jpg



View of ticket booth on crown. Fall 2020.

LM Start	0.23	Rating **	M	Issue No.	12
LM End	0.27	Issue Type +	En	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.672803 °	38.672400 °
				-121.627416 °	-121.626890 °
DWR ID	DWR_RD0827_01_s_2016_12				
Comment Code					
MA : Material					
Inspector Comment					
RR rails and ties on the levee crown.					

Photo 1 of 1 : FA_2021_RD0827_187_12_20210907_00001.jpg



View of railroad ties on the crown. Fall 2018.

LM Start	0.34	Rating **	M	Issue No.	21
LM End	0.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.671773 °	38.671773 °
				-121.626077 °	-121.626077 °
DWR ID	DWR_RD0827_01_f_2019_21				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion on the waterside shoulder.					

Photo 1 of 1 : FA_2021_RD0827_187_21_20211102_00010.jpg



View of erosion on the waterside slope. Fall 2021.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	10/27/2021 10/27/2021	Zach Jojola

LM Start	0.73	Rating **	M	Issue No.	32 (cont)
LM End	0.73	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.667731 °	38.667731 °
				-121.620992 °	-121.620992 °
DWR ID	21147				

Photo 2 of 3 : UCIP_FA_2021_38983_59736.jpg



Pipe visible on waterward side.

LM Start	0.73	Rating **	M	Issue No.	32 (cont)
LM End	0.73	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2021_38983_59735.jpg



Slant pump located on waterward side.

LM Start	1.02	Rating **	A/W	Issue No.	18
LM End	1.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.664690 °	38.664690 °
				-121.617266 °	-121.617266 °
DWR ID	DWR_RD0827_01_f_2018_18				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Minor runoff on the waterside slope. Recommend monitoring.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	10/27/2021 10/27/2021	Zach Jojola

LM Start	1.09	Rating **	A/W	Issue No.	17
LM End	1.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663946 °	38.663946 °
				-121.616453 °	-121.616453 °
DWR ID	DWR_RD0827_01_s _ 2019_17				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Previous runoff site that has filled in with material. Recommend monitoring.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet**

Reclamation District No. 0827 Elkhorn

Waterway			Bank	Unit Miles
Unit No. 02 Yolo Bypass			Left	2.78
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/20/2021 - 4/20/2021		10/27/2021 - 10/27/2021	
DWR Inspector	Zach Jojola		Zach Jojola	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	0.02	Rating **	A	Issue No.	7
LM End	0.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.676569 °	38.676569 °
				-121.642692 °	-121.642692 °
DWR ID	DWR_RD0827_02_f_2021_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The LMA maintains the vegetation at a high level.					

Photo 1 of 1 : FA_2021_RD0827_188_7_20211102_00015.jpg



View of maintained landside slope. Fall 2021.

LM Start	0.10	Rating **	M	Issue No.	5
LM End	0.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.675397 °	38.675397 °
				-121.643025 °	-121.643025 °
DWR ID	DWR_RD0827_02_s_2021_5				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Active rodent holes on the landside slope.					

Photo 1 of 1 : FA_2021_RD0827_188_5_20210907_00001.jpg



View of rodent holes on the landside slope. Spring 2021.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	1.00	Rating **	M	Issue No.	14
LM End	1.00	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.663485 °	38.663485 °
				-121.637021 °	-121.637021 °
DWR ID	24844				

Comment Code

Inspector Comment

DS_ID:24844
FS_ID:50065
EP_NO: 17403
Repair Type: Non-Urgent
EVAL Issue:
Crossing Status: Indicator Found
UCIP Comments: 9/27/2016 Need to coordinate with Greg Lucas (gregory.lucas@crc.com) with California Resources Corporation to determine if line will be brought online. Crossing was downgraded from Urgent to Non-Urgent--new owner has not brought the pipe online. New owner will need to update permit name and if line becomes active markers will be required per Title 23. (DWR UCIP - omagana)9/02/2016 Meet with Jimmy Preston from California Resources Corporation at site. Alignment of crossing was confirmed (new location is approximately 290 feet upstream from previous point)--report has been updated. Pending action -- Name Change (DWR UCIP - omagana)9/01/2016 Email was sent to Greg Lucas from California Resources Corporation with an updated UCIP detailed report and Central Valley Flood Protection Board (CVFPB) name change form. New owner will need to update permit information with the CVFPB to be compliant with Title 23 requirements. (DWR UCIP - omagana)8/31/2016 New owner--California Resources Corporation. Gas line is currently not in use.Meet with Greg Lucas, Assistant Production Coordinator from California Resources Corporation and Steve Stein from Noble Methan, Inc. to clarify current status of crossing and determine crossing alignment. Gas well is part of the gas line appurtenances. Gas line alignment is still pending--California Resources Corporation will send out someone to confirm alignment. Crossing is missing markers, if line becomes active markers will be needed on both the WS and LS to comply with Title 23--encouraged owner to contact CVFPB. (DWR UCIP - omagana)8/30/2016 Coordinating with AA Production Services, Inc. to determine location of where crossing goes through levee. It appears that the gas well located on LS is not part of this crossing. (DWR UCIP - omagana)8/04/2016 Meet with Bill Mattos, representative of RD 827, and he took me to the gas well visible from levee crown. Mr. Mattos was unable to confirm if gas well and pipeline that goes through the levee were connected.3/18/2014 No markers visible on either banks. Need to contact owner to determine status of crossing. Need date of last inspection and confirmation that crossing is still in operable condition. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: [Hanks 34-2] 2.375-inch steel natural gas pipe through the levee, 30 feet below the crown and under (bored) Tule Canal. Gas well is located on the landside (LS) approximately 994 feet from levee crown. California Resources Corporation acquired AA Production Services, Inc. The new owner of the 2.375-inch gas pipe is California Resources Corporation. (2.375-inch line authorized under

Photo 1 of 3 : UCIP_FA_2021_50065_75673.jpg



View of WS--Tule Canal.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

Permit No. 17403, 2001 - AA Production Services, Inc.)
FS Date: 8/4/2016

LM Start	1.00	Rating **	M	Issue No.	14 (cont)
LM End	1.00	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2021_50065_75672.jpg



View of levee crown at crossing--yellow flag markers visible on both WS and LS shoulder.

LM Start	1.00	Rating **	M	Issue No.	14 (cont)
LM End	1.00	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2021_50065_75671.jpg



View of LS.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.03	Rating **	M	Issue No.	15
LM End	2.03	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.651052 °	38.651052 °
				-121.626501 °	-121.626501 °
DWR ID	21159				
Comment Code					
Inspector Comment					
DS_ID:21159 FS_ID:53087 EP_NO: 15904 Repair Type: Non-Urgent EVAL Issue: Crossing Status: Indicator Found UCIP Comments: 10/25/2018 Markers on levee not found. Pipe not in use. Valve located on pipe bend near ditch on LS is shut down. Crossing has been downgraded to "Non-Urgent" due to reclassification of gas lines. (O.Yakimov - DWR UCIP) 8/31/2016 Meet with Greg Lucas, Assistant Production Coordinator from California Resources Corporation and Steve Steim from Noble Methan, Inc. to discuss the status of a different line upstream. Mr. Steve Steim was aware of the 3-inch line by Two Bay Petroleum as known as a PG&E old pipe at this location. According to Steve Stein the appurtenances previously located on the landside have been removed and the 3-inch line abandoned. Need to contact owner to confirm status of crossing. If crossing is no longer in use the owner will need to coordinate with CVFPB to comply with Title 23. (DWR UCIP - omagana)8/04/2016 No markers found on either WS or LS. Need to coordinate with owner to determine status of crossing. (DWR UCIP - omagana)3/10/2015 Sign missing on WS and LS. Need to confirm status of crossing with permittee. Appears abandoned. (DWR UCIP - wwylie) 03/18/2014 crossing not found. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 3-inch steel gas pipeline through the levee, 20 feet below the crown. Sign on waterside (WS) (not found 2015). Yellow pipe visible east of ditch approximately 150 feet off landside (LS) toe. Contact Number 415-459-3445 for Two Bay Petroleum also referred as Pacific Energetics, Inc. (3-inch line authorized under Permit No. 15904, 1992 - Two Bay Petroleum) FS Date: 10/25/2018 10:29:07 AM					

Photo 1 of 3 : UCIP_FA_2021_53087_78352.jpg



Gas pipe with shut-down valve closed.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.03	Rating **	M	Issue No.	15 (cont)
LM End	2.03	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.651052 °	38.651052 °	
			-121.626501 °	-121.626501 °	
DWR ID	21159				

Photo 2 of 3 : UCIP_FA_2021_53087_78353.jpg



Closer view of gas pipe with shut-down valve closed.

LM Start	2.03	Rating **	M	Issue No.	15 (cont)
LM End	2.03	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2021_53087_78354.jpg



View of WS slope at crossing.

LM Start	2.62	Rating **	M	Issue No.	6
LM End	2.62	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.643375 °	38.643375 °
				-121.621776 °	-121.621776 °
DWR ID	DWR_RD0827_02_s_2018_6				
Comment Code					
DE : Debris					
Inspector Comment					
Fridge on the waterside slope.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.72	Rating **	A/W	Issue No.	13
LM End	2.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.642139 °	38.642028 °
				-121.620750 °	-121.620667 °
DWR ID	RD 827-01				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Sloughing on the landside slope near pump. Movement has stabilized and the LMA will be constructing a setback levee within the next few years. The current levee will be degraded. Recommend monitoring.					
Site ID No:199					
Site Designation:RD 827-01					

Photo 1 of 1 : FA_2021_RD0827_188_13_20210907_00002.jpg



View of sloughing on the landside slope. Fall 2020.

LM Start	2.73	Rating **	M	Issue No.	16	
LM End	2.73	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.641922 °	38.641922 °	
				-121.620884 °	-121.620884 °	
DWR ID	21151					
Comment Code						
Inspector Comment						
DS_ID:21151 FS_ID:38984 EP_NO: 3277 Repair Type: Non-Urgent EVAL Issue: Crossing Status: Found UCIP Comments: Crossing appears to have been removed and replaced under maintenance back in 2008. No permit has been found--need to contact owner to obtain additional information about replacement. Landward slope sloughing--does not appear to be associated with crossing. Landward slope is being monitored by LMA. FIELD_STRUCT_DESC: 18-inch (not 20-inch as noted in desk study) steel drainage pipe through the levee, 4 feet below the crown. Cutoff wall around pipe at center of levee. Siphon breaker on apex of pipe at waterside (WS) shoulder. Pump on pipe structure in drainage ditch at landside (LS) toe. Rock revetment on WS slope. (20-inch drainage pipe authorized under Permit No. 3277, 1960-Reclamation District No. 827; no permit found authorizing the 18-inch pipe) [Additional Reference(s): DWR Levee Logs, 2005] FS Date: 3/18/2014						

Photo 1 of 3 : UCIP_FA_2021_38984_59769.jpg



View of pipe visible on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.73	Rating **	M	Issue No.	16 (cont)
LM End	2.73	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.641922 °	38.641922 °	
			-121.620884 °	-121.620884 °	
DWR ID	21151				

Photo 2 of 3 : UCIP_FA_2021_38984_59768.jpg



View of landward side.

LM Start	2.73	Rating **	M	Issue No.	16 (cont)
LM End	2.73	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2021_38984_59767.jpg



Pipe exposed on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.75	Rating **	M	Issue No.	17
LM End	2.75	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.641633 °	38.641633 °
				-121.620725 °	-121.620725 °
DWR ID	21169				

Comment Code

Inspector Comment

DS_ID:21169
FS_ID:33032
EP_NO: 5611
Repair Type: Non-Urgent
EVAL Issue:
Crossing Status: Found
UCIP Comments: Crossing appears to have been removed and replaced under maintenance back in 2008. No permit has been found--need to contact owner to obtain additional information about replacement.
FIELD_STRUCT_DESC: [RD No. 827 Pumping Plant] 22-inch (not 24-inch as mentioned in desk study) steel drainage pipe through the levee, 8 feet below the crown. Corrugated metal cutoff wall around pipe at center of levee. Siphon breaker on waterside (WS) slope. Flap gate on WS end. Pipe is exposed along WS slope. (portion of pipe was removed and replaced, from landside to waterside shoulder, under Permit No. 5611 (1968)). [Additional Reference(s): DWR Levee Logs, 2005. USACE Sacramento O&M Manual Unit No. 122 Part No. 1, August 1955, (Station 3+75)]
FS Date: 3/18/2014

LM Start	2.75	Rating **	M	Issue No.	17 (cont)
LM End	2.75	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_FA_2021_33032_59778.jpg



Pipe exposed on waterward side.

Photo 2 of 3 : UCIP_FA_2021_33032_59777.jpg



Pump station located on landward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2021

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	10/27/2021 10/27/2021	Zach Jojola

LM Start	2.75	Rating **	M	Issue No.	17 (cont)
LM End	2.75	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.641633 °	38.641633 °
				-121.620725 °	-121.620725 °
DWR ID	21169				

Photo 3 of 3 : UCIP_FA_2021_33032_59776.jpg



Reminise piles located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---