

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	7.70	10/03/2024 10/03/2024	Marvin Marshall

LM Start	0.00	Rating **	A	Issue No.	6					
LM End	0.00	Issue Type +	Ma	Location *	N/A					
Category	Earthen Levee		GPS Latitude/Longitude							
			Start	End						
Item	Operations & Maintenance Manuals									
DWR ID	DWR_RD0900_01_f_2018_6									
Comment Code										
OM : O&M Manuals										
Inspector Comment										
This LMA has the updated O&M manuals for the district.										

No Photos

LM Start	0.00	Rating **	A	Issue No.	12							
LM End	0.00	Issue Type +	Ma	Location *	N/A							
Category	Earthen Levee		GPS Latitude/Longitude									
			Start	End								
Item	Emergency Supplies & Equipment		38.580931°	38.580931°								
			-121.509693°	-121.509693°								
DWR ID	DWR_RD0900_01_s_2013_12											
Comment Code												
ES : Emergency Supplies & Equipment												
Inspector Comment												
This LMA has an adequate amount of sandbags, sand, and various flood fight supplies in their possession.												

No Photos

LM Start	0.00	Rating **	A	Issue No.	16					
LM End	0.00	Issue Type +	Ma	Location *	N/A					
Category	Earthen Levee		GPS Latitude/Longitude							
			Start	End						
Item	Flood Preparedness & Training									
DWR ID	DWR_RD0900_01_s_2013_16									
Comment Code										
FP : Flood Preparedness & Training										
Inspector Comment										
The LMA attended November 2024 Flood Fighting Methods Training.										

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	7.70	10/03/2024 10/03/2024	Marvin Marshall

LM Start	0.04	Rating **	M	Issue No.	2
LM End	0.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.580400°	38.580400°
				-121.510000°	-121.510000°
DWR ID	DWR_RD0900_01_s _ 2024_2				
Comment Code					
T3 : Fallen tree with root ball.					
Inspector Comment					

Photo 1 of 1 : FA\_2024\_RD0900\_230\_2\_20241007\_00010.jpg



Tree with rootball on the WS slope. Fall 2024

LM Start	0.84	Rating **	M	Issue No.	39
LM End	0.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.571150°	38.571150°
				-121.518137°	-121.518137°
DWR ID	DWR_RD0900_01_s _ 2020_39				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Bank erosion observed on high bank condition					

Photo 1 of 1 : FA\_2024\_RD0900\_230\_39\_20240911\_00006.jpg



Bank Erosion. Spring 2024

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.96	Rating **	A	Issue No.	22	
LM End	4.96	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.516274°	38.516274°	
				-121.582198°	-121.582198°	
DWR ID	17880					
Comment Code						
Inspector Comment						
DS_ID:17880 FS_ID:56688 EP_NO: 18116 Repair Type: No Action Needed EVAL Issue: Crossing Status: Found UCIP Comments: 04/15/2020 Record remains No Action Needed. No issues observed during inspection. (D.Sanoski - DWR UCIP) Under construction Oct-2009. Need updated photos of completed structure. FIELD_STRUCT_DESC: [West Sacramento Main Drain Pump Station] 1 of 4: 54-inch steel drainage pipe through the levee, 5 feet below the crown. Pump house is located on the landside (LS), siphon breaker is located on the waterside (WS) slope, and concrete headwall with flap gate at WS end. (54-inch pipe authorized under Permit No. 18116, 2007 - Reclamation District No. 900 [RD0900]. This crossing (group of 4) replaces dual 48-inch (listed as 60-inch) pipe (see DSID 25606, 25607)). [Additional Reference(s): DWR Levee Log, 2003 (HLM 4.97). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 December 2016, (Station 140+00)]. FS Date: 4/15/2020 12:51:19 PM						

LM Start	<b>4.96</b>	Rating **	A	Issue No.	<b>22 (cont)</b>
LM End	<b>4.96</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_FA\_2024\_56688\_83963.jpg



Water-Side: view of WS slope and valve box with welded close lid and concrete headwall with flap gate at toe

Photo 2 of 3 : UCIP\_FA\_2024\_56688\_83964.jpg



Top of Levee: view of levee crown

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.96	Rating **	A	Issue No.	22 (cont)
LM End	4.96	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.516274°	38.516274°
				-121.582198°	-121.582198°
DWR ID	17880				

Photo 3 of 3 : UCIP\_FA\_2024\_56688\_83965.jpg



Land-Side: view of LS slope and pumphouse at toe

LM Start	4.96	Rating **	A	Issue No.	23
LM End	4.96	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.516225°	38.516225°
				-121.582194°	-121.582194°
DWR ID	17881				

**Comment Code****Inspector Comment**

DS\_ID:17881  
FS\_ID:56689  
EP\_NO: 18116  
Repair Type: No Action Needed  
EVAL Issue:  
Crossing Status: Found  
UCIP Comments: 04/15/2020 Record updated from Non-Urgent to No Action Needed. No issues observed during inspection. (D.Sanoski - DWR UCIP)  
Under construction Oct-2009. Need updated photos of completed structure.  
FIELD\_STRUCT\_DESC: [West Sacramento Main Drain Pump Station]  
2 of 4: 54-inch steel drainage pipe through the levee, 5 feet below the crown. Pump house is located on the landside (LS), siphon breaker is located on the waterside (WS) slope, and concrete headwall with flap gate at WS end. (54-inch pipe authorized under Permit No. 18116, 2007 - Reclamation District No. 900 [RD0900]. This crossing (group of 4) replaces dual 48-inch (listed as 60-inch) pipe (see DSID 25606, 25607)). [Additional Reference(s): DWR Levee Log, 2003 (HLM 4.97). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 December 2016, (Station 140+00)].  
FS Date: 4/15/2020 1:14:31 PM

Photo 1 of 3 : UCIP\_FA\_2024\_56689\_83966.jpg



Water-Side: view of WS slope and valve box with welded close lid and concrete headwall with flap gate at toe

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.96	Rating **	A	Issue No.	23 (cont)	
LM End	4.96	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.516225°	38.516225°	
				-121.582194°	-121.582194°	
DWR ID	17881					

Photo 2 of 3 : UCIP\_FA\_2024\_56689\_83967.jpg



Top of Levee: view of levee crown

LM Start	<b>4.96</b>	Rating **	A	Issue No.	<b>23 (cont)</b>
LM End	<b>4.96</b>	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_FA\_2024\_56689\_83968.jpg



Land-Side: view of LS slope and pumphouse at toe

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.97	Rating **	A	Issue No.	24
LM End	4.97	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.516175°	38.516175°
				-121.582191°	-121.582191°
DWR ID	17882				
Comment Code					
Inspector Comment					
DS_ID:17882 FS_ID:56691 EP_NO: 18116 Repair Type: No Action Needed EVAL Issue: Crossing Status: Found UCIP Comments: 04/15/2020 Record updated from Non-Urgent to No Action Needed. No issues observed during inspection. (D.Sanoski - DWR UCIP) Under construction Oct-2009. Need updated photos of completed structure. FIELD_STRUCT_DESC: [West Sacramento Main Drain Pump Station] 3 of 4: 54-inch steel drainage pipe through the levee, 5 feet below the crown. Pump house is located on the landside (LS), siphon breaker is located on the waterside (WS) slope, and concrete headwall with flap gate at WS end. (54-inch pipe authorized under Permit No. 18116, 2007 - Reclamation District No. 900 [RD0900]. This crossing (group of 4) replaces dual 48-inch (listed as 60-inch) pipe (see DSID 25606, 25607)). [Additional Reference(s): DWR Levee Log, 2003 (HLM 4.97). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 December 2016, (Station 140+00)]. FS Date: 4/15/2020 1:18:52 PM					

LM Start	<b>4.97</b>	Rating **	A	Issue No.	<b>24 (cont)</b>
LM End	<b>4.97</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_FA\_2024\_56691\_83971.jpg



Water-Side: view of WS slope and valve box with welded close lid and concrete headwall with flap gate at toe

Photo 2 of 3 : UCIP\_FA\_2024\_56691\_83972.jpg



Top of Levee: view of levee crown

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024**

**Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	<b>4.97</b>	Rating **	A	Issue No.	<b>24 (cont)</b>
LM End	<b>4.97</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.516175°	38.516175°
				-121.582191°	-121.582191°
DWR ID	17882				

Photo 3 of 3 : UCIP\_FA\_2024\_56691\_83973.jpg



Land-Side: view of LS slope and pumphouse at toe

LM Start	<b>4.97</b>	Rating **	A	Issue No.	<b>25</b>
LM End	<b>4.97</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.516141°	38.516141°
				-121.582189°	-121.582189°
DWR ID	17883				

**Comment Code**

**Inspector Comment**

DS\_ID:17883  
 FS\_ID:56692  
 EP\_NO: 18116  
 Repair Type: No Action Needed  
 EVAL Issue:  
 Crossing Status: Found  
 UCIP Comments: 04/15/2020 Record updated from Non-Urgent to No Action Needed. No issues observed during inspection. (D.Sanoski - DWR UCIP)  
 Under construction Oct-2009. Need updated photos of completed structure.  
 FIELD\_STRUCT\_DESC: [West Sacramento Main Drain Pump Station]  
 4 of 4: 54-inch steel drainage pipe through the levee, 5 feet below the crown. Pump house is located on the landside (LS), siphon breaker is located on the waterside (WS) slope, and concrete headwall with flap gate at WS end. (54-inch pipe authorized under Permit No. 18116, 2007 - Reclamation District No. 900 [RD0900]. This crossing (group of 4) replaces dual 48-inch (listed as 60-inch) pipe (see DSID 25606, 25607)). [Additional Reference(s): DWR Levee Log, 2003 (HLM 4.97). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 December 2016, (Station 140+00)].  
 FS Date: 4/15/2020 2:05:57 PM

Photo 1 of 3 : UCIP\_FA\_2024\_56692\_83974.jpg



Water-Side: view of WS slope and valve box with welded close lid and concrete headwall with flap gate at toe

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.97	Rating **	A	Issue No.	25 (cont)	
LM End	4.97	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.516141°		38.516141°
				-121.582189°		-121.582189°
DWR ID	17883					

Photo 2 of 3 : UCIP\_FA\_2024\_56692\_83975.jpg



Top of Levee: view of levee crown

LM Start	<b>4.97</b>	Rating **	A	Issue No.	<b>25 (cont)</b>
LM End	<b>4.97</b>	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_FA\_2024\_56692\_83976.jpg



Land-Side: view of LS slope and pumphouse toe

LM Start	5.09	Rating **	U	Issue No.	3
LM End	5.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.514355°	38.514355°
				-121.582165°	-121.582165°
DWR ID	DWR_RD0900_02_s_2023_3				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Fall 2024: USACE has visited the site for PL 84-99 repair. PGE has relocated pole.					
Spring 2023:Levee slip at power pole. Scarp ~50' long, 5' vertical face, 10' separation. LMA has placed raincoat.					

Photo 1 of 1 : FA\_2024\_RD0900\_231\_3\_20240911\_00001.jpg



Slope slip on the LS. Spring 2024

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/03/2024 10/03/2024	Marvin Marshall

LM Start	5.24	Rating **	U	Issue No.	18
LM End	5.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.512197°	38.512197°
				-121.582143°	-121.582143°
DWR ID	DWR_RD0900_02_f _ 2020_18				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Fall 2024: USACE has visited the site for PL 84-99 repair.					
Spring 2023: Slope slip, ~50 long, 4' vertical face, 5' seperation					

Photo 1 of 1 : FA\_2024\_RD0900\_231\_18\_20240911\_00003.jpg



Slope slip on the LS. Spring 2024

* Location	** Rating	+ Issue Type
LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yolo Bypass	Left	1.19	10/03/2024 10/03/2024	Marvin Marshall

LM Start	0.18	Rating **	A	Issue No.	1
LM End	0.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.594900°	38.594900°
				-121.576000°	-121.576000°
DWR ID	DWR_RD0900_03_f_2024_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Vegetation has been maintained to standard.					

Photo 1 of 1 : FA\_2024\_RD0900\_174\_1\_20241007\_00002.jpg



Vegetation on the LS slope. Fall 2024

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	0.62	10/03/2024 10/03/2024	Marvin Marshall

LM Start	<b>4.14</b>	Rating **	A/W	Issue No.	<b>19</b>
LM End	<b>4.24</b>	Issue Type +	Ma	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
Item	2018 USACE Erosion Survey		Start	End	
			38.602874°	38.601718°	
			-121.554620°	-121.553629°	

DWR ID DWR\_RD0537\_01\_s\_2022\_19

## Comment Code

## Inspector Comment

2018 Site ID: SAC 62.9 R

Status: Eroding

2018 Field Notes: Increased undercutting erosion at upstream end.  
Site History: 1997 - This may have been a cobble rehabilitation site to the 1957 cobble that was place all the way to the I-80 Bridge. 2000 - Local damage induced by human use. 2003 - Site is still very close to the levee and into the levee toe. 2011 - One new tree has fallen. 2015 - Sites 62.9 and 63 were combined into one site. 2017 - Fresh erosion pocket near downstream end.

LM Start	<b>4.14</b>	Rating **	A/W	Issue No.	<b>19 (cont)</b>
LM End	<b>4.24</b>	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : FA\_2024\_RD0900\_173\_19\_20240913\_00002.jpg



USACE 2018 Erosion Photo #1

Photo 2 of 2 : FA\_2024\_RD0900\_173\_19\_20240913\_00003.jpg



USACE 2018 Erosion Photo #2

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	

Flood Control Project Maintenance  
Levee Inspections

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024

## Reclamation District No. 0900 West Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	0.62	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.34	Rating **	C	Issue No.	56
LM End	4.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.600405°	38.600384°
				-121.552730°	-121.552705°
DWR ID	DWR_RD0537_01_s_2017_56				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

No Photos

LM Start	4.48	Rating **	M	Issue No.	24
LM End	4.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.598854°	38.598854°
				-121.551141°	-121.551141°
DWR ID	DWR_RD0537_01_f_2017_24				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff erosion on overbuilt section of levee on the waterside.					

Photo 1 of 1 : FA\_2024\_RD0900\_173\_24\_20240913\_00004.jpg



View of erosion on the waterside hinge point (Spring 2024).

LM Start	4.69	Rating **	C	Issue No.	48
LM End	4.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.597153°	38.597153°
				-121.548548°	-121.548548°
DWR ID	DWR_RD0537_01_f_2022_48				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance  
Levee Inspections****Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2024****Reclamation District No. 0900 West Sacramento**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	0.62	10/03/2024 10/03/2024	Marvin Marshall

LM Start	4.69	Rating **	U	Issue No.	55
LM End	4.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.597062°	38.596962°
				-121.548577°	-121.548360°
DWR ID	DWR_RD0537_01_s_2022_55				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Large rodent holes on the landside slope. LMA has implemented rodent control program.					

Photo 1 of 1 : FA\_2024\_RD0900\_173\_55\_20241007\_00008.jpg



Rodent holes on the LS slope. Fall 2024

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	