

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>53</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD0999_01_s_2013_53				
Comment Code					
Inspector Comment					
The LMA has copy of the O & M manual on file.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>54</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD0999_01_s_2013_54				
Comment Code					
Inspector Comment					
The LMA has adequate floodfight supplies and equipment on hand.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	55
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				o
					o
DWR ID	DWR_RD0999_01_s_2013_55				
Comment Code					
Inspector Comment					
The LMA is prepared for responding to floods and has received training.					

No Photos

LM Start	0.27	Rating **	M	Issue No.	3
LM End	0.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.501113 °	38.501113 °
				-121.581975 °	-121.581975 °
DWR ID	DWR_RD0999_01_s_2012_3				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_232\_3\_20180301\_00011.jpg



View of landside slope looking south.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	1.73	Rating **	U	Issue No.	919
LM End	1.73	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.480097 °	38.480097 °
				-121.580844 °	-121.580844 °
DWR ID					

Comment Code

Inspector Comment

FS\_ID:50092  
DS\_ID:22743  
EP\_NO: N/A  
Repair Type: Urgent  
Crossing Status: Found  
UCIP Comments: 07/07/2016 Condition largely unchanged from previous inspection. Pipe open on the WS, waterward of the siphon breaker. Dense vegetation and steep slope limited inspection of WS outlet into Ship Channel. (T. Hatch/UCIP)  
06/25/2013 Pipe abandoned and open on WS slope. Pipe should be abandoned properly. (W. Wylie/UCIP)  
FIELD\_STRUCT\_DESC: \*ABANDONED\* 30-inch steel drainage pipe through the levee, 6.5 feet below the crown. Pump on a platform in the canal off the landside (LS) toe, not found. Flap gate on the waterside (WS), not found. Siphon breaker and an air vent on the WS shoulder. 1-inch galvanized iron filler pipe visible on the WS shoulder along same alignment. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 113 (Revised), October 1966, (HLM 1.73)].  
FS Date: 7/7/2016

LM Start	<b>1.73</b>	Rating **	U	Issue No.	<b>919 (cont)</b>
LM End	<b>1.73</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_SP\_2018\_50092\_25191.jpg



Pipe open on WS slope

Photo 2 of 3 : UCIP\_SP\_2018\_50092\_25190.jpg



Pump platform visible off LS toe, but no appurtances remain.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---





**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	1.79	Rating **	M	Issue No.	30 (cont)	
LM End	2.04	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.479165 °		38.475463 °
				-121.580640 °		-121.580722 °
DWR ID	DWR_RD0999_01_s_2012_30					
Comment Code						
T1 : Trim trees to at least five feet above ground level.						
Inspector Comment						

Photo 2 of 2 : SP\_2018\_RD0999\_232\_30\_20180301\_00025.jpg



Looking southeast at dense trees on landward slope. (Spring 2016)

LM Start	2.13	Rating **	C	Issue No.	7
LM End	2.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.474258 °	38.474258 °
				-121.580528 °	-121.580528 °
DWR ID	DWR_RD0999_01_s_2012_7				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	2.13	Rating **	U	Issue No.	31
LM End	2.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.474200 °	38.474200 °
				-121.580480 °	-121.580480 °
DWR ID	DWR_RD0999_01_s_2012_31				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_232\_31\_20180301\_00026.jpg



Looking north at untrimmed trees on landward slope. ( Fall 2016)

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	2.13	Rating **	U	Issue No.	31 (cont)	
LM End	2.13	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.474200 °		38.474200 °
				-121.580480 °		-121.580480 °
DWR ID	DWR_RD0999_01_s_2012_31					
Comment Code						
T1 : Trim trees to at least five feet above ground level.						
Inspector Comment						

Photo 2 of 2 : SP\_2018\_RD0999\_232\_31\_20180301\_00027.jpg



Looking southeast at untrimmed trees on landward slope. (Spring 2016)

LM Start	2.17	Rating **	M	Issue No.	32
LM End	2.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.473650 °	38.473650 °
				-121.580756 °	-121.580756 °
DWR ID	DWR_RD0999_01_f_2017_32				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	2.18	Rating **	C	Issue No.	8
LM End	2.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.473542 °	38.473417 °
				-121.580793 °	-121.580885 °
DWR ID	DWR_RD0999_01_s_2012_8				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	2.51	Rating **	M	Issue No.	40
LM End	2.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.469048 °	38.469048 °
				-121.583075 °	-121.583075 °
DWR ID	DWR_RD0999_01_s_2012_40				
Comment Code					
MA : Material					
Inspector Comment					
Excavation activity on landside shoulder. Hole is approximately 15ft x 12" x 15". Hole appears to be excavated by a backhoe.					

Photo 1 of 4 : SP\_2018\_RD0999\_232\_40\_20180301\_00033.jpg



Looking south at trench along landward shoulder. (spring 2016)

LM Start	<b>2.51</b>	Rating **	M	Issue No.	<b>40 (cont)</b>
LM End	<b>2.51</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 4 : SP\_2018\_RD0999\_232\_40\_20180301\_00034.jpg



Looking south at excavation on landside shoulder.

LM Start	<b>2.51</b>	Rating **	M	Issue No.	<b>40 (cont)</b>
LM End	<b>2.51</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 4 : SP\_2018\_RD0999\_232\_40\_20180301\_00035.jpg



Looking south at close-up view of excavation on landside shoulder.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	2.51	Rating **	M	Issue No.	40 (cont)	
LM End	2.51	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.469048 °		38.469048 °
				-121.583075 °		-121.583075 °
DWR ID	DWR_RD0999_01_s_2012_40					
Comment Code						
MA : Material						
Inspector Comment						
Excavation activity on landside shoulder. Hole is approximately 15ft x 12" x 15". Hole appears to be excavated by a backhoe.						

Photo 4 of 4 : SP\_2018\_RD0999\_232\_40\_20180301\_00036.jpg



Looking north at excavation on landside shoulder.

LM Start	3.22	Rating **	M	Issue No.	51
LM End	3.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.459399 °	38.459399 °
				-121.587523 °	-121.587523 °
DWR ID	DWR_RD0999_01_s_2013_51				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Depression on landward shoulder and slope 40' x 20'. Earthen material appears to be sliding toward levee toe.					

Photo 1 of 3 : SP\_2018\_RD0999\_232\_51\_20180301\_00052.jpg



View of landside slope looking south.

LM Start	<b>3.22</b>	Rating **	M	Issue No.	<b>51 (cont)</b>
LM End	<b>3.22</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : SP\_2018\_RD0999\_232\_51\_20180301\_00053.jpg



Looking northeast at depression on landward slope. (Fall 2016)

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	3.22	Rating **	M	Issue No.	51 (cont)	
LM End	3.22	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			38.459399 °		38.459399 °
				-121.587523 °		-121.587523 °
DWR ID	DWR_RD0999_01_s_2013_51					
Comment Code						
S1 : Repair slope instability.						
Inspector Comment						
Depression on landward shoulder and slope 40' x 20'. Earthen material appears to be sliding toward levee toe.						

Photo 3 of 3 : SP\_2018\_RD0999\_232\_51\_20180301\_00054.jpg



Looking north at depression on landside shoulder and slope. (Spring 2016)

LM Start	4.16	Rating **	N	Issue No.	14
LM End	4.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.446619 °	38.446619 °
				-121.593442 °	-121.593442 °
DWR ID	DWR_RD0999_01_s_2012_14				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	4.17	Rating **	N	Issue No.	15
LM End	4.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.446478 °	38.446478 °
				-121.593508 °	-121.593508 °
DWR ID	DWR_RD0999_01_s_2012_15				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	4.31	Rating **	M	Issue No.	27
LM End	4.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.444560 °	38.444560 °
				-121.594440 °	-121.594440 °
DWR ID	DWR_RD0999_01_f_2012_27				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Local farmer causing slope damage by driving equipment and trucks on slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_232\_27\_20180301\_00020.jpg



Looking at slope damage cause by vehicle traffic on waterward slope.  
(Fall 2016)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

Photo 2 of 2 : SP\_2018\_RD0999\_232\_27\_20180301\_00021.jpg



No Photos

* Location	** Rating	+ Issue Type
LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	6.56	Rating **	C	Issue No.	41
LM End	6.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.413856 °	38.413475 °
				-121.608635 °	-121.608817 °
DWR ID	DWR_RD0999_01_s_2016_41				
Comment Code					
PR : Prunings					
Inspector Comment					
Pruning piles on landward toe.					

No Photos

LM Start	7.13	Rating **	C	Issue No.	22
LM End	9.67	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.406130 °	38.371621 °
				-121.612211 °	-121.628232 °
DWR ID	DWR_RD0999_01_s_2012_22				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					
Also control growth on levee crown. LMA has controlled growth on portions of the crown but still need to add appropriate road base.					

No Photos

LM Start	7.61	Rating **	M	Issue No.	58
LM End	7.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.399600 °	38.399600 °
				-121.615224 °	-121.615224 °
DWR ID	DWR_RD0999_01_f_2016_58				
Comment Code					
Inspector Comment					
Depression 10' by 20' on landward slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_232\_58\_20180301\_00057.jpg



<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	7.61	Rating **	M	Issue No.	58 (cont)	
LM End	7.61	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.399600 °		38.399600 °
				-121.615224 °		-121.615224 °
DWR ID	DWR_RD0999_01_f_2016_58					
Comment Code						
Inspector Comment						
Depression 10' by 20' on landward slope.						

Photo 2 of 2 : SP\_2018\_RD0999\_232\_58\_20180301\_00058.jpg



Looking northeast at depression on landward slope.

LM Start	9.63	Rating **	M	Issue No.	21
LM End	9.63	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.372118 °	38.372118 °
				-121.627982 °	-121.627982 °
DWR ID	DWR_RD0999_01_s_2018_21				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	10.81	Rating **	C	Issue No.	23
LM End	11.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.356077 °	38.352640 °
				-121.635598 °	-121.637078 °
DWR ID	DWR_RD0999_01_s_2012_23				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	11.30	Rating **	M	Issue No.	43
LM End	11.59	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.349380 °	38.345353 °
				-121.638540 °	-121.640432 °
DWR ID	DWR_RD0999_01_s_2012_43				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_232\_43\_20180301\_00040.jpg



Looking north at growth on levee crown.

LM Start	13.64	Rating **	A	Issue No.	24	
LM End	13.64	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.316208 °		38.316208 °
				-121.644951 °		-121.644951 °
DWR ID	DWR_RD0999_01_s_2018_24					
Comment Code						
V1 : Control annual grass and weeds on the levee slopes and easements.						
Inspector Comment						
Good vegetation control.						

Photo 1 of 1 : SP\_2018\_RD0999\_232\_24\_20180509\_00091.jpg



Good vegetation control waterside looking north.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	13.64	Rating **	A	Issue No.	25
LM End	13.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.316208 °	38.316208 °
				-121.644951 °	-121.644951 °
DWR ID	DWR_RD0999_01_s_2018_25				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Good vegetation control.					

Photo 1 of 1 : SP\_2018\_RD0999\_232\_25\_20180509\_00090.jpg



Good vegetation control landside looking north.

LM Start	14.04	Rating **	M	Issue No.	49
LM End	14.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.310347 °	38.310347 °
				-121.644955 °	-121.644955 °
DWR ID	DWR_RD0999_01_f_2012_49				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Caving, 4' x 10', on landside slope.					

Photo 1 of 4 : SP\_2018\_RD0999\_232\_49\_20180301\_00044.jpg



Looking southeast at caving on landward slope fall 2015.

LM Start	<b>14.04</b>	Rating **	M	Issue No.	<b>49 (cont)</b>
LM End	<b>14.04</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 4 : SP\_2018\_RD0999\_232\_49\_20180301\_00045.jpg



Looking east at caving on landward shoulder and slope. (Spring 2015)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	14.04	Rating **	M	Issue No.	49 (cont)	
LM End	14.04	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.310347 °		38.310347 °
				-121.644955 °		-121.644955 °
DWR ID	DWR_RD0999_01_f_2012_49					
Comment Code						
E1 : Note and monitor erosion site.						
Inspector Comment						
Caving, 4' x 10', on landside slope.						

Photo 3 of 4 : SP\_2018\_RD0999\_232\_49\_20180301\_00046.jpg



Looking east caving on landside slope.

LM Start	<b>14.04</b>	Rating **	M	Issue No.	<b>49 (cont)</b>
LM End	<b>14.04</b>	Issue Type +	Ma	Location *	LS

Photo 4 of 4 : SP\_2018\_RD0999\_232\_49\_20180301\_00047.jpg



Looking southeast at caving on landside slope.

LM Start	15.22	Rating **	C	Issue No.	52
LM End	15.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.293207 °	38.293207 °
				-121.644947 °	-121.644947 °
DWR ID	DWR_RD0999_01_f_2017_52				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	15.24	Rating **	A/W	Issue No.	925	
LM End	15.24	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.293005 °	38.293005 °	
				-121.644974 °	-121.644974 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:15366 DS_ID:22757 EP_NO: 14199 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch steel discharge pipe through the levee, 6.3 feet below the crown. Pump house on the landside (LS) toe with a siphon breaker in a steel riser on the waterside (WS) shoulder. (Permit No. 14199, 1985, [owner not indicated in permit database]). FS Date: 6/25/2013						

Photo 1 of 3 : UCIP\_SP\_2018\_15366\_25231.jpg



Pump in pumphouse on LS toe.

LM Start	<b>15.24</b>	Rating **	A/W	Issue No.	<b>925 (cont)</b>
LM End	<b>15.24</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP\_SP\_2018\_15366\_25230.jpg



siphon breaker in steel riser on WS shoulder

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	15.24	Rating **	A/W	Issue No.	925 (cont)	
LM End	15.24	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.293005 °	38.293005 °	
				-121.644974 °	-121.644974 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:15366 DS_ID:22757 EP_NO: 14199 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch steel discharge pipe through the levee, 6.3 feet below the crown. Pump house on the landside (LS) toe with a siphon breaker in a steel riser on the waterside (WS) shoulder. (Permit No. 14199, 1985, [owner not indicated in permit database]). FS Date: 6/25/2013						

Photo 3 of 3 : UCIP\_SP\_2018\_15366\_25229.jpg



Closeup of 24-inch pipe on LS toe.

LM Start	15.24	Rating **	A/W	Issue No.	926
LM End	15.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.292973 °	38.292973 °
				-121.644977 °	-121.644977 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:15365					
DS_ID:22756					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 30-inch steel drainage pipe through the levee, 7 feet below the crown. Flap gate on the waterside (WS) end. Pump in pump house on the landside (LS) toe. Siphon breaker in a corrugated metal pipe (CMP) riser on the WS shoulder. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 113 (Revised), October 1966, (HLM 15.25) (36-inch pipe listed)].					
FS Date: 6/25/2013					

Photo 1 of 3 : UCIP\_SP\_2018\_15365\_25227.jpg



Pumphouse on LS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	15.24	Rating **	A/W	Issue No.	926 (cont)
LM End	15.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.292973 °	38.292973 °
				-121.644977 °	-121.644977 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:15365 DS_ID:22756 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 30-inch steel drainage pipe through the levee, 7 feet below the crown. Flap gate on the waterside (WS) end. Pump in pump house on the landside (LS) toe. Siphon breaker in a corrugated metal pipe (CMP) riser on the WS shoulder. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 113 (Revised), October 1966, (HLM 15.25) (36-inch pipe listed)]. FS Date: 6/25/2013					

Photo 2 of 3 : UCIP\_SP\_2018\_15365\_25226.jpg



Siphon breaker in CMP riser on WS shoulder.

LM Start	15.24	Rating **	A/W	Issue No.	926 (cont)
LM End	15.24	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_SP\_2018\_15365\_25225.jpg



Closeup of pipe at pump house on LS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	15.24	Rating **	A/W	Issue No.	927
LM End	15.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.292943 °	38.292943 °
				-121.644980 °	-121.644980 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:15363 DS_ID:22755 EP_NO: 15303 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 30-inch steel discharge pipe through the levee, 7 feet below the crown. Pump on platform on the landside (LS) toe. Siphon breaker in corrugated metal pipe (CMP) riser on the waterside (WS) shoulder. (Permit No. 15303, 1989 - Reclamation District No. 999). [Additional Reference(s): DWR Levee Log, 1992]. FS Date: 6/25/2013					

Photo 1 of 3 : UCIP\_SP\_2018\_15363\_25219.jpg



Pump platform to right of pumphouse.

LM Start	15.24	Rating **	A/W	Issue No.	927 (cont)
LM End	15.24	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP\_SP\_2018\_15363\_25218.jpg



Siphon breaker in CMP riser on WS shoulder.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	15.41	05/08/2018 05/08/2018	Dave Torres

LM Start	15.24	Rating **	A/W	Issue No.	927 (cont)	
LM End	15.24	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.292943 °	38.292943 °	
				-121.644980 °	-121.644980 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:15363 DS_ID:22755 EP_NO: 15303 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 30-inch steel discharge pipe through the levee, 7 feet below the crown. Pump on platform on the landside (LS) toe. Siphon breaker in corrugated metal pipe (CMP) riser on the waterside (WS) shoulder. (Permit No. 15303, 1989 - Reclamation District No. 999). [Additional Reference(s): DWR Levee Log, 1992]. FS Date: 6/25/2013						

Photo 3 of 3 : UCIP\_SP\_2018\_15363\_25217.jpg



Pump and platform on LS toe.

LM Start	15.30	Rating **	C	Issue No.	62
LM End	15.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.292030 °	38.292030 °
				-121.644971 °	-121.644971 °
DWR ID	DWR_RD0999_01_f_2014_62				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.06	Rating **	M	Issue No.	21
LM End	0.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.290434 °	38.290434 °
				-121.643873 °	-121.643873 °
DWR ID	DWR_RD0999_02_f_2017_21				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_233\_21\_20180301\_00018.jpg



View of landside slope looking north.

LM Start	0.08	Rating **	U	Issue No.	32
LM End	0.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.290543 °	38.290753 °
				-121.643501 °	-121.642288 °
DWR ID	DWR_RD0999_02_s_2018_32				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_233\_32\_20180507\_00053.jpg



Vegetation landside looking east.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.08	Rating **	U	Issue No.	34
LM End	0.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.290543 °	38.290753 °
				-121.643501 °	-121.642288 °
DWR ID	DWR_RD0999_02_s_2018_34				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_233\_34\_20180507\_00054.jpg



Vegetation waterside looking east.

LM Start	0.35	Rating **	M	Issue No.	12
LM End	0.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.291125 °	38.291125 °
				-121.638730 °	-121.638730 °
DWR ID	DWR_RD0999_02_s_2018_12				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.71	Rating **	M	Issue No.	44
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.292689 °	38.292689 °
				-121.632730 °	-121.632730 °
DWR ID	DWR_RD0999_02_f_2015_44				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.73	Rating **	M	Issue No.	37
LM End	0.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.292783 °	38.292783 °
				-121.632317 °	-121.632317 °
DWR ID	DWR_RD0999_02_s_2014_37				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 3 : SP\_2018\_RD0999\_233\_37\_20180301\_00025.jpg



View of landside slope looking north.

LM Start	<b>0.73</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>0.73</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : SP\_2018\_RD0999\_233\_37\_20180301\_00026.jpg



Looking at untrimmed tree on landward slope and toe. (Fall 2016)

LM Start	<b>0.73</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>0.73</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 3 : SP\_2018\_RD0999\_233\_37\_20180301\_00027.jpg



Looking at untrimmed tree on landward slope. (Spring 2016)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.76	Rating **	M	Issue No.	26
LM End	0.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.292668 °	38.292613 °
				-121.631755 °	-121.631542 °
DWR ID	DWR_RD0999_02_f_2013_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.82	Rating **	M	Issue No.	14
LM End	0.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.292439 °	38.292439 °
				-121.630781 °	-121.630781 °
DWR ID	DWR_RD0999_02_f_2012_14				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Century plant on landside slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_233\_14\_20180301\_00011.jpg



Looking north at century plant at landward toe fall 2015.

LM Start	<b>0.82</b>	Rating **	M	Issue No.	<b>14 (cont)</b>
LM End	<b>0.82</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_233\_14\_20180301\_00012.jpg



Looking north at century plant at landside toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.83	Rating **	M	Issue No.	19
LM End	0.83	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.292386 °	38.292386 °
				-121.630543 °	-121.630543 °
DWR ID	DWR_RD0999_02_f_2012_19				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_233\_19\_20180301\_00016.jpg



View of landside slope looking north.

LM Start	<b>0.83</b>	Rating **	M	Issue No.	<b>19 (cont)</b>
LM End	<b>0.83</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_233\_19\_20180301\_00017.jpg



Looking north at untrimmed trees to be thinned at landward toe fall 2015.

LM Start	0.84	Rating **	M	Issue No.	13
LM End	0.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.292352 °	38.292352 °
				-121.630452 °	-121.630452 °
DWR ID	DWR_RD0999_02_s_2012_13				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_233\_13\_20180301\_00010.jpg



Looking northwest at tree limb on landside slope.

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	0.85	Rating **	A/W	Issue No.	22
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.292290 °	38.292290 °
				-121.630167 °	-121.630167 °
DWR ID	DWR_RD0999_02_f_2017_22				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	0.87	Rating **	M	Issue No.	23
LM End	0.87	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.292211 °	38.292211 °
				-121.629950 °	-121.629950 °
DWR ID	DWR_RD0999_02_f_2017_23				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---







**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	1.04	Rating **	A/W	Issue No.	20
LM End	1.53	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.291206 °	38.290915 °
				-121.627030 °	-121.618227 °
DWR ID	DWR_RD0999_02_f_2012_20				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	1.15	Rating **	A/W	Issue No.	40
LM End	1.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.291069 °	38.291069 °
				-121.625138 °	-121.625138 °
DWR ID	DWR_RD0999_02_f_2014_40				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.93	Rating **	M	Issue No.	16
LM End	1.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.288713 °	38.288713 °
				-121.611620 °	-121.611620 °
DWR ID	DWR_RD0999_02_s_2012_16				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Miner Slough	Right	2.31	05/02/2018 05/02/2018	Dave Torres

LM Start	1.97	Rating **	A/W	Issue No.	33
LM End	1.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.288712 °	38.288712 °
				-121.610920 °	-121.610920 °
DWR ID	DWR_RD0999_02_s_2017_33				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	0.01	Rating **	M	Issue No.	16
LM End	0.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.286678 °	38.286678 °
				-121.605971 °	-121.605971 °
DWR ID	DWR_RD0999_03_f_2017_16				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_16\_20180301\_00017.jpg



View of waterside slope looking east.

LM Start	0.04	Rating **	M	Issue No.	32
LM End	0.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.287040 °	38.287040 °
				-121.605667 °	-121.605667 °
DWR ID	DWR_RD0999_03_f_2017_32				
Comment Code					
PR : Prunings					
Inspector Comment					
Large pruning pile on waterside slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_32\_20180301\_00033.jpg



View of waterside slope looking east.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	0.06	Rating **	M	Issue No.	17
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.287290 °	38.287290 °
				-121.605472 °	-121.605472 °
DWR ID	DWR_RD0999_03_s_2017_17				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Century plants on waterward slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_17\_20180301\_00018.jpg



Looking east at century plants on waterward slope.

LM Start	0.09	Rating **	M	Issue No.	23
LM End	0.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.287595 °	38.287595 °
				-121.605275 °	-121.605275 °
DWR ID	DWR_RD0999_03_s_2017_23				
Comment Code					
PR : Prunings					
Inspector Comment					
Large pruning piles on waterward slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_23\_20180301\_00023.jpg



Looking east large pruning piles on waterward slope.

LM Start	0.22	Rating **	U	Issue No.	35
LM End	0.29	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.289427 °	38.290416 °
				-121.604544 °	-121.604545 °
DWR ID	DWR_RD0999_03_s_2018_35				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_35\_20180507\_00050.jpg



Vegetation landside looking north.

<b>* Location</b>		<b>** Rating</b>		<b>+ Issue Type</b>	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	0.22	Rating **	U	Issue No.	36
LM End	0.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.289427 °	38.290416 °
				-121.604544 °	-121.604545 °
DWR ID	DWR_RD0999_03_s_2018_36				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_36\_20180507\_00051.jpg



Vegetation waterside looking north.

LM Start	0.24	Rating **	U	Issue No.	29
LM End	0.65	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.289634 °	38.295505 °
				-121.604343 °	-121.605648 °
DWR ID	DWR_RD0999_03_s_2016_29				
Comment Code					
Inspector Comment					
1997 - Intermittent over-steepened sections. Large riparian vegetation along the length of the entire reach. Attempts to repair with rock on bank have failed. 1999 - New rock repair at the downstream end. 2002 - Some minor spot repairs. 2009 - Minimal new erosion. 2010 - Appears that fresh rock placed on downstream portion of site. Toe scour and overhanging trees with some overturned. 2012 - Minor new erosion at the toe. 2013 - Site upgraded to CRITICAL. Severe slumping into levee at downstream end of site. Fresh erosion into bank toe. 2015: New slumping, tall vertical sections. [2015 Site ID: STR_24-7 R]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_29\_20180301\_00029.jpg



USACE 2013 Photo #1

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	0.38	Rating **	M	Issue No.	33
LM End	0.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.291640 °	38.291640 °
				-121.604799 °	-121.604799 °
DWR ID	DWR_RD0999_03_f_2017_33				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_33\_20180301\_00034.jpg



View of landside slope looking southwest.

LM Start	0.62	Rating **	M	Issue No.	37
LM End	0.67	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.295021 °	38.295839 °
				-121.605826 °	-121.605925 °
DWR ID	DWR_RD0999_03_s_2018_37				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					

No Photos

LM Start	0.66	Rating **	U	Issue No.	8
LM End	0.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.295618 °	38.295618 °
				-121.605923 °	-121.605923 °
DWR ID	DWR_RD0999_03_s_2012_8				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Dense veg on landward slope.					

No Photos

<b>* Location</b>		<b>** Rating</b>		<b>+ Issue Type</b>	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	0.93	Rating **	M	Issue No.	43
LM End	0.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.299130 °	38.299362 °
				-121.603768 °	-121.603462 °
DWR ID	DWR_RD0999_03_f_2014_43				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_234\_43\_20180301\_00035.jpg



View of landside slope looking northeast.

LM Start	<b>0.93</b>	Rating **	M	Issue No.	<b>43 (cont)</b>
LM End	<b>0.95</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_234\_43\_20180301\_00036.jpg



Looking at untrimmed trees on landward slope and toe.

LM Start	0.97	Rating **	M	Issue No.	30
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.299402 °	38.300542 °
				-121.603056 °	-121.601118 °
DWR ID	DWR_RD0999_03_s_2016_30				
Comment Code					
Inspector Comment					
2008 - Over steepened levee section. 2009 - Significant new erosion. 2010 - Minor new erosion. 2015: No observed changes. [2015 Site ID: STR_25-2_R]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_30\_20180301\_00030.jpg



USACE 2013 Photo #1

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	1.43	Rating **	M	Issue No.	1
LM End	1.58	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.305229 °	38.306667 °
				-121.599933 °	-121.598266 °
DWR ID	DWR_RD0999_03_s_2016_1				
Comment Code					
Inspector Comment					
2011 - Toe scour along length of site and erosion pockets. 2012 - Site extended slightly upstream due to new erosion pocket. 2013 - Tall vertical sections at upstream end of site. 2015: No observed changes. [2015 Site ID: STR_25-7_R]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_1\_20180301\_00001.jpg



USACE 2013 Photo #1

LM Start	1.50	Rating **	M	Issue No.	11
LM End	1.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.306062 °	38.306062 °
				-121.599495 °	-121.599495 °
DWR ID	DWR_RD0999_03_s_2012_11				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_234\_11\_20180301\_00010.jpg



Looking at untrimmed trees on landward slope and toe. (Fall 2016)

LM Start	<b>1.50</b>	Rating **	M	Issue No.	<b>11 (cont)</b>
LM End	<b>1.50</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_234\_11\_20180301\_00011.jpg



Looking at untrimmed trees on landward slope and toe. (Spring 2016)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	1.53	Rating **	U	Issue No.	12
LM End	1.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.306332 °	38.306332 °
				-121.599109 °	-121.599109 °
DWR ID	DWR_RD0999_03_s_2012_12				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_12\_20180301\_00012.jpg



Looking east at untrimmed trees on landward slope.

LM Start	1.57	Rating **	M	Issue No.	13
LM End	1.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.306762 °	38.306948 °
				-121.598541 °	-121.598320 °
DWR ID	DWR_RD0999_03_s_2012_13				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_13\_20180301\_00013.jpg



Looking north at untrimmed trees on landward toe. (Spring 2015)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	1.61	Rating **	M	Issue No.	25
LM End	1.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.307295 °	38.307295 °
				-121.598202 °	-121.598202 °
DWR ID	DWR_RD0999_03_s_2017_25				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_234\_25\_20180301\_00024.jpg



View of waterside slope looking east.

LM Start	<b>1.61</b>	Rating **	M	Issue No.	<b>25 (cont)</b>
LM End	<b>1.61</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP\_2018\_RD0999\_234\_25\_20180301\_00025.jpg



Looking east at several large pruning piles on waterward slope.

LM Start	1.66	Rating **	M	Issue No.	19
LM End	1.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.307883 °	38.307883 °
				-121.598407 °	-121.598407 °
DWR ID	DWR_RD0999_03_s_2018_19				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	1.67	Rating **	M	Issue No.	20
LM End	1.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.308087 °	38.308733 °
				-121.598565 °	-121.599021 °
DWR ID	DWR_RD0999_03_s _ 2018_20				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.68	Rating **	M	Issue No.	14
LM End	1.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.308129 °	38.308129 °
				-121.598610 °	-121.598610 °
DWR ID	DWR_RD0999_03_s _ 2012_14				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.83	Rating **	M	Issue No.	24
LM End	1.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.310291 °	38.311168 °
				-121.599110 °	-121.598006 °
DWR ID	DWR_RD0999_03_s _ 2018_24				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	2.32	Rating **	M	Issue No.	34
LM End	2.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.315046 °	38.315329 °
				-121.592678 °	-121.592564 °
DWR ID	DWR_RD0999_03_f_2017_34				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	2.78	Rating **	M	Issue No.	28
LM End	2.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.321244 °	38.323362 °
				-121.590969 °	-121.590208 °
DWR ID	DWR_RD0999_03_s_2012_28				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	2.87	Rating **	M	Issue No.	21
LM End	2.92	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.322457 °	38.323042 °
				-121.590693 °	-121.590209 °
DWR ID	DWR_RD0999_03_s_2016_21				
Comment Code					
Inspector Comment					
2012 - Slumping of upper levee slope. 2015: No observed changes. [2015 Site ID: STR_27-1_R]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_21\_20180301\_00020.jpg



USACE 2013 Photo #1

LM Start	2.88	Rating **	U	Issue No.	10
LM End	2.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.322757 °	38.322757 °
				-121.590817 °	-121.590817 °
DWR ID	DWR_RD0999_03_f_2012_10				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Wild growth at landside slope and toe.					

Photo 1 of 2 : SP\_2018\_RD0999\_234\_10\_20180507\_00053.jpg



Trim thin trees landside looking west.

LM Start	<b>2.88</b>	Rating **	U	Issue No.	<b>10 (cont)</b>
LM End	<b>2.88</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_234\_10\_20180301\_00006.jpg

Looking northwest at dense vegetation on landward slope and toe.  
(Spring 2016)

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	3.02	Rating **	U	Issue No.	31
LM End	3.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.323832 °	38.324031 °
				-121.588736 °	-121.587763 °
DWR ID	DWR_RD0999_03_s_2012_31				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_234\_31\_20180301\_00031.jpg



Looking northwest at untrimmed trees on landward slope. (Spring 2016)

LM Start	<b>3.02</b>	Rating **	U	Issue No.	<b>31 (cont)</b>
LM End	<b>3.08</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_234\_31\_20180301\_00032.jpg



Looking north at trimmed trees on landward slope.

LM Start	3.05	Rating **	A/W	Issue No.	5
LM End	3.23	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.323667 °	38.325592 °
				-121.588226 °	-121.585925 °
DWR ID	DWR_RD0999_03_s_2016_5				
Comment Code					
Inspector Comment					
2011 - Multiple erosion pockets. Some likely from tree popouts. 2013 - Tall vertical sections. 2015: New tree popout and significant new erosion. [2015 Site ID: STR_27-3_R]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_5\_20180301\_00002.jpg



USACE 2013 Photo #1

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	3.09	Rating **	A/W	Issue No.	9	
LM End	3.12	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.323986 °	38.324275 °	
				-121.587403 °	-121.586967 °	
DWR ID	DWR_RD0999_03_f_2017_9					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 147 feet in length along the west (right) bank of Sutter Slough. See attached pages for photos. Site location T06N R03E Section 36 and 25.						
Site ID No:355						
Site Designation:LMA-182						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/27/2017						
Notes:						

Photo 1 of 3 : LEVAL\_SP\_2018\_355\_2523.jpg



LM Start	<b>3.09</b>	Rating **	A/W	Issue No.	<b>9 (cont)</b>
LM End	<b>3.12</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL\_SP\_2018\_355\_2525.jpg



<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

Photo 3 of 3 : LEVAL\_SP\_2018\_355\_2529.jpg

A photograph showing a dense thicket of tall green grasses and reeds in the foreground, with a body of water and bare tree branches visible in the background.

Photo 1 of 3 : LEVAL\_SP\_2018\_356\_2492.jpg

A photograph showing a person standing in a grassy area next to a body of water, surrounded by dense green trees and foliage. The person is wearing a plaid shirt and light-colored pants. The water is visible on the left side of the frame, and the trees are on the right. The image is labeled "Photo 1 of 3 : LEVAL\_SP\_2018\_356\_2492.jpg" at the top.

* Location	** Rating	+ Issue Type
LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement





**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Right	3.74	05/02/2018 05/02/2018	Dave Torres

LM Start	4.56	Rating **	M	Issue No.	18
LM End	4.68	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.313836 °	38.315407 °
				-121.592259 °	-121.591433 °
DWR ID	DWR_RD0999_03_s_2016_18				
Comment Code					
Inspector Comment					
2002 - Original rock over geotextile is sliding off and the end is coming unraveled. 2003 - Some minor new erosion on the downstream end. 2004 - Site has gotten worse. Underlined geofabric is exposed. 2005 - Still looks bad with exposed geotextile fabric. 2006 - Still have some new unraveling and exposed fabric. Site lengthened upstream. 2009 - Minimal new erosion. 2010 - geotextile fabric placed since last year, possible flood fight. 2012 - Exposed geotech style fabric, assume rock on top slid off. 2015: Erosion pockets covered with plastic. [2015 Site ID: STR_26-5_L]					

Photo 1 of 1 : SP\_2018\_RD0999\_234\_18\_20180301\_00019.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.00	Rating **	A/W	Issue No.	54
LM End	0.00	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.414022 °	38.414022 °
				-121.522986 °	-121.522986 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:15708					
DS_ID:22788					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments: 10/27/2017 This structure is inspected annually under the Structure and Channel Summer Inspection (part of the Levee Inspection Program) conducted by the DWR Flood Project Integrity and Inspection Branch (FPIIB). (DWR UCIP - O. Magana)					
FIELD_STRUCT_DESC: [Elk Slough Inlet Structure] 60-inch by 60-inch reinforced concrete drainage culvert through the levee, 30 feet below the crown. Slide gate in a 6-foot by 8-foot concrete vault on the waterside (WS) shoulder. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 113 (Revised), October 1966, (HLM 0.00)].					
FS Date: 7/12/2013					

Photo 1 of 2 : UCIP\_SP\_2018\_15708\_26137.jpg



Slide gate in concrete vault on WS shoulder.

LM Start	<b>0.00</b>	Rating **	A/W	Issue No.	<b>54 (cont)</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	

Photo 2 of 2 : UCIP\_SP\_2018\_15708\_26136.jpg



Toe of LS at approximate location of outlet/inlet.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---







**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.03	Rating **	M	Issue No.	45 (cont)	
LM End	0.03	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.414335 °		38.414335 °
				-121.523348 °		-121.523348 °
DWR ID	DWR_RD0999_04_s_2017_45					
Comment Code						
TR : Tree or limb						
Inspector Comment						
Large downed tree on landside slope.						

Photo 2 of 2 : SP\_2018\_RD0999\_235\_45\_20180301\_00035.jpg



Looking west at fallen tree on landward slope.

LM Start	0.04	Rating **	U	Issue No.	53
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.414533 °	38.414750 °
				-121.523394 °	-121.523543 °
DWR ID	DWR_RD0999_04_f_2017_53				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Dense vegetation on waterside slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_235\_53\_20180301\_00042.jpg



Looking southeast at the waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.10	Rating **	A/W	Issue No.	42
LM End	0.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.415319 °	38.417744 °
				-121.523717 °	-121.525344 °
DWR ID	DWR_RD0999_04_f_2017_42				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower and mid waterside levee slope approximately 997 feet in length along the west (right) bank of the Sacramento River. See attached pages for photos.					
Site location T06N R04E Section 3 and 4.					
Site ID No:357					
Site Designation:LMA-184					
Repair Type: Erosion					
Rating:Serious					
Field Date:7/27/2017					
Notes: on bank slope, big trees with exposed tree roots observed					

Photo 1 of 3 : LEVAL\_SP\_2018\_357\_2461.jpg



Photo 2 of 3 : LEVAL\_SP\_2018\_357\_2465.jpg



LM Start	<b>0.10</b>	Rating **	A/W	Issue No.	<b>42 (cont)</b>
LM End	<b>0.29</b>	Issue Type +	Ma	Location *	

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.10	Rating **	A/W	Issue No.	42 (cont)
LM End	0.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.415319 °	38.417744 °
				-121.523717 °	-121.525344 °
DWR ID	DWR_RD0999_04_f_2017_42				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower and mid waterside levee slope approximately 997 feet in length along the west (right) bank of the Sacramento River. See attached pages for photos. Site location T06N R04E Section 3 and 4.					
Site ID No:357					
Site Designation:LMA-184					
Repair Type: Erosion					
Rating:Serious					
Field Date:7/27/2017					
Notes: on bank slope, big trees with exposed tree roots observed					

Photo 3 of 3 : LEVAL\_SP\_2018\_357\_2475.jpg



LM Start	0.11	Rating **	A/W	Issue No.	15
LM End	0.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.415425 °	38.416733 °
				-121.523920 °	-121.524705 °
DWR ID	DWR_RD0999_04_s_2017_15				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Waterside erosion 2ft vertical cut.					

Photo 1 of 2 : SP\_2018\_RD0999\_235\_15\_20180301\_00012.jpg



Looking downstream at 2ft plus vertical erosion on waterward slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.11	Rating **	A/W	Issue No.	15 (cont)	
LM End	0.21	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.415425 °		38.416733 °
				-121.523920 °		-121.524705 °
DWR ID	DWR_RD0999_04_s_2017_15					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Waterside erosion 2ft vertical cut.						

Photo 2 of 2 : SP\_2018\_RD0999\_235\_15\_20180301\_00013.jpg



Looking upstream at 2ft plus vertical erosion on waterward slope.

LM Start	0.20	Rating **	M	Issue No.	24
LM End	0.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.416653 °	38.417070 °
				-121.524656 °	-121.525006 °
DWR ID	DWR_RD0999_04_s_2012_24				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.53	Rating **	M	Issue No.	37
LM End	0.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.420791 °	38.421219 °
				-121.527553 °	-121.527913 °
DWR ID	DWR_RD0999_04_s_2015_37				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.55	Rating **	M	Issue No.	44
LM End	0.59	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.421108 °	38.421513 °
				-121.527805 °	-121.528102 °
DWR ID	DWR_RD0999_04_f_2016_44				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.60	Rating **	M	Issue No.	19
LM End	0.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.421647 °	38.421997 °
				-121.528235 °	-121.528470 °
DWR ID	DWR_RD0999_04_s_2012_19				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	<b>0.63</b>	Rating **	M	Issue No.	<b>34</b>
LM End	<b>0.63</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.422096 °	38.422096 °	
			-121.528486 °	-121.528486 °	
DWR ID	DWR_RD0999_04_s_2018_34				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	<b>0.65</b>	Rating **	M	Issue No.	<b>35</b>
LM End	<b>0.65</b>	Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.422337 °	38.422337 °	
			-121.528690 °	-121.528690 °	
DWR ID	DWR_RD0999_04_s_2018_35				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	<b>0.75</b>	Rating **	N	Issue No.	<b>17</b>
LM End	<b>0.75</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.423560 °	38.423560 °	
			-121.529653 °	-121.529653 °	
DWR ID	DWR_RD0999_04_f_2017_17				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.79	Rating **	U	Issue No.	33
LM End	0.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.424068 °	38.424068 °
				-121.530017 °	-121.530017 °
DWR ID	DWR_RD0999_04_s_2018_33				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove downed tree on landside slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_235\_33\_20180503\_00085.jpg



Downed tree landside looking southwest.

LM Start	0.82	Rating **	N	Issue No.	14
LM End	0.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.424432 °	38.424432 °
				-121.530265 °	-121.530265 °
DWR ID	DWR_RD0999_04_s_2012_14				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.84	Rating **	N	Issue No.	9
LM End	0.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.424722 °	38.424722 °
				-121.530470 °	-121.530470 °
DWR ID	DWR_RD0999_04_s_2012_9				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	0.85	Rating **	M	Issue No.	50
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.424805 °	38.424805 °
				-121.530541 °	-121.530541 °
DWR ID	DWR_RD0999_04_f_2017_50				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_235\_50\_20180301\_00041.jpg



Looking west at the landside slope.

LM Start	0.93	Rating **	M	Issue No.	21
LM End	0.93	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.425857 °	38.425857 °
				-121.531270 °	-121.531270 °
DWR ID	DWR_RD0999_04_s_2018_21				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.94	Rating **	C	Issue No.	3
LM End	0.98	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.425972 °	38.426500 °
				-121.531228 °	-121.531560 °
DWR ID	DWR_RD0999_04_s_2012_3				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.94	Rating **	M	Issue No.	43
LM End	0.94	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.426005 °	38.426005 °
				-121.531382 °	-121.531382 °
DWR ID	DWR_RD0999_04_f_2017_43				
Comment Code					
PR : Prunings					
Inspector Comment					
Pruning piles on waterside slope,					

Photo 1 of 1 : SP\_2018\_RD0999\_235\_43\_20180301\_00033.jpg



Looking east at the waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	0.95	Rating **	M	Issue No.	39
LM End	0.95	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.426139 °	38.426139 °
				-121.531386 °	-121.531386 °
DWR ID	DWR_RD0999_04_s_2018_39				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.01	Rating **	U	Issue No.	16	
LM End	1.04	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.426873 °		38.427295 °
				-121.531778 °		-121.532164 °
DWR ID	DWR_RD0999_04_f_2012_16					
Comment Code						
V2 : Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comment						
Blackberries blocking view of landside toe.						

Photo 1 of 4 : SP\_2018\_RD0999\_235\_16\_20180301\_00014.jpg



Looking southwest at dense vegetation on landward slope and toe.  
(Spring 2016)

LM Start	<b>1.01</b>	Rating **	U	Issue No.	<b>16 (cont)</b>
LM End	<b>1.04</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 4 : SP\_2018\_RD0999\_235\_16\_20180301\_00015.jpg



Looking northwest at dense vines at landward toe. Fall 2015

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--





**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	1.10	Rating **	M	Issue No.	47 (cont)	
LM End	1.10	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.428152 °		38.428152 °
				-121.532502 °		-121.532502 °
DWR ID	DWR_RD0999_04_s_2017_47					
Comment Code						
E1 : Note and monitor erosion site.						
Inspector Comment						
Small erosion just above rip rap on waterside toe and runoff erosion on waterside slope.						

Photo 2 of 3 : SP\_2018\_RD0999\_235\_47\_20180301\_00039.jpg



Looking east at the waterside slope.

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>47 (cont)</b>
LM End	<b>1.10</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : SP\_2018\_RD0999\_235\_47\_20180301\_00040.jpg



Looking west at runoff erosion on waterward slope.

LM Start	1.15	Rating **	U	Issue No.	5
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.428823 °	38.428823 °
				-121.532885 °	-121.532885 °
DWR ID	DWR_RD0999_04_s_2012_5				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Berry vines and wild roses on landside toe.					

Photo 1 of 3 : SP\_2018\_RD0999\_235\_5\_20180301\_00003.jpg



Looking south at the dense vegetation on the landside slope.

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	1.15	Rating **	U	Issue No.	5 (cont)	
LM End	1.15	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.428823 °		38.428823 °
				-121.532885 °		-121.532885 °
DWR ID	DWR_RD0999_04_s_2012_5					
Comment Code						
V2 : Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comment						
Berry vines and wild roses on landside toe.						

Photo 2 of 3 : SP\_2018\_RD0999\_235\_5\_20180301\_00004.jpg



Looking at dense vines at landward toe. Fall 2015.

LM Start	<b>1.15</b>	Rating **	U	Issue No.	<b>5 (cont)</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 3 : SP\_2018\_RD0999\_235\_5\_20180301\_00005.jpg



Looking north at dense vegetation on landside slope near ramp.

LM Start	1.16	Rating **	U	Issue No.	40
LM End	1.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.428877 °	38.428877 °
				-121.532922 °	-121.532922 °
DWR ID	DWR_RD0999_04_f_2015_40				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Large hole and erosion on landside shoulder, slope and toe.					

Photo 1 of 3 : SP\_2018\_RD0999\_235\_40\_20180301\_00027.jpg



Looking southwest at the landside slope.

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement





**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sacramento River	Right	1.22	05/03/2018 05/03/2018	Dave Torres

LM Start	1.18	Rating **	M	Issue No.	46 (cont)	
LM End	1.18	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.429201 °		38.429201 °
				-121.533012 °		-121.533012 °
DWR ID	DWR_RD0999_04_s_2016_46					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Erosion located just below asphalt on waterside shoulder.						

Photo 2 of 2 : SP\_2018\_RD0999\_235\_46\_20180301\_00037.jpg



Looking west at foot erosion on waterward shoulder and slope.

LM Start	1.20	Rating **	M	Issue No.	22
LM End	1.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.429467 °	38.429750 °
				-121.533110 °	-121.533188 °
DWR ID	DWR_RD0999_04_f_2013_22				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_235\_22\_20180301\_00020.jpg



Looking south at dense trees on landside slope.

LM Start	<b>1.20</b>	Rating **	M	Issue No.	<b>22 (cont)</b>
LM End	<b>1.22</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_235\_22\_20180301\_00021.jpg



Looking south at dense trees on landward slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.08	Rating **	M	Issue No.	58
LM End	0.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.333751 °	38.333751 °
				-121.584390 °	-121.584390 °
DWR ID	DWR_RD0999_05_s_2018_58				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.11	Rating **	M	Issue No.	165
LM End	0.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.334198 °	38.334327 °
				-121.584308 °	-121.584275 °
DWR ID	DWR_RD0999_05_s_2017_165				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Crack greater than two inches along top of half of waterward slope. Three dead trees along slope damage section. Trees should be removed.					

Photo 1 of 3 : SP\_2018\_RD0999\_236\_165\_20180301\_00080.jpg



Looking at two inch plus crack on waterward shoulder.

LM Start	<b>0.11</b>	Rating **	M	Issue No.	<b>165 (cont)</b>
LM End	<b>0.12</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP\_2018\_RD0999\_236\_165\_20180301\_00081.jpg



Looking upstream at cracking along waterward shoulder.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.11	Rating **	M	Issue No.	165 (cont)	
LM End	0.12	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			38.334198 °		38.334327 °
				-121.584308 °		-121.584275 °
DWR ID	DWR_RD0999_05_s _ 2017_165					
Comment Code						
S1 : Repair slope instability.						
Inspector Comment						
Crack greater than two inches along top of half of waterward slope. Three dead trees along slope damage section. Trees should be removed.						

Photo 3 of 3 : SP\_2018\_RD0999\_236\_165\_20180301\_00082.jpg



Looking downstream at crack along waterward shoulder.

LM Start	0.16	Rating **	M	Issue No.	59
LM End	0.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.334924 °	38.334924 °
				-121.584077 °	-121.584077 °
DWR ID	DWR_RD0999_05_s _ 2018_59				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	0.35	Rating **	M	Issue No.	61
LM End	0.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.337442 °	38.337442 °
				-121.582522 °	-121.582522 °
DWR ID	DWR_RD0999_05_s _ 2018_61				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

<b>* Location</b>		<b>** Rating</b>		<b>+ Issue Type</b>	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.37	Rating **	M	Issue No.	8
LM End	0.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.337654 °	38.338412 °
				-121.582427 °	-121.582267 °
DWR ID	DWR_RD0999_05_s_2012_8				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_236\_8\_20180301\_00005.jpg



Looking northwest at dense vegetation on landward slope. (Fall 2016)

LM Start	<b>0.37</b>	Rating **	M	Issue No.	<b>8 (cont)</b>
LM End	<b>0.42</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_236\_8\_20180301\_00006.jpg



Looking northwest at dense vegetation on landward slope. (Spring 2016)

LM Start	0.37	Rating **	M	Issue No.	3
LM End	0.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.337697 °	38.337963 °
				-121.582420 °	-121.582352 °
DWR ID	DWR_RD0999_05_s_2012_3				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.56	Rating **	M	Issue No.	7
LM End	0.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.340475 °	38.340475 °
				-121.581942 °	-121.581942 °
DWR ID	DWR_RD0999_05_s_2012_7				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.68	Rating **	M	Issue No.	189
LM End	0.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.342032 °	38.342032 °
				-121.581372 °	-121.581372 °
DWR ID	DWR_RD0999_05_f_2014_189				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Dense wild grapevines on landside slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_236\_189\_20180301\_00103.jpg



Looking southwest at dense vegetation on landward slope and toe. (Fall 2016)

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.68	Rating **	M	Issue No.	189 (cont)	
LM End	0.68	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Vegetation			38.342032 °	38.342032 °	
				-121.581372 °	-121.581372 °	
DWR ID	DWR_RD0999_05_f_2014_189					
Comment Code						
V2 : Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comment						
Dense wild grapevines on landside slope.						

Photo 2 of 2 : SP\_2018\_RD0999\_236\_189\_20180301\_00104.jpg



Looking northwest at dense vegetation on landward slope. (Spring 2016)

LM Start	0.71	Rating **	U	Issue No.	166
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.342483 °	38.342483 °
				-121.581235 °	-121.581235 °
DWR ID	DWR_RD0999_05_s_2017_166				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Dead tree fallen on waterward slope. Root ball Left hole on waterward slope 10 to 12 inches deep and approximately 5-ft in diameter.					

Photo 1 of 3 : SP\_2018\_RD0999\_236\_166\_20180301\_00083.jpg



Looking at hole left by fallen tree on waterward slope.

LM Start	<b>0.71</b>	Rating **	U	Issue No.	<b>166 (cont)</b>
LM End	<b>0.71</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP\_2018\_RD0999\_236\_166\_20180301\_00084.jpg



Looking east at fallen tree on waterward slope.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.71	Rating **	U	Issue No.	166 (cont)	
LM End	0.71	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.342483 °	38.342483 °	
				-121.581235 °	-121.581235 °	
DWR ID	DWR_RD0999_05_s_2017_166					
Comment Code						
TR : Tree or limb						
Inspector Comment						
Dead tree fallen on waterward slope. Root ball Left hole on waterward slope 10 to 12 inches deep and approximately 5-ft in diameter.						

Photo 3 of 3 : SP\_2018\_RD0999\_236\_166\_20180301\_00085.jpg



Looking downstream at fallen tree on waterward slope.

LM Start	0.78	Rating **	M	Issue No.	128
LM End	0.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343495 °	38.343617 °
				-121.581282 °	-121.581249 °
DWR ID	DWR_RD0999_05_s_2012_128				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0999\_236\_128\_20180301\_00061.jpg



Looking northwest at untrimmed trees on landward slope. (Spring 2015)

LM Start	<b>0.78</b>	Rating **	M	Issue No.	<b>128 (cont)</b>
LM End	<b>0.79</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_236\_128\_20180301\_00062.jpg



Looking at dense trees on landside slope and toe.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	0.84	Rating **	U	Issue No.	10
LM End	0.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.344294 °	38.344294 °
				-121.581054 °	-121.581054 °
DWR ID	DWR_RD0999_05_s_2018_10				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_10\_20180507\_00200.jpg



Vegetation waterside looking north.

LM Start	0.93	Rating **	M	Issue No.	197
LM End	0.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345564 °	38.345844 °
				-121.580614 °	-121.580458 °
DWR ID	DWR_RD0999_05_f_2014_197				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.00	Rating **	M	Issue No.	180
LM End	1.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.346477 °	38.346864 °
				-121.580086 °	-121.579864 °
DWR ID	DWR_RD0999_05_s_2015_180				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	1.04	Rating **	M	Issue No.	146
LM End	1.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.347067 °	38.347331 °
				-121.579735 °	-121.579582 °
DWR ID	DWR_RD0999_05_f_2013_146				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.07	Rating **	M	Issue No.	14
LM End	1.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.347427 °	38.347863 °
				-121.579395 °	-121.579113 °
DWR ID	DWR_RD0999_05_s_2012_14				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_14\_20180301\_00011.jpg



Looking west at untrimmed trees on landward slope and toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	1.15	Rating **	U	Issue No.	15
LM End	1.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.348237 °	38.348328 °
				-121.578440 °	-121.577735 °
DWR ID	DWR_RD0999_05_s_2012_15				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_15\_20180301\_00012.jpg



Looking north at untrimmed trees on landward slope and toe.

LM Start	1.30	Rating **	M	Issue No.	36
LM End	1.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.348252 °	38.348252 °
				-121.575704 °	-121.575704 °
DWR ID	DWR_RD0999_05_s_2012_36				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.46	Rating **	U	Issue No.	18
LM End	1.83	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.348670 °	38.353852 °
				-121.573320 °	-121.573570 °
DWR ID	DWR_RD0999_05_s_2012_18				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_18\_20180301\_00018.jpg



Looking east at dense trees on landward slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	1.69	Rating **	U	Issue No.	199
LM End	1.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.351957 °	38.351957 °
				-121.574096 °	-121.574096 °
DWR ID	DWR_RD0999_05_f_2014_199				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Dense vegetation on landward slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_199\_20180301\_00109.jpg



Looking northwest at dense vegetation on landward slope.

LM Start	1.70	Rating **	M	Issue No.	21
LM End	1.77	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.352088 °	38.352968 °
				-121.574052 °	-121.574008 °
DWR ID	DWR_RD0999_05_s_2012_21				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	2.14	Rating **	M	Issue No.	24
LM End	2.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.355402 °	38.355282 °
				-121.568893 °	-121.568547 °
DWR ID	DWR_RD0999_05_s _ 2012_24				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_24\_20180301\_00021.jpg



Looking west at dense trees on landward slope. (Spring 2015)

LM Start	2.36	Rating **	M	Issue No.	42
LM End	2.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.354916 °	38.355982 °
				-121.565167 °	-121.563561 °
DWR ID	DWR_RD0999_05_s _ 2012_42				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	2.51	Rating **	M	Issue No.	82
LM End	2.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.356270 °	38.358132 °
				-121.563218 °	-121.562347 °
DWR ID	DWR_RD0999_05_s _ 2012_82				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_82\_20180301\_00041.jpg



Looking northwest at dense trees on landward slope. (Spring 2015)

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	3.22	Rating **	M	Issue No.	191
LM End	3.63	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.364698 °	38.366911 °
				-121.560158 °	-121.556784 °
DWR ID	DWR_RD0999_05_s_2014_191				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					

No Photos

LM Start	3.29	Rating **	M	Issue No.	68
LM End	3.29	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.364341 °	38.364341 °
				-121.558928 °	-121.558928 °
DWR ID	DWR_RD0999_05_s_2018_68				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_68\_20180503\_00197.jpg



Trim thin trees landside looking north.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	3.39	Rating **	U	Issue No.	213
LM End	3.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.363906 °	38.363906 °
				-121.557220 °	-121.557220 °
DWR ID	DWR_RD0999_05_s_2016_213				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					


Photo 1 of 2 : SP\_2018\_RD0999\_236\_213\_20180301\_00116.jpg



Looking northwest at untrimmed trees on landward toe. (Fall 2016)

LM Start	<b>3.39</b>	Rating **	U	Issue No.	<b>213 (cont)</b>
LM End	<b>3.39</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2018\_RD0999\_236\_213\_20180301\_00117.jpg



Looking northwest at untrimmed trees at landward toe. (Spring 2016)

LM Start	3.56	Rating **	M	Issue No.	173
LM End	3.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.365882 °	38.365882 °
				-121.556762 °	-121.556762 °
DWR ID	DWR_RD0999_05_f_2015_173				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_173\_20180301\_00095.jpg



Looking at the tree overhanging the levee crown.

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



# Reclamation District No. 0999 Netherlands

Page 14 of 27



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	3.80	Rating **	M	Issue No.	174
LM End	3.80	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.368207 °	38.368207 °
				-121.554360 °	-121.554360 °
DWR ID	DWR_RD0999_05_f_2015_174				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Downed tree branch and limbs on waterside slope.					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_174\_20180301\_00096.jpg



Looking at downed tree branch on waterward slope.

LM Start	4.25	Rating **	U	Issue No.	12
LM End	4.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.372872 °	38.372872 °
				-121.552185 °	-121.552185 °
DWR ID	DWR_RD0999_05_s_2017_12				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Large slough on waterside slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_236\_12\_20180301\_00009.jpg



Looking downstream at finger erosion on downstream side of slough.

LM Start	<b>4.25</b>	Rating **	U	Issue No.	<b>12 (cont)</b>
LM End	<b>4.25</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP\_2018\_RD0999\_236\_12\_20180301\_00010.jpg



<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	4.51	Rating **	M	Issue No.	32
LM End	4.85	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.375084 °	38.377176 °
				-121.548750 °	-121.543571 °
DWR ID	DWR_RD0999_05_f_2012_32				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					

No Photos

LM Start	4.55	Rating **	M	Issue No.	72
LM End	4.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.375073 °	38.375073 °
				-121.548044 °	-121.548044 °
DWR ID	DWR_RD0999_05_s_2018_72				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	4.55	Rating **	M	Issue No.	70
LM End	4.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.375076 °	38.375076 °
				-121.548043 °	-121.548043 °
DWR ID	DWR_RD0999_05_s_2018_70				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	4.65	Rating **	N	Issue No.	62
LM End	4.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.375365 °	38.375365 °
				-121.546305 °	-121.546305 °
DWR ID	DWR_RD0999_05_s_2012_62				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	5.12	Rating **	U	Issue No.	176
LM End	5.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.380420 °	38.380420 °
				-121.541102 °	-121.541102 °
DWR ID	DWR_RD0999_05_f_2015_176				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Large hole on waterside shoulder caused by fallen tree.					

Photo 1 of 3 : SP\_2018\_RD0999\_236\_176\_20180301\_00097.jpg



Looking at hole from falling tree on waterward shoulder. (Fall 2016)

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



### Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	<b>5.12</b>	Rating **	U	Issue No.	<b>176 (cont)</b>
LM End	<b>5.12</b>	Issue Type +	Ma	Location *	WS

Looking at hole on waterward shoulder caused by fallen tree.

Looking at fallen tree and hole on waterward slope and shoulder.

A photograph showing a large pile of cut branches and debris on a riverbank. A large tree is on the left, and a body of water is in the background. The ground is covered with dry leaves and twigs.

Looking southeast at prunings on waterward shoulder.

* Location	** Rating	+ Issue Type
LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	5.41	Rating **	C	Issue No.	215
LM End	5.41	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.381763 °	38.381763 °
				-121.545904 °	-121.545904 °
DWR ID	DWR_RD0999_05_s_2016_215				
Comment Code					
MA : Material					
Inspector Comment					
Concrete piled on waterside shoulder and slope					

No Photos

LM Start	5.50	Rating **	U	Issue No.	71
LM End	5.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.382790 °	38.383548 °
				-121.546754 °	-121.546728 °
DWR ID	DWR_RD0999_05_s_2012_71				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_71\_20180301\_00039.jpg



Looking northeast at dense vegetation on waterside slope.

LM Start	5.53	Rating **	M	Issue No.	74
LM End	5.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.383349 °	38.383349 °
				-121.546778 °	-121.546778 °
DWR ID	DWR_RD0999_05_s_2018_74				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Removed downed tree limbs.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	6.13	Rating **	M	Issue No.	60
LM End	6.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.388225 °	38.388225 °
				-121.542697 °	-121.542697 °
DWR ID	DWR_RD0999_05_s_2012_60				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_60\_20180301\_00034.jpg



Looking north at dense trees on landward slope. (Spring 2015)

LM Start	6.43	Rating **	M	Issue No.	92
LM End	6.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.391355 °	38.391776 °
				-121.540113 °	-121.539295 °
DWR ID	DWR_RD0999_05_s_2012_92				
Comment Code					
PR : Prunings					
Inspector Comment					
Large pruning piles and fallen tree on waterside and landside shoulder and slope.					

Photo 1 of 2 : SP\_2018\_RD0999\_236\_92\_20180301\_00045.jpg



Looking east at fallen tree and pruning on landward and waterward shoulder and slope.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	6.43	Rating **	M	Issue No.	92 (cont)	
LM End	6.48	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Encroachments			38.391355 °	38.391776 °	
				-121.540113 °	-121.539295 °	
DWR ID	DWR_RD0999_05_s_2012_92					
Comment Code						
PR : Prunings						
Inspector Comment						
Large pruning piles and fallen tree on waterside and landside shoulder and slope.						

Photo 2 of 2 : SP\_2018\_RD0999\_236\_92\_20180301\_00046.jpg



Looking east at tree branches and limbs on waterward and landward shoulder and slope.

LM Start	6.44	Rating **	M	Issue No.	181
LM End	6.44	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.391502 °	38.391502 °
				-121.539897 °	-121.539897 °
DWR ID	DWR_RD0999_05_f_2015_181				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Untrimmed trees on landside slope and toe.					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_181\_20180301\_00100.jpg



Looking northwest at untrimmed trees on landward slope and toe.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	7.30	Rating **	M	Issue No.	79
LM End	7.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.401509 °	38.402295 °
				-121.538116 °	-121.538785 °
DWR ID	DWR_RD0999_05_s_2018_79				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	7.30	Rating **	M	Issue No.	80	
LM End	7.37	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.401540 °		38.402301 °
				-121.538150 °		-121.538788 °
DWR ID	DWR_RD0999_05_s_2018_80					
Comment Code						
V1 : Control annual grass and weeds on the levee slopes and easements.						
Inspector Comment						

No Photos

LM Start	8.14	Rating **	M	Issue No.	205
LM End	8.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.409876 °	38.409876 °
				-121.539348 °	-121.539348 °
DWR ID	DWR_RD0999_05_f_2014_205				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	8.15	Rating **	A/W	Issue No.	220
LM End	8.42	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.409892 °	38.408612 °
				-121.539225 °	-121.534570 °
DWR ID	DWR_RD0999_05_s_2016_220				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					

No Photos

LM Start	8.22	Rating **	U	Issue No.	206
LM End	8.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.409679 °	38.409679 °
				-121.537920 °	-121.537920 °
DWR ID	DWR_RD0999_05_f _ 2014_206				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_206\_20180301\_00114.jpg



Looking west at untrimmed trees on landward toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	8.22	Rating **	U	Issue No.	118
LM End	8.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.409665 °	38.409665 °
				-121.537898 °	-121.537898 °
DWR ID	DWR_RD0999_05_s _ 2012_118				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_118\_20180301\_00058.jpg



Looking northeast at untrimmed trees on watward slope.

LM Start	8.44	Rating **	M	Issue No.	88
LM End	8.54	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.408800 °	38.409835 °
				-121.534284 °	-121.533124 °
DWR ID	DWR_RD0999_05_s _ 2018_88				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					
Crown is degraded by animal traffic.					

No Photos

LM Start	8.61	Rating **	M	Issue No.	123
LM End	8.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.410434 °	38.410434 °
				-121.532050 °	-121.532050 °
DWR ID	DWR_RD0999_05_s _ 2012_123				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	8.64	Rating **	M	Issue No.	223
LM End	8.72	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.410696 °	38.411560 °
				-121.531584 °	-121.530479 °
DWR ID	DWR_RD0999_05_f_2016_223				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Control growth on levee crown					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_223\_20180301\_00125.jpg



Looking east at overgrowth on levee crown.

LM Start	8.73	Rating **	U	Issue No.	89
LM End	8.77	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.411637 °	38.411959 °
				-121.530312 °	-121.529838 °
DWR ID	DWR_RD0999_05_s_2018_89				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

LM Start	9.01	Rating **	M	Issue No.	108
LM End	9.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.415412 °	38.415412 °
				-121.529500 °	-121.529500 °
DWR ID	DWR_RD0999_05_f_2017_108				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0999\_236\_108\_20180301\_00057.jpg



Looking southeast at the waterside slope.

LM Start	9.18	Rating **	M	Issue No.	90
LM End	9.18	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.415294 °	38.415294 °
				-121.527037 °	-121.527037 °
DWR ID	DWR_RD0999_05_s_2018_90				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	9.39	Rating **	A/W	Issue No.	114
LM End	9.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.413377 °	38.413377 °
				-121.524500 °	-121.524500 °
DWR ID	DWR_RD0999_05_s_2012_114				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0999 Netherlands

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elk Slough	Right	9.48	05/02/2018 05/08/2018	Dave Torres

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---