

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2014 Levee Inspection Results**

**Reclamation District No. 1602 Del Puerto**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2014 Levee Inspection Results**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles
Unit No. 01 San Joaquin River	Left	6.29

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/24/2014 - 04/24/2014			
DWR Inspector	Pavel Kazi			
Accompanied By	Tony Martinez RD1602			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>39</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD1602_01_s_2012_39				
Action/Comments					
Inspector Comments: The LMA has all the O&M manuals.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>77</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD1602_01_s_2012_77				
Action/Comments					
Inspector Comments: The LMA has enough flood materials in case of an incident.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>97</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD1602_01_s_2012_97				
Action/Comments					
Inspector Comments: The LMA has solid understanding and most of them have flood preparedness training.					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.00</b>	Rating **	M	Issue No.	<b>1</b>
LM End	<b>0.11</b>	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.476560 °	37.477295 °	
			-121.083862 °	-121.082087 °	
DWR ID	DWR_RD1602_01_s_2012_1				
Action/Comments					
Building Inspector Comments: Animal pens across levee crown.					

Photo 1 of 1 : pkazi\_s\_20140415\_638.jpg



Looking at animal pens on crown of levee from LM 0.00 to 0.11.

LM Start	<b>0.32</b>	Rating **	C	Issue No.	<b>21</b>
LM End	<b>0.32</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478555 °	37.478555 °	
			-121.078851 °	-121.078851 °	
DWR ID	DWR_RD1602_01_s_2012_21				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Large animal hole on the waterside shoulder of the levee.					

No Photos

LM Start	<b>0.32</b>	Rating **	A	Issue No.	<b>172</b>
LM End	<b>0.32</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478581 °	37.478581 °	
			-121.078811 °	-121.078811 °	
DWR ID	DWR_RD1602_01_s_2014_172				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_909.jpg



The rodent hole was filled with material on the waterside shoulder of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway			Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River			Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.37</b>	Rating **	C	Issue No.	<b>23</b>
LM End	<b>0.37</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478881 °	37.478881 °	
			-121.078131 °	-121.078131 °	
DWR ID	DWR_RD1602_01_s_2012_23				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>0.47</b>	Rating **	C	Issue No.	<b>14</b>
LM End	<b>0.47</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.479678 °	37.479678 °	
			-121.076418 °	-121.076418 °	
DWR ID	DWR_RD1602_01_f_2013_14				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

No Photos

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.58</b>	Rating **	M	Issue No.	<b>159</b>
LM End	<b>0.58</b>	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.480182 °	37.480182 °	
			-121.074765 °	-121.074765 °	
DWR ID	DWR_RD1602_01_s_2014_159				
Action/Comments					
Inspector Comments: FS_ID:21623 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Open 60-inch CMP riser on WS needs lid as it's depth may be a hazard to the public. FIELD_STRUCT_DESC: 16-inch pipe through levee 11.3 feet below crown. Slide gate in 60-inch corrugated metal pipe riser on the waterward side. Concrete inlet 110-feet west of the levee crown. Originally included in 1964 O&M manual. FS Date: 10/1/2013 7:57:22 AM					

Photo 1 of 1 : UCIP\_2622.jpg



60-inch CMP riser on WS shoulder.

LM Start	<b>0.58</b>	Rating **	M	Issue No.	<b>160</b>
LM End	<b>0.58</b>	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.480176 °	37.480176 °	
			-121.074736 °	-121.074736 °	
DWR ID	DWR_RD1602_01_s_2014_160				
Action/Comments					
Inspector Comments: FS_ID:22937 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: No permit identified for this crossing. FIELD_STRUCT_DESC: Communication line through the levee at an unknown depth. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_3271.jpg



Communication line access box on LS shoulder.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.60</b>	Rating **	M	Issue No.	<b>4</b>
LM End	<b>0.60</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.479968 °	37.479968 °	
			-121.074583 °	-121.074583 °	
DWR ID	DWR_RD1602_01_s_2012_4				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_639.jpg



Rodent holes were found on the waterside of the levee. The picture was taken from the toe of the waterside of the levee looking upstream.

LM Start	<b>0.60</b>	Rating **	M	Issue No.	<b>4 (cont)</b>
LM End	<b>0.60</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_640.jpg



A rodent hole was found on the waterside slope looking from the toe of the levee.

LM Start	<b>0.60</b>	Rating **	M	Issue No.	<b>70</b>
LM End	<b>0.72</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.479967 °	37.478514 °	
			-121.074582 °	-121.073435 °	
DWR ID	DWR_RD1602_01_s_2012_70				
Action/Comments					
Fence					

Photo 1 of 1 : pkazi\_s\_20140415\_719.jpg



View of barbed wire fence at landward toe looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.64</b>	Rating **	C	Issue No.	<b>38</b>
LM End	<b>0.64</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479390 °	37.479390 °
				-121.074177 °	-121.074177 °
DWR ID	DWR_RD1602_01_f_2012_38				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>0.66</b>	Rating **	C	Issue No.	<b>41</b>
LM End	<b>0.66</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479202 °	37.479202 °
				-121.074042 °	-121.074042 °
DWR ID	DWR_RD1602_01_s_2012_41				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

No Photos

LM Start	<b>0.67</b>	Rating **	A	Issue No.	<b>173</b>
LM End	<b>0.67</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479072 °	37.479072 °
				-121.073934 °	-121.073934 °
DWR ID	DWR_RD1602_01_s_2014_173				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_910.jpg



The rodent holes were filled with material on the landside shoulder of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.69</b>	Rating **	M	Issue No.	<b>26</b>
LM End	<b>0.69</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478792 °	37.478792 °
				-121.073740 °	-121.073740 °
DWR ID	DWR_RD1602_01_f_2013_26				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140428\_911.jpg



Updated picture of the rodent hole on the waterside shoulder of the levee during spring 2014 inspection.

LM Start	<b>0.69</b>	Rating **	M	Issue No.	<b>26 (cont)</b>
LM End	<b>0.69</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_674.jpg



An animal hole was found on the waterside shoulder of the levee looking upstream.

LM Start	<b>0.69</b>	Rating **	C	Issue No.	<b>31</b>
LM End	<b>0.69</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478788 °	37.478788 °
				-121.073740 °	-121.073740 °
DWR ID	DWR_RD1602_01_s_2012_31				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.71</b>	Rating **	C	Issue No.	<b>32</b>
LM End	<b>0.71</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478629 °	37.478629 °
				-121.073590 °	-121.073590 °
DWR ID	DWR_RD1602_01_s_2012_32				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	<b>0.75</b>	Rating **	M	Issue No.	<b>174</b>
LM End	<b>0.75</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478263 °	37.478263 °
				-121.072955 °	-121.072955 °
DWR ID	DWR_RD1602_01_s_2014_174				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_912.jpg



A rodent hole was found on the landside toe of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.78</b>	Rating **	M	Issue No.	<b>161</b>
LM End	<b>0.78</b>	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.477992 °	37.477992 °	
			-121.072645 °	-121.072645 °	
DWR ID	DWR_RD1602_01_s_2014_161				
Action/Comments					
Inspector Comments: FS_ID:21629 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Flap gate blocked from functioning by soil buildup on WS toe. Soil should be cleared. FIELD_STRUCT_DESC: 30-inch square reinforced concrete box culvert through levee 14.4 feet below crown. Concrete "U" headwall on both ends. Slide gate in 6'X7' concrete surge box on the waterward shoulder. Flap gate on the waterward end. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2629.jpg



Slide gate in concrete box on WS shoulder.

LM Start	<b>0.78</b>	Rating **	A/W	Issue No.	<b>72</b>
LM End	<b>0.78</b>	Issue Type +	Ma	Location *	WS
Category	Interior Drainage & Piping Systems		GPS Latitude/Longitude		
			Start	End	
Item	Flap Gates		37.477965 °	37.477965 °	
			-121.072595 °	-121.072595 °	
DWR ID	DWR_RD1602_01_s_2012_72				
Action/Comments					
Inspector Comments: Sediment around the flap gate was cleaned, and the area should be watched for future sediment deposits.					

Photo 1 of 4 : pkazi\_s\_20140415\_720.jpg



View of a flap gate with sediment preventing it from closing.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.78</b>	Rating **	A/W	Issue No.	<b>72 (cont)</b>
LM End	<b>0.78</b>	Issue Type +	Ma	Location *	WS
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Flap Gates			37.477965 °	37.477965 °
				-121.072595 °	-121.072595 °
DWR ID	DWR_RD1602_01_s_2012_72				
Action/Comments					
Inspector Comments: Sediment around the flap gate was cleaned, and the area should be watched for future sediment deposits.					

Photo 2 of 4 : pkazi\_s\_20140415\_721.jpg



Debris and sediments were obstructing the flap gate. The picture was taken from toe of waterside of the levee looking towards the crown. This picture was taken during the fall 2011 inspection.

LM Start	<b>0.78</b>	Rating **	A/W	Issue No.	<b>72 (cont)</b>
LM End	<b>0.78</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 4 : pkazi\_s\_20140415\_722.jpg



Debris and sediments were obstructing the flap gate from closing completely. The picture was taken from toe of waterside of the levee during the fall 2012 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.78</b>	Rating **	A/W	Issue No.	<b>72 (cont)</b>
LM End	<b>0.78</b>	Issue Type +	Ma	Location *	WS
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Flap Gates			37.477965 °	37.477965 °
				-121.072595 °	-121.072595 °
DWR ID	DWR_RD1602_01_s_2012_72				
Action/Comments					
Inspector Comments: Sediment around the flap gate was cleaned, and					

Photo 4 of 4 : pkazi\_s\_20140415\_723.jpg



Debris were obstructing the flap gate from closing completely. The picture was taken from toe of waterside of the levee during the fall 2013 inspection.

LM Start	<b>0.81</b>	Rating **	M	Issue No.	<b>57</b>
LM End	<b>0.81</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.477844 °	37.477844 °
				-121.072132 °	-121.072132 °
DWR ID	DWR_RD1602_01_s_2012_57				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_707.jpg



A rodent hole was found on the waterside of the levee looking upstream.

LM Start	<b>0.81</b>	Rating **	M	Issue No.	<b>57 (cont)</b>
LM End	<b>0.81</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_708.jpg



Updated picture of the rodent hole on the waterside slope of the levee looking upstream during spring spring 2013 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.83</b>	Rating **	M	Issue No.	<b>76</b>
LM End	<b>0.83</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.477907 °	37.477907 °
				-121.071754 °	-121.071754 °
DWR ID	DWR_RD1602_01_s_2012_76				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 3 : pkazi\_s\_20140428\_913.jpg



Updated picture of the rodent holes on the waterside of the levee looking upstream during spring 2014 inspection.

LM Start	<b>0.83</b>	Rating **	M	Issue No.	<b>76 (cont)</b>
LM End	<b>0.83</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : pkazi\_s\_20140415\_727.jpg



Updated picture of the rodent hole on the waterside slope of the levee looking downstream.

LM Start	<b>0.83</b>	Rating **	M	Issue No.	<b>76 (cont)</b>
LM End	<b>0.83</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : pkazi\_s\_20140415\_726.jpg



A rodent hole was found on the waterside of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.95</b>	Rating **	M	Issue No.	<b>175</b>
LM End	<b>0.95</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478487 °	37.478487 °
				-121.069591 °	-121.069591 °
DWR ID	DWR_RD1602_01_s_2014_175				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_914.jpg



View of the rodent hole on the waterside shoulder of the levee looking upstream.

LM Start	<b>0.95</b>	Rating **	M	Issue No.	<b>47</b>
LM End	<b>0.95</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478474 °	37.478474 °
				-121.069586 °	-121.069586 °
DWR ID	DWR_RD1602_01_f_2012_47				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_696.jpg



Updated picture of a rodent hole on the waterside slope of the levee looking upstream during fall 2013 inspection.

LM Start	<b>0.95</b>	Rating **	M	Issue No.	<b>47 (cont)</b>
LM End	<b>0.95</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_695.jpg



A rodent hole was found on the waterside slope of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>0.99</b>	Rating **	M	Issue No.	<b>36</b>
LM End	<b>0.99</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.478719 °	37.478719 °
				-121.069072 °	-121.069072 °
DWR ID	DWR_RD1602_01_s_2012_36				
Action/Comments					
Ramp					

Photo 1 of 1 : pkazi\_s\_20140415\_683.jpg



View of the ramp on the crown. The picture was taken from crown looking downstream.

LM Start	<b>1.01</b>	Rating **	M	Issue No.	<b>162</b>
LM End	<b>1.01</b>	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.478817 °	37.478817 °
				-121.068772 °	-121.068772 °
DWR ID	DWR_RD1602_01_s_2014_162				
Action/Comments					
Inspector Comments: FS_ID:21642 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Appears abandoned siphon breakers covered in soil and flapgate missing. FIELD_STRUCT_DESC: 2 of 2: 16-inch pipe through levee 17.0 feet below crown. Pumps on pump platform on the landward side. Siphon breakers in 24-inch risers on the waterward shoulder. Concrete "U" headwall and flap gate on the waterward end. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2667.jpg



Pipe visible under walkway at puming plant on LS toe.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown
--

<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N</b> : Not Inspected/Rated <b>C</b> : Corrected <b>A/W</b> : Acceptable but Monitor & Maintain
--	--

<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.01</b>	Rating **	M	Issue No.	<b>163</b>
LM End	<b>1.01</b>	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.478815 °	37.478815 °
				-121.068780 °	-121.068780 °
DWR ID	DWR_RD1602_01_s_2014_163				
Action/Comments					
Inspector Comments: FS_ID:21639 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Appears abandoned and if so should be done so properly. Flaggate missing. FIELD_STRUCT_DESC: 1 of 2: 16-inch pipe through levee 17.0 feet below crown. Pumps on pump platform on the landward side. Siphon breaker in 24-inch CMP risers on the waterward shoulder. Concrete "U" headwall and flap gate on the waterward end. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

No Photos

LM Start	<b>1.02</b>	Rating **	C	Issue No.	<b>9</b>
LM End	<b>1.02</b>	Issue Type +	Ma	Location *	WS
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.478838 °	37.478838 °
				-121.068707 °	-121.068707 °
DWR ID	DWR_RD1602_01_s_2012_9				
Action/Comments					
Inspector Comments: PVC pipe has been removed.					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.02</b>	Rating **	M	Issue No.	<b>164</b>
LM End	<b>1.02</b>	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.478779 °	37.478779 °
				-121.068508 °	-121.068508 °
DWR ID	DWR_RD1602_01_s_2014_164				
Action/Comments					
Inspector Comments: FS_ID:21647					

Photo 1 of 1 : UCIP\_2678.jpg



Grated inlet and 5'X5' concrete box on LS toe.

LM Start	<b>1.04</b>	Rating **	M	Issue No.	<b>55</b>
LM End	<b>1.04</b>	Issue Type +	Ma	Location *	WS
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Concrete Tilting / Settlement			37.478678 °	37.478678 °
				-121.068305 °	-121.068305 °
DWR ID	DWR_RD1602_01_s_2012_55				
Action/Comments					
Inspector Comments: The outlet headwall is tilting away from the pipe rendering the existing flap gate ineffective. Repair gap between pipe and headwall and stabilize headwall to prevent further damage.					

Photo 1 of 2 : pkazi\_s\_20140415\_704.jpg



Separation of outfall structure from the outlet pipe at LM 1.04.

LM Start	<b>1.04</b>	Rating **	M	Issue No.	<b>55 (cont)</b>
LM End	<b>1.04</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_705.jpg



Additional view of outfall structure at LM 1.04.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.04</b>	Rating **	M	Issue No.	<b>176</b>
LM End	<b>1.04</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478652 °	37.478652 °	
			-121.068114 °	-121.068114 °	
DWR ID	DWR_RD1602_01_s_2014_176				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_915.jpg



A rodent hole was found on the waterside toe of the levee.

LM Start	<b>1.06</b>	Rating **	M	Issue No.	<b>28</b>
LM End	<b>1.06</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478577 °	37.478577 °	
			-121.067920 °	-121.067920 °	
DWR ID	DWR_RD1602_01_f_2013_28				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_675.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>1.07</b>	Rating **	M	Issue No.	<b>37</b>
LM End	<b>1.07</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		37.478567 °	37.478567 °	
			-121.067847 °	-121.067847 °	
DWR ID	DWR_RD1602_01_s_2012_37				
Action/Comments					
Repair slope instability. Inspector Comments: Small amount of slumping at waterside toe of the levee.					

Photo 1 of 3 : pkazi\_s\_20140415\_684.jpg



Small amount of slumping at water toe.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.07</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>1.07</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.478567 °	37.478567 °
				-121.067847 °	-121.067847 °
DWR ID	DWR_RD1602_01_s_2012_37				
Action/Comments					
Repair slope instability. Inspector Comments: Small amount of slumping at waterside toe of the levee.					

Photo 2 of 3 : pkazi\_s\_20140415\_685.jpg



Depression at the waterside slope of the levee during Spring 2011 inspection.

LM Start	<b>1.07</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>1.07</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : pkazi\_s\_20140415\_686.jpg



Updated picture of the depression at the waterside toe of the levee. The picture was taken from the crown of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>1.10</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478454 °	37.478454 °	
			-121.067209 °	-121.067209 °	
DWR ID	DWR_RD1602_01_s_2012_8				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_642.jpg



Rodent hole was found on the waterside of the levee. The picture was taken from waterside looking upstream.

LM Start	<b>1.11</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>1.11</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478371 °	37.478371 °	
			-121.066793 °	-121.066793 °	
DWR ID	DWR_RD1602_01_s_2013_11				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_645.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>1.11</b>	Rating **	M	Issue No.	<b>11 (cont)</b>
LM End	<b>1.11</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_646.jpg



Rodent holes were found on the waterside slope of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.12</b>	Rating **	M	Issue No.	<b>56</b>
LM End	<b>1.12</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478372 °	37.478372 °	
			-121.066797 °	-121.066797 °	
DWR ID	DWR_RD1602_01_f_2012_56				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140415\_706.jpg



A rodent hole was found on the waterside toe of the levee looking upstream.

LM Start	<b>1.13</b>	Rating **	M	Issue No.	<b>7</b>
LM End	<b>1.13</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478331 °	37.478331 °	
			-121.066705 °	-121.066705 °	
DWR ID	DWR_RD1602_01_s_2012_7				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_641.jpg



Animal burrow was found on the landside of the levee. The picture was taken from the toe of the levee looking upstream.

LM Start	<b>1.15</b>	Rating **	M	Issue No.	<b>65</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478285 °	37.478285 °	
			-121.066299 °	-121.066299 °	
DWR ID	DWR_RD1602_01_f_2012_65				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_714.jpg



Rodent holes were found on the waterside toe of the levee. The picture was taken from toe of the levee looking towards the crown.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.15</b>	Rating **	M	Issue No.	<b>65 (cont)</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478285 °	37.478285 °	
			-121.066299 °	-121.066299 °	
DWR ID	DWR_RD1602_01_f_2012_65				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 2 of 2 : pkazi\_s\_20140415\_715.jpg



Updated picture of rodent hole on the waterside slope of the levee looking upstream during fall 2013 inspection.

LM Start	<b>1.16</b>	Rating **	M	Issue No.	<b>12</b>
LM End	<b>1.16</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478256 °	37.478256 °	
			-121.065898 °	-121.065898 °	
DWR ID	DWR_RD1602_01_s_2013_12				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_647.jpg



A rodent hole was found on the waterside shoulder of the levee looking downstream.

LM Start	<b>1.17</b>	Rating **	M	Issue No.	<b>78</b>
LM End	<b>1.17</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478267 °	37.478267 °	
			-121.065895 °	-121.065895 °	
DWR ID	DWR_RD1602_01_s_2012_78				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_728.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.19</b>	Rating **	M	Issue No.	<b>79</b>
LM End	<b>1.19</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478324 °	37.478324 °	
			-121.065444 °	-121.065444 °	
DWR ID	DWR_RD1602_01_s_2012_79				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140428\_916.jpg



Updated picture of the rodent holes on the waterside toe of the levee during spring 2014 inspection.

LM Start	<b>1.19</b>	Rating **	M	Issue No.	<b>79 (cont)</b>
LM End	<b>1.19</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_729.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>1.21</b>	Rating **	M	Issue No.	<b>80</b>
LM End	<b>1.21</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478391 °	37.478391 °	
			-121.065111 °	-121.065111 °	
DWR ID	DWR_RD1602_01_s_2012_80				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 2 : pkazi\_s\_20140428\_917.jpg



Updated picture of the rodent holes on the waterside shoulder of the levee during spring 2014 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.21</b>	Rating **	M	Issue No.	<b>80 (cont)</b>
LM End	<b>1.21</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478391 °	37.478391 °
				-121.065111 °	-121.065111 °
DWR ID	DWR_RD1602_01_s_2012_80				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 2 of 2 : pkazi\_s\_20140415\_730.jpg



Rodent hole on the waterside shoulder of the levee looking upstream.

LM Start	<b>1.23</b>	Rating **	M	Issue No.	<b>98</b>
LM End	<b>1.23</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478522 °	37.478522 °
				-121.064723 °	-121.064723 °
DWR ID	DWR_RD1602_01_f_2012_98				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_740.jpg



Rodent holes were found on the waterside toe of the levee looking downstream.

LM Start	<b>1.27</b>	Rating **	M	Issue No.	<b>30</b>
LM End	<b>1.27</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478761 °	37.478761 °
				-121.064313 °	-121.064313 °
DWR ID	DWR_RD1602_01_f_2013_30				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_676.jpg



A rodent hole was found on the waterside shoulder of the levee looking downstream.

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.53</b>	Rating **	M	Issue No.	<b>177</b>
LM End	<b>1.53</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478504 °	37.478504 °	
			-121.060005 °	-121.060005 °	
DWR ID	DWR_RD1602_01_s_2014_177				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_918.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>1.57</b>	Rating **	M	Issue No.	<b>178</b>
LM End	<b>1.57</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.478221 °	37.478221 °	
			-121.059483 °	-121.059483 °	
DWR ID	DWR_RD1602_01_s_2014_178				
Action/Comments					

No Photos

LM Start	<b>1.62</b>	Rating **	M	Issue No.	<b>43</b>
LM End	<b>2.29</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.477663 °	37.470264 °	
			-121.058716 °	-121.054377 °	
DWR ID	DWR_RD1602_01_s_2012_43				
Action/Comments					
Fence Inspector Comments: Fence at the landside toe of the levee.					

Photo 1 of 1 : pkazi\_s\_20140415\_693.jpg



View of the fence on the landside toe of the levee. The picture was taken from crown looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>1.68</b>	Rating **	M	Issue No.	<b>103</b>
LM End	<b>1.68</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.476880 °	37.476880 °	
			-121.058329 °	-121.058329 °	
DWR ID	DWR_RD1602_01_f_2012_103				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_742.jpg



Rodent holes were found on the waterside toe of the levee looking upstream.

LM Start	<b>1.69</b>	Rating **	M	Issue No.	<b>18</b>
LM End	<b>1.69</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.476576 °	37.476576 °	
			-121.058174 °	-121.058174 °	
DWR ID	DWR_RD1602_01_s_2013_18				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_656.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>1.81</b>	Rating **	C	Issue No.	<b>33</b>
LM End	<b>2.65</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.475151 °	37.468636 °	
			-121.057956 °	-121.048630 °	
DWR ID	DWR_RD1602_01_f_2013_33				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>2.00</b>	Rating **	A	Issue No.	<b>179</b>
LM End	<b>2.00</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.472321 °	37.472321 °	
			-121.057900 °	-121.057900 °	
DWR ID	DWR_RD1602_01_s_2014_179				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: LMA worked on the clearing up vegetation on the slopes of the levee.					

Photo 1 of 1 : pkazi\_s\_20140428\_919.jpg



View of the waterside slope of the levee looking upstream.

LM Start	<b>2.03</b>	Rating **	M	Issue No.	<b>45</b>
LM End	<b>2.03</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.471734 °	37.471734 °	
			-121.057670 °	-121.057670 °	
DWR ID	DWR_RD1602_01_s_2012_45				
Action/Comments					
Equipment Inspector Comments: A well is present at the toe of the landside of the slope.					

Photo 1 of 1 : pkazi\_s\_20140415\_694.jpg



A well is located at the landside toe of the levee. The picture was taken from the crown looking toward the landside of the levee.

LM Start	<b>2.06</b>	Rating **	C	Issue No.	<b>82</b>
LM End	<b>2.06</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.471507 °	37.471507 °	
			-121.057542 °	-121.057542 °	
DWR ID	DWR_RD1602_01_s_2012_82				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>2.11</b>	Rating **	M	Issue No.	<b>85</b>
LM End	<b>2.11</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.470858 °	37.470858 °
				-121.057140 °	-121.057140 °
DWR ID	DWR_RD1602_01_s_2012_85				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_733.jpg



A rodent hole was found on the waterside shoulder of the levee looking upstream.

LM Start	<b>2.11</b>	Rating **	M	Issue No.	<b>85 (cont)</b>
LM End	<b>2.11</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_734.jpg



Updated picture of a rodent hole on the waterside shoulder of the levee looking upstream during fall 2013 inspection.

LM Start	<b>2.18</b>	Rating **	M	Issue No.	<b>86</b>
LM End	<b>2.18</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.470323 °	37.470323 °
				-121.056148 °	-121.056148 °
DWR ID	DWR_RD1602_01_s_2012_86				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140415\_735.jpg



Rodent holes were found on the waterside toe of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>2.20</b>	Rating **	M	Issue No.	<b>180</b>
LM End	<b>2.20</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.470278 °	37.470278 °	
			-121.055945 °	-121.055945 °	
DWR ID	DWR_RD1602_01_s_2014_180				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>2.20</b>	Rating **	C	Issue No.	<b>34</b>
LM End	<b>2.20</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.470245 °	37.470245 °	
			-121.055793 °	-121.055793 °	
DWR ID	DWR_RD1602_01_f_2013_34				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>2.24</b>	Rating **	M	Issue No.	<b>59</b>
LM End	<b>3.45</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.470119 °	37.459606 °	
			-121.055117 °	-121.043240 °	
DWR ID	DWR_RD1602_01_s_2012_59				
Action/Comments					
Ditch Inspector Comments: Concrete ditch was constructed before the levee was built.					

Photo 1 of 1 : pkazi\_s\_20140415\_709.jpg



Concrete drain was built at the toe of the levee. The picture was taken from the crown looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>2.29</b>	Rating **	M	Issue No.	<b>35</b>
LM End	<b>2.29</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.470290 °	37.470290 °	
			-121.054278 °	-121.054278 °	
DWR ID	DWR_RD1602_01_f_2013_35				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_682.jpg



Animal holes were found on the waterside shoulder of the levee looking upstream.

LM Start	<b>2.59</b>	Rating **	C	Issue No.	<b>20</b>
LM End	<b>2.59</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.468945 °	37.468945 °	
			-121.049008 °	-121.049008 °	
DWR ID	DWR_RD1602_01_s_2013_20				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>2.63</b>	Rating **	A	Issue No.	<b>181</b>
LM End	<b>2.83</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.468820 °	37.466743 °	
			-121.048855 °	-121.046274 °	
DWR ID	DWR_RD1602_01_s_2014_181				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>2.92</b>	Rating **	C	Issue No.	<b>40</b>
LM End	<b>3.31</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.465782 °	37.461370 °	
			-121.045094 °	-121.041644 °	
DWR ID	DWR_RD1602_01_f_2013_40				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>2.98</b>	Rating **	M	Issue No.	<b>182</b>
LM End	<b>2.98</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.465132 °	37.465132 °	
			-121.044529 °	-121.044529 °	
DWR ID	DWR_RD1602_01_s_2014_182				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_920.jpg



A rodent hole was found on the landside toe of the levee looking downstream.

LM Start	<b>2.99</b>	Rating **	C	Issue No.	<b>48</b>
LM End	<b>3.10</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.465057 °	37.463804 °	
			-121.044461 °	-121.043132 °	
DWR ID	DWR_RD1602_01_f_2013_48				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.13</b>	Rating **	C	Issue No.	<b>49</b>
LM End	<b>3.32</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.463500 °	37.461243 °	
			-121.042699 °	-121.041713 °	
DWR ID	DWR_RD1602_01_s_2012_49				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	<b>3.30</b>	Rating **	M	Issue No.	<b>165</b>
LM End	<b>3.30</b>	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.461507 °	37.461507 °	
			-121.041609 °	-121.041609 °	
DWR ID	DWR_RD1602_01_s_2014_165				
Action/Comments					
Inspector Comments: FS_ID:21652 EP_NO: 8193 Repair Type: Crossing Status: UCIP Comments: Appears abandoned, and if so should be done so properly. No handle on slide gate, no cover on CMP standpipe on WS shoulder. FIELD_STRUCT_DESC: 16-inch pipe through levee 11.5 feet below crown. Slide gate in 60-inch corrugated metal pipe riser on the waterward slope. Discharge into concrete-lined ditch on the landward side (Permit No. 8193, 1964). Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2694.jpg



Slide gate in 60-inch CMP riser on WS shoulder.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.32</b>	Rating **	M	Issue No.	<b>54</b>
LM End	<b>3.49</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.461147 °	37.459242 °	
			-121.041785 °	-121.043582 °	
DWR ID	DWR_RD1602_01_f_2013_54				
Action/Comments					
Ditch Inspector Comments: Concrete lined ditch on the landside toe of the levee.					

Photo 1 of 1 : pkazi\_s\_20140415\_703.jpg



A concrete lined ditch was found on the landside toe of the levee looking upstream.

LM Start	<b>3.39</b>	Rating **	M	Issue No.	<b>50</b>
LM End	<b>3.56</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.460327 °	37.458373 °	
			-121.042497 °	-121.044081 °	
DWR ID	DWR_RD1602_01_s_2012_50				
Action/Comments					
Ditch Inspector Comments: A ditch is located on waterside toe of the levee.					

Photo 1 of 1 : pkazi\_s\_20140415\_699.jpg



A ditch was located on the waterside toe of the levee. The picture was taken from the crown looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.47</b>	Rating **	M	Issue No.	<b>93</b>
LM End	<b>3.47</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.459511 °	37.459511 °	
			-121.043350 °	-121.043350 °	
DWR ID	DWR_RD1602_01_s_2012_93				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_736.jpg



Rodent holes were found on the waterside slope of the levee looking upstream.

LM Start	<b>3.47</b>	Rating **	M	Issue No.	<b>93 (cont)</b>
LM End	<b>3.47</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_737.jpg



Updated picture of rodent hole on the waterside shoulder of the levee looking downstream.

LM Start	<b>3.49</b>	Rating **	M	Issue No.	<b>183</b>
LM End	<b>3.49</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.459279 °	37.459279 °	
			-121.043578 °	-121.043578 °	
DWR ID	DWR_RD1602_01_s_2014_183				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_921.jpg



A rodent hole was found on the waterside shoulder of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.52</b>	Rating **	M	Issue No.	<b>106</b>
LM End	<b>3.52</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.458810 °	37.458810 °	
			-121.043850 °	-121.043850 °	
DWR ID	DWR_RD1602_01_f_2012_106				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_744.jpg



Rodent holes were found on the waterside slope of the levee looking downstream.

LM Start	<b>3.53</b>	Rating **	M	Issue No.	<b>107</b>
LM End	<b>3.53</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.458762 °	37.458762 °	
			-121.043875 °	-121.043875 °	
DWR ID	DWR_RD1602_01_f_2012_107				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_745.jpg



A rodent hole was found on the waterside shoulder of the levee looking upstream.

LM Start	<b>3.53</b>	Rating **	M	Issue No.	<b>107 (cont)</b>
LM End	<b>3.53</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_746.jpg



Updated picture of rodent hole on the waterside shoulder of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.54</b>	Rating **	M	Issue No.	<b>25</b>
LM End	<b>3.54</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.458139 °	37.458139 °
				-121.044225 °	-121.044225 °
DWR ID	DWR_RD1602_01_s_2013_25				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 2 : pkazi\_s\_20140428\_922.jpg



Updated picture of the rodent hole on the waterside toe of the levee looking upstream.

LM Start	<b>3.54</b>	Rating **	M	Issue No.	<b>25 (cont)</b>
LM End	<b>3.54</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_673.jpg



A rodent hole was found on the waterside toe of the levee looking upstream.

LM Start	<b>3.64</b>	Rating **	M	Issue No.	<b>184</b>
LM End	<b>3.64</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.457282 °	37.457282 °
				-121.044671 °	-121.044671 °
DWR ID	DWR_RD1602_01_s_2014_184				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_923.jpg



View of the rodent holes on the waterside slope of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.64</b>	Rating **	M	Issue No.	<b>185</b>
LM End	<b>3.64</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.457206 °	37.457206 °	
			-121.044692 °	-121.044692 °	
DWR ID	DWR_RD1602_01_s_2014_185				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>3.67</b>	Rating **	M	Issue No.	<b>108</b>
LM End	<b>3.67</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.456775 °	37.456775 °	
			-121.044704 °	-121.044704 °	
DWR ID	DWR_RD1602_01_f_2012_108				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_747.jpg



A rodent hole was found on the waterside slope of the levee looking upstream.

LM Start	<b>3.71</b>	Rating **	M	Issue No.	<b>186</b>
LM End	<b>3.71</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.456304 °	37.456304 °	
			-121.044242 °	-121.044242 °	
DWR ID	DWR_RD1602_01_s_2014_186				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_924.jpg



A rodent hole was found on the waterside slope of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.75</b>	Rating **	M	Issue No.	<b>187</b>
LM End	<b>3.75</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.455828 °	37.455828 °	
			-121.043974 °	-121.043974 °	
DWR ID	DWR_RD1602_01_s_2014_187				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>3.77</b>	Rating **	M	Issue No.	<b>188</b>
LM End	<b>3.77</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.455671 °	37.455671 °	
			-121.043898 °	-121.043898 °	
DWR ID	DWR_RD1602_01_s_2014_188				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_925.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>3.80</b>	Rating **	M	Issue No.	<b>83</b>
LM End	<b>3.80</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.455238 °	37.455238 °	
			-121.043635 °	-121.043635 °	
DWR ID	DWR_RD1602_01_s_2012_83				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_732.jpg



A rodent hole was found on the waterside shoulder of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.83</b>	Rating **	M	Issue No.	<b>15</b>
LM End	<b>3.83</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.454872 °	37.454872 °	
			-121.043370 °	-121.043370 °	
DWR ID	DWR_RD1602_01_s_2012_15				
Action/Comments					
Garbage					

Photo 1 of 2 : pkazi\_s\_20140415\_650.jpg



Garbage was found on the landside of the levee. The picture was taken from the crown looking upstream.

LM Start	<b>3.83</b>	Rating **	M	Issue No.	<b>15 (cont)</b>
LM End	<b>3.83</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : pkazi\_s\_20140415\_651.jpg



Debris was located on the landside of the levee. The picture was taken from the crown looking upstream.

LM Start	<b>3.85</b>	Rating **	M	Issue No.	<b>42</b>
LM End	<b>3.85</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.454574 °	37.454574 °	
			-121.043142 °	-121.043142 °	
DWR ID	DWR_RD1602_01_s_2012_42				
Action/Comments					
Landscaping					

Photo 1 of 1 : pkazi\_s\_20140415\_692.jpg



Remove landscaping from within 10' of landside toe.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.89</b>	Rating **	M	Issue No.	<b>166</b>
LM End	<b>3.89</b>	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.454080 °	37.454080 °	
			-121.042758 °	-121.042758 °	
DWR ID	DWR_RD1602_01_s_2014_166				
Action/Comments					
Inspector Comments: FS_ID:21656 EP_NO: 7796 Repair Type: Crossing Status: UCIP Comments: Gasline needs sign markers at levee. FIELD_STRUCT_DESC: 12.75-inch gas line crossing through levee 3.0 feet below crown (Permit No. 7796, 1972). Originally included in the 1964 O&M manual. FS Date: 10/1/2013					

No Photos

LM Start	<b>3.90</b>	Rating **	M	Issue No.	<b>66</b>
LM End	<b>3.96</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.453936 °	37.453309 °	
			-121.042673 °	-121.042191 °	
DWR ID	DWR_RD1602_01_f_2013_66				
Action/Comments					
Fence					

Photo 1 of 1 : pkazi\_s\_20140415\_716.jpg



Fences were found on the landside toe of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.91</b>	Rating **	M	Issue No.	<b>94</b>
LM End	<b>3.91</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.453891 °	37.453891 °	
			-121.042629 °	-121.042629 °	
DWR ID	DWR_RD1602_01_s_2012_94				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_738.jpg



Rodent holes were found on the waterside toe of the levee looking upstream.

LM Start	<b>3.96</b>	Rating **	M	Issue No.	<b>62</b>
LM End	<b>3.96</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		37.453216 °	37.453216 °	
			-121.042127 °	-121.042127 °	
DWR ID	DWR_RD1602_01_s_2012_62				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible. Inspector Comments: Significant damage to USACE constructed seepage berm due to human activity.					

Photo 1 of 1 : pkazi\_s\_20140415\_712.jpg



Repair damage to USACE constructed seepage berm by pedestrian and cycle traffic at LM 3.96.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.97</b>	Rating **	M	Issue No.	<b>63</b>
LM End	<b>4.07</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.452983 °	37.451866 °	
			-121.042301 °	-121.041206 °	
DWR ID	DWR_RD1602_01_s_2012_63				
Action/Comments					
Fence					

Photo 1 of 1 : pkazi\_s\_20140415\_713.jpg



View of a barbed wire fence on the landward slope looking upstream.

LM Start	<b>3.99</b>	Rating **	M	Issue No.	<b>16</b>
LM End	<b>3.99</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.452805 °	37.452805 °	
			-121.041769 °	-121.041769 °	
DWR ID	DWR_RD1602_01_s_2012_16				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 3 : pkazi\_s\_20140415\_652.jpg



Rodent hole at the waterside slope of the levee. The picture was taken from the crown looking upstream.

LM Start	<b>3.99</b>	Rating **	M	Issue No.	<b>16 (cont)</b>
LM End	<b>3.99</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : pkazi\_s\_20140415\_653.jpg



Animal burrow was found on the waterside of the levee. The picture was taken from the toe of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>3.99</b>	Rating **	M	Issue No.	<b>16 (cont)</b>
LM End	<b>3.99</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.452805 °	37.452805 °
				-121.041769 °	-121.041769 °
DWR ID	DWR_RD1602_01_s_2012_16				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 3 of 3 : pkazi\_s\_20140415\_654.jpg



Updated view of the rodent holes on the waterside slope of the levee looking upstream during fall 2013 inspection.

LM Start	<b>4.00</b>	Rating **	M	Issue No.	<b>95</b>
LM End	<b>4.00</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.452820 °	37.452820 °
				-121.041776 °	-121.041776 °
DWR ID	DWR_RD1602_01_s_2012_95				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_739.jpg



A rodent hole was found on the waterside of the levee looking upstream.

LM Start	<b>4.05</b>	Rating **	M	Issue No.	<b>68</b>
LM End	<b>4.05</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.452207 °	37.452207 °
				-121.041350 °	-121.041350 °
DWR ID	DWR_RD1602_01_f_2013_68				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_718.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.11</b>	Rating **	M	Issue No.	<b>189</b>
LM End	<b>4.11</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.451541 °	37.451541 °
				-121.040688 °	-121.040688 °
DWR ID	DWR_RD1602_01_s_2014_189				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>4.11</b>	Rating **	M	Issue No.	<b>51</b>
LM End	<b>4.11</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.451520 °	37.451520 °
				-121.040699 °	-121.040699 °
DWR ID	DWR_RD1602_01_f_2012_51				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_700.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>4.15</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>4.15</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.451051 °	37.451051 °
				-121.040109 °	-121.040109 °
DWR ID	DWR_RD1602_01_s_2012_17				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_655.jpg



Rodent hole was found on the waterside of the levee. The picture was taken from the crown looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.22</b>	Rating **	M	Issue No.	<b>190</b>
LM End	<b>4.22</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.450241 °	37.450241 °	
			-121.039421 °	-121.039421 °	
DWR ID	DWR_RD1602_01_s_2014_190				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_926.jpg



A rodent hole was found on the waterside shoulder of the levee looking upstream.

LM Start	<b>4.23</b>	Rating **	M	Issue No.	<b>53</b>
LM End	<b>4.23</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.450142 °	37.450142 °	
			-121.039397 °	-121.039397 °	
DWR ID	DWR_RD1602_01_s_2012_53				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_702.jpg



Rodent holes were found on the waterside slope of the levee looking upstream.

LM Start	<b>4.32</b>	Rating **	M	Issue No.	<b>191</b>
LM End	<b>4.32</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.448987 °	37.448987 °	
			-121.038574 °	-121.038574 °	
DWR ID	DWR_RD1602_01_s_2014_191				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_927.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.35</b>	Rating **	M	Issue No.	<b>193</b>
LM End	<b>4.35</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.448473 °	37.448473 °
				-121.038264 °	-121.038264 °
DWR ID	DWR_RD1602_01_s_2014_193				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>4.35</b>	Rating **	M	Issue No.	<b>192</b>
LM End	<b>4.35</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.448474 °	37.448474 °
				-121.038265 °	-121.038265 °
DWR ID	DWR_RD1602_01_s_2014_192				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>4.37</b>	Rating **	M	Issue No.	<b>52</b>
LM End	<b>4.37</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.448327 °	37.448327 °
				-121.038192 °	-121.038192 °
DWR ID	DWR_RD1602_01_f_2012_52				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_701.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.39</b>	Rating **	M	Issue No.	<b>109</b>
LM End	<b>4.39</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.448076 °	37.448076 °
				-121.038037 °	-121.038037 °
DWR ID	DWR_RD1602_01_f_2012_109				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : pkazi\_s\_20140415\_748.jpg



A rodent hole was found on the waterside toe of the levee looking downstream.

LM Start	<b>4.39</b>	Rating **	M	Issue No.	<b>109 (cont)</b>
LM End	<b>4.39</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_749.jpg



Updated pictures of rodent holes were found on the waterside toe of the levee looking upstream.

LM Start	<b>4.42</b>	Rating **	M	Issue No.	<b>194</b>
LM End	<b>4.42</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.447484 °	37.447484 °
				-121.037667 °	-121.037667 °
DWR ID	DWR_RD1602_01_s_2014_194				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

Photo 1 of 1 : pkazi\_s\_20140428\_928.jpg



A rodent hole was found on the waterside shoulder of the levee looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.42</b>	Rating **	M	Issue No.	<b>195</b>
LM End	<b>4.42</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.447484 °	37.447484 °	
			-121.037667 °	-121.037667 °	
DWR ID	DWR_RD1602_01_s_2014_195				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>4.45</b>	Rating **	M	Issue No.	<b>67</b>
LM End	<b>4.92</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.447213 °	37.441014 °	
			-121.037665 °	-121.036932 °	
DWR ID	DWR_RD1602_01_s_2012_67				
Action/Comments					
Fence					

Photo 1 of 1 : pkazi\_s\_20140415\_717.jpg



View of the fence on the landside toe of the levee. The picture was taken from the crown looking upstream.

LM Start	<b>4.50</b>	Rating **	M	Issue No.	<b>64</b>
LM End	<b>4.66</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.446485 °	37.444290 °	
			-121.038037 °	-121.037953 °	
DWR ID	DWR_RD1602_01_s_2012_64				
Action/Comments					
Ditch					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.51</b>	Rating **	M	Issue No.	<b>167</b>
LM End	<b>4.51</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.446545 °	37.446545 °
				-121.037941 °	-121.037941 °
DWR ID	DWR_RD1602_01_s_2014_167				
Action/Comments					
Inspector Comments: FS_ID:21657 EP_NO: 8195 Repair Type: Crossing Status: UCIP Comments: Lid missing from 60-inch CMP riser, may be an attractive nuisance or hazard to public. FIELD_STRUCT_DESC: 18-inch pipe through levee 10.0 feet below crown. Slide gate in 60-inch corrugated metal pipe riser on the waterward slope. Concrete discharge box on landward end. Pipe is buried across waterward berm to pump on the riverbank approximately 1,000 feet from the levee. (Permit No. 8195, 1972). Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2696.jpg



Concrete ditch at outlet from pipe on LS toe.

LM Start	<b>4.65</b>	Rating **	M	Issue No.	<b>196</b>
LM End	<b>4.65</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.444443 °	37.444443 °
				-121.037876 °	-121.037876 °
DWR ID	DWR_RD1602_01_s_2014_196				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>4.72</b>	Rating **	M	Issue No.	<b>13</b>
LM End	<b>4.72</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.443481 °	37.443481 °	
			-121.037736 °	-121.037736 °	
DWR ID	DWR_RD1602_01_s_2012_13				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140415\_648.jpg



View of rodent holes on the landward slope looking upstream.

LM Start	<b>4.78</b>	Rating **	U	Issue No.	<b>197</b>
LM End	<b>4.78</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.442819 °	37.442819 °	
			-121.037214 °	-121.037214 °	
DWR ID	DWR_RD1602_01_s_2014_197				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_929.jpg



Few rodent holes were found on the landside shoulder of the levee looking downstream.

LM Start	<b>4.89</b>	Rating **	M	Issue No.	<b>198</b>
LM End	<b>4.89</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.441400 °	37.441400 °	
			-121.036706 °	-121.036706 °	
DWR ID	DWR_RD1602_01_s_2014_198				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.13</b>	Rating **	M	Issue No.	<b>199</b>
LM End	<b>5.13</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.438165 °	37.438165 °
				-121.037073 °	-121.037073 °
DWR ID	DWR_RD1602_01_s_2014_199				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_930.jpg



Few rodent holes were found on the waterside toe of the levee looking upstream.

LM Start	<b>5.14</b>	Rating **	M	Issue No.	<b>200</b>
LM End	<b>5.14</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.437950 °	37.437950 °
				-121.037032 °	-121.037032 °
DWR ID	DWR_RD1602_01_s_2014_200				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River		Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.23</b>	Rating **	M	Issue No.	<b>168</b>
LM End	<b>5.23</b>	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.436748 °	37.436748 °
				-121.036597 °	-121.036597 °
DWR ID	DWR_RD1602_01_s_2014_168				
Action/Comments					
Inspector Comments: FS_ID:21663 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Slide gate won't close completely due to sediment buildup. CMP riser needs cover. FIELD_STRUCT_DESC: 24-inch pipe through levee 11.6 feet below crown. Concrete headwall on the landward end. Concrete "U" headwall and flap gate on the waterward end. Slide gate in 60-inch corrugated metal pipe riser on the waterward slope. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2701.jpg



Slide gate in CMP riser on WS slope. Outlet visible under tree in background.

LM Start	<b>5.25</b>	Rating **	C	Issue No.	<b>24</b>
LM End	<b>5.25</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436503 °	37.436503 °
				-121.036374 °	-121.036374 °
DWR ID	DWR_RD1602_01_s_2012_24				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Possible dog made the rodent hole worse than before.					

No Photos

<p><b>* Location</b> LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.28</b>	Rating **	M	Issue No.	<b>201</b>
LM End	<b>5.50</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.436160 °	37.433631 °
				-121.036025 °	-121.033763 °
DWR ID	DWR_RD1602_01_s_2014_201				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>5.29</b>	Rating **	M	Issue No.	<b>202</b>
LM End	<b>5.29</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.436041 °	37.436041 °
				-121.035868 °	-121.035868 °
DWR ID	DWR_RD1602_01_s_2014_202				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					

Photo 1 of 1 : pkazi\_s\_20140428\_931.jpg



Erosion was found on the landside slope of the levee looking upstream.

LM Start	<b>5.29</b>	Rating **	M	Issue No.	<b>203</b>
LM End	<b>5.29</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436041 °	37.436041 °
				-121.035867 °	-121.035867 °
DWR ID	DWR_RD1602_01_s_2014_203				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : pkazi\_s\_20140428\_932.jpg



A rodent hole was found on the crown of the levee looking upstream.

<p><b>* Location</b>                  LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable                  N : Not Inspected/Rated                  C : Corrected                  A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b>                  Ma : Maintenance Deficiency                  Ob : Design &amp; System Obsolescence                  En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.34</b>	Rating **	M	Issue No.	<b>102</b>
LM End	<b>5.34</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.435533 °	37.435533 °
				-121.035371 °	-121.035371 °
DWR ID	DWR_RD1602_01_s_2012_102				
Action/Comments					
Repair slope instability.					

Photo 1 of 1 : pkazi\_s\_20140415\_741.jpg



View of significant damage and erosion to the landward slope looking upstream.

LM Start	<b>5.34</b>	Rating **	M	Issue No.	<b>75</b>
LM End	<b>5.54</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.435555 °	37.433277 °
				-121.035362 °	-121.033318 °
DWR ID	DWR_RD1602_01_s_2012_75				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 2 : pkazi\_s\_20140415\_724.jpg



Overgrown vegetation was found on the waterside slope of the levee looking upstream.

LM Start	<b>5.34</b>	Rating **	M	Issue No.	<b>75 (cont)</b>
LM End	<b>5.54</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : pkazi\_s\_20140415\_725.jpg



Vegetation was found on the waterside slope of the levee looking upstream during fall 2013 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.36</b>	Rating **	M	Issue No.	<b>61</b>
LM End	<b>5.36</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.435236 °	37.435236 °
				-121.035271 °	-121.035271 °
DWR ID	DWR_RD1602_01_s_2012_61				
Action/Comments					
Remove the wild growth other than native grasses from the levee					

Photo 1 of 2 : pkazi\_s\_20140415\_710.jpg



Vegetation was obstructing the view of the landside of the levee. The picture was taken from the crown looking upstream.

LM Start	<b>5.36</b>	Rating **	M	Issue No.	<b>61 (cont)</b>
LM End	<b>5.36</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : pkazi\_s\_20140415\_711.jpg



Updated picture of vegetation on the landside of the levee. The picture was taken from the crown looking upstream during fall 2013 inspection.

LM Start	<b>5.39</b>	Rating **	M	Issue No.	<b>204</b>
LM End	<b>5.39</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.434845 °	37.434845 °
				-121.035100 °	-121.035100 °
DWR ID	DWR_RD1602_01_s_2014_204				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and					

No Photos

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.40</b>	Rating **	M	Issue No.	<b>105</b>
LM End	<b>5.40</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.434699 °	37.434699 °
				-121.035063 °	-121.035063 °
DWR ID	DWR_RD1602_01_s_2012_105				
Action/Comments					
Repair slope instability.					

Photo 1 of 1 : pkazi\_s\_20140415\_743.jpg



View of tilling into the landward slope of the levee looking upstream. This slope has also been significantly damaged by rodent activity.

LM Start	<b>5.42</b>	Rating **	M	Issue No.	<b>22</b>
LM End	<b>5.49</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.434447 °	37.433791 °
				-121.034865 °	-121.034000 °
DWR ID	DWR_RD1602_01_f_2012_22				
Action/Comments					
Fence					

Photo 1 of 1 : pkazi\_s\_20140415\_663.jpg



A fence was found on the landside toe of the levee looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>5.50</b>	Rating **	M	Issue No.	<b>169</b>
LM End	<b>5.50</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.433646 °	37.433646 °
				-121.033845 °	-121.033845 °
DWR ID	DWR_RD1602_01_s_2014_169				
Action/Comments					
Inspector Comments: FS_ID:21674 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Pipe appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: 12-inch drain pipe through levee 6.9 feet below crown. Flap gate on the waterward end. (Maint. 1602) (could not locate 3/84) Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2715.jpg



Pipe and flapgate visible on WS toe.

LM Start	<b>5.76</b>	Rating **	M	Issue No.	<b>170</b>
LM End	<b>5.76</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.433003 °	37.433003 °
				-121.029346 °	-121.029346 °
DWR ID	DWR_RD1602_01_s_2014_170				
Action/Comments					
Inspector Comments: FS_ID:21681 EP_NO: N/A Repair Type: Crossing Status: UCIP Comments: Flapgate has minor blockage preventing gate from fully closing. FIELD_STRUCT_DESC: 30-inch square reinforced concrete box culvert through levee 9.0 feet below crown. Slide gate in concrete surge box on the waterward slope. Concrete "U" headwalls on both ends. Flap gate on the waterward end. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2739.jpg



Slide gate in concrete riser on WS shoulder.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.29	04/24/2014 04/24/2014	Pavel Kazi

LM Start	<b>6.29</b>	Rating **	M	Issue No.	<b>171</b>
LM End	<b>6.29</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.429031 °	37.429031 °
				-121.029867 °	-121.029867 °
DWR ID	DWR_RD1602_01_s_2014_171				
Action/Comments					
Inspector Comments: FS_ID:21683 EP_NO: 8194 Repair Type: Crossing Status: UCIP Comments: Pipe heavily deteriorated on LS toe. May indicate condition of rest of pipe is bad. Good candidate for video inspection. FIELD_STRUCT_DESC: 18-inch concrete pipe through levee 3.0 feet below crown (Permit No. 8194 1972). Slide gate inside 36-inch concrete standpipe on WS shoulder. Originally included in 1964 O&M manual. FS Date: 10/1/2013					

Photo 1 of 1 : UCIP\_2742.jpg



36-inch concrete standpipe on WS shoulder.

<p><b>* Location</b> LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
--	--	---