

Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet

Reclamation District No. 1602 Del Puerto

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

†
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet**

Reclamation District No. 1602 Del Puerto

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Left	6.24
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/27/2024 - 3/27/2024			
DWR Inspector	Nate Hicks			
Accompanied By	Nick Short RD1602			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.00	Rating **	A	Issue No.	39
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_RD1602_01_s _ 2012_39				
Comment Code					
OM : O&M Manuals					
Inspector Comment					
The LMA has all the O&M manuals on hand.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	77
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD1602_01_s _ 2012_77				
Comment Code					
ES : Emergency Supplies & Equipment					
Inspector Comment					
The LMA has a DWR flood fight container on site at their yard.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	97
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_RD1602_01_s _ 2012_97				
Comment Code					
FP : Flood Preparedness & Training					
Inspector Comment					
The LMA participated in DWR Flood Fight Training in Spring 2024.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.00	Rating **	U	Issue No.	34
LM End	0.12	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.476578°	37.477252°
				-121.083898°	-121.081967°
DWR ID	DWR_RD1602_01_s_2024_34				
Comment Code					
AT : Agricultural tilling					
Inspector Comment					
Active tilling along the waterside slope.					

Photo 1 of 1 : SP_2024_RD1602_110_34_20240402_00084.jpg



View of tilling along the waterside slope (Spring 2024).

LM Start	0.00	Rating **	U	Issue No.	28
LM End	0.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.476578°	37.477248°
				-121.083898°	-121.081971°
DWR ID	DWR_RD1602_01_s_2024_28				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Rodent burrows in the crown and waterside shoulder should be backfilled and compacted.					

Photo 1 of 1 : SP_2024_RD1602_110_28_20240402_00085.jpg



View of animal holes along the waterside slope (Spring 2024).

LM Start	0.11	Rating **	M	Issue No.	60
LM End	0.11	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.477289°	37.477289°
				-121.082183°	-121.082183°
DWR ID	DWR_RD1602_01_f_2022_60				
Comment Code					
EQ : Equipment					
Inspector Comment					
Farming equipment should be moved off of the landside slope and toe.					

Photo 1 of 1 : SP_2024_RD1602_110_60_20240308_00024.jpg



Equipment should be moved off of the landside slope and toe. (Fall 2022)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.18	Rating **	A/W	Issue No.	20
LM End	0.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.477575°	37.477575°
				-121.080943°	-121.080943°
DWR ID	DWR_RD1602_01_f_2016_20				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.22	Rating **	M	Issue No.	58
LM End	0.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.477854°	37.477854°
				-121.080361°	-121.080361°
DWR ID	DWR_RD1602_01_f_2022_58				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.40	Rating **	M	Issue No.	73
LM End	0.40	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Vehicle Traffic			37.479172°	37.479172°
				-121.077494°	-121.077494°
DWR ID	DWR_RD1602_01_s_2024_73				
Comment Code					
E6 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_73_20240402_00086.jpg



View of vehicle traffic that has cut ruts into the waterside slope (Spring 2024).

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.47	Rating **	A/W	Issue No.	31
LM End	0.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479659°	37.479659°
				-121.076419°	-121.076419°
DWR ID	DWR_RD1602_01_f_2015_31				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
No rodent holes visible but monitor for future development.					

No Photos

LM Start	0.50	Rating **	M	Issue No.	110
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479899°	37.479899°
				-121.075930°	-121.075930°
DWR ID	DWR_RD1602_01_f_2018_110				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.58	Rating **	U	Issue No.	200
LM End	0.58	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.480182°	37.480182°
				-121.074765°	-121.074765°
DWR ID	20215				
Comment Code					
Inspector Comment					
DS_ID:20215 FS_ID:74549 EP_NO: N/A Repair Type: Urgent EVAL Issue: 1, Pipe Integrity Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Urgent. DMP internal video inspection has found pipe integrity issues. LOF of crossing is between 5 and 6. Crossing will be monitored until funding becomes available to address the issues. No cover on CMP riser causing a safety hazard. (M. Thao - DWR UCIP) 11/18/2016 Crossing has been downgraded from Urgent to No Action Needed a cover has been added to the CMP riser. (O. Magana - DWR UCIP)10/01/2013 Open 60-inch CMP riser on WS needs lid as it's depth may be a hazard to the public. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 16-inch steel drainage pipe through levee, 11.3 feet below crown. Slide gate in 60-inch corrugated metal pipe (CMP) riser located on the waterside (WS). Concrete inlet is approximately 110 feet west of the levee crown or 110 feet off landside (LS) toe next to roadway. [Additional Reference(s): DWR Levee Log, 1992 (HLM 0.58). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 0.58), Station 290+48, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

LM Start	0.58	Rating **	U	Issue No.	200 (cont)
LM End	0.58	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_SP_2024_74549_111308.jpg



WS view: Looking into CMP riser at slide gate.

Photo 2 of 2 : UCIP_SP_2024_74549_111309.jpg



WS view: Looking into CMP riser at deteriorated pipe inlet.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.60	Rating **	M	Issue No.	70
LM End	0.71	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.479967°	37.478514°
				-121.074582°	-121.073435°
DWR ID	DWR_RD1602_01_s_ 2012_70				
Comment Code					
FE : Fence					
Inspector Comment					
Barbed wire fence along the landward toe.					

Photo 1 of 1 : SP_2024_RD1602_110_70_20240308_00032.jpg



View of barbed wire fence at landward toe looking upstream. (Spring 2022)

LM Start	0.61	Rating **	U	Issue No.	29
LM End	0.73	Issue Type +	En	Location *	WS
Category	Rivers, Channels & Designated Floodways			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.479815°	37.478415°
				-121.074479°	-121.073284°
DWR ID	DWR_RD1602_01_f_ 2021_29				
Comment Code					
Inspector Comment					
Material piled within the channel and excavation. Was initially reported by the RD as a BMX course.					

Photo 1 of 1 : SP_2024_RD1602_110_29_20240402_00087.jpg



Haul road constructed by an adjacent landowner and material piled in the channel (Spring 2024).

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.63	Rating **	M	Issue No.	107
LM End	0.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479569 °	37.479569 °
				-121.074299 °	-121.074299 °
DWR ID	DWR_RD1602_01_f _ 2018_107				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.64	Rating **	M	Issue No.	30
LM End	0.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.479391°	37.479391°
				-121.074168°	-121.074168°
DWR ID	DWR_RD1602_01_f_2017_30				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent burrows have collapsed in but need to be backfilled and compacted.					

Photo 1 of 1 : SP_2024_RD1602_110_30_20240402_00088.jpg



View of collapsed rodent holes that need to be backfilled and compacted properly (Spring 2024).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	0.77	Rating **	M	Issue No.	201
LM End	0.77	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.477993°	37.477993°
				-121.072645°	-121.072645°
DWR ID	20216				
Comment Code					
Inspector Comment					
DS_ID:20216 FS_ID:75648 EP_NO: N/A Repair Type: Non-Urgent EVAL Issue: 10, Unauthorized Modification or Non-Compliant Permit Crossing Status: Found UCIP Comments: 04/05/2022 Record updated from No Action Needed to Non-Urgent. A new concrete discharge box was installed on the LS toe since the last inspection; unable to find a permit for modification. (M. Thao - DWR UCIP) 11/18/2016 Crossing has been downgraded from Urgent to No Action Needed the debris blocking the outlet has been cleared. (O. Magana - DWR UCIP)10/01/2013 Flap gate blocked from functioning by soil buildup on WS toe. Soil should be cleared. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 30-inch square reinforced concrete box drainage culvert through levee, 14.4 feet below crown. Concrete "U" headwall on the waterside (WS) and landside (LS) ends. Slide gate in 6-foot by 7-foot concrete surge box is located on the WS shoulder. Flap gate is located on the WS end. [Additional Reference(s): DWR Levee Log, 1992 (HLM 0.78). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 0.78), Station 279+60, listed as 30-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

Photo 1 of 1 : UCIP_SP_2024_75648_111281.jpg



LS view: Looking from crown; new concrete drainage box on toe.

LM Start	1.00	Rating **	C	Issue No.	36
LM End	1.00	Issue Type +	En	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.478810°	37.478810°
				-121.068738°	-121.068738°
DWR ID	DWR_RD1602_01_s_2012_36				
Comment Code					
RA : Ramp					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.00	Rating **	M	Issue No.	202	
LM End	1.00	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			37.478816°	37.478816°	
				-121.068780°	-121.068780°	
DWR ID	20217					
Comment Code						
Inspector Comment						
DS_ID:20217 FS_ID:74539 EP_NO: N/A Repair Type: Non-Urgent EVAL Issue: 4b, Safety Issue Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Non-Urgent. Pump and platform on LS has been removed. The crossing has been capped and exposed on the LS toe. Unable to find a permit for modification. Crossing appears abandoned. Unable to locate a permit and confirm proper pipe abandonment. Recommend owner to contact CVFPB to abandon or remove pipe from levee. Cover missing on CMP riser causing a safety hazard. (M. Thao - DWR UCIP) 11/18/2016 Crossing has been downgraded from Urgent to Non-Urgent a flap gate has been added to the WS but pipe is currently not connected to pump. According to Tony Martinez, LMA representative, this crossing is currently not in use. Owner will need to coordinate with CVFPB to obtain permit. (O. Magana - DWR UCIP)10/01/2013 Appears abandoned and if so should be done so properly. Flapgate missing. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 1 of 2: 16-inch steel drainage pipe through levee, 17 feet below crown. Pipe is capped on the landside (LS) end. Pumps on the pump platform are located on LS. Siphon breaker in 24-inch corrugated metal pipe (CMP) riser is located on the waterside (WS) shoulder. Concrete "U" headwall and flap gate are located on the WS end. [Additional Reference(s): DWR Levee Log, 1992 (HLM 1.01). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 1.01), Station 266+68, listed as 16-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022						

Photo 1 of 2 : UCIP_SP_2024_74539_111263.jpg



LS view: Close-up view of pipe inlet capped.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.00	Rating **	M	Issue No.	202 (cont)
LM End	1.00	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.478816°	37.478816°
				-121.068780°	-121.068780°
DWR ID	20217				

Photo 2 of 2 : UCIP_SP_2024_74539_111264.jpg



WS view: Siphon breaker in CMP riser on shoulder; missing cover on riser. Concrete headwall on toe in background.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.00	Rating **	M	Issue No.	203	
LM End	1.00	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			37.478817°	37.478817°	
				-121.068773°	-121.068773°	
DWR ID	20219					
Comment Code						
Inspector Comment						
DS_ID:20219 FS_ID:74536 EP_NO: N/A Repair Type: Non-Urgent EVAL Issue: 10, Unauthorized Modification or Non-Compliant Permit Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Non-Urgent. Pump and platform on LS has been removed. The crossing has been capped and exposed on the LS toe. Unable to find a permit for modification. Crossing appears abandoned. Unable to locate a permit and confirm proper pipe abandonment. Recommend owner to contact CVFPB to abandon or remove pipe from levee. (M. Thao - DWR UCIP) 11/18/2016 Crossing has been downgraded from Urgent to Non-Urgent a flap gate has been added to the WS. According to Tony Martinez, LMA representative, this crossing is currently not in use. Owner will need to coordinate with CVFPB to obtain permit. (O. Magana - DWR UCIP) 10/01/2013 Appears abandoned siphon breakers covered in soil and flapgate missing. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 2 of 2: 16-inch steel drainage pipe through levee, 17 feet below crown. Pipe is capped on the landside (LS) end. Pumps on the pump platform are located on LS. Siphon breaker in 24-inch riser located on the waterside (WS) shoulder. Concrete "U" headwall and flap gate are located on the WS end. [Additional Reference(s): DWR Levee Log, 1992 (HLM 1.01). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 1.01), Station 266+68, listed as 16-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022						

Photo 1 of 2 : UCIP_SP_2024_74536_111245.jpg



LS view: Looking from crown; general overview.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown N/A: Not Applicable	A: Acceptable M: Minimally Acceptable U: Unacceptable N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.00	Rating **	M	Issue No.	203 (cont)
LM End	1.00	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.478817°	37.478817°
				-121.068773°	-121.068773°
DWR ID	20219				

Photo 2 of 2 : UCIP_SP_2024_74536_111247.jpg



LS view: Close-up view of pipe inlet capped.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.02	Rating **	U	Issue No.	204
LM End	1.02	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.478779°	37.478779°
				-121.068508°	-121.068508°
DWR ID	20218				

Comment Code

Inspector Comment

DS_ID:20218
FS_ID:75649
EP_NO: N/A
Repair Type: Urgent
EVAL Issue: 2b, Levee Integrity
Crossing Status: Found
UCIP Comments: 04/05/2022 Record remains Urgent. WS concrete headwall is still detached with vertical erosion behind the headwall on the WS slope. Was not able to inspect the flap gate due to water on present on WS. Modification was made on the LS to move the grated inlet at the toe landward approximately 100 feet; unable to find a permit for modification. (M. Thao - DWR UCIP)
10/19/2018 Pipe remains the same. WS concrete headwall is still detached with vertical erosion on the WS slope. Dense vegetation along pipe alignment made it difficult to inspect levee slopes and identify any potential issues present at this site. Recommend clearing vegetation along pipe alignment to be able to conduct a proper UCIP inspection. This crossing is part of DWR's Flood System Repair Project (FSRP) and Deferred Maintenance Project (DMP). Crossing will be monitored to identify progress of erosion on the WS slope. Crossing remains Urgent due to the detachment of the concrete wall and vertical cut on the WS. (O. Magana - DWR UCIP)
11/18/2016 Same as previous inspection headwall on the WS toe has seperated from pipe and flap gate is still missing. Erosion around concrete headwall and undermined WS slope are visible from WS. The slope undermined appears to have progressed but no photos were taken due to the dense vegetation covering area. According to Tony Martinez, LMA representative, the WS concrete headwall has been detached since 2008/2009. LMA has been in contact with CVFPB, DWR, and USACE regarding this site. (O. Magana - DWR UCIP)
10/01/2013 Headwall on WS toe seperated from pipe. Erosion around concrete headwall and undermined at WS toe. Flap gate missing from WS toe headwall. (W. Wylie - DWR UCIP)
FIELD_STRUCT_DESC: 30-inch square reinforced concrete box culvert through levee, 25.4 feet below crown. Concrete "U" headwalls on both waterside (WS) and landside (LS) ends. Slide gate in concrete surge box located on the WS slope. A 5-foot by 5-foot concrete box is located on LS toe. Flap gate is located on the WS end. [Additional Reference(s): DWR Levee Log, 1992 (HLM 1.03). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 1.02), Station 266+29, listed as 30-inch pipe, Drawing No. 7-4-1784].
FS Date: 4/5/2022

Photo 1 of 2 : UCIP_SP_2024_75649_111240.jpg



WS view: Looking toward levee; concrete headwall on toe with erosion.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.02	Rating **	U	Issue No.	204 (cont)
LM End	1.02	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.478779°	37.478779°
				-121.068508°	-121.068508°
DWR ID	20218				

Photo 2 of 2 : UCIP_SP_2024_75649_111241.jpg



WS view: Close-up view of detached concrete headwall on toe.

LM Start	1.19	Rating **	C	Issue No.	32
LM End	1.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.478347°	37.478347°
				-121.065361°	-121.065361°
DWR ID	DWR_RD1602_01_f _ 2017_32				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	1.35	Rating **	U	Issue No.	78
LM End	1.43	Issue Type +	En	Location *	WS
Category	Rivers, Channels & Designated Floodways			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.479240°	37.478999°
				-121.062884°	-121.061457°
DWR ID	DWR_RD1602_01_s_2024_78				
Comment Code					
Inspector Comment					
Material piled up within the channel.					

Photo 1 of 1 : SP_2024_RD1602_110_78_20240402_00089.jpg



View of wood chippings within the channel (Spring 2024).

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.47	Rating **	C	Issue No.	38
LM End	1.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.478876°	37.478876°
				-121.060739°	-121.060739°
DWR ID	DWR_RD1602_01_f _ 2023_38				
Comment Code					
V2 : Remove the wild growth and woody vegetation other than native grasses from the levee slopes.					
Inspector Comment					
Corrected.					

No Photos

LM Start	1.51	Rating **	A/W	Issue No.	81
LM End	1.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.478603°	37.474463°
				-121.060242°	-121.057952°
DWR ID	DWR_RD1602_01_s_2024_81				
Comment Code					
T1 : Trim and thin trees to at least five feet above ground level to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Issue has improved but is limiting visibility and access. Additional trimming and removal will be necessary to prevent future growth from becoming an issue.					

No Photos

LM Start	1.61	Rating **	M	Issue No.	43
LM End	2.22	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.477663°	37.470125°
				-121.058716°	-121.055244°
DWR ID	DWR_RD1602_01_s_2012_43				
Comment Code					
FE : Fence					
Inspector Comment					
Fence at the landside toe of the levee.					

Photo 1 of 1 : SP_2024_RD1602_110_43_20240308_00014.jpg



View of the fence on the landside toe of the levee. The picture was taken from crown looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	1.96	Rating **	M	Issue No.	85
LM End	1.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Rills			37.472737°	37.472737°
				-121.057939°	-121.057939°
DWR ID	DWR_RD1602_01_s_2024_85				
Comment Code					
E5 : Schedule repair of rills prior to the next inspection.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_85_20240402_00092.jpg



View of erosion/rills along the landside slope (Spring 2024).

LM Start	2.03	Rating **	M	Issue No.	45
LM End	2.03	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.471734°	37.471734°
				-121.057670°	-121.057670°
DWR ID	DWR_RD1602_01_s_2012_45				
Comment Code					
EQ : Equipment					
Inspector Comment					
A well is present at the toe of the landside slope.					

Photo 1 of 1 : SP_2024_RD1602_110_45_20240308_00016.jpg



A well is located at the landside toe of the levee. The picture was taken from the crown looking toward the landside of the levee.

LM Start	2.07	Rating **	C	Issue No.	93
LM End	2.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.471195°	37.470812°
				-121.057356°	-121.057109°
DWR ID	DWR_RD1602_01_s_2020_93				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	2.23	Rating **	M	Issue No.	41
LM End	2.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.470152°	37.470152°
				-121.055075°	-121.055075°
DWR ID	DWR_RD1602_01_f_2023_41				
Comment Code					
T3 : Fallen tree with root ball.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_41_20240308_00012.jpg



View of downed tree with root ball exposed on waterside slope (Fall 2023).

LM Start	2.29	Rating **	C	Issue No.	79
LM End	2.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.470348°	37.470348°
				-121.053987°	-121.053987°
DWR ID	DWR_RD1602_01_s_2017_79				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	2.82	Rating **	M	Issue No.	89
LM End	2.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.466627°	37.465419°
				-121.046106°	-121.044796°
DWR ID	DWR_RD1602_01_s_2024_89				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair erosion under wavewash protection when plastic is removed.					

No Photos

LM Start	2.85	Rating **	A/W	Issue No.	47
LM End	2.86	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.466294°	37.466166°
				-121.045693°	-121.045527°
DWR ID	DWR_RD1602_01_f _ 2016_47				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	2.89	Rating **	A/W	Issue No.	49
LM End	2.89	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.465898°	37.465898°
				-121.045209°	-121.045209°
DWR ID	DWR_RD1602_01_f_2016_49				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	2.93	Rating **	A/W	Issue No.	61
LM End	3.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.465435°	37.462497°
				-121.044790°	-121.041681°
DWR ID	DWR_RD1602_01_f_2023_61				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Monitor site for additional wave wash damage.					

No Photos

LM Start	2.95	Rating **	C	Issue No.	51
LM End	2.95	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.465190°	37.465190°
				-121.044584°	-121.044584°
DWR ID	DWR_RD1602_01_f _ 2016_51				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	3.20	Rating **	C	Issue No.	59
LM End	3.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.462476°	37.462476°
				-121.041686°	-121.041686°
DWR ID	DWR_RD1602_01_f_2020_59				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.27	Rating **	U	Issue No.	205
LM End	3.27	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.461507°	37.461507°
				-121.041609°	-121.041609°
DWR ID	20204				
Comment Code					
Inspector Comment					
DS_ID:20204 FS_ID:74530 EP_NO: 8193 Repair Type: Urgent EVAL Issue: 1, Pipe Integrity Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Urgent. Pipe inlet within CMP riser is deteriorated. CMP riser cover has broken and fallen into the riser; no cover on the riser causing a safety hazard. Crossing appears abandoned. Recommend owner to contact CVFPB to abandon or remove pipe from levee. (M. Thao - DWR UCIP) 10/19/2018 Pipe is deteriorated on the LS toe (pipe section missing at inlet). This crossing remains Urgent due to the wall deterioration at the inlet. If wall is rusted out at the inlet, need to determine the condition of the pipe section through the levee. According to the LMA representative, this crossing is no longer in use (crossing is abandoned). LMA is interested in abandoning crossing in place. LMA was referred to the CVFPB staff for direction regarding proper action under Title 23 for this crossing. (O. Magana - DWR UCIP) 11/18/2016 Same as previous inspection riser cover and handle on slide gate are still missing. Crossing remains Urgent due to the public safety issue of the 60-inch CMP cover still missing. According to Tony Martinez, LMA representative, the condition and future use of this crossing is being evaluated. Owner will need to coordinate with CVFPB for future use requirements or proper abandonment/removal. (O. Magana - DWR UCIP) 10/01/2013 Appears abandoned, and if so should be done so properly. No handle on slide gate, no cover on CMP standpipe on WS shoulder. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 16-inch steel irrigation pipe through levee, 11.5 feet below crown. Slide gate in 60-inch corrugated metal pipe riser is located on the waterside (WS) slope. Pipe discharges into concrete-lined ditch on the landside (LS) (irrigation pipe was authorized under Automatic Board Order (ABO) issued as Permit No. 8193, 1964 - Sabatte). [Additional Reference(s): DWR Levee Log, 1992 (HLM 3.30). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 3.30), Station 146+62, listed as 16-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

Photo 1 of 3 : UCIP_SP_2024_74530_76528.jpg



Concrete drain channel located on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.27	Rating **	U	Issue No.	205 (cont)
LM End	3.27	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.461507°	37.461507°
				-121.041609°	-121.041609°
DWR ID	20204				

Photo 2 of 3 : UCIP_SP_2024_74530_76529.jpg



View of WS--CMP riser located on WS shoulder and concrete riser approximately 100 feet from levee crown.

LM Start	3.27	Rating **	U	Issue No.	205 (cont)
LM End	3.27	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_SP_2024_74530_76530.jpg



Concrete riser located in the floodway, photo 1 of 2.

LM Start	3.32	Rating **	C	Issue No.	56
LM End	3.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.460811°	37.460811°
				-121.042078°	-121.042078°
DWR ID	DWR_RD1602_01_s_2017_56				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.34	Rating **	M	Issue No.	50
LM End	3.53	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.460644 °	37.458373 °
				-121.042231 °	-121.044081 °
DWR ID	DWR_RD1602_01_s _ 2012_50				
Comment Code					
DT : Ditch					
Inspector Comment					
A ditch is located on the waterside toe of the levee.					

Photo 1 of 1 : SP_2024_RD1602_110_50_20240403_00094.jpg



Looking upstream along the waterside toe (Spring 2024).

LM Start	3.43	Rating **	C	Issue No.	26
LM End	3.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.459653 °	37.459653 °
				-121.043204 °	-121.043204 °
DWR ID	DWR_RD1602_01_s _ 2022_26				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.53	Rating **	M	Issue No.	206
LM End	3.53	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.458300°	37.458300°
				-121.044138°	-121.044138°
DWR ID	20221				
Comment Code					
Inspector Comment					
DS_ID:20221 FS_ID:74520 EP_NO: 8191 Repair Type: Non-Urgent EVAL Issue: 6, Levee Damage or Threat for Levee Damage Crossing Status: Found UCIP Comments: 04/05/2022 Record updated from No Action Needed to Non-Urgent. Minor erosion was present around the downstream sides of the concrete distribution box on the LS toe. (M. Thao - DWR UCIP) FIELD_STRUCT_DESC: 1 of 3: 20-inch steel irrigation pipe through the levee, 3.7 feet below the crown. Pump on pump platform on the waterside (WS) bank. Siphon breaker in a 24-inch riser on the landside (LS) shoulder. Concrete discharge box on the LS end. (two 18-inch and one 20-inch pipes were authorized under Automatic Board Order (ABO) issued as Permit No. 8191, 1972 - Twin Oaks Irrigation District c/o Mr. V. R. Peterson). [Additional Reference(s): DWR Levee Log, 1992 (HLM 3.57). USACE San Joaquin O&M Manual 13, April 1964, (HLM 3.57), Station 132+32, listed as 20-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

LM Start	3.53	Rating **	M	Issue No.	206 (cont)
LM End	3.53	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2024_74520_111227.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

Photo 2 of 2 : UCIP_SP_2024_74520_111228.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.53	Rating **	M	Issue No.	207
LM End	3.53	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.458292°	37.458292°
				-121.044149°	-121.044149°
DWR ID	20220				
Comment Code					
Inspector Comment					
DS_ID:20220 FS_ID:74519 EP_NO: 8191 Repair Type: Non-Urgent EVAL Issue: 6, Levee Damage or Threat for Levee Damage Crossing Status: Found UCIP Comments: 04/05/2022 Record updated from No Action Needed to Non-Urgent. Minor erosion was present around the downstream sides of the concrete distribution box on the LS toe. (M. Thao - DWR UCIP) FIELD_STRUCT_DESC: 2 of 3: 18-inch steel irrigation pipe through the levee, 3.7 feet below the crown. Pump on pump platform on the waterside (WS) bank. Siphon breaker in a 24-inch riser on the landside (LS) shoulder. Concrete discharge box on the LS end. (Two 18-inch and one 20-inch pipes were authorized under Automatic Board Order (ABO) issued as Permit No. 8191, 1972 - Twin Oaks Irrigation District c/o Mr. V. R. Peterson). [Additional Reference(s): DWR Levee Log, 1992 (HLM 3.57). USACE San Joaquin O&M Manual 13, April 1964, (HLM 3.57), Station 132+32, listed as 18-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

LM Start	3.53	Rating **	M	Issue No.	207 (cont)
LM End	3.53	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2024_74519_111221.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

Photo 2 of 2 : UCIP_SP_2024_74519_111222.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.54	Rating **	M	Issue No.	208
LM End	3.54	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.458283 °	37.458283 °
				-121.044146 °	-121.044146 °
DWR ID	20205				
Comment Code					
Inspector Comment					
DS_ID:20205 FS_ID:74503 EP_NO: 8191 Repair Type: Non-Urgent EVAL Issue: 6, Levee Damage or Threat for Levee Damage Crossing Status: Found UCIP Comments: 04/05/2022 Record updated from No Action Needed to Non-Urgent. Siphon breaker in CMP riser is broken; recommend repairing the siphon breaker. Minor erosion was present around the downstream sides of the concrete distribution box on the LS toe. (M. Thao - DWR UCIP) FIELD_STRUCT_DESC: 3 of 3: 18-inch steel irrigation pipe through the levee, 3.7 feet below the crown. Pump on pump platform on the waterside (WS) bank. Siphon breaker in a 24-inch riser on the landside (LS) shoulder. Concrete discharge box on the LS end. (two 18-inch and one 20-inch pipes were authorized under Automatic Board Order (ABO) issued as Permit No. 8191, 1972 - Twin Oaks Irrigation District c/o Mr. V. R. Peterson). [Additional Reference(s): DWR Levee Log, 1992 (HLM 3.57). USACE San Joaquin O&M Manual 13, April 1964, (HLM 3.57), Station 132+32, listed as 18-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

LM Start	3.54	Rating **	M	Issue No.	208 (cont)
LM End	3.54	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2024_74503_111215.jpg



LS view: Close-up view of broken siphon breaker.

Photo 2 of 3 : UCIP_SP_2024_74503_111216.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.54	Rating **	M	Issue No.	208 (cont)
LM End	3.54	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.458283°	37.458283°
				-121.044146°	-121.044146°
DWR ID	20205				

Photo 3 of 3 : UCIP_SP_2024_74503_111217.jpg



LS view: Concrete discharge box on toe; erosion around downstream sides.

LM Start	3.76	Rating **	A/W	Issue No.	83
LM End	3.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.455414°	37.455414°
				-121.043765°	-121.043765°
DWR ID	DWR_RD1602_01_s_2017_83				
Comment Code					
T2 : Tree or limb.					
Inspector Comment					
Fallen tree has been moved from the levee slope and into the floodway. Tree should be removed from the floodway.					

Photo 1 of 1 : SP_2024_RD1602_110_83_20240308_00037.jpg



View of a tree trunk on the waterside slope of the levee.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.82	Rating **	M	Issue No.	66
LM End	3.92	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.454611°	37.453309°
				-121.043193°	-121.042191°
DWR ID	DWR_RD1602_01_f _ 2013_66				
Comment Code					
FE : Fence					
Inspector Comment					
Fence, animal pen and other encroachments at landward toe.					

Photo 1 of 1 : SP_2024_RD1602_110_66_20240403_00095.jpg



Looking southwest at fence and other encroachments on landward toe (Spring 2024).

LM Start	3.82	Rating **	C	Issue No.	42
LM End	3.82	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.454574°	37.454574°
				-121.043142°	-121.043142°
DWR ID	DWR_RD1602_01_s_2012_42				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Corrected.					

No Photos

LM Start	3.90	Rating **	A/W	Issue No.	18
LM End	3.90	Issue Type +	Ob	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Seepage / Sandboils			37.453620°	37.453620°
				-121.042410°	-121.042410°
DWR ID	190-FOC-1				
Comment Code					
SS : Seepage / Sandboils					
Inspector Comment					
2017 Storm Damage					
Site ID No:118					
Site Designation:190-FOC-1					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.90	Rating **	C	Issue No.	84
LM End	3.90	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.453566°	37.453566°
				-121.042376°	-121.042376°
DWR ID	DWR_RD1602_01_s_2017_84				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	3.93	Rating **	C	Issue No.	64
LM End	3.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Rills			37.453304°	37.453304°
				-121.042175°	-121.042175°
DWR ID	DWR_RD1602_01_f_2023_64				
Comment Code					
E5 : Schedule repair of rills prior to the next inspection.					
Inspector Comment					
Corrected.					

No Photos

LM Start	3.93	Rating **	M	Issue No.	63
LM End	4.04	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.453226°	37.451866°
				-121.042118°	-121.041206°
DWR ID	DWR_RD1602_01_s_2012_63				
Comment Code					
FE : Fence					
Inspector Comment					
Fence on landward slope.					

Photo 1 of 1 : SP_2024_RD1602_110_63_20240403_00097.jpg



View of fence along the landside slope and shoulder (Spring 2024).

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	3.93	Rating **	M	Issue No.	62
LM End	3.93	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Foot Traffic			37.453216°	37.453216°
				-121.042127°	-121.042127°
DWR ID	DWR_RD1602_01_s_2012_62				
Comment Code					
E3 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Damage to USACE constructed seepage berm due to human activity.					

Photo 1 of 1 : SP_2024_RD1602_110_62_20240403_00098.jpg



View of damage to USACE seepage berm that appears to be caused by foot traffic (Spring 2024).

LM Start	4.03	Rating **	A/W	Issue No.	21
LM End	4.03	Issue Type +	Ob	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Seepage / Sandboils			37.451990°	37.451990°
				-121.041240°	-121.041240°
DWR ID	190-FOC-2				
Comment Code					
SS : Seepage / Sandboils					
Inspector Comment					
2017 Storm Damage					
Site ID No:119					
Site Designation:190-FOC-2					

No Photos

LM Start	4.04	Rating **	C	Issue No.	74
LM End	4.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.451892°	37.448492°
				-121.041168°	-121.038303°
DWR ID	DWR_RD1602_01_s_2019_74				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	4.13	Rating **	A/W	Issue No.	23
LM End	4.45	Issue Type +	Ob	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Seepage / Sandboils			37.450930°	37.446820°
				-121.039990°	-121.037840°
DWR ID	DWR_RD1602_01_f_2023_23				
Comment Code					
SS : Seepage / Sandboils					
Inspector Comment					
2017 Storm Damage					
Site ID No:120					
Site Designation:190-101					

No Photos

LM Start	4.14	Rating **	C	Issue No.	65
LM End	4.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.450768°	37.450768°
				-121.039865°	-121.039865°
DWR ID	DWR_RD1602_01_f _ 2023_65				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Corrected.					

No Photos

LM Start	4.38	Rating **	C	Issue No.	71
LM End	4.44	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.447761°	37.446872°
				-121.037845°	-121.037822°
DWR ID	DWR_RD1602_01_s_2019_71				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	4.39	Rating **	M	Issue No.	90
LM End	4.51	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.447554°	37.446009°
				-121.037728°	-121.037831°
DWR ID	DWR_RD1602_01_s_2024_90				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair wave wash erosion under the placed plastic.					

No Photos

LM Start	4.42	Rating **	M	Issue No.	67
LM End	4.88	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.447213°	37.441014°
				-121.037665°	-121.036932°
DWR ID	DWR_RD1602_01_s_2012_67				
Comment Code					
FE : Fence					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_67_20240308_00029.jpg



View of the fence on the landside toe of the levee. The picture was taken from the crown looking upstream.

LM Start	4.42	Rating **	M	Issue No.	94
LM End	4.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Rills			37.447195°	37.447195°
				-121.037694°	-121.037694°
DWR ID	DWR_RD1602_01_s_2024_94				
Comment Code					
E5 : Schedule repair of rills prior to the next inspection.					
Inspector Comment					
Rills have formed on the landside slope and are beginning to encroach into the levee crown.					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	4.47	Rating **	U	Issue No.	209	
LM End	4.47	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			37.446545°	37.446545°	
				-121.037941°	-121.037941°	
DWR ID	20207					
Comment Code						
Inspector Comment						
DS_ID:20207 FS_ID:74531 EP_NO: 8195 Repair Type: Urgent EVAL Issue: 1, Pipe Integrity Crossing Status: Found UCIP Comments: 04/05/2022 Record updated from Non-Urgent to Urgent. Pipe inlet and outlet within CMP riser is deteriorated. Broken wood pallet was used as a cover causing a safety hazard. No handle on slide gate in CMP riser on WS slope. Alfalfa valve was not capped in concrete distribution box on LS toe. (M. Thao - DWR UCIP) 11/18/2016 60-inch riser has a temporary cover therefore crossing has been downgraded from Urgent to Non-Urgent. (O. Magana - DWR UCIP) 10/01/2013 Lid missing from 60-inch CMP riser, may be an attractive nuisance or hazard to public. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 18-inch steel irrigation pipe through levee, 10 feet below crown. Slide gate in 60-inch corrugated metal pipe riser located on the waterside (WS) slope. Concrete discharge box is located on landside (LS) end. Pipe is buried across WS berm to pump located on the riverbank approximately 1,000 feet from the levee. (18-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 8195, 1972 - Larry Buehner). [Additional Reference(s): DWR Levee Log, 1992 (HLM 4.51). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 4.51), Station 81+60, listed as 18-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022						

LM Start	4.47	Rating **	U	Issue No.	209 (cont)
LM End	4.47	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2024_74531_111172.jpg



LS view: Pipe outlet on toe within concrete ditch.

Photo 2 of 2 : UCIP_SP_2024_74531_111174.jpg



WS view: Looking into CMP riser; inlet of pipe through levee is deteriorating.

* Location LS: Land Side N/A: Not Applicable WS: Water Side CR: Crown		** Rating A: Acceptable N: Not Inspected/Rated M: Minimally Acceptable C: Corrected U: Unacceptable A/W: Acceptable but Monitor & Maintain		+ Issue Type Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement	
--	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	4.55	Rating **	C	Issue No.	91
LM End	4.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.445402°	37.445402°
				-121.037706°	-121.037706°
DWR ID	DWR_RD1602_01_s _ 2017_91				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	4.55	Rating **	C	Issue No.	55
LM End	4.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.445400°	37.445400°
				-121.037728°	-121.037728°
DWR ID	DWR_RD1602_01_f_2020_55				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	4.59	Rating **	C	Issue No.	54
LM End	4.59	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.444758°	37.444758°
				-121.037703°	-121.037703°
DWR ID	DWR_RD1602_01_f_2022_54				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	4.76	Rating **	C	Issue No.	46
LM End	4.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.442490°	37.441905°
				-121.037005°	-121.036591°
DWR ID	DWR_RD1602_01_f_2020_46				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	4.82	Rating **	A/W	Issue No.	68
LM End	4.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.441726°	37.441726°
				-121.036538°	-121.036538°
DWR ID	DWR_RD1602_01_f_2023_68				
Comment Code					
T3 : Fallen tree with root ball.					
Inspector Comment					
Trees are no longer within the levee easement but need to be removed from the floodway.					

No Photos

LM Start	4.86	Rating **	C	Issue No.	19
LM End	4.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.441235°	37.441235°
				-121.036792°	-121.036792°
DWR ID	DWR_RD1602_01_f_2021_19				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.00	Rating **	U	Issue No.	44
LM End	5.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.439404°	37.439404°
				-121.037470°	-121.037470°
DWR ID	DWR_RD1602_01_f_2020_44				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes have collapsed in on themselves and should be backfilled and compacted properly.					

Photo 1 of 1 : SP_2024_RD1602_110_44_20240308_00015.jpg



Several rodent holes noted at this location. (Fall 2020)

LM Start	5.00	Rating **	U	Issue No.	95
LM End	5.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.439326°	37.439326°
				-121.037455°	-121.037455°
DWR ID	DWR_RD1602_01_s_2024_95				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes appear to have collapsed in on themselves but need to be backfill and compact rodent holes.					

Photo 1 of 1 : SP_2024_RD1602_110_95_20240403_00100.jpg



View of rodent holes along the waterside slope (Spring 2024).

LM Start	5.02	Rating **	U	Issue No.	53
LM End	5.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.439036°	37.439036°
				-121.037350°	-121.037350°
DWR ID	DWR_RD1602_01_f_2022_53				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_53_20240308_00021.jpg



Several large animal burrows were observed at this location. (Fall 2022)

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.03	Rating **	M	Issue No.	33
LM End	5.03	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.438936°	37.438936°
				-121.037291°	-121.037291°
DWR ID	DWR_RD1602_01_s_2024_33				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion pocket near the waterside toe.					

Photo 1 of 1 : SP_2024_RD1602_110_33_20240503_00105.jpg



View of erosion pocket on the waterside slope near the toe (Spring 2024).

LM Start	5.07	Rating **	U	Issue No.	25
LM End	5.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.438335°	37.437817°
				-121.037133°	-121.037029°
DWR ID	DWR_RD1602_01_s_2022_25				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_25_20240308_00004.jpg



View of rodent burrows in the landside slope. (Spring 2022)

LM Start	5.09	Rating **	C	Issue No.	199
LM End	5.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.438165°	37.438165°
				-121.037073°	-121.037073°
DWR ID	DWR_RD1602_01_s_2014_199				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.13	Rating **	C	Issue No.	92
LM End	5.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.437527°	37.437527°
				-121.036967°	-121.036967°
DWR ID	DWR_RD1602_01_s _ 2017_92				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	5.16	Rating **	C	Issue No.	141
LM End	5.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.437146°	37.437146°
				-121.036814°	-121.036814°
DWR ID	DWR_RD1602_01_s _ 2020_141				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Corrected.					

No Photos

LM Start	5.18	Rating **	U	Issue No.	48
LM End	5.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436785°	37.436785°
				-121.036593°	-121.036593°
DWR ID	DWR_RD1602_01_s _ 2016_48				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_48_20240403_00101.jpg



View of animal burrows along the waterside slope near the gate (Spring 2024).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.19	Rating **	U	Issue No.	210
LM End	5.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436748°	37.436748°
				-121.036597°	-121.036597°
DWR ID	20208				
Comment Code					
Inspector Comment					
DS_ID:20208 FS_ID:74358 EP_NO: N/A Repair Type: Urgent EVAL Issue: 1, Pipe Integrity Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Urgent. DMP internal video inspection has found pipe integrity issues. LOF of crossing is between 5 and 6. Crossing will be monitored until funding becomes available to address the issues. No cover present on CMP riser causing a safety hazard. Vegetation is growing and partially blocking the inlet on LS; recommend removing vegetation. No cover was present on CMP riser causing a safety hazard. Soil and debris, previously mentioned, have been cleared so flap gate and slide gate was operational. (M. Thao - DWR UCIP) 11/18/2016 Same as previous inspection soil and debris prevent flap gate from properly functioning and slide gate won't close due to sediment build up. Crossing has been downgraded from Urgent to Non-Urgent due to no pipe or levee integrity issues observed during the site visit. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to coordinate with CVFPB to properly abandon or remove according to Title 23 requirements. (O. Magana - DWR UCIP)10/01/2013 Soil and debris prevent flapgate from proper function. Slide gate won't close completely due to sediment buildup. CMP riser needs cover. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch steel drainage pipe through levee, 11.6 feet below crown. Concrete headwall on the landside (LS) end. Concrete "U" headwall and flap gate located on the waterside (WS) end. Slide gate in a 60-inch corrugated metal pipe (CMP) riser is located on the WS slope. [Additional Reference(s): DWR Levee Log, 1992 (HLM 5.23). USACE San Joaquin River O&M Manual Unit 13, April 1964, (HLM 5.23), Station 43+40, listed as 24-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

Photo 1 of 2 : UCIP_SP_2024_74358_111160.jpg



WS view: Looking from crown; CMP riser with no cover on slope.

* Location LS: Land Side N/A: Not Applicable WS: Water Side CR: Crown	** Rating A: Acceptable M: Minimally Acceptable U: Unacceptable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	+ Issue Type Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
--	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.19	Rating **	U	Issue No.	210 (cont)
LM End	5.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436748 °	37.436748 °
				-121.036597 °	-121.036597 °
DWR ID	20208				

Photo 2 of 2 : UCIP_SP_2024_74358_111161.jpg



WS view: Looking into CMP riser.

LM Start	5.21	Rating **	M	Issue No.	27
LM End	5.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436470°	37.436470°
				-121.036356°	-121.036356°
DWR ID	DWR_RD1602_01_s_2021_27				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_27_20240403_00102.jpg



View of animal burrow along the landside slope (Spring 2024).

LM Start	5.22	Rating **	U	Issue No.	52
LM End	5.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436393°	37.436393°
				-121.036296°	-121.036296°
DWR ID	DWR_RD1602_01_s_2018_52				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Large animal burrow on the waterward slope.					

Photo 1 of 1 : SP_2024_RD1602_110_52_20240403_00103.jpg



View of animal burrow on the waterside slope (Spring 2024).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.22	Rating **	C	Issue No.	72
LM End	5.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.436365 °	37.436365 °
				-121.036262 °	-121.036262 °
DWR ID	DWR_RD1602_01_f _ 2023_72				
Comment Code					
T2 : Tree or limb.					
Inspector Comment					
Corrected.					

No Photos

LM Start	5.23	Rating **	A	Issue No.	211	
LM End	5.23	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			37.436246°	37.436246°	
				-121.036193°	-121.036193°	
DWR ID	20209					
Comment Code						
Inspector Comment						
DS_ID:20209						
FS_ID:77639						
EP_NO: 8192						
Repair Type: No Action Needed						
EVAL Issue:						
Crossing Status: Found						
UCIP Comments: 04/05/2022 Record remains No Action Needed. No						
issues observed during inspection. (M. Thao - DWR UCIP)						
FIELD_STRUCT_DESC: 1 of 2: 36-inch by 36-inch reinforced concrete						
box drainage culvert through the levee, 15.8 feet below the crown. Slide						
gate in a 6-foot by 7-foot concrete surge box on the waterside (WS)						
slope. 36-inch concrete pipes buried on both sides of the levee and						
connected to the reinforced concrete box culvert. Constructed through						
the levee section. (two 36-inch by 36-inch culvert [HLM 5.27] authorized						
under Automatic Board Order (ABO) issued as Permit No. 8192, 1972 -						
Stanislaus County). [Additional Reference(s): DWR Levee Log, 1992						
(HLM 5.27). USACE San Joaquin O&M Manual 13, April 1964, (HLM						
5.27), Station 39+25, Drawing No. 7-4-1784].						
FS Date: 4/5/2022						

Photo 1 of 3 : UCIP_SP_2024_77639_111146.jpg



Levee crown looking downstream.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.23	Rating **	A	Issue No.	211 (cont)
LM End	5.23	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436246°	37.436246°
				-121.036193°	-121.036193°
DWR ID	20209				

Photo 2 of 3 : UCIP_SP_2024_77639_111141.jpg



LS view: Looking from crown; general overview.

LM Start	5.23	Rating **	A	Issue No.	211 (cont)
LM End	5.23	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2024_77639_111145.jpg



LS view: Likely risers for pipe off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.23	Rating **	A	Issue No.	212	
LM End	5.23	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.436227°		37.436227°
				-121.036169°		-121.036169°
DWR ID	20222					
Comment Code						
Inspector Comment						
DS_ID:20222 FS_ID:77640 EP_NO: 8192 Repair Type: No Action Needed EVAL Issue: Crossing Status: Found UCIP Comments: 04/05/2022 Record remains No Action Needed. No issues observed during inspection. (M. Thao - DWR UCIP) FIELD_STRUCT_DESC: 2 of 2: 36-inch by 36-inch reinforced concrete box drainage culvert through the levee, 15.8 feet below the crown. Slide gate in a 6-foot by 7-foot concrete surge box on the waterside (WS) slope. 36-inch concrete pipes buried on both sides of the levee and connected to the reinforced concrete box culvert. Constructed through the levee section. (two 36-inch by 36-inch culvert [HLM 5.27] authorized under Automatic Board Order (ABO) issued as Permit No. 8192, 1972 - Stanislaus County). [Additional Reference(s): DWR Levee Log, 1992 (HLM 5.27). USACE San Joaquin O&M Manual 13, April 1964, (HLM 5.27), Station 39+05, Drawing No. 7-4-1784]. FS Date: 4/5/2022						

LM Start	5.23	Rating **	A	Issue No.	212 (cont)
LM End	5.23	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2024_77640_111150.jpg



Levee crown looking downstream.

Photo 2 of 3 : UCIP_SP_2024_77640_111147.jpg



LS view: Looking from crown; general overview.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.23	Rating **	A	Issue No.	212 (cont)
LM End	5.23	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436227°	37.436227°
				-121.036169°	-121.036169°
DWR ID	20222				

Photo 3 of 3 : UCIP_SP_2024_77640_111149.jpg




LS view: Likely risers for pipe off LS toe.

LM Start	5.24	Rating **	A	Issue No.	213
LM End	5.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436129°	37.436129°
				-121.036065°	-121.036065°
DWR ID	20210				

Comment Code**Inspector Comment**

DS_ID:20210
FS_ID:81195
EP_NO: N/A
Repair Type: No Action Needed
EVAL Issue:
Crossing Status: Found
UCIP Comments: 04/05/2022 Record remains No Action Needed. DWR DMP internal video inspection has not found pipe integrity issues. LOF of crossing is less or equal to 4.0. Recommend next video inspection in 5 years. No issues observed during inspection. (M. Thao - DWR UCIP)
FIELD_STRUCT_DESC: 30-inch by 30-inch reinforced concrete box drainage culvert through the levee, 12.9 feet below the crown. Slide gate in a concrete surge box on the waterside (WS) slope. Concrete discharge boxes on both ends. [Additional Reference(s): DWR Levee Log, 1992 (HLM 5.28). USACE San Joaquin O&M Manual 13, April 1964, (HLM 5.28), Station 38+58, Drawing No. 7-4-1784].
FS Date: 4/5/2022

Photo 1 of 3 : UCIP_SP_2024_81195_111126.jpg



Levee crown looking downstream.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.24	Rating **	A	Issue No.	213 (cont)
LM End	5.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.436129°	37.436129°
				-121.036065°	-121.036065°
DWR ID	20210				

Photo 2 of 3 : UCIP_SP_2024_81195_111127.jpg



LS view: Looking from levee crown; general overview.

LM Start	5.24	Rating **	A	Issue No.	213 (cont)
LM End	5.24	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2024_81195_111128.jpg



LS view: Concrete inlet on toe.

LM Start	5.38	Rating **	M	Issue No.	22
LM End	5.44	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.434447°	37.433791°
				-121.034865°	-121.034000°
DWR ID	DWR_RD1602_01_f_2012_22				
Comment Code					
FE : Fence					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_22_20240308_00002.jpg



A fence was found on the landside toe of the levee looking upstream.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.43	Rating **	M	Issue No.	75
LM End	5.43	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.433975°	37.433975°
				-121.034212°	-121.034212°
DWR ID	DWR_RD1602_01_f_2023_75				
Comment Code					
T3 : Fallen tree with root ball.					
Inspector Comment					
Issue has improved, however, fallen tree and root ball still pose a likely threat to the integrity of the levee. Visibility is also limited with remaining tree limbs on the levee slope.					

Photo 1 of 1 : SP_2024_RD1602_110_75_20240308_00034.jpg



View of fallen tree on waterside slope (Fall 2023).

LM Start	5.46	Rating **	M	Issue No.	214
LM End	5.46	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.433646°	37.433646°
				-121.033846°	-121.033846°
DWR ID	20211				
Comment Code					
Inspector Comment					
DS_ID:20211 FS_ID:75650 EP_NO: N/A Repair Type: Non-Urgent EVAL Issue: Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Non-Urgent. Crossing appears abandoned. Recommend owner to contact CVFPB to abandon or remove pipe from levee. DWR DMP internal video inspection has not found pipe integrity issues. LOF of crossing is less or equal to 4.0. Recommend next video inspection in 5 years. (M. Thao - DWR UCIP) 10/01/2013 Pipe appears abandoned and if so should be done so properly. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 12-inch CMP drainage pipe through the levee, 6.9 feet below the crown. Flap gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 1992 (HLM 5.50). USACE San Joaquin O&M Manual 13, April 1964, (HLM 5.50), listed as 12-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

Photo 1 of 3 : UCIP_SP_2024_75650_111112.jpg



Levee crown looking downstream.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.46	Rating **	M	Issue No.	214 (cont)
LM End	5.46	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.433646 °	37.433646 °
				-121.033846 °	-121.033846 °
DWR ID	20211				

Photo 2 of 3 : UCIP_SP_2024_75650_111113.jpg



LS view: Looking from crown; general overview.

LM Start	5.46	Rating **	M	Issue No.	214 (cont)
LM End	5.46	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2024_75650_111114.jpg



WS view: Looking from crown; 12-inch CMP outlet with flap gate on toe.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.72	Rating **	M	Issue No.	215	
LM End	5.72	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.433003°		37.433003°
				-121.029346°		-121.029346°
DWR ID	20212					
Comment Code						
Inspector Comment						
DS_ID:20212						
FS_ID:81197						
EP_NO: N/A						
Repair Type: Non-Urgent						
EVAL Issue: 5, Pipe Damage						
Crossing Status: Found						
UCIP Comments: 04/05/2022 Record remains Non-Urgent. DMP						
internal video inspection has found pipe integrity issues. LOF of						
crossing is greater than or equal to 4.1 and less than 5. Crossing will be						
monitored until funding becomes available for rehabilitation. (M. Thao -						
DWR UCIP)						
11/18/2016 Crossing has been downgraded from Urgent to Non-Urgent						
flap gate is functional. Recommend clearing dense vegetation from WS						
and LS slopes. (O. Magana - DWR UCIP)10/01/2013 Flapgate has						
minor blockage preventing gate from fully closing. (W. Wylie - DWR						
UCIP)						
FIELD_STRUCT_DESC: 30-inch square reinforced concrete drainage						
box culvert through levee, 9 feet below crown. Slide gate in concrete						
riser located on the waterside (WS) slope. Concrete "U" headwalls are						
located on both the waterside (WS) and landside (LS) ends. Flap gate						
is located on the WS end. [Additional Reference(s): DWR Levee Log,						
1992 (HLM 5.76). USACE San Joaquin River O&M Manual Unit 13,						
April 1964, (HLM 5.28), Drawing No. 7-4-1784].						
FS Date: 4/5/2022						

LM Start	5.72	Rating **	M	Issue No.	215 (cont)
LM End	5.72	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_SP_2024_81197_111109.jpg



LS view: Close-up view of concrete headwall on toe.

Photo 2 of 2 : UCIP_SP_2024_81197_111111.jpg



WS view: Concrete headwall and flap gate; surge box in the background.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	5.90	Rating **	M	Issue No.	98
LM End	6.23	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.432770°	37.429128°
				-121.026086°	-121.029741°
DWR ID	DWR_RD1602_01_s_2024_98				
Comment Code					
DT : Ditch					
Inspector Comment					
Landowner has cut a ditch into the landward toe.					

Photo 1 of 1 : SP_2024_RD1602_110_98_20240403_00104.jpg



View of ditch along the landward toe (Spring 2024).

LM Start	5.92	Rating **	C	Issue No.	76
LM End	5.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Vehicle Traffic			37.432625°	37.432625°
				-121.026187°	-121.026187°
DWR ID	DWR_RD1602_01_f _ 2023_76				
Comment Code					
E6 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Corrected.					

No Photos

LM Start	6.01	Rating **	M	Issue No.	96
LM End	6.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Vehicle Traffic			37.431567°	37.431567°
				-121.027289°	-121.027289°
DWR ID	DWR_RD1602_01_s_2024_96				
Comment Code					
E6 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Vehicle ruts have cut into the waterside slope.					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2024

Reclamation District No. 1602 Del Puerto

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	6.13	Rating **	U	Issue No.	86
LM End	6.13	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.430181°	37.430181°
				-121.028679°	-121.028679°
DWR ID	DWR_RD1602_01_s_2020_86				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Cactus blocking view of waterward slope.					

Photo 1 of 1 : SP_2024_RD1602_110_86_20240308_00039.jpg



Looking at dense cactus growth on the waterside slope (Fall 2023).

LM Start	6.22	Rating **	M	Issue No.	24
LM End	6.22	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.429145°	37.429145°
				-121.029714°	-121.029714°
DWR ID	DWR_RD1602_01_f_2020_24				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

Photo 1 of 1 : SP_2024_RD1602_110_24_20240308_00003.jpg



Depression in levee crown from vehicle traffic. (Spring 2022)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2024****Reclamation District No. 1602 Del Puerto**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	6.24	03/27/2024 03/27/2024	Nate Hicks

LM Start	6.24	Rating **	U	Issue No.	216
LM End	6.24	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.429032°	37.429032°
				-121.029867°	-121.029867°
DWR ID	20214				
Comment Code					
Inspector Comment					
DS_ID:20214 FS_ID:77638 EP_NO: 8194 Repair Type: Urgent EVAL Issue: 1, Pipe Integrity Crossing Status: Found UCIP Comments: 04/05/2022 Record remains Urgent. DMP internal video inspection has found pipe integrity issues. LOF of crossing is between 5 and 6. Crossing will be monitored until funding becomes available to address the issues. (M. Thao - DWR UCIP) 10/01/2013 Pipe heavily deteriorated on LS toe. May indicate condition of rest of pipe is bad. Good candidate for video inspection. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 18-inch reinforced concrete irrigation pipe through the levee, 3 feet below the crown. Slide gate in a 36-inch concrete standpipe on the waterside (WS) shoulder. (18-inch concrete pipe was authorized under Automatic Board Order (ABO) issued as Permit No. 8194, 1972 - Ernest F. Nunes). [Additional Reference(s): DWR Levee Log, 1992 (HLM 6.28). USACE San Joaquin O&M Manual 13, April 1964, (HLM 6.28), Station 0+50A, listed as 18-inch pipe, Drawing No. 7-4-1784]. FS Date: 4/5/2022					

LM Start	6.24	Rating **	U	Issue No.	216 (cont)
LM End	6.24	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2024_77638_111103.jpg



LS view: Outlet of irrigation pipe is deteriorated.

Photo 2 of 2 : UCIP_SP_2024_77638_111106.jpg



LS view: View of inside of pipe outlet.

* Location	** Rating	+ Issue Type
LS: Land Side WS: Water Side CR: Crown	A: Acceptable M: Minimally Acceptable U: Unacceptable	Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
N/A: Not Applicable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	