

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/19/2018 04/19/2018	Sterling York

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD2035_01_s_2013_3				
Comment Code					
Inspector Comment					
The LMA stated that they keep a copy of the O&M manuals on hand at the district office.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD2035_01_s_2013_4				
Comment Code					
Inspector Comment					
The district has emergency supplies and equipment on hand at their district office.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/19/2018 04/19/2018	Sterling York

LM Start	0.00	Rating **	M	Issue No.	5		
LM End	0.00	Issue Type +	Ma	Location *	CR		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD2035_01_s_2013_5						
Comment Code							
Inspector Comment							
The LMA plans on attending DWR Flood Fight training class this fall.							

No Photos

LM Start	0.02	Rating **	M	Issue No.	9
LM End	2.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677368 °	38.677186 °
				-121.709565 °	-121.672912 °
DWR ID	DWR_RD2035_01_s_2018_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_238_9_20180430_00013.jpg



View looking downstream landside of the annual vegetation that needs to be maintained, Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/19/2018 04/19/2018	Sterling York

LM Start	0.02	Rating **	M	Issue No.	10
LM End	2.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677368 °	38.677186 °
				-121.709565 °	-121.672912 °
DWR ID	DWR_RD2035_01_s_2018_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_238_10_20180430_00014.jpg



View looking downstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

LM Start	0.02	Rating **	A/W	Issue No.	12
LM End	0.02	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.677377 °	38.677377 °
				-121.709487 °	-121.709487 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:10827 DS_ID:17814 EP_NO: 10127 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 42-inch concrete encased corrugated metal drainage pipe through the levee, 10 feet below the crown. Flap gate on the waterside (WS) end. Grouted spillway on the WS. Pipe exposed on the landside (LS). (36-inch pipe [HLM 0.02] authorized under Automatic Board Order (ABO) issued as Permit No. 10127, 1974 - City of Woodland, Department of Public Works). [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 126, November 1961, (HLM 0.01), listed as 5.5 feet below the crown]. FS Date: 4/2/2013					

Photo 1 of 3 : UCIP_SP_2018_10827_18109.jpg



Flap gate and spillway on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/19/2018 04/19/2018	Sterling York

LM Start	0.02	Rating **	A/W	Issue No.	12 (cont)
LM End	0.02	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.677377 °	38.677377 °
				-121.709487 °	-121.709487 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:10827
DS_ID:17814
EP_NO: 10127
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments:
FIELD_STRUCT_DESC: 42-inch concrete encased corrugated metal drainage pipe through the levee, 10 feet below the crown. Flap gate on the waterside (WS) end. Grouted spillway on the WS. Pipe exposed on the landside (LS). (36-inch pipe [HLM 0.02] authorized under Automatic Board Order (ABO) issued as Permit No. 10127, 1974 - City of Woodland, Department of Public Works). [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 126, November 1961, (HLM 0.01), listed as 5.5 feet below the crown].
FS Date: 4/2/2013

LM Start	0.02	Rating **	A/W	Issue No.	12 (cont)
LM End	0.02	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_10827_18108.jpg



Flap gate and spillway on WS toe.

Photo 3 of 3 : UCIP_SP_2018_10827_18107.jpg



Concrete encased pipe on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	0.02	Rating **	A	Issue No.	20
LM End	3.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.676898 °	38.630112 °
				-121.672717 °	-121.654087 °
DWR ID	DWR_RD2035_02_s_2018_20				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD2035_239_20_20180430_00059.jpg



View looking downstream waterside of the annual vegetation that is maintained, Spring 2018.

LM Start	0.02	Rating **	A	Issue No.	21
LM End	3.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.676897 °	38.630112 °
				-121.672717 °	-121.654087 °
DWR ID	DWR_RD2035_02_s_2018_21				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD2035_239_21_20180430_00058.jpg



View looking downstream landside of the annual vegetation that is maintained, Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	0.28	Rating **	A/W	Issue No.	1
LM End	0.36	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.673229 °	38.672069 °
				-121.671732 °	-121.671516 °
DWR ID	DWR_RD2035_02_s_2016_1				
Comment Code					
Inspector Comment					
2006 - Wave wash erosion and some saturation slumping occurring. Tension/separation cracks evident in fine grained levee slope materials. 2011 - Slumping of the lower toe. New slumped section on downstream end. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_0-1_R]					

No Photos

LM Start	0.38	Rating **	U	Issue No.	980
LM End	0.38	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.671813 °	38.671813 °
				-121.671581 °	-121.671581 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50171					
DS_ID:17822					
EP_NO: N/A					
Repair Type: Urgent					
Crossing Status: Found					
UCIP Comments: 09/14/2016 - Flap gate on the WS was submerged at time of inspection. LS headwall at the pumping plant has exposed rebar. There is still erosion present behind the headwall. However, water was present making it difficult to determine if it is getting worse. As-built drawings were requested from LMA consultant representative. (T. Hatch/UCIP)04/02/2013 - Flap gate broken in half on WS toe. Some erosion at headwalls on pumping plant. (W. Wylie/UCIP) FIELD_STRUCT_DESC: 44-inch corrugated metal drainage pipe through the levee, 22 feet below the crown. Pump on platform in drainage ditch at the landside (LS) toe. Slide gate and flap gates in a 5-foot by 9-foot concrete box. Flap gate on the waterside (WS) toe. 8-inch vent/standpipe at the WS toe. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 0.4) (4-foot by 4-foot concrete culvert listed)].					
FS Date: 9/14/2016					

Photo 1 of 3 : UCIP_SP_2018_50171_18202.jpg



Pumping plant off LS toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	0.38	Rating **	U	Issue No.	980 (cont)
LM End	0.38	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.671813 °	38.671813 °
				-121.671581 °	-121.671581 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50171
DS_ID:17822
EP_NO: N/A
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 09/14/2016 - Flap gate on the WS was submerged at time of inspection. LS headwall at the pumping plant has exposed rebar. There is still erosion present behind the headwall. However, water was present making it difficult to determine if it is getting worse. As-built drawings were requested from LMA consultant representative. (T. Hatch/UCIP)04/02/2013 - Flap gate broken in half on WS toe. Some erosion at headwalls on pumping plant. (W. Wylie/UCIP) FIELD_STRUCT_DESC: 44-inch corrugated metal drainage pipe through the levee, 22 feet below the crown. Pump on platform in drainage ditch at the landside (LS) toe. Slide gate and flap gates in a 5-foot by 9-foot concrete box. Flap gate on the waterside (WS) toe. 8-inch vent/standpipe at the WS toe. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 0.4) (4-foot by 4-foot concrete culvert listed)].
FS Date: 9/14/2016

LM Start	0.38	Rating **	U	Issue No.	980 (cont)
LM End	0.38	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_50171_18201.jpg



Pipe and flap gate with vent riser on WS toe.

Photo 3 of 3 : UCIP_SP_2018_50171_18200.jpg



Broken flap gate at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	1.20	Rating **	A/W	Issue No.	2
LM End	1.24	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.660050 °	38.659465 °
				-121.669028 °	-121.668940 °
DWR ID	DWR_RD2035_02_s _ 2016_2				
Comment Code					
Inspector Comment					
2011 - Small sections of slumping, likely from wind wave. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_1-2_R]					

No Photos

LM Start	1.98	Rating **	A/W	Issue No.	4
LM End	2.03	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.648881 °	38.648178 °
				-121.666653 °	-121.666385 °
DWR ID	DWR_RD2035_02_s _ 2016_4				
Comment Code					
Inspector Comment					
2006 - Wave wash erosion and some saturation slumping occurring. Tension/separation cracks evident in fine grained levee slope materials. 2011 - Small sections of slumping lower bank, just downstream of bank rock. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_2-0_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.11	Rating **	A/W	Issue No.	17
LM End	6.97	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.647061 °	38.583800 °
				-121.666439 °	-121.630879 °
DWR ID	DWR_RD2035_02_f_2017_17				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:196					
Site Designation:RD 2035-09					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:5/18/2017					
Notes: This site had wave wash for approximatly 4.5 miles. The USACE has accepted it for repair under the PL84-99 program, but it is a lower priority for them so will not be repaired this year.					

No Photos

LM Start	2.15	Rating **	A/W	Issue No.	982	
LM End	2.15	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.646445 °	38.646445 °	
				-121.666423 °	-121.666423 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:10933 DS_ID:17833 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 1 of 2: 60-inch drainage pipe of an unknown material through the levee, 26 feet below the crown. Concrete well and gate structure on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 2.3) (6-foot by 6-foot concrete culvert listed)]. FS Date: 4/2/2013						

Photo 1 of 3 : UCIP_SP_2018_10933_18226.jpg



Slide gates in concrete vault on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.15	Rating **	A/W	Issue No.	982 (cont)	
LM End	2.15	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.646445 °	38.646445 °	
				-121.666423 °	-121.666423 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:10933						
DS_ID:17833						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 1 of 2: 60-inch drainage pipe of an unknown material through the levee, 26 feet below the crown. Concrete well and gate structure on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 2.3) (6-foot by 6-foot concrete culvert listed)].						
FS Date: 4/2/2013						

Photo 2 of 3 : UCIP_SP_2018_10933_18225.jpg



LS at intake.

LM Start	2.15	Rating **	A/W	Issue No.	982 (cont)
LM End	2.15	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2018_10933_18224.jpg



Outlet on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.15	Rating **	A/W	Issue No.	983 (cont)
LM End	2.15	Issue Type +	Ma	Location *	

A photograph of a wetland area. In the foreground, there is a small pond with murky water, surrounded by green and brown vegetation. A small, dark building is visible in the middle ground. In the background, a tall, lattice tower stands against a blue sky with scattered clouds. The date and time '04/02/2018 12:40' are printed in orange in the bottom right corner.

Intake at channel on LS toe.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

Photo 3 of 3 : UCIP_SP_2018_10934_18228.jpg



04/02/2018 12:40

Concrete headwall on WS toe.

LM Start	2.26	Rating **	A/W	Issue No.	5
LM End	2.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.645319 °	38.640997 °
				-121.665089 °	-121.661878 °
DWR ID	DWR_RD2035_02_s_2016_5				
Comment Code					
Inspector Comment					
2011 - Erosion from wind waves along entire length of the levee toe. Several sections of slumping bank along the toe. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_2-3_R]					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enfranchisement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.69	Rating **	C	Issue No.	18
LM End		Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.639790 °	°
				-121.661290 °	1.000000 °
DWR ID	DWR_RD2035_02_f_2017_18				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:188					
Site Designation:RD 2035-01					
Repair Type: Erosion					
Rating:Critical					
Field Date:7/13/2017					
Notes: Site was repaired fall of 2017					

No Photos

LM Start	2.78	Rating **	A/W	Issue No.	6
LM End	3.26	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.638731 °	38.632783 °
				-121.660247 °	-121.655864 °
DWR ID	DWR_RD2035_02_s_2016_6				
Comment Code					
Inspector Comment					
2011 - Wave wash erosion and several sections of slumping bank along the toe. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_2-8_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.91	Rating **	C	Issue No.	19		
LM End	2.95	Issue Type +	Ma	Location *			
Category	Supplemental			GPS Latitude/Longitude			
				Start		End	
Item	2017 Storm Damage			38.637030	°	38.636525	°
				-121.659300	°	-121.658841	°
DWR ID	DWR_RD2035_02_f_2017_19						
Comment Code							
Inspector Comment							
Levee Evaluation Comments							
Description:							
Site ID No:189							
Site Designation:RD 2035-02							
Repair Type: Erosion							
Rating:Critical							
Field Date:7/13/2017							
Notes: Site was repaired fall 2017							

No Photos

LM Start	2.96	Rating **	C	Issue No.	26	
LM End	3.00	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.636450°	38.635973°	
				-121.658880°	-121.658456°	
DWR ID	DWR_RD2035_02_f_2017_26					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:190						
Site Designation:RD 2035-03						
Repair Type: Erosion						
Rating:Critical						
Field Date:7/13/2017						
Notes: Site was repaired in fall 2017						

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	2.98	Rating **	C	Issue No.	27
LM End	3.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.636090 °	38.635187 °
				-121.658630 °	-121.657974 °
DWR ID	DWR_RD2035_02_f_2017_27				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:191					
Site Designation:RD 2035-04					
Repair Type: Erosion					
Rating:Critical					
Field Date:7/13/2017					
Notes: Site was repaired fall of 2017					

No Photos

LM Start	3.12	Rating **	C	Issue No.	28	
LM End	3.18	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.634430 °	38.633680 °	
				-121.657380 °	-121.656813 °	
DWR ID	DWR_RD2035_02_f_2017_28					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:192						
Site Designation:RD 2035-05						
Repair Type: Erosion						
Rating:Critical						
Field Date:7/13/2017						
Notes: Site was repaired fall 2017						

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	3.28	Rating **	C	Issue No.	29	
LM End	3.29	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			38.632420 °		38.632200 °
				-121.655920 °		-121.655750 °
DWR ID	DWR_RD2035_02_f_2017_29					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:193						
Site Designation:RD 2035-06						
Repair Type: Erosion						
Rating:Critical						
Field Date:7/13/2017						
Notes: Site was repaired fall 2017						

No Photos

LM Start	3.39	Rating **	C	Issue No.	30
LM End	3.41	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.631040°	38.630730°
				-121.654910°	-121.654670°
DWR ID	DWR_RD2035_02_f_2017_30				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:194					
Site Designation:RD 2035-07					
Repair Type: Erosion					
Rating:Critical					
Field Date:7/13/2017					
Notes: Site repaired fall 2017					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	3.46	Rating **	A	Issue No.	22
LM End	7.60	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.630112 °	38.575489 °
				-121.654087 °	-121.635021 °
DWR ID	DWR_RD2035_02_s_2018_22				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_239_22_20180430_00060.jpg



View looking downstream landside of the annual vegetation that is maintained, Spring 2018.

LM Start	3.46	Rating **	A	Issue No.	23
LM End	7.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.630111 °	38.575489 °
				-121.654087 °	-121.635021 °
DWR ID	DWR_RD2035_02_s_2018_23				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_239_23_20180430_00061.jpg



View looking downstream waterside of the annual vegetation that is maintained, Spring 2018.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	4.09	Rating **	A/W	Issue No.	7
LM End	4.41	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.622224 °	38.618302 °
				-121.648201 °	-121.645296 °
DWR ID	DWR_RD2035_02_s_2016_7				
Comment Code					
Inspector Comment					
2006 - Wave wash erosion and some saturation slumping occurring. Several small scallops present in lower levee slope/toe due to saturation slumping. Tension/separation cracks evident in fine-grained levee slope materials. 2011 - Small pockets of erosion throughout the site. Site formerly called 3.8. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: YOL_4-2_R]					

No Photos

LM Start	4.43	Rating **	M	Issue No.	985
LM End	4.43	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.618030 °	38.618030 °
				-121.645192 °	-121.645192 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:11526 DS_ID:17828 EP_NO: 1701 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Animal activity at outlet causing damage to berm and undermining the pipe at the outlet headwall on WS toe. FIELD_STRUCT_DESC: 60-inch corrugated metal drainage pipe encased in 6 inches of reinforced concrete through the levee, 20.6 feet below the crown. Slide gate in a 7-foot-diameter corrugated metal pipe (CMP) riser on the waterside (WS) slope. Pumping plant with 6 pumps and pipes that discharge into a 4-foot by 18-foot surge box on the landside (LS) toe. (Permit No. 1701, 1952 - Reclamation District No. 2035). [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 4.7)]. FS Date: 4/3/2013					

Photo 1 of 3 : UCIP_SP_2018_11526_18935.jpg



Surge box and pumping plant on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	6.35	Rating **	A/W	Issue No.	31
LM End	6.38	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.592840 °	38.592390 °
				-121.631340 °	-121.631320 °
DWR ID	DWR_RD2035_02 f _ 2017_31				

Comment Code

Inspector Comment

Levee Evaluation Comments

Description:

Site ID No:195

Site Designation:RD 2035-08

Repair Type: Erosion

Rating:Critical

Field Date:7/13/2017

Notes: long longitudinal cracks on the crown. Scheduled for repair 2019.

LM Start	6.35	Rating **	A/W	Issue No.	31 (cont)
LM End	6.38	Issue Type +	Ma	Location *	

Photo 1 of 4 : SP_2018_RD2035_239_31_20180302_00032.jpg



View looking downstream landside of 2017 Storm Damage, sluffing site. All plastic is remove, sandbags remain, and is NOT scheduled to be repaired in 2017.

Photo 2 of 4 : LEVAL_SP_2018_195_1600.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/19/2018 04/19/2018	Sterling York

LM Start	6.35	Rating **	A/W	Issue No.	31 (cont)	
LM End	6.38	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.592840 °	38.592390 °	
				-121.631340 °	-121.631320 °	
DWR ID	DWR_RD2035_02_f_2017_31					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:195						
Site Designation:RD 2035-08						
Repair Type: Erosion						
Rating:Critical						
Field Date:7/13/2017						
Notes: long longitudinal cracks on the crown. Scheduled for repair 2019.						

Photo 3 of 4 : LEVAL_SP_2018_195_1603.jpg



Photo 4 of 4 : LEVAL_SP_2018_195_1592.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/19/2018 04/19/2018	Sterling York

LM Start	0.00	Rating **	M	Issue No.	6
LM End	2.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.575365 °	38.590787 °
				-121.635652 °	-121.665279 °
DWR ID	DWR_RD2035_03_s_2018_6				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_240_6_20180430_00014.jpg



View looking upstream landside of the annual vegetation that needs to be maintained, Spring 2018.

LM Start	0.00	Rating **	U	Issue No.	7
LM End	2.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.575364 °	38.590787 °
				-121.635652 °	-121.665278 °
DWR ID	DWR_RD2035_03_s_2018_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD2035_240_7_20180430_00015.jpg



View looking upstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/19/2018 04/19/2018	Sterling York

LM Start	1.39	Rating **	M	Issue No.	975
LM End	1.39	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.589425 °	38.589425 °
				-121.645359 °	-121.645359 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41128 DS_ID:17836 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to clear vegetation and debris from WS at outlet. FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 17.5 feet below the crown. Flap gate on the waterside (WS) end. Slide gate and concrete headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 327+75)]. FS Date: 4/3/2013					

Photo 1 of 3 : UCIP_SP_2018_41128_18348.jpg



Slide gate and headwall in canal at LS toe.

LM Start	1.39	Rating **	M	Issue No.	975 (cont)
LM End	1.39	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_41128_18347.jpg



Slide gate and headwall in canal at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/19/2018 04/19/2018	Sterling York

LM Start	2.17	Rating **	M	Issue No.	976 (cont)	
LM End	2.17	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.590934 °	38.590934 °	
				-121.658940 °	-121.658940 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:11011 DS_ID:17837 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris and vegetation partially blocking inlet and outlet at both toes. FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe through the levee, 19 feet below the crown. Slide gates on both ends. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 290+37)]. FS Date: 4/3/2013						

Photo 2 of 2 : UCIP_SP_2018_11011_18353.jpg



Slide gate at LS toe showing excessive vegetation.

LM Start	2.19	Rating **	M	Issue No.	977
LM End	2.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.590909 °	38.590909 °
				-121.659311 °	-121.659311 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:11012					
DS_ID:17838					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Debris and vegetation partially blocking both ends of pipe.					
FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 18 feet below the crown. Slide gate on the landside (LS) toe. Combination flap and slide gate on the waterside (WS) toe.					
[Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 289+33)].					
FS Date: 4/3/2013					

Photo 1 of 3 : UCIP_SP_2018_11012_18357.jpg



Combination flap and slide gate on WS toe. With excessive vegetation

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/19/2018 04/19/2018	Sterling York

LM Start	2.19	Rating **	M	Issue No.	977 (cont)
LM End	2.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.590909 °	38.590909 °
				-121.659311 °	-121.659311 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:11012					
DS_ID:17838					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Debris and vegetation partially blocking both ends of pipe.					
FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 18 feet below the crown. Slide gate on the landside (LS) toe. Combination flap and slide gate on the waterside (WS) toe.					
[Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 289+33)].					
FS Date: 4/3/2013					

Photo 2 of 3 : UCIP_SP_2018_11012_18356.jpg



Headwall at bottom of fenceline on LS toe

LM Start	2.19	Rating **	M	Issue No.	977 (cont)
LM End	2.19	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2018_11012_18355.jpg



Headwall and pipe on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---