

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	37.744860 °
				°	-121.289828 °
DWR ID	DWR_RD2075_01_f_2014_9				
Comment Code					
Inspector Comment					
RD 2075 has the O&M Manual on file.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	
				°	
DWR ID	DWR_RD2075_01_f_2014_10				
Comment Code					
Inspector Comment					
RD 2075 has emergency supplies stored in their building.					

No Photos

LM Start		Rating **	A	Issue No.	11
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	
				°	
DWR ID	DWR_RD2075_01_f_2014_11				
Comment Code					
Inspector Comment					
RD 2075 has regular training for their work crews.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	0.12	Rating **	M	Issue No.	24
LM End	0.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.748175 °	37.748175 °	
			-121.289717 °	-121.289717 °	
DWR ID	DWR_RD2075_01_s_2019_24				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	0.12	Rating **	C	Issue No.	17
LM End	0.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.748129 °	37.746502 °	
			-121.289667 °	-121.289467 °	
DWR ID	DWR_RD2075_01_f_2019_17				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	0.16	Rating **	C	Issue No.	35
LM End	0.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		37.747638 °	37.747638 °	
			-121.289452 °	-121.289452 °	
DWR ID	DWR_RD2075_01_f_2019_35				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	1.15	Rating **	C	Issue No.	36
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.737844 °	37.737844 °	
			-121.281650 °	-121.281650 °	
DWR ID	DWR_RD2075_01_f_2019_36				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	1.18	Rating **	M	Issue No.	37
LM End	1.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.737403 °	37.737403 °	
			-121.281542 °	-121.281542 °	
DWR ID	DWR_RD2075_01_f_2019_37				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	1.25	Rating **	A/W	Issue No.	38
LM End	1.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.736384 °	37.736384 °	
			-121.281529 °	-121.281529 °	
DWR ID	DWR_RD2075_01_f_2019_38				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	1.43	Rating **	C	Issue No.	29
LM End	1.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.735061 °	37.734213 °
				-121.284269 °	-121.287660 °
DWR ID	DWR_RD2075_01_s_2018_29				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Wild growth at the landward toe is blocking the view and should be cleared to fifteen feet from the landward toe.					

No Photos

LM Start	2.32	Rating **	M	Issue No.	50
LM End	2.32	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.731314 °	37.731314 °
				-121.293713 °	-121.293713 °
DWR ID	24737				
Comment Code					
Inspector Comment					
DS_ID:24737 FS_ID:24666 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - service pole on landside.- looks abandoned. Walkway in dilapidated condition. FIELD_STRUCT_DESC: 16-inch steel drainage discharge pipe through the levee, 4.5 feet below the crown. Corrugated metal cutoff wall. Pump mounted on a pile structure in a drainage ditch on the landside (LS). Siphon breaker in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual 3, December 1968, (HLM 2.30)]. FS Date: 11/13/2013					

Photo 1 of 3 : UCIP_SP_2020_24666_45600.jpg



WS view: concrete standpipe (top) and steel pipe riser (bottom marked) on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	2.32	Rating **	M	Issue No.	50 (cont)
LM End	2.32	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.731314 °	37.731314 °
				-121.293713 °	-121.293713 °
DWR ID	24737				

Photo 2 of 3 : UCIP_SP_2020_24666_44030.jpg



WS view: blocked siphon breaker in steel pipe riser on levee slope.

LM Start	2.32	Rating **	M	Issue No.	50 (cont)
LM End	2.32	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_24666_44029.jpg



WS view: concrete standpipe on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	2.32	Rating **	A/W	Issue No.	15
LM End	2.78	Issue Type +	Ma	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		37.731200 °	37.724900 °	
			-121.293400 °	-121.293800 °	

DWR ID LMA-306

Comment Code

Inspector Comment

Planned For PL 84-99 Repair in 2020.
Sinkholes have formed along the landside levee toe as a result of the high water. The cause of the sinkholes is not clear, but a similar phenomenon in this area is believed to have caused the levee breach earlier this year. Further geotechnical investigation is needed. Sink holes appear to have already been filled. 10/23/17: LMA has removed pipes (parallel to levee) in this area, and drainage ditch has been relocated to approx 60 feet away from levee toe. Known sandy soils in region may contribute to sinkholes
Site ID No:479 Site Designation:LMA-306

LM Start	2.32	Rating **	A/W	Issue No.	15 (cont)
LM End	2.78	Issue Type +	Ma	Location *	LS

Photo 1 of 4 : LEVAL_SP_2020_479_2203.jpg



Photo 2 of 4 : LEVAL_SP_2020_479_2215.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	2.32	Rating **	A/W	Issue No.	15 (cont)
LM End	2.78	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			37.731200 °	37.724900 °
				-121.293400 °	-121.293800 °
DWR ID	LMA-306				

Photo 3 of 4 : SP_2020_RD2075_315_15_20200228_00013.jpg



10/23/17: LMA has removed pipes (parallel to levee) in this area, and drainage ditch has been relocated to approx 60 feet away from levee toe. Known sandy soils in region may contribute to sinkholes.

LM Start	2.32	Rating **	A/W	Issue No.	15 (cont)
LM End	2.78	Issue Type +	Ma	Location *	LS

Photo 4 of 4 : SP_2020_RD2075_315_15_20200327_00063.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	2.74	Rating **	A/W	Issue No.	16
LM End	2.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.725200 °	37.724000 °
				-121.294400 °	-121.293200 °
DWR ID	LMA-307				

Comment Code

E1 : Note and monitor erosion site.

Inspector Comment

Slope protection repairs are needed along the waterside slope due to erosion. Based upon levee inspections, it was determined the waterside levee slopes were eroding, deteriorating and degrading in concave pocket sections at various locations along this levee reach. The eroded levee sections need to be restored back to design standards to prevent further deterioration of the damaged levee sections. Low priority because of the wide berm. Could not see all of the bank because of vegetation. Rock was placed on LS here during this years (2017) storms

Site ID No:480 & 81, Site Designation: LMA-307 & LMA-35

LM Start	2.74	Rating **	A/W	Issue No.	16 (cont)
LM End	2.84	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2020_RD2075_315_16_20200327_00064.jpg



View of waterside slope looking upstream. Spring 2020

Photo 2 of 2 : LEVAL_SP_2020_480_2209.jpg



View of erosion on channel bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	3.90	Rating **	A/W	Issue No.	19
LM End	4.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.713388 °	37.714630 °
				-121.280018 °	-121.278263 °
DWR ID	LMA-483				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Slope protection repairs are needed along the waterside slope due to erosion and riprap displacement from high water. Based upon levee inspections, it was determined the waterside levee slope is eroding, deteriorating, and degrading. The eroded levee sections need to be restored back to design standards to prevent further deterioration and damage.					
Site ID No: 576 & 577, Site Designation: LMA-482 & LMA-483					

LM Start	3.90	Rating **	A/W	Issue No.	19 (cont)
LM End	4.04	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : LEVAL_SP_2020_577_4471.jpg



Photo 2 of 2 : LEVAL_SP_2020_577_4475.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	5.21	Rating **	M	Issue No.	39
LM End	5.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.728727 °	37.726179 °
				-121.274983 °	-121.272004 °
DWR ID	DWR_RD2075_01_f_2019_39				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	5.24	Rating **	A/W	Issue No.	23
LM End	5.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.728460 °	37.727799 °
				-121.274670 °	-121.274250 °
DWR ID	LMA-33				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Slope protection repairs are needed along the waterside slope due to erosion and riprap displacement from high water. Based upon levee inspections, it was determined the waterside levee slope is eroding, deteriorating, and degrading. The eroded levee sections need to be restored back to design standards to prevent further deterioration and damage. Site ID No: 578 & 79, Site Designation: LMA-484 & LMA-33					

LM Start	5.24	Rating **	A/W	Issue No.	23 (cont)
LM End	5.29	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2020_RD2075_315_23_20200402_00065.jpg



View of 2017 storm damage waterside erosion-area of concern. Spring 2020

Photo 2 of 2 : LEVAL_SP_2020_79_1331.jpg



June 2017

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	5.28	Rating **	A/W	Issue No.	1
LM End	5.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.727933 °	37.727933 °
				-121.274491 °	-121.274491 °
DWR ID	RD2075U01RM64.34				

Comment Code

Inspector Comment

Site ID: RD2075U01RM64.34
 09/17/2019: No significant change observed.
 09/13/2017: No significant change observed.
 07/12/2016: No significant change observed.
 08/28/2015: No significant change observed. Loose material is visible at the upper levee slope. The loose soil may have been caused by runoff.
 08/18/2014: No significant change observed.
 09/10/2013: No significant change observed.
 09/13/2012: No significant change observed.
 08/18/2011: No significant change observed. Some new material added to the water side levee slope, but the added material is loose and seems not helping the levee protection.
 10/05/2010: No significant change observed. Levee slope has minimal vegetation and lacks rip rap protection. Sandy material found on the lower and middle slope is an undesirable material to have on a levee.
 08/05/2010: Recommended for annual assessment and monitoring during flood events, per CLRO.
 08/20/2009: No major change since last visit; site is located in an oxbow; slope surface consists of very sandy material; there is a tree on site leaning and with exposed tree roots; site is recommended as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza from the district is aware of the site and is looking for recommendation; site is previously rated "U".
 08/17/2007: Site is close to an irrigation pump inlet.

LM Start	5.28	Rating **	A/W	Issue No.	1 (cont)
LM End	5.29	Issue Type +	Ma	Location *	

Photo 1 of 3 : SP_2020_RD2075_315_1_20200228_00001.jpg



Upstream view of the erosion site.

Photo 2 of 3 : SP_2020_RD2075_315_1_20200228_00002.jpg



Close-up view of the site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	5.28	Rating **	A/W	Issue No.	1 (cont)
LM End	5.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.727933 °	37.727933 °
				-121.274491 °	-121.274491 °
DWR ID	RD2075U01RM64.34				

Photo 3 of 3 : SP_2020_RD2075_315_1_20200228_00003.jpg



Looking at the eroded levee slope.

LM Start	5.30	Rating **	C	Issue No.	40
LM End	5.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.727742 °	37.725010 °
				-121.274050 °	-121.271120 °
DWR ID	DWR_RD2075_01_f_2019_40				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	5.50	Rating **	M	Issue No.	41
LM End	5.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.725629 °	37.725629 °
				-121.271596 °	-121.271596 °
DWR ID	DWR_RD2075_01_f_2019_41				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	5.61	Rating **	M	Issue No.	43
LM End	5.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.724371 °	37.722472 °	
			-121.270647 °	-121.269210 °	
DWR ID	DWR_RD2075_01_f_2019_43				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	5.73	Rating **	A/W	Issue No.	44
LM End	5.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.722763 °	37.722763 °	
			-121.269427 °	-121.269427 °	
DWR ID	DWR_RD2075_01_f_2019_44				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	5.87	Rating **	A/W	Issue No.	28
LM End	6.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		37.721710 °	37.720960 °	
			-121.267490 °	-121.259830 °	
DWR ID	LMA-485				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Slope protection repairs are needed along the waterside slope due to erosion and riprap displacement from high water. Based upon levee inspections, it was determined the waterside levee slope is eroding, deteriorating, and degrading. The eroded levee sections need to be restored back to design standards to prevent further deterioration and damage. Site ID No: 579 & 580, Site Designation: LMA-485 & LMA-486					

Photo 1 of 2 : SP_2020_RD2075_315_28_20200402_00067.jpg



View of waterside slope looking downstream. Spring 2020

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	5.87	Rating **	A/W	Issue No.	28 (cont)
LM End	6.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.721710 °	37.720960 °
				-121.267490 °	-121.259830 °
DWR ID	LMA-485				

Photo 2 of 2 : SP_2020_RD2075_315_28_20200402_00068.jpg



View of waterside slope looking upstream. Spring 2020

LM Start	6.02	Rating **	M	Issue No.	12
LM End	6.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.722371 °	37.721251 °
				-121.264874 °	-121.260290 °
DWR ID	DWR_RD2075_01_s_2020_12				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	6.37	Rating **	M	Issue No.	45
LM End	6.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.720675 °	37.718157 °
				-121.259357 °	-121.258543 °
DWR ID	DWR_RD2075_01_f_2019_45				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.45	03/25/2020 03/25/2020	Alberto De Leon

LM Start	6.71	Rating **	M	Issue No.	46
LM End	6.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.715761 °	37.715032 °	
			-121.258401 °	-121.258539 °	
DWR ID	DWR_RD2075_01_f_2019_46				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	6.84	Rating **	M	Issue No.	42
LM End	7.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.714122 °	37.713533 °	
			-121.259267 °	-121.262667 °	
DWR ID	DWR_RD2075_01_f_2019_42				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---