

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2014 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including DWR Erosion Survey**

**San Joaquin River Basin**

<b>RD2089</b>		Overall LMA Rating	Total LMA Miles						
<b>Reclamation District No. 2089 Stark</b>		<b>U</b>	<b>2.86</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
<i>Earthen Levee</i>									
Vegetation	1.60	0.24	2.56	89.58%	0.01				
Trim / Thin Trees		0.01	0.04	1.40%					
Encroachments	0.04		0.04	1.40%	0.44	0.05			
Animal Control	0.11	0.12	0.59	20.65%					
Slope Stability	0.14		0.14	4.90%					
Crown Surface / Depressions / Rutting	0.05		0.05	1.75%					
<i>Supplemental</i>									
DWR Erosion Survey	0.03	0.01	0.07	2.45%					
DWR UCIP Field Study					0.05	0.01			
<i>LMA Totals:</i>	1.97	0.38	3.49	122.12%	0.50	0.06	0.00	0.00	

<b>Unit No. 01 Old River RB</b>		Overall Unit Rating	Total Unit Miles						
<b>RD2089</b>		<b>U</b>	<b>1.51</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
<i>Earthen Levee</i>									
Vegetation	1.29	0.19	2.05	135.56%					
Trim / Thin Trees		0.01	0.04	2.65%					
Encroachments	0.02		0.02	1.32%	0.40				
Animal Control	0.03		0.03	1.98%					
Slope Stability	0.13		0.13	8.60%					
Crown Surface / Depressions / Rutting	0.04		0.04	2.65%					
<i>Supplemental</i>									
DWR Erosion Survey	0.02	0.01	0.06	3.97%					
DWR UCIP Field Study					0.04	0.01			
<i>Unit Totals:</i>	1.53	0.21	2.37	156.72%	0.44	0.01	0.00	0.00	

<b>Unit No. 02 Salmon Slough RB</b>		Overall Unit Rating	Total Unit Miles						
<b>RD2089</b>		<b>U</b>	<b>1.35</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
<i>Earthen Levee</i>									
Vegetation	0.31	0.05	0.51	37.90%	0.01				
Encroachments	0.02		0.02	1.49%	0.04	0.05			
Animal Control	0.08	0.12	0.56	41.62%					
Slope Stability	0.01		0.01	0.74%					
Crown Surface / Depressions / Rutting	0.01		0.01	0.74%					
<i>Supplemental</i>									
DWR Erosion Survey	0.01		0.01	0.74%					
DWR UCIP Field Study					0.01				
<i>Unit Totals:</i>	0.44	0.17	1.12	83.24%	0.06	0.05	0.00	0.00	

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2014 Levee Inspection Results**

**Reclamation District No. 2089 Stark**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>U</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2014 Levee Inspection Results**

**Reclamation District No. 2089 Stark**

Waterway		Bank	Unit Miles
Unit No. 01 Old River		Right	1.51
	Spring (March - May)	Summer (June - August)	(September - November) Fall Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>U</b>
Date of Inspection	05/07/2014 - 05/07/2014		10/27/2014 - 10/27/2014
DWR Inspector	Maksim Khashchuk		Maksim Khashchuk
Accompanied By			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	<b>4</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals		°	°	°
DWR ID	DWR_RD2089_01_s_2013_4				
Action/Comments					
Inspector Comments: The O&M Manual is available at the LMA's office.					

No Photos

LM Start		Rating **	A	Issue No.	<b>15</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment		°	°	°
DWR ID	DWR_RD2089_01_s_2013_15				
Action/Comments					
Inspector Comments: The LMA has flood fighting supplies on-site.					

No Photos

LM Start		Rating **	A	Issue No.	<b>34</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training		°	°	°
DWR ID	DWR_RD2089_01_s_2013_34				
Action/Comments					
Inspector Comments: The LMA has flood fight training and an emergency plan.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.00</b>	Rating **	M	Issue No.	<b>9</b>
LM End	<b>0.39</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.811681 °	37.809755 °	
			-121.384930 °	-121.391520 °	
DWR ID	DWR_RD2089_01_s_2012_9				
Action/Comments					
Ditch Inspector Comments: 05/24/2011 Photo added of Ag ditch.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_9\_20141001\_00006.jpg



05/24/2011 Ditch flows parallel with the utility line shown in the photo.

LM Start	<b>0.04</b>	Rating **	A/W	Issue No.	<b>7</b>
LM End	<b>0.04</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.811467 °	37.811467 °	
			-121.385569 °	-121.385569 °	
DWR ID	DWR_RD2089_01_s_2012_7				
Action/Comments					
Pipe Inspector Comments: Drainage pump					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_7\_20141001\_00005.jpg



Waterside of drainage discharge to Old River.

LM Start	<b>0.04</b>	Rating **	M	Issue No.	<b>1</b>
LM End	<b>0.04</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.811474 °	37.811474 °	
			-121.385573 °	-121.385573 °	
DWR ID	DWR_RD2089_01_s_2012_1				
Action/Comments					
Stairway Inspector Comments: Steps have been cut into the levee slope, this could become an erosion point, please fill and compact.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_1\_20141001\_00001.jpg



View of the stairs eroding into the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.07</b>	Rating **	M	Issue No.	<b>42</b>
LM End	<b>0.14</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.811368 °	37.811048 °	
			-121.386085 °	-121.387242 °	
DWR ID	DWR_RD2089_01_f_2013_42				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_42\_20141001\_00020.jpg



View of the tall vegetation obstructing visibility of the landside levee slope.

LM Start	<b>0.25</b>	Rating **	M	Issue No.	<b>940</b>
LM End	<b>0.25</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.810412 °	37.810412 °	
			-121.389115 °	-121.389115 °	
DWR ID	DWR_RD2089_01_s_2012_940				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Arundo has been trimmed back from the crown but still remains as an obstruction to the slope and obstructs visibility, needs to be removed.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_940\_20141001\_00028.jpg



The LMA is actively trying to remove the vegetation on the landside levee slope and toe.

LM Start	<b>0.27</b>	Rating **	U	Issue No.	<b>12</b>
LM End	<b>0.39</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.810319 °	37.809740 °	
			-121.389510 °	-121.391645 °	
DWR ID	DWR_RD2089_01_s_2012_12				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Access and visibility completely blocked. 11/10/2011 issue has not changed.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_12\_20141001\_00007.jpg



Thick brush and wild rose completely block access and visibility of landside slope and toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.34</b>	Rating **	M	Issue No.	<b>19</b>
LM End	<b>0.34</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.809978 °	37.809978 °
				-121.390704 °	-121.390704 °
DWR ID	DWR_RD2089_01_s_2012_19				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Bamboo completely blocks access and visibility. 11/10/2011 Arundo has been trimmed back from the roadway, but still completely blocks access and visibility to the landside slope. This plant was improperly identified as bamboo in previous inspections.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_19\_20141001\_00010.jpg



Arundo has been trimmed back from the road, but needs to be removed to so that it does not obstruct visibility and access to the landside toe.

LM Start	<b>0.38</b>	Rating **	U	Issue No.	<b>946</b>
LM End	<b>0.38</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.809865 °	37.809865 °
				-121.391303 °	-121.391303 °
DWR ID	DWR_RD2089_01_s_2012_946				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_946\_20141001\_00029.jpg



Trees on levee slope obstruct access and visibility.

LM Start	<b>0.42</b>	Rating **	U	Issue No.	<b>28</b>
LM End	<b>0.48</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.809593 °	37.809507 °
				-121.391963 °	-121.392907 °
DWR ID	DWR_RD2089_01_s_2012_28				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Vegetation is too thick to allow access and visibility.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_28\_20141001\_00014.jpg



05/24/2011 Photo shows thick dead vegetation and continuation of trees in area that are preventing access and visibility of landside slope and toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	0.45	Rating **	M	Issue No.	5	
LM End	0.45	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
			Start	End		
Item	DWR Erosion Survey			37.809394 °	37.809394 °	
				-121.392791 °	-121.392791 °	
DWR ID						
Action/Comments						
Inspector Comments: 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: The site shows loose material around the pipe crossing. The operation of the pipe might have caused an impact on the levee. [2014 Site ID:RD2089U01RM29.8]						

Photo 1 of 1 : SJR2014\_RD2089U01RM29.8\_1.jpg



Front view of the site.

LM Start	0.46	Rating **	M	Issue No.	6	
LM End	0.46	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
			Start	End		
Item	DWR UCIP Field Study			37.809501 °	37.809501 °	
				-121.392798 °	-121.392798 °	
DWR ID	DWR_RD2089_01_f_2014_6					
Action/Comments						
Inspector Comments: FS_ID:21635 EP_NO: 5641 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - damaged siphon breakermost of the pipe on landside exposed on levee slope. FIELD_STRUCTURE_DESC: 20-inch steel pipe and electric conduit through the levee, 5.8 feet below the crown, pump on pile structure in the stream. Siphon breaker on the landward slope. (App. No. 5641- Ted Stark) FS Date: 9/12/2013						

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.50</b>	Rating **	M	Issue No.	<b>30</b>
LM End	<b>0.50</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.809665 °	37.809665 °	
			-121.393219 °	-121.393219 °	
DWR ID	DWR_RD2089_01_s_2012_30				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Dead growth is too thick to allow access during flood fight situation and completely obstructs visibility of the landside toe.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_30\_20141001\_00015.jpg



05/24/2011 Dead brush is too thick to allow access and visibility of landside slope and toe.

LM Start	<b>0.56</b>	Rating **	M	Issue No.	<b>14</b>
LM End	<b>0.56</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.810087 °	37.810087 °	
			-121.394200 °	-121.394200 °	
DWR ID	DWR_RD2089_01_s_2012_14				
Action/Comments					
Add appropriate gravel or road base. Grade and compact. Inspector Comments: 11/10/2011 Minor depressions will cause ponding.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_14\_20141001\_00008.jpg



11/10/2011 Depressions in crown.

LM Start	<b>0.64</b>	Rating **	M	Issue No.	<b>18</b>
LM End	<b>1.53</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.810048 °	37.806534 °	
			-121.395762 °	-121.407531 °	
DWR ID	DWR_RD2089_01_s_2012_18				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 11/10/2011 Waterside vegetation is too thick to allow access and visibility.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_18\_20141001\_00009.jpg



11/10/2011 Vegetation needs to be cleared on the upper 20' of the waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.73</b>	Rating **	M	Issue No.	<b>20</b>
LM End	<b>0.77</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.809516 °	37.808909 °
				-121.396955 °	-121.397557 °
DWR ID	DWR_RD2089_01_s_2012_20				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 11/10/2011 Dead vegetation prohibits visibility of the landside toe.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_20\_20141001\_00011.jpg



11/10/2011 Vegetation obstructs visibility of slope and toe.

LM Start	<b>0.81</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>0.81</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.808387 °	37.808387 °
				-121.397843 °	-121.397843 °
DWR ID	DWR_RD2089_01_f_2014_8				
Action/Comments					
Inspector Comments: FS_ID:21587 EP_NO: 3385 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - powerline on landside.electric control box on waterside.waterside slope erosion under pump platform. FIELD_STRUCT_DESC: 16-inch pipe through the levee, 5.5 feet below the crown, slant pump in pump house on the waterward slope. Siphon breaker on the landward slope. (App. No. 3385-Elinore Lawrence). Originally included in O+M (1968) FS Date: 9/12/2013					

No Photos

LM Start	<b>0.83</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>0.96</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.808319 °	37.806453 °
				-121.397881 °	-121.397755 °
DWR ID	DWR_RD2089_01_f_2014_17				
Action/Comments					
Repair slope instability. Inspector Comments: Landside levee toe cut due to farming.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_17\_20141027\_00035.jpg



View of the vertical cut along the landside levee toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> <b>C : Corrected</b> <b>A/W : Acceptable but Monitor &amp; Maintain</b>	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.85</b>	Rating **	M	Issue No.	<b>36</b>
LM End	<b>0.97</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.807938 °	37.806361 °
				-121.397898 °	-121.397778 °
DWR ID	DWR_RD2089_01_s_2012_36				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Tall weeds and brush on top 20' of waterside slope obstruct visibility.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_36\_20141001\_00019.jpg



View of tall weeds and brush obstructing visibility on waterside slope. 05/24/2012

LM Start	<b>0.96</b>	Rating **	M	Issue No.	<b>33</b>
LM End	<b>0.96</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.806397 °	37.806397 °
				-121.397758 °	-121.397758 °
DWR ID	DWR_RD2089_01_s_2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 11/10/2011 Large arundo on waterside prevents visibility and access to waterside slope.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_33\_20141001\_00017.jpg



11/10/2011 Arundo on upper 20' of waterside slope.

LM Start	<b>0.98</b>	Rating **	M	Issue No.	<b>35</b>
LM End	<b>1.07</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.806264 °	37.805885 °
				-121.397961 °	-121.399726 °
DWR ID	DWR_RD2089_01_s_2012_35				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 11/10/2011 Thick vegetation blocks visibility and access to top 20' of waterside slope.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_35\_20141001\_00018.jpg



Thick vegetation on upper 20' of waterside slope obstructing visibility and access.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.04</b>	Rating **	M	Issue No.	<b>956</b>
LM End	<b>1.06</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.806063 °	37.805967 °	
			-121.398930 °	-121.399348 °	
DWR ID	DWR_RD2089_01_s_2012_956				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry and tobacco block visibility.					

No Photos

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>957</b>
LM End	<b>1.10</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.805848 °	37.805848 °	
			-121.400003 °	-121.400003 °	
DWR ID	DWR_RD2089_01_s_2012_957				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Brush blocks access.					

No Photos

LM Start	<b>1.15</b>	Rating **	M	Issue No.	<b>16</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.805699 °	37.805699 °	
			-121.400952 °	-121.400952 °	
DWR ID	DWR_RD2089_01_f_2014_16				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_16\_20141027\_00034.jpg



View of the rodent burrow on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.16</b>	Rating **	A/W	Issue No.	<b>21</b>
LM End	<b>1.16</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.805623 °	37.805623 °	
			-121.401207 °	-121.401207 °	
DWR ID	DWR_RD2089_01_s_2012_21				
Action/Comments					
Pipe					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_21\_20141001\_00012.jpg



Drainage discharge into Old River.

LM Start	<b>1.22</b>	Rating **	M	Issue No.	<b>2</b>
LM End	<b>1.23</b>	Issue Type +	Ma	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR Erosion Survey		37.805580 °	37.805580 °	
			-121.403010 °	-121.403010 °	
DWR ID					
Action/Comments					
Inspector Comments: 07/02/2014: No significant change observed. 08/13/2013: The erosion is around a tree at the levee toe. Dense vegetation is visible. [2014 Site ID:RD2089U01RM29.04]					

Photo 1 of 1 : SJR2014\_RD2089U01RM29.04\_1.jpg



Close view of the site. Note the tree and the vegetation.

LM Start	<b>1.22</b>	Rating **	M	Issue No.	<b>25</b>
LM End	<b>1.22</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.805663 °	37.805663 °	
			-121.402151 °	-121.402151 °	
DWR ID	DWR_RD2089_01_s_2012_25				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Bamboo within top 20' of waterside levee slope.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_25\_20141001\_00013.jpg



View of the Arundo on the waterside slope obstructing visibility. LMA is actively trying to remove the wild growth.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.25</b>	Rating **	M	Issue No.	<b>43</b>
LM End	<b>1.25</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.805735 °	37.805735 °	
			-121.402614 °	-121.402614 °	
DWR ID	DWR_RD2089_01_s_2012_43				
Action/Comments					
Add appropriate gravel or road base. Grade and compact. Inspector Comments: 11/10/2011 Depression needs to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_43\_20141001\_00021.jpg



11/10/2011 Depression in roadway.

LM Start	<b>1.26</b>	Rating **	M	Issue No.	<b>44</b>
LM End	<b>1.26</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.805801 °	37.805801 °	
			-121.402913 °	-121.402913 °	
DWR ID	DWR_RD2089_01_s_2012_44				
Action/Comments					
Add appropriate gravel or road base. Grade and compact. Inspector Comments: 11/10/2011 Depression in roadway needs to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_44\_20141001\_00022.jpg



11/10/2011 Roadway depression.

LM Start	<b>1.38</b>	Rating **	M	Issue No.	<b>45</b>
LM End	<b>1.38</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.806128 °	37.806128 °	
			-121.404890 °	-121.404890 °	
DWR ID	DWR_RD2089_01_s_2012_45				
Action/Comments					
Add appropriate gravel or road base. Grade and compact. Inspector Comments: 11/10/2011 Depression needs to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_45\_20141001\_00023.jpg



11/10/2011 Roadway depression.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.43</b>	Rating **	M	Issue No.	<b>47</b>
LM End	<b>1.43</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.806268 °	37.806268 °	
			-121.405874 °	-121.405874 °	
DWR ID	DWR_RD2089_01_s_2012_47				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: 11/10/2011 No rodents visible, but active burrows are present.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_47\_20141001\_00025.jpg



11/10/2011 Active rodent burrow on landside slope.

LM Start	<b>1.43</b>	Rating **	M	Issue No.	<b>46</b>
LM End	<b>1.43</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.806266 °	37.806266 °	
			-121.405876 °	-121.405876 °	
DWR ID	DWR_RD2089_01_s_2012_46				
Action/Comments					
Tree or limb Inspector Comments: 11/10/2011 Downed tree at levee toe prevents access to levee from landside.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_46\_20141001\_00024.jpg



Decaying tree at the landside levee toe is obstructing visibility and access.

LM Start	<b>1.44</b>	Rating **	M	Issue No.	<b>10</b>
LM End	<b>1.44</b>	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.806323 °	37.806323 °	
			-121.406149 °	-121.406149 °	
DWR ID	DWR_RD2089_01_f_2014_10				
Action/Comments					
Inspector Comments: FS_ID:21581 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - if abandoned, it needs proper abandonment. FIELD_STRUCT_DESC: A 6-inch PVC pipe through the levee, 2 ft. below the crown and open both ends. Field study discovered pipe. FS Date: 9/12/2013					

No Photos

<b>* Location</b> LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.51	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.44</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>1.44</b>	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.806323 °	37.806323 °	
			-121.406155 °	-121.406155 °	
DWR ID	DWR_RD2089_01_f_2014_11				
Action/Comments					
Inspector Comments: FS_ID:21585 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - siphon breaker needs repair. FIELD_STRUCT_DESC: 10-inch steel pipe through the levee, 2.4 feet below the crown. Pump in drain ditch on the landward side. Siphon breaker on the waterward shoulder. FS Date: 9/12/2013					

No Photos

LM Start	<b>1.47</b>	Rating **	M	Issue No.	<b>52</b>
LM End	<b>1.47</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.806378 °	37.806378 °	
			-121.406486 °	-121.406486 °	
DWR ID	DWR_RD2089_01_f_2013_52				
Action/Comments					
Prunings					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_52\_20141001\_00027.jpg



View of the tree branches obstructing landside levee slope.

LM Start	<b>1.47</b>	Rating **	M	Issue No.	<b>49</b>
LM End	<b>1.47</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.806383 °	37.806383 °	
			-121.406599 °	-121.406599 °	
DWR ID	DWR_RD2089_01_s_2012_49				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Deep burrow on waterside needs to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_316\_49\_20141001\_00026.jpg



11/10/2011 Deep burrow on waterside.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2014 Levee Inspection Results**

**Reclamation District No. 2089 Stark**

Waterway		Bank	Unit Miles
Unit No. 02 Salmon Slough		Right	1.35
	Spring (March - May)	Summer (June - August)	(September - November) Fall Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>U</b>
Date of Inspection	05/07/2014 - 05/07/2014		10/27/2014 - 10/27/2014
DWR Inspector	Maksim Khashchuk		Maksim Khashchuk
Accompanied By			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.08</b>	Rating **	U	Issue No.	<b>4</b>
LM End	<b>0.08</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.807375 °	37.807375 °	
			-121.408605 °	-121.408605 °	
DWR ID	DWR_RD2089_02_s_2012_4				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Thick brush may include some elderberries. 05/24/2011 updated photo.					

Photo 1 of 2 : FA\_2014\_RD2089\_317\_4\_20141001\_00003.jpg



05/24/2011 Updated photo of issue noted in Fall 2010 inspection.

LM Start	<b>0.08</b>	Rating **	U	Issue No.	<b>4 (cont)</b>
LM End	<b>0.08</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA\_2014\_RD2089\_317\_4\_20141001\_00004.jpg



Fall 2009 photo of unacceptable vegetation on levee slope.

LM Start	<b>0.10</b>	Rating **	M	Issue No.	<b>19</b>
LM End	<b>0.10</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.807486 °	37.807486 °	
			-121.408791 °	-121.408791 °	
DWR ID	DWR_RD2089_02_s_2013_19				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Vegetation on the levee slope and toe is partially obstructive.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_19\_20141001\_00015.jpg



View of the vegetation on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.18</b>	Rating **	U	Issue No.	<b>48</b>
LM End	<b>0.18</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.808583 °	37.808583 °
				-121.409432 °	-121.409432 °
DWR ID	DWR_RD2089_02_f_2013_48				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_48\_20141001\_00025.jpg



View of the rodent burrow on the landside levee slope.

LM Start	<b>0.21</b>	Rating **	M	Issue No.	<b>49</b>
LM End	<b>0.21</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.809148 °	37.809148 °
				-121.409897 °	-121.409897 °
DWR ID	DWR_RD2089_02_f_2013_49				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_49\_20141001\_00026.jpg



View of the multiple rodent burrows on the landside levee hinge and slope.

LM Start	<b>0.28</b>	Rating **	M	Issue No.	<b>24</b>
LM End	<b>0.28</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.809717 °	37.809717 °
				-121.410511 °	-121.410511 °
DWR ID	DWR_RD2089_02_s_2012_24				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Ground squirrel sighted and active borrowing in area.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_24\_20141001\_00017.jpg



05/24/2011 Active burrows, ground squirrel sighted in area.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.30</b>	Rating **	M	Issue No.	<b>52</b>
LM End	<b>0.32</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.809899 °	37.809997 °	
			-121.410888 °	-121.411298 °	
DWR ID	DWR_RD2089_02_f_2013_52				
Action/Comments					
Prunings Inspector Comments: Remove prunings and other debris from the levee toe.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_52\_20141027\_00040.jpg



View of the tree branches on the landside levee toe obstructing access.

LM Start	<b>0.30</b>	Rating **	U	Issue No.	<b>51</b>
LM End	<b>0.30</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.809899 °	37.809899 °	
			-121.410889 °	-121.410889 °	
DWR ID	DWR_RD2089_02_f_2013_51				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_51\_20141001\_00027.jpg



View of the rodent burrow on the landside levee toe.

LM Start	<b>0.32</b>	Rating **	U	Issue No.	<b>53</b>
LM End	<b>0.33</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.809977 °	37.810022 °	
			-121.411189 °	-121.411387 °	
DWR ID	DWR_RD2089_02_f_2013_53				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Exterminating rodents and grouting the burrows recommended.					

Photo 1 of 3 : FA\_2014\_RD2089\_317\_53\_20141001\_00029.jpg



View of the multiple rodent burrows on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> <b>C : Corrected</b> <b>A/W : Acceptable but Monitor &amp; Maintain</b>	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.32</b>	Rating **	U	Issue No.	<b>53 (cont)</b>
LM End	<b>0.33</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.809977 °	37.810022 °	
			-121.411189 °	-121.411387 °	
DWR ID	DWR_RD2089_02_f_2013_53				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Exterminating rodents and grouting the burrows recommended.					

Photo 2 of 3 : FA\_2014\_RD2089\_317\_53\_20141001\_00030.jpg



View of the rodent burrow on the landside levee slope.

LM Start	<b>0.32</b>	Rating **	U	Issue No.	<b>53 (cont)</b>
LM End	<b>0.33</b>	Issue Type +	Ma	Location *	N/A

Photo 3 of 3 : FA\_2014\_RD2089\_317\_53\_20141001\_00031.jpg



Another view of the multiple rodent burrows on the landside levee slope.

LM Start	<b>0.37</b>	Rating **	A/W	Issue No.	<b>2</b>
LM End	<b>0.37</b>	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.810106 °	37.810106 °	
			-121.412133 °	-121.412133 °	
DWR ID	DWR_RD2089_02_s_2012_2				
Action/Comments					
Fence Inspector Comments: Gates across levee.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_2\_20141001\_00002.jpg



View of gate across levee crown.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.38</b>	Rating **	M	Issue No.	<b>26</b>
LM End	<b>0.38</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.810125 °	37.810125 °	
			-121.412317 °	-121.412317 °	
DWR ID	DWR_RD2089_02_s_2012_26				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Active burrow needs to be repaired.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_26\_20141001\_00018.jpg



05/24/2011 Active rodent burrow.

LM Start	<b>0.40</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>0.66</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.810109 °	37.812395 °	
			-121.412619 °	-121.415813 °	
DWR ID	DWR_RD2089_02_s_2012_8				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Tobacco leaf and other brush block access and visibility.					

Photo 1 of 2 : FA\_2014\_RD2089\_317\_8\_20141001\_00008.jpg



Brush on landside slope limits access.

LM Start	<b>0.40</b>	Rating **	M	Issue No.	<b>8 (cont)</b>
LM End	<b>0.66</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA\_2014\_RD2089\_317\_8\_20141001\_00009.jpg



Fall 2009 photo: Brush on landside toe limits visibility and accessibility.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.42</b>	Rating **	M	Issue No.	<b>1</b>
LM End	<b>0.43</b>	Issue Type +	Ma	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR Erosion Survey		37.809960 °	37.809960 °	
			-121.413200 °	-121.413200 °	
DWR ID					
Action/Comments					
Inspector Comments: 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed. 08/23/2011: No significant change observed on site. 09/07/2010: Site consists of a jutting rip rap that has created an eddy,					

Photo 1 of 1 : SJR2014\_RD2089U02RM28.35\_1.jpg



View of the site from the survey boat.

LM Start	<b>0.46</b>	Rating **	M	Issue No.	<b>27</b>
LM End	<b>0.46</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.810490 °	37.810490 °	
			-121.413638 °	-121.413638 °	
DWR ID	DWR_RD2089_02_s_2012_27				
Action/Comments					
Building Inspector Comments: Portable toilet on bank, at water's edge.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_27\_20141001\_00019.jpg



05/24/2011 Portable toilet is in the shadows in the center of the photo at the water's edge.

LM Start	<b>0.49</b>	Rating **	M	Issue No.	<b>13</b>
LM End	<b>0.49</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.810691 °	37.810691 °	
			-121.414014 °	-121.414014 °	
DWR ID	DWR_RD2089_02_s_2012_13				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Two old burrows that need to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_13\_20141001\_00012.jpg



11/10/2011 Two large burrows on crown, need to be filled.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.49</b>	Rating **	M	Issue No.	<b>10</b>
LM End	<b>0.49</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.810714 °	37.810714 °	
			-121.414057 °	-121.414057 °	
DWR ID	DWR_RD2089_02_s_2012_10				
Action/Comments					
Add appropriate gravel or road base. Grade and compact. Inspector Comments: Surface depression needs to be filled.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_10\_20141001\_00011.jpg



11/10/2011 Depression in crown needs to be filled.

LM Start	<b>0.52</b>	Rating **	U	Issue No.	<b>54</b>
LM End	<b>0.52</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.810989 °	37.810989 °	
			-121.414517 °	-121.414517 °	
DWR ID	DWR_RD2089_02_f_2013_54				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					


Photo 1 of 1 : FA\_2014\_RD2089\_317\_54\_20141001\_00032.jpg



View of the rodent burrow on the landside levee slope.

LM Start	<b>0.54</b>	Rating **	U	Issue No.	<b>14</b>
LM End	<b>0.54</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.811150 °	37.811150 °	
			-121.414748 °	-121.414748 °	
DWR ID	DWR_RD2089_02_s_2012_14				
Action/Comments					
Repair the levee slope damaged by livestock and prevent large animal access. Inspector Comments: 11/10/2011 Repair damage to slope caused by livestock.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_14\_20141001\_00013.jpg



11/10/2011 Approximately 1' scarp has been created by livestock travel.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> <b>C : Corrected</b> <b>A/W : Acceptable but Monitor &amp; Maintain</b>	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.56</b>	Rating **	M	Issue No.	<b>3</b>
LM End	<b>0.56</b>	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.811369 °	37.811369 °	
			-121.415050 °	-121.415050 °	
DWR ID	DWR_RD2089_02_f_2014_3				
Action/Comments					
Inspector Comments: FS_ID:21676 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - air relief valve on waterside. Needs repair. concrete standpipe on landside. FIELD_STRUCT_DESC: 14-inch pipe through the levee, 8.0 feet below the crown, pump on pile structure in the stream. Air relief valve on the waterside slope. Timber walkway to the pump. Concrete distribution standpipe on landside toe. Originally included in O+M (1968) FS Date: 9/12/2013					

No Photos

LM Start	<b>0.79</b>	Rating **	M	Issue No.	<b>15</b>
LM End	<b>0.79</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		37.813969 °	37.813969 °	
			-121.414324 °	-121.414324 °	
DWR ID	DWR_RD2089_02_f_2014_15				
Action/Comments					
Repair slope instability.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_15\_20141027\_00039.jpg



View of the scour from surface runoff on the landside levee slope.

LM Start	<b>0.82</b>	Rating **	U	Issue No.	<b>36</b>
LM End	<b>0.86</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.814421 °	37.814913 °	
			-121.414203 °	-121.414594 °	
DWR ID	DWR_RD2089_02_s_2012_36				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild growth and dead underbrush prevents visibility of levee slope and area cannot be accessed if needed for a flood fight.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_36\_20141001\_00021.jpg



Extremely thick dead brush prevents access and visibility.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.85</b>	Rating **	M	Issue No.	<b>21</b>
LM End	<b>0.85</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.814773 °	37.814773 °	
			-121.414555 °	-121.414555 °	
DWR ID	DWR_RD2089_02_s_2012_21				
Action/Comments					
Repair the levee slope damaged by livestock and prevent large animal access. Inspector Comments: Livestock have worn paths into levee slope.					

No Photos

LM Start	<b>0.85</b>	Rating **	M	Issue No.	<b>38</b>
LM End	<b>0.85</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.814844 °	37.814844 °	
			-121.414566 °	-121.414566 °	
DWR ID	DWR_RD2089_02_s_2012_38				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Active burrows present.					

No Photos

LM Start	<b>0.86</b>	Rating **	M	Issue No.	<b>25</b>
LM End	<b>0.86</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.814906 °	37.814906 °	
			-121.414745 °	-121.414745 °	
DWR ID	DWR_RD2089_02_s_2012_25				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry and blackberry on levee slope.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.86</b>	Rating **	A/W	Issue No.	<b>9</b>
LM End	<b>0.86</b>	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.814881 °	37.814881 °	
			-121.414676 °	-121.414676 °	
DWR ID	DWR_RD2089_02_s_2012_9				
Action/Comments					
Fence Inspector Comments: Gate across levee crown.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_9\_20141001\_00010.jpg



View of the fence gate across levee crown.

LM Start	<b>0.87</b>	Rating **	U	Issue No.	<b>40</b>
LM End	<b>0.92</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.814997 °	37.814970 °	
			-121.414774 °	-121.415767 °	
DWR ID	DWR_RD2089_02_s_2012_40				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Numerous burrows on landside slope adjacent to hay storage area. Deep burrows in crown and landside ramp.					

Photo 1 of 2 : FA\_2014\_RD2089\_317\_40\_20141001\_00022.jpg



05/24/2011 Deep vertical burrow in ramp on land side of levee.

LM Start	<b>0.87</b>	Rating **	U	Issue No.	<b>40 (cont)</b>
LM End	<b>0.92</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA\_2014\_RD2089\_317\_40\_20141001\_00023.jpg



05/24/2011 Deep vertical burrow in levee crown.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>0.95</b>	Rating **	M	Issue No.	<b>41</b>
LM End	<b>0.95</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.814940 °	37.814940 °	
			-121.416499 °	-121.416499 °	
DWR ID	DWR_RD2089_02_s_2012_41				
Action/Comments					
Pipe Inspector Comments: Debris/CMP on levee slope needs to be removed.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_41\_20141001\_00024.jpg



05/24/2011 Old CMP left on waterside levee slope, needs to be removed.

LM Start	<b>0.97</b>	Rating **	U	Issue No.	<b>5</b>
LM End	<b>0.97</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.814915 °	37.814915 °	
			-121.416606 °	-121.416606 °	
DWR ID	DWR_RD2089_02_s_2014_5				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_5\_20141001\_00005.jpg



View of the rodent holes on the landside levee slope.

LM Start	<b>1.02</b>	Rating **	U	Issue No.	<b>12</b>
LM End	<b>1.02</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.815182 °	37.815182 °	
			-121.417439 °	-121.417439 °	
DWR ID	DWR_RD2089_02_f_2014_12				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 2 : FA\_2014\_RD2089\_317\_12\_20141027\_00037.jpg



View of several large rodent holes on the levee crown.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.02</b>	Rating **	U	Issue No.	<b>12 (cont)</b>
LM End	<b>1.02</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.815182 °	37.815182 °	
			-121.417439 °	-121.417439 °	
DWR ID	DWR_RD2089_02_f_2014_12				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 2 of 2 : FA\_2014\_RD2089\_317\_12\_20141027\_00038.jpg



View of several rodent burrows on landside levee hinge and crown.

LM Start	<b>1.07</b>	Rating **	N	Issue No.	<b>29</b>
LM End	<b>1.07</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		37.815629 °	37.815629 °	
			-121.418133 °	-121.418133 °	
DWR ID	DWR_RD2089_02_s_2012_29				
Action/Comments					
Tree stumps. Inspector Comments: 14" dia stump. Could not verify as the area is overgrown with high weeds.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_29\_20141001\_00020.jpg



Tree stump >2" left after vegetation and tree removal.

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>1.10</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.816100 °	37.816100 °	
			-121.418487 °	-121.418487 °	
DWR ID	DWR_RD2089_02_s_2012_17				
Action/Comments					
Debris Inspector Comments: Water tanks disposed of on levee are obstructive.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_17\_20141001\_00014.jpg



View of water tanks disposed on waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>+</b> Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.15</b>	Rating **	M	Issue No.	<b>30</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.816487 °	37.816487 °	
			-121.418948 °	-121.418948 °	
DWR ID	DWR_RD2089_02_s_2012_30				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	<b>1.20</b>	Rating **	M	Issue No.	<b>6</b>
LM End	<b>1.20</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.817271 °	37.817271 °	
			-121.419380 °	-121.419380 °	
DWR ID	DWR_RD2089_02_s_2014_6				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_6\_20141001\_00006.jpg



View of the large rodent hole on the landside levee slope.

LM Start	<b>1.24</b>	Rating **	M	Issue No.	<b>7</b>
LM End	<b>1.24</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.817796 °	37.817796 °	
			-121.419650 °	-121.419650 °	
DWR ID	DWR_RD2089_02_s_2014_7				
Action/Comments					
Crops Inspector Comments: Animal feed stored at the landside levee toe.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_7\_20141027\_00036.jpg



View of the animal feed stockpiled at the landside levee toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> <b>C : Corrected</b> <b>A/W : Acceptable but Monitor &amp; Maintain</b>	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.26</b>	Rating **	M	Issue No.	<b>31</b>
LM End	<b>1.26</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.818051 °	37.818051 °	
			-121.419743 °	-121.419743 °	
DWR ID	DWR_RD2089_02_s_2012_31				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	<b>1.28</b>	Rating **	U	Issue No.	<b>23</b>
LM End	<b>1.33</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.818277 °	37.819040 °	
			-121.419725 °	-121.419760 °	
DWR ID	DWR_RD2089_02_s_2012_23				
Action/Comments					
Building Inspector Comments: Buildings and equipment encroach within 10-ft of landside toe. The boat was removed.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_23\_20141001\_00016.jpg



Fall 2009 photo: Buildings and patio decks are built within 10-ft of the levee slope.

LM Start	<b>1.29</b>	Rating **	M	Issue No.	<b>57</b>
LM End	<b>1.29</b>	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.818499 °	37.818499 °	
			-121.419754 °	-121.419754 °	
DWR ID	DWR_RD2089_02_f_2013_57				
Action/Comments					
Landscaping Inspector Comments: Remove cactus from levee crown.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_57\_20141027\_00035.jpg



View of the cactus on the landside levee shoulder.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2089 Stark**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Salmon Slough	Right	1.35	10/27/2014 10/27/2014	Maksim Khashchuk

LM Start	<b>1.32</b>	Rating **	M	Issue No.	<b>32</b>
LM End	<b>1.32</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.818829 °	37.818829 °	
			-121.419776 °	-121.419776 °	
DWR ID	DWR_RD2089_02_s_2012_32				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	<b>1.35</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>1.35</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.819371 °	37.819371 °	
			-121.419774 °	-121.419774 °	
DWR ID	DWR_RD2089_02_f_2014_11				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2089\_317\_11\_20141027\_00034.jpg



View of the multiple rodent burrows on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---