

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2015 Levee Inspection Results**

**Reclamation District No. 2092 Dos Rios**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2015 Levee Inspection Results**

**Reclamation District No. 2092 Dos Rios**

Waterway		Bank	Unit Miles
Unit No. 01 San Joaquin River		Right	3.71

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/02/2015 - 04/02/2015			
DWR Inspector	Pavel Kazi			
Accompanied By	Stuart Mattos			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>18</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training		o	o	
DWR ID	DWR_RD2092_01_f_2012_18				
Action/Comments					
Inspector Comments: River Partner crews will attend the upcoming flood fighting class offered in their area. A few members of the company have already been through a few flood events and received proper training.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>24</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals		o	o	
DWR ID	DWR_RD2092_01_s_2012_24				
Action/Comments					
Inspector Comments: They have the latest O&M manual for their district.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>26</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment		o	o	
DWR ID	DWR_RD2092_01_s_2012_26				
Action/Comments					
Inspector Comments: LMA has adequate flood fighting supplies.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>0.18</b>	Rating **	M	Issue No.	<b>1</b>
LM End	<b>0.18</b>	Issue Type +	En	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.602031 °	37.602031 °
				-121.161249 °	-121.161249 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:27123 DS_ID:20561 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe rusted through at headwall on LS toe. Good candidate for video inspection. FIELD_STRUCT_DESC: 60-inch corrugated metal drainpipe through levee 19.0 feet below crown. Flap gate on the waterward end. Slide gate in 80-inch corrugated metal pipe riser on the waterward slope. Concrete "U" headwalls on both ends. Originally included in the 1961 O&M manual. FS Date: 01/16/2014					

No Photos

LM Start	<b>0.19</b>	Rating **	M	Issue No.	<b>3</b>
LM End	<b>0.19</b>	Issue Type +	En	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.601978 °	37.601978 °
				-121.161370 °	-121.161370 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:20886 DS_ID:20573 EP_NO: 4699 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Appears abandoned and should be verified as having been removed from levee. FIELD_STRUCT_DESC: *Abandoned* 12-inch steel pipe over the levee with 3.5 feet of fill on top. Siphon breakers on waterward shoulder. Pad constructed over pipes. This pumping plant was constructed in 1969 during emergency conditions without a permit. 12-inch pipe debris on WS berm at WS toe. FS Date: 09/24/2013					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>0.19</b>	Rating **	M	Issue No.	<b>4</b>
LM End	<b>0.19</b>	Issue Type +	En	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.601976 °	37.601976 °
				-121.161395 °	-121.161395 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:20885 DS_ID:20579 EP_NO: 6254 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Verify pipe has been removed from levee. Pipe visible on WS at riverbank. FIELD_STRUCT_DESC: *Abandoned* 16-inch steel pipe over the levee with 3.5 feet of fill on top. Siphon breakers on waterward shoulder. Pad constructed over pipes. This pumping plant was constructed in 1969 during emergency conditions without a permit (Permit No. 6254, 1968). FS Date: 09/24/2013					

No Photos

LM Start	<b>0.42</b>	Rating **	M	Issue No.	<b>28</b>
LM End	<b>0.42</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.601207 °	37.601207 °
				-121.165508 °	-121.165508 °
DWR ID	DWR_RD2092_01_f_2014_28				
Action/Comments					
Pole					

No Photos

LM Start	<b>0.44</b>	Rating **	M	Issue No.	<b>27</b>
LM End	<b>0.44</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.601161 °	37.601161 °
				-121.165805 °	-121.165805 °
DWR ID	DWR_RD2092_01_f_2014_27				
Action/Comments					
Pole					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>0.44</b>	Rating **	A	Issue No.	<b>14</b>
LM End	<b>0.44</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.601192 °	37.601192 °	
			-121.165838 °	-121.165838 °	
DWR ID	DWR_RD2092_01_s_2015_14				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_14\_20150406\_00015.jpg



View of the landside slope of the levee looking upstream during spring 2015 inspection.

LM Start	<b>0.76</b>	Rating **	M	Issue No.	<b>968</b>
LM End	<b>1.31</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.597291 °	37.590568 °	
			-121.168496 °	-121.164028 °	
DWR ID	DWR_RD2092_01_s_2012_968				
Action/Comments					
Ditch					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_968\_20150313\_00006.jpg



View of agricultural ditch at the landward toe looking upstream.

LM Start	<b>1.32</b>	Rating **	M	Issue No.	<b>7</b>
LM End	<b>1.55</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.590479 °	37.587758 °	
			-121.163844 °	-121.162349 °	
DWR ID	DWR_RD2092_01_s_2012_7				
Action/Comments					
Ditch					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_7\_20150313\_00001.jpg



An agricultural ditch was found on the toe of the landside of the levee looking upstream.

<b>* Location</b> LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>1.32</b>	Rating **	A/W	Issue No.	<b>10</b>
LM End	<b>1.32</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.590467 °	37.590467 °
				-121.163822 °	-121.163822 °
DWR ID	DWR_RD2092_01_s_2012_10				
Action/Comments					
Pipe Inspector Comments: A sand boil appeared on the landside toe of the levee because of an underground pipe leakage. The pipe and boil have been repaired but should be monitored.					

Photo 1 of 2 : SP\_2015\_RD2092\_116\_10\_20150313\_00003.jpg



During spring inspection 2012, the sand boil was not active but materials were present on the landside toe of the levee. The sand boil occurred due to an underground irrigation pipe leakage. The picture was taken from the crown looking toward the toe of the levee. The area was repaired but should be monitored.

LM Start	<b>1.32</b>	Rating **	A/W	Issue No.	<b>10 (cont)</b>
LM End	<b>1.32</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2015\_RD2092\_116\_10\_20150313\_00004.jpg



A sand boil was found on the landside of the levee. It was caused by a pipe leak couple of feet below the boil location. LMA was notified to repair it as soon as possible. The picture was taken from the crown looking upstream.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>1.56</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>1.84</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.587575 °	37.584057 °	
			-121.162454 °	-121.162387 °	
DWR ID	DWR_RD2092_01_s_2012_8				
Action/Comments					
Ditch					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_8\_20150313\_00002.jpg



View of an agricultural ditch at the waterward toe of the slope.

LM Start	<b>1.65</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>1.65</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.586362 °	37.586362 °	
			-121.163202 °	-121.163202 °	
DWR ID	DWR_RD2092_01_s_2015_17				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	<b>2.37</b>	Rating **	M	Issue No.	<b>20</b>
LM End	<b>2.37</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.580821 °	37.580821 °	
			-121.156468 °	-121.156468 °	
DWR ID	DWR_RD2092_01_f_2014_20				
Action/Comments					
Pole					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>2.40</b>	Rating **	M	Issue No.	<b>53</b>
LM End	<b>2.40</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.580436 °	37.580436 °
				-121.156783 °	-121.156783 °
DWR ID	DWR_RD2092_01_s_2014_53				
Action/Comments					
Pipe Inspector Comments: Pump and abandoned pipe was found.					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_53\_20150313\_00005.jpg



A pump and an abandon pipe was found on the landside toe of the levee looking downstream.

LM Start	<b>2.44</b>	Rating **	M	Issue No.	<b>9</b>
LM End	<b>2.44</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.580426 °	37.580426 °
				-121.156798 °	-121.156798 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:20943 DS_ID:20567 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: 24-inch corrugated metal drain pipe through levee 15.0 feet below crown. Flap gate on the waterward end. Concrete "U" headwall on the waterward end and concrete headwall on LS toe next to pump. Originally included in the 1961 O&M manual. FS Date: 09/24/2013					

No Photos

<b>* Location</b> LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>2.44</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>2.44</b>	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.580405 °	37.580405 °
				-121.156825 °	-121.156825 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:20923 DS_ID:20568 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Pipe abandoned and should be verified as having been removed from the levee. FIELD_STRUCT_DESC: 4-inch pipe through levee 1.0 foot below crown. Pump on sump at LS toe. Roadway extending to the landward pump. FS Date: 09/24/2013					

No Photos

LM Start	<b>2.55</b>	Rating **	M	Issue No.	<b>21</b>
LM End	<b>2.55</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.578311 °	37.578311 °
				-121.157012 °	-121.157012 °
DWR ID	DWR_RD2092_01_f_2014_21				
Action/Comments					
Pole					

No Photos

LM Start	<b>2.61</b>	Rating **	M	Issue No.	<b>22</b>
LM End	<b>2.61</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.577387 °	37.577387 °
				-121.157133 °	-121.157133 °
DWR ID	DWR_RD2092_01_f_2014_22				
Action/Comments					
Pole					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>2.69</b>	Rating **	M	Issue No.	<b>23</b>
LM End	<b>2.69</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.576363 °	37.576363 °	
			-121.157212 °	-121.157212 °	
DWR ID	DWR_RD2092_01_f_2014_23				
Action/Comments					
Pole					

No Photos

LM Start	<b>2.70</b>	Rating **	M	Issue No.	<b>19</b>
LM End	<b>2.70</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		37.576165 °	37.576165 °	
			-121.157230 °	-121.157230 °	
DWR ID	DWR_RD2092_01_s_2015_19				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_19\_20150406\_00016.jpg



A rodent hole was found on the landside toe of the levee looking downstream.

LM Start	<b>2.72</b>	Rating **	M	Issue No.	<b>25</b>
LM End	<b>2.72</b>	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.575923 °	37.575923 °	
			-121.157228 °	-121.157228 °	
DWR ID	DWR_RD2092_01_f_2014_25				
Action/Comments					
Pole					

No Photos

<b>* Location</b> LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>2.79</b>	Rating **	M	Issue No.	<b>972</b>
LM End	<b>3.05</b>	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		37.574973 °	37.574001 °	
			-121.156647 °	-121.152183 °	
DWR ID	DWR_RD2092_01_s_2012_972				
Action/Comments					
Fence Inspector Comments: Barbed wire fence on waterside toe of the levee.					

Photo 1 of 1 : SP\_2015\_RD2092\_116\_972\_20150313\_00007.jpg



View of barbed wire fence along the waterward slope looking upstream.

LM Start	<b>2.90</b>	Rating **	M	Issue No.	<b>12</b>
LM End	<b>2.90</b>	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		37.574741 °	37.574741 °	
			-121.155495 °	-121.155495 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:20944 DS_ID:20570 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Appears abandoned and if so, should be done so properly. FIELD_STRUCT_DESC: 24-inch corrugated metal pipe through levee 6.5 feet below crown. Concrete "U" headwall and flap gate on the waterward end. Concrete headwall on LS slope. Originally included in the 1961 O&M manual. FS Date: 09/24/2013					

No Photos

<b>* Location</b> LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2092 Dos Rios**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.71	04/02/2015 04/02/2015	Pavel Kazi

LM Start	<b>3.52</b>	Rating **	M	Issue No.	<b>13</b>
LM End	<b>3.52</b>	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.573304 °	37.573304 °
				-121.144747 °	-121.144747 °
DWR ID					
<b>Action/Comments</b>					
Inspector Comments: FS_ID:20945 DS_ID:20572 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe appears abandoned and if so, should be done so properly. FIELD_STRUCT_DESC: 36-inch corrugated metal pipe through levee 11.0 feet below crown. Slide gate in corrugated metal pipe riser on the waterward slope. Concrete headwalls on both ends. Originally included in the 1961 O&M manual. FS Date: 09/24/2013					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---