

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD2098_01_f_2014_3				
Comment Code					
Inspector Comment					
RD 2098 has on file O+M Manual.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD2098_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 2098 has emergency supplies in storage along with equipment.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD2098_01_f_2014_5				
Comment Code					
Inspector Comment					
RD 2098 has their team well prepared for a flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	0.01	Rating **	M	Issue No.	11
LM End	3.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.328885 °	38.282482 °	
			-121.694061 °	-121.693922 °	
DWR ID	DWR_RD2098_01_s_2022_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.01	Rating **	M	Issue No.	24
LM End	3.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.328884 °	38.284936 °	
			-121.694061 °	-121.693630 °	
DWR ID	DWR_RD2098_01_s_2022_24				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.57	Rating **	M	Issue No.	13
LM End	1.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.320755 °	38.313700 °	
			-121.693982 °	-121.693639 °	
DWR ID	DWR_RD2098_01_s_2017_13				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
There is erosion on the waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	0.96	Rating **	A/W	Issue No.	19
LM End	0.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.315200 °	38.315100 °
				-121.694100 °	-121.694100 °
DWR ID	DWR_RD2098_01_s_2021_19				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of cracking and sloughing of the lower landside levee slope. Site ID No:414 Site Designation:LMA-241 4/24/2020 Field Notes: Vegetation is to thick to see. Verify in fall when vegetation less.					

Photo 1 of 1 : LEVAL_SP_2022_414_3596.jpg



LM Start	1.76	Rating **	M	Issue No.	18
LM End	1.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.303611 °	38.303611 °
				-121.693607 °	-121.693607 °
DWR ID	DWR_RD2098_01_s_2018_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
There is erosion at the waterside toe.					

Photo 1 of 1 : SP_2022_RD2098_244_18_20220310_00003.jpg



View of erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	1.82	Rating **	M	Issue No.	1	
LM End	1.82	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.302770 °	38.302770 °	
				-121.693640 °	-121.693640 °	
DWR ID	20965					
Comment Code						
Inspector Comment						
FS_ID:32197 DS_ID:20965 EP_NO: 10168 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/22/2016 Met with Mike Hadesty, LMA Superintendent, and Brian Bush, LMA General Manager, to go over the list of pipes in RD2098. Per LMA records, this pipe has a different owner. (O. Magana - DWR UCIP) 03/18/2014 Erosion under pipe at WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 10-inch steel drainage pipe through the levee, 2.8 feet below the crown. Pump in pump house off the landside (LS). (This pipe was retained under Automatic Board Order (ABO) issued as Permit No. 10168, 1974 - Moresco Brothers). [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 1.80)]. FS Date: 3/18/2014						

LM Start	1.82	Rating **	M	Issue No.	1 (cont)
LM End	1.82	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2022_32197_58662.jpg



Pipe on WS slope.

Photo 2 of 3 : UCIP_SP_2022_32197_58661.jpg



Pumphouse at lowpoint off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	1.82	Rating **	M	Issue No.	1 (cont)
LM End	1.82	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.302770 °	38.302770 °	
			-121.693640 °	-121.693640 °	
DWR ID	20965				

Photo 3 of 3 : UCIP_SP_2022_32197_58660.jpg



Erosion under pipe at WS toe.

LM Start	2.20	Rating **	A/W	Issue No.	15
LM End	2.24	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2018 USACE Erosion Survey			38.297232 °	38.296678 °
				-121.693200 °	-121.693223 °
DWR ID	DWR_RD2098_01_s_2022_15				
Comment Code					
Inspector Comment					
2018 Site ID: YOL 2.2 R					
Status: Eroding					
2018 Field Notes: Last observed in 2017.					
Site History: POTENTIALLY UNDER REPAIR; full landslide from levee crown down, revetment failure , additional slumping ds and slump cracks observed.					

No Photos

LM Start	2.29	Rating **	U	Issue No.	27
LM End	2.32	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.295900 °	38.295468 °
				-121.693500 °	-121.693619 °
DWR ID	LMA-248				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour and sloughing of the waterside levee slope. Site ID No:421 Site Designation:LMA-248					

Photo 1 of 1 : SP_2022_RD2098_244_27_20220310_00006.jpg



View looking upstream at erosion in the waterside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	2.35	Rating **	U	Issue No.	28
LM End	2.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.295100 °	38.294500 °
				-121.693400 °	-121.693400 °
DWR ID	LMA-250				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour, sloughing, and cracking of the lower and mid waterside levee slope. Site ID No:423 Site Designation:LMA-250					

Photo 1 of 1 : SP_2022_RD2098_244_28_20220310_00007.jpg



View looking upstream at erosion into the waterside slope (Spring 2020).

LM Start	2.75	Rating **	U	Issue No.	34
LM End	2.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.289200 °	38.288405 °
				-121.693500 °	-121.693617 °
DWR ID	LMA-256				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour and sloughing of the waterside levee slope. Site ID No:429 & 430 Site Designation:LMA-256, LMA-257					

Photo 1 of 1 : SP_2022_RD2098_244_34_20220310_00008.jpg



View looking downstream at erosion into the waterside slope (Spring 2020).

LM Start	2.91	Rating **	U	Issue No.	36
LM End	2.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.286900 °	38.286700 °
				-121.693500 °	-121.693500 °
DWR ID	LMA-258				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour and sloughing of the waterside levee slope. Site ID No:431 Site Designation:LMA-258					

Photo 1 of 1 : SP_2022_RD2098_244_36_20220310_00009.jpg



View looking upstream at erosion into the waterside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	2.99	Rating **	M	Issue No.	37
LM End	3.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.285700 °	38.281500 °
				-121.693500 °	-121.694300 °
DWR ID	LMA-259				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour and sloughing of the waterside levee slope. Site ID No:432 Site Designation:LMA-259					

Photo 1 of 1 : SP_2022_RD2098_244_37_20220310_00010.jpg



View of erosion on the waterside slope. Photo was taken in 2017.

LM Start	3.13	Rating **	M	Issue No.	20
LM End	3.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.283800 °	38.283800 °
				-121.693618 °	-121.693618 °
DWR ID	DWR_RD2098_01_s_2020_20				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_244_20_20220310_00005.jpg



View of tree limb on the landside slope (Fall 2020).

LM Start	3.23	Rating **	U	Issue No.	22
LM End	3.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.282395 °	38.277577 °
				-121.693982 °	-121.696227 °
DWR ID	DWR_RD2098_01_s_2022_22				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_244_22_20220318_00033.jpg



View looking upstream at vegetation on the landside slope (Spring 2022).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	03/18/2022 03/18/2022	David Julian

LM Start	3.23	Rating **	U	Issue No.	23
LM End	3.59	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.282389 °	38.277577 °
				-121.693987 °	-121.696227 °
DWR ID	DWR_RD2098_01_s _ 2022_23				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_244_23_20220318_00032.jpg



View looking upstream at vegetation on the waterside slope (Spring 2022).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01A Cross Levee	Right	0.53	03/18/2022 03/18/2022	David Julian

LM Start	0.01	Rating **	M	Issue No.	1
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.277392 °	38.275739 °	
			-121.696396 °	-121.705456 °	
DWR ID	DWR_RD2098_01A_f_2021_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_245_1_20220318_00001.jpg



View looking downstream at vegetation on the landside slope (Spring 2022).

LM Start	0.01	Rating **	M	Issue No.	2
LM End	0.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.277392 °	38.275721 °	
			-121.696396 °	-121.705517 °	
DWR ID	DWR_RD2098_01A_s_2022_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_245_2_20220318_00002.jpg



View looking downstream at vegetation on the waterside slope (Spring 2022).

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	5.31	Rating **	U	Issue No.	8
LM End	7.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275898 °	38.292985 °
				-121.705914 °	-121.723733 °
DWR ID	DWR_RD2098_02_s_2022_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_246_8_20220318_00027.jpg



View looking downstream at vegetation on the waterside slope (Spring 2022).

LM Start	5.31	Rating **	U	Issue No.	7
LM End	7.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275898 °	38.292986 °
				-121.705914 °	-121.723733 °
DWR ID	DWR_RD2098_02_f_2021_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_246_7_20220318_00026.jpg



View looking downstream at vegetation on the landside slope (Spring 2022).

LM Start	5.88	Rating **	U	Issue No.	11
LM End	5.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.282946 °	38.282946 °
				-121.710902 °	-121.710902 °
DWR ID	DWR_RD2098_02_f_2020_11				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This waterside slump site is not new, and is somewhat protected by riprap and thick brushy vegetation, but it has the potential to erode into crown during high water with a strong south wind. It currently has a two-foot vertical scarp at the levee shoulder.					

Photo 1 of 1 : SP_2022_RD2098_246_11_20220310_00004.jpg



View looking upstream at erosion into waterside slope (Fall 2020).

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	6.46	Rating **	U	Issue No.	15
LM End	6.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.288700 °	38.289061 °
				-121.717000 °	-121.716885 °
DWR ID	LMA-267				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour of the lower and mid waterside levee slope. Site ID No:440 & 441 Site Designation:LMA-267 & LMA-268					

Photo 1 of 1 : SP_2022_RD2098_246_15_20220310_00006.jpg



View looking upstream at erosion into the waterside slope (Fall 2020).

LM Start	6.64	Rating **	U	Issue No.	18
LM End	6.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.291300 °	38.291400 °
				-121.716100 °	-121.716000 °
DWR ID	LMA-269				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour, cracking, instability, and sloughing of the waterside levee slope. Site ID No:442 Site Designation:LMA-269					

Photo 1 of 1 : SP_2022_RD2098_246_18_20220310_00007.jpg



View looking upstream at erosion into the waterside slope (Fall 2020).

LM Start	6.68	Rating **	U	Issue No.	9
LM End	6.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.291779 °	38.291779 °
				-121.715727 °	-121.715727 °
DWR ID	DWR_RD2098_02_s_2022_9				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove tree prunings on the landside shoulder.					

Photo 1 of 1 : SP_2022_RD2098_246_9_20220318_00025.jpg



View of cut up tree limbs on the landside shoulder (Spring 2022).

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	6.71	Rating **	M	Issue No.	2	
LM End	6.71	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.292194 °	38.292194 °	
				-121.715853 °	-121.715853 °	
DWR ID	20976					
Comment Code						
Inspector Comment						
FS_ID:33784 DS_ID:20976 EP_NO: 10172 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 03/18/2014 Headwalls on WS toe failing at outlet. It is unclear if these were permanent installations or something that was installed as a temporary fix. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 1 of 2: 48-inch corrugated metal drainage pipe through the levee, 29 feet below the crown. Two slide gates in a 7-foot-diameter corrugated metal pipe (CMP) riser on the waterside (WS) slope. (two 48-inch [HLM 6.75] authorized under Automatic Board Order (ABO) issued as Permit No. 10172, 1974 - Moresco Brothers). [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 6.75)]. FS Date: 3/18/2014						

LM Start	6.71	Rating **	M	Issue No.	2 (cont)
LM End	6.71	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2022_33784_61162.jpg



Two slide gates in 7-foot diameter CMP riser on waterward slope.

Photo 2 of 3 : UCIP_SP_2022_33784_61161.jpg



Inlet not visible on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	6.71	Rating **	M	Issue No.	2 (cont)
LM End	6.71	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.292194 °	38.292194 °	
			-121.715853 °	-121.715853 °	
DWR ID	20976				

Photo 3 of 3 : UCIP_SP_2022_33784_61160.jpg



View inside CMP riser on WS shoulder.

LM Start	6.72	Rating **	M	Issue No.	3
LM End	6.72	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.292234 °	38.292234 °	
			-121.715875 °	-121.715875 °	
DWR ID	20961				

Comment Code

Inspector Comment

FS_ID:32285
 DS_ID:20961
 EP_NO: 10172
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: 03/18/2014 Headwalls at WS toe failing. It is uncertain if these retaining walls were a permanent fixture or a temporary fix that failed. (W. Wylie - DWR UCIP)
 FIELD_STRUCT_DESC: 2 of 2: 48-inch corrugated metal drainage pipe through the levee, 29 feet below the crown. Two slide gates in a 7-foot-diameter corrugated metal pipe (CMP) riser on the waterside (WS) slope. (two 48-inch pipes [HLM 6.75] authorized under Automatic Board Order (ABO) issued as Permit No. 10172, 1974 - Moresco Brothers).
 [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 6.75)].
 FS Date: 3/18/2014

Photo 1 of 3 : UCIP_SP_2022_32285_58749.jpg



Inlet not visible on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	6.72	Rating **	M	Issue No.	3 (cont)	
LM End	6.72	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.292234 °		38.292234 °
				-121.715875 °		-121.715875 °
DWR ID	20961					

Photo 2 of 3 : UCIP_SP_2022_32285_58748.jpg



7-foot diameter CMP riser with two slide gates inside.

LM Start	6.72	Rating **	M	Issue No.	3 (cont)
LM End	6.72	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2022_32285_58747.jpg



7-foot diameter CMP riser with two slide gates inside.

LM Start	6.74	Rating **	M	Issue No.	19
LM End	6.75	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.292500 °	38.292600 °
				-121.716100 °	-121.716200 °
DWR ID	LMA-270				

Photo 1 of 1 : SP_2022_RD2098_246_19_20220310_00008.jpg



View of landside sloughing. Photo taken in 2017.

Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of scour and sloughing of the landside levee slope. Site ID No:443 Site Designation:LMA-270					

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	6.77	Rating **	A/W	Issue No.	20
LM End	6.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.292900 °	38.293000 °
				-121.716600 °	-121.717000 °
DWR ID	LMA-271				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. The damage consists of cracking of the levee crest. Site ID No:444 Site Designation:LMA-271 Spring 2022: Do not see any evidence of cracking.					

Photo 1 of 1 : SP_2022_RD2098_246_20_20220310_00009.jpg



View of erosion on the landside levee crest. Photo taken in 2017.

LM Start	6.86	Rating **	M	Issue No.	12
LM End	6.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.292965 °	38.292965 °
				-121.718188 °	-121.718188 °
DWR ID	DWR_RD2098_02_s_2020_12				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion at the top of the landside slope.					

Photo 1 of 1 : SP_2022_RD2098_246_12_20220310_00005.jpg



View looking upstream at erosion at the top of the landside slope (Spring 2020).

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	7.24	Rating **	A/W	Issue No.	5
LM End	7.24	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.293741 °	38.293741 °	
			-121.724787 °	-121.724787 °	
DWR ID	20978				

Comment Code

Inspector Comment

FS_ID:32303
DS_ID:20978
EP_NO: 10171
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 09/14/2017 Permit review indicates this 24-inch pipe was authorized as an irrigation and drainage pipe under ABO issued as Permit No. 10171, structure description was updated. Structure type logged as drainage. (DWR UCIP - O. Magana)
FIELD_STRUCT_DESC: *ABANDONED* 24-inch steel dual-purpose irrigation and drainage pipe through the levee, 4.5 feet below the crown. Corrugated metal cutoff wall around the pipe. Pipe has welded steel plate over end on the landside (LS) slope and is not visible on the waterside (WS) slope. (24-inch pipe [HLM 7.23] authorized under Automatic Board Order (ABO) issued as Permit No. 10171, 1974 - Glenn A. Bowlsbey). [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 7.28)].
FS Date: 3/18/2014 7:07:14 AM

LM Start	7.24	Rating **	A/W	Issue No.	5 (cont)
LM End	7.24	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2022_32303_58782.jpg



Pipe visible under new pipe on LS slope.

Photo 2 of 3 : UCIP_SP_2022_32303_58781.jpg



Pipe visible under new pipe on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	03/18/2022 03/18/2022	David Julian

LM Start	7.24	Rating **	A/W	Issue No.	5 (cont)
LM End	7.24	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.293741 °	38.293741 °
				-121.724787 °	-121.724787 °
DWR ID	20978				

Photo 3 of 3 : UCIP_SP_2022_32303_58780.jpg



Welded steel cap over LS end of pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	7.18	Rating **	M	Issue No.	8
LM End	8.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.293112 °	38.306546 °
				-121.724156 °	-121.731545 °
DWR ID	DWR_RD2098_03_f _ 2021_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	7.33	Rating **	M	Issue No.	7
LM End	7.72	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2018 USACE Erosion Survey			38.294858 °	38.299606 °
				-121.725433 °	-121.728621 °
DWR ID	DWR_RD2098_03_s_2022_7				
Comment Code					
Inspector Comment					
2018 Site ID: HAS 7.9 L					
Status: Eroding					
2018 Field Notes: Last observed in 2017.					
Site History: 2011 - Large vertical erosion pockets and bank slumping.					
2017 - POSSIBLY BEING FIXED BY RD; deep cracks along bank and toe, intermittent slump.					

No Photos

LM Start	7.75	Rating **	M	Issue No.	14
LM End	7.75	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.299994 °	38.299994 °
				-121.728347 °	-121.728347 °
DWR ID	DWR_RD2098_03_s_2022_14				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove tree limbs on the landside shoulder.					

Photo 1 of 1 : SP_2022_RD2098_247_14_20220318_00013.jpg



View of cut up tree branches on the landside shoulder (Spring 2022).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	7.85	Rating **	M	Issue No.	5
LM End	7.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.301398 °	38.301398 °
				-121.728063 °	-121.728063 °
DWR ID	DWR_RD2098_03_s_2022_5				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove cuttup tree limbs on the landside slope and toe.					

Photo 1 of 1 : SP_2022_RD2098_247_5_20220318_00012.jpg



View of cut up tree limbs and trunks on the landside shoulder and toe (Spring 2022).

LM Start	8.05	Rating **	M	Issue No.	9
LM End	8.34	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2018 USACE Erosion Survey			38.304278 °	38.306705 °
				-121.727960 °	-121.732014 °
DWR ID	DWR_RD2098_03_s_2022_9				
Comment Code					
Inspector Comment					
2018 Site ID: HAS 8.4 L					
Status: Eroding					
2018 Field Notes: Last observed in 2017.					
Site History: Horizontal cracks; scour along toe; poorly constructed levee susceptible to erosion.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	8.16	Rating **	A/W	Issue No.	2	
LM End	8.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.305462 °	38.305462 °	
				-121.728881 °	-121.728881 °	
DWR ID	20981					
Comment Code						
Inspector Comment						
FS_ID:51453 DS_ID:20981 EP_NO: 10174 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 12/22/2016 Crossing has been downgraded from Urgent to No Action Needed walkways on both WS and LS have been rebuilt and the WS gate has been upgraded to stainless steel where previous corrodable material was present. (O. Magana - DWR UCIP)03/19/2014 Current walkway to slidegate on WS toe does not provide safe access to operate slidegate. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 36-inch steel dual-purpose irrigation and drainage pipe through the levee, 26 feet below the crown. Two corrugated metal cutoff walls around the pipe. Walkway to the slide gate on the waterside (WS) end. Combination slide and flap gate on the landside (LS) end. 48-inch corrugated metal pipe (CMP) riser and an adjoining pump on a metal pier at the LS toe. (36-inch pipe [HLM 8.20] authorized under Automatic Board Order (ABO) issued as Permit No. 10174, 1974 - Glen A. Bowsbey). [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 8.20)]. FS Date: 12/22/2016						

LM Start	8.16	Rating **	A/W	Issue No.	2 (cont)
LM End	8.16	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2022_51453_76858.jpg



Walkway has been re-built, photo 1 of 2.

Photo 2 of 3 : UCIP_SP_2022_51453_76861.jpg



Walkway has been re-built, photo 2 of 2.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	8.16	Rating **	A/W	Issue No.	2 (cont)
LM End	8.16	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.305462 °	38.305462 °	
			-121.728881 °	-121.728881 °	
DWR ID	20981				

Photo 3 of 3 : UCIP_SP_2022_51453_76859.jpg



View of levee crown at pipe crossing.

LM Start	8.35	Rating **	A/W	Issue No.	3
LM End	8.35	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.306916 °	38.306916 °	
			-121.731984 °	-121.731984 °	
DWR ID	20962				

Comment Code

Inspector Comment

FS_ID:32384
 DS_ID:20962
 EP_NO: 10174
 Repair Type: No Action Needed
 Crossing Status: Found
 UCIP Comments:
 FIELD_STRUCT_DESC: 60-inch corrugated metal drainage pipe through the levee, 25.5 feet below the crown. Walkway to the slide gates at both ends of the pipe. (Permit No. 1607, 1951 - R. F. Moore and Lorraine W. Zanetti. This pipe was retained under Automatic Board Order (ABO) issued as Permit No. 10174, 1974 - Glen A. Bowlsbey).
 [Additional Reference(s): DWR Levee Log, 2003. USACE Sacramento O&M Manual 109, April 1962, (HLM 8.40)].
 FS Date: 3/19/2014

Photo 1 of 2 : UCIP_SP_2022_32384_58883.jpg



Slide gate at LS toe.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	8.35	Rating **	A/W	Issue No.	3 (cont)
LM End	8.35	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.306916 °	38.306916 °
				-121.731984 °	-121.731984 °
DWR ID	20962				

Photo 2 of 2 : UCIP_SP_2022_32384_58882.jpg



Walkway with slide gate on WS toe.

LM Start	8.36	Rating **	M	Issue No.	11
LM End	9.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Livestock			38.306951 °	38.315096 °
				-121.732001 °	-121.739121 °
DWR ID	DWR_RD2098_03_s_2022_11				
Comment Code					
E4 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					

No Photos

LM Start	8.39	Rating **	U	Issue No.	12
LM End	8.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.307344 °	38.307344 °
				-121.732273 °	-121.732273 °
DWR ID	DWR_RD2098_03_s_2022_12				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_247_12_20220318_00010.jpg



View of down tree on the landside slope (Spring 2022).

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	03/18/2022 03/18/2022	David Julian

LM Start	8.50	Rating **	M	Issue No.	4
LM End	9.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Livestock			38.308628 °	38.315096 °
				-121.733495 °	-121.739121 °
DWR ID	DWR_RD2098_03_s_2021_4				
Comment Code					
E4 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_247_4_20220310_00001.jpg



View of slope terracing caused by cattle on the landside slope (Spring 2021).

LM Start	9.07	Rating **	U	Issue No.	10	
LM End	9.07	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Livestock			38.315205 °		38.315205 °
				-121.739252 °		-121.739252 °
DWR ID	DWR_RD2098_03_s_2022_10					
Comment Code						
E4 : Repair the levee slope damaged by livestock and prevent large animal access.						
Inspector Comment						

Photo 1 of 1 : SP_2022_RD2098_247_10_20220318_00009.jpg



View looking downstream erosion due to livestock into the landside slope (Spring 2022).

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	03/18/2022 03/18/2022	David Julian

LM Start	9.19	Rating **	M	Issue No.	11
LM End	9.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Livestock			38.316733 °	38.324861 °
				-121.740076 °	-121.740124 °
DWR ID	DWR_RD2098_04_s_2021_11				
Comment Code					
E4 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_248_11_20220310_00003.jpg



View of terracing due to cows on the landside slope (Spring 2021).

LM Start	9.19	Rating **	M	Issue No.	10
LM End	9.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Livestock			38.316734 °	38.324861 °
				-121.740075 °	-121.740124 °
DWR ID	DWR_RD2098_04_f_2019_10				
Comment Code					
E4 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_248_10_20220310_00002.jpg



View looking upstream at depressions in the landside slope due to cows (Fall 2020).

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	03/18/2022 03/18/2022	David Julian

LM Start	9.44	Rating **	U	Issue No.	9
LM End	9.74	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2018 USACE Erosion Survey			38.320240 °	38.324587 °
				-121.740183 °	-121.740254 °
DWR ID	DWR_RD2098_04_s_2022_9				
Comment Code					
Inspector Comment					
2018 Site ID: HAS 9.7 L					
Status: Critical					
2018 Field Notes: Last observed in 2017.					
Site History: 2011 - Several scallops of erosion. Erosion primarily due to the weight of cattle on the slope. 2016 - Two new large scallop pockets in the middle of the site. 2017 - Upgraded to CRITICAL. Multiple slump on top of old slumping ; slump is into levee prism.					

No Photos

LM Start	9.86	Rating **	U	Issue No.	8
LM End	10.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.326009 °	38.328394 °
				-121.740661 °	-121.740638 °
DWR ID	DWR_RD2098_04_f_2021_8				
Comment Code					
MA : Material					
Inspector Comment					
Dredge material on the waterside hinge.					

Photo 1 of 1 : SP_2022_RD2098_248_8_20220310_00001.jpg



View looking upstream at dredge materials on the waterside hinge (Fall 2021).

* Location
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

** Rating
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	03/18/2022 03/18/2022	David Julian

LM Start	9.97	Rating **	M	Issue No.	16
LM End	10.37	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.327680 °	38.333537 °
				-121.740646 °	-121.740606 °
DWR ID	DWR_RD2098_04_s_2022_16				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	10.55	Rating **	M	Issue No.	15
LM End	10.60	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.336082 °	38.336754 °
				-121.740663 °	-121.740787 °
DWR ID	DWR_RD2098_04_s_2022_15				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_248_15_20220318_00023.jpg



View looking upstream at erosion into the landside slope (Spring 2022).

LM Start	10.98	Rating **	M	Issue No.	14
LM End	10.98	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.342307 °	38.342307 °
				-121.740812 °	-121.740812 °
DWR ID	DWR_RD2098_04_s_2022_14				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : SP_2022_RD2098_248_14_20220318_00024.jpg



View looking downstream at erosion into the landside slope (Spring 2022).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2022

Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	03/18/2022 03/18/2022	David Julian

LM Start	11.08	Rating **	M	Issue No.	12
LM End	11.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343742 °	38.355356 °
				-121.740816 °	-121.740505 °
DWR ID	DWR_RD2098_04_f_2021_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	12.06	Rating **	M	Issue No.	13
LM End	12.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.357988 °	38.357988 °
				-121.740384 °	-121.740384 °
DWR ID	DWR_RD2098_04_f_2021_13				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove cattail trimmings from the landside slope.					

Photo 1 of 1 : SP_2022_RD2098_248_13_20220310_00004.jpg



View of cattails on the landside hinge (Fall 2021).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---