

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals		o		o
			o		o
DWR ID	DWR_RD2060_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 2060 has the O&M Manual on file.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment		o		o
			o		o
DWR ID	DWR_RD2060_01_f_2014_7				
Comment Code					
Inspector Comment					
RD 2060 has emergency supplies on hand.					

No Photos

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training		o		o
			o		o
DWR ID	DWR_RD2060_01_s_2012_12				
Comment Code					
Inspector Comment					
RD 2060 has trained staff for a flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	0.08	Rating **	M	Issue No.	19
LM End	5.08	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.247305 °	38.263296 °	
			-121.697734 °	-121.771525 °	
DWR ID	DWR_RD2060_01_s_2020_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_241_19_20200417_00074.jpg



View looking upstream at vegetation on the waterside slope (Spring 2020).

LM Start	0.40	Rating **	C	Issue No.	5
LM End	0.40	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.247894 °	38.247911 °	
			-121.703492 °	-121.703539 °	
DWR ID	LMA-185				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This has been corrected. Levee Evaluation Comments Description: Erosion commences approximately 3/4 of the way down the slope, near the water line towards the waterside toe. Site ID No: 358 Site Designation: LMA-185 Repair Type: Erosion Rating: Area of Concern Field Date: 7/12/2017 Notes: Small erosion into bank.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	1.09	Rating **	A/W	Issue No.	16
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.250844 °	38.250833 °	
			-121.714944 °	-121.714994 °	
DWR ID	LMA-190				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion at the waterside toe. Site ID No:363 Site Designation:LMA-190 4/17/2020 Field Notes: Unable to view erosion due to thick vegetation. Verify using a boat survey. Monitor.					

Photo 1 of 2 : SP_2020_RD2060_241_16_20200304_00020.jpg



LM Start	1.09	Rating **	A/W	Issue No.	16 (cont)
LM End	1.10	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2020_RD2060_241_16_20200304_00021.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	1.39	Rating **	A/W	Issue No.	20
LM End	1.43	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.251886 °	38.251910 °	
			-121.719933 °	-121.720620 °	
DWR ID	LMA-192				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion commences approximately halfway down the water side slope extending to the toe. Site ID No:365 Site Designation:LMA-192 4/17/2020 Field Notes: Do a boat inspection to get a better view of erosion.					

Photo 1 of 2 : SP_2020_RD2060_241_20_20200304_00024.jpg



LM Start	1.39	Rating **	A/W	Issue No.	20 (cont)
LM End	1.43	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2020_RD2060_241_20_20200304_00025.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	1.81	Rating **	A/W	Issue No.	21
LM End	1.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.255972 °	38.256247 °	
			-121.724197 °	-121.724464 °	
DWR ID	LMA-193				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
<p>This was a 2017 Storm Damage site. Erosion commences approximately halfway down the water side slope extending to the toe. Some slipping into the toe has occurred due to deep erosion. Site ID No:366 Site Designation:LMA-193 4/17/2020 Field Notes: Do a boat inspection to get a better view of erosion.</p>					

Photo 1 of 1 : SP_2020_RD2060_241_21_20200304_00027.jpg



LM Start	1.90	Rating **	C	Issue No.	22
LM End	1.90	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.257208 °	38.257208 °	
			-121.724619 °	-121.724619 °	
DWR ID	LMA-194				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
<p>This has been corrected. Levee Evaluation Comments Description:Erosion commences approximately halfway down the water side slope extending to the toe. Some slipping into the toe has occurred. Site ID No:367 Site Designation:LMA-194 Repair Type: Erosion Rating:Area of Concern Field Date:7/12/2017 Notes: Minor cracking observed below the hinge point and minor erosion at levee toe.</p>					

No Photos

<p>* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	2.10	Rating **	A/W	Issue No.	23
LM End	2.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.259317 °	38.259258 °	
			-121.726314 °	-121.726939 °	
DWR ID	LMA-195				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion commences approximately halfway down the water side slope extending to the rip rap. Site ID No:368 Site Designation:LMA-195 4/17/2020 Field Notes: Do a boat inspection to get a better view of erosion.					

Photo 1 of 1 : SP_2020_RD2060_241_23_20200304_00033.jpg



LM Start	2.57	Rating **	C	Issue No.	24
LM End	2.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.257467 °	38.257286 °	
			-121.734153 °	-121.734683 °	
DWR ID	LMA-196				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This has been corrected. Levee Evaluation Comments Description:Erosion commences approximately halfway down the water side slope. Part of the levee has sloughed down toward the waterline where further erosion occurs. Site ID No:369 Site Designation:LMA-196 Repair Type: Erosion Rating:Area of Concern Field Date:7/13/2017 Notes: Levee slope is concave due slumping. Erosion at waterline.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	3.07	Rating **	U	Issue No.	25
LM End	3.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.260772 °	38.260569 °
				-121.740817 °	-121.741194 °
DWR ID	LMA-197				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage Site Large erosion halfway into levee. Horizontal cracking on slope almost 24" deep. Site ID No:370 Site Designation:LMA-197					

Photo 1 of 2 : SP_2020_RD2060_241_25_20200304_00039.jpg



LM Start	3.07	Rating **	U	Issue No.	25 (cont)
LM End	3.10	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2020_RD2060_241_25_20200304_00040.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	3.60	Rating **	A/W	Issue No.	27 (cont)
LM End	3.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.261469 °	38.261464 °	
			-121.748389 °	-121.748442 °	
DWR ID	LMA-200				

Photo 2 of 2 : SP_2020_RD2060_241_27_20200304_00047.jpg



LM Start	3.67	Rating **	A/W	Issue No.	28
LM End	3.67	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.261181 °	38.261167 °	
			-121.749542 °	-121.749592 °	
DWR ID	LMA-201				

Photo 1 of 2 : SP_2020_RD2060_241_28_20200304_00048.jpg



Comment Code
E1 : Note and monitor erosion site.

Inspector Comment
Erosion is concentrated near the water line.
Site ID No:374
Site Designation:LMA-201
4/6/2020 Notes: Planned for repair.

LM Start	3.67	Rating **	A/W	Issue No.	28 (cont)
LM End	3.67	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2020_RD2060_241_28_20200304_00049.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	3.74	Rating **	M	Issue No.	17
LM End	5.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.261179 °	38.263295 °	
			-121.750797 °	-121.771526 °	
DWR ID	DWR_RD2060_01_s_2020_17				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_241_17_20200417_00075.jpg



View looking upstream at vegetation on the landside slope (Spring 2020).

LM Start	4.28	Rating **	A/W	Issue No.	29
LM End	4.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.260992 °	38.261017 °	
			-121.759806 °	-121.759847 °	
DWR ID	LMA-203				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion commences halfway down the slope and extends to the toe. Erosion is concentrated at the water line. Site ID No:376 4/17/2020 Field Notes: Could not get to erosion due to dense vegetation. A boat survey will allow for a better inspection.					

Photo 1 of 1 : SP_2020_RD2060_241_29_20200304_00051.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	4.40	Rating **	A/W	Issue No.	30
LM End	4.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.260850 °	38.260425 °	
			-121.761875 °	-121.762861 °	
DWR ID	LMA-204				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion/sloughing commences approximately halfway down the slope. Erosion is concentrated mostly near the water line and has resulting in slippage of the slope. Site ID No:377 Site Designation:LMA-204 4/17/2020 Field Notes: Vegetation thick to properly rate. A boat survey will provide a better inspection.					

Photo 1 of 1 : SP_2020_RD2060_241_30_20200304_00054.jpg



LM Start	4.50	Rating **	U	Issue No.	31
LM End	4.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.260150 °	38.259939 °	
			-121.763556 °	-121.764064 °	
DWR ID	LMA-205				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Deep, wide, vertical cut into slope almost 1/2 way into sope. Site ID No:378 Site Designation:LMA-205					

Photo 1 of 2 : SP_2020_RD2060_241_31_20200417_00076.jpg



View looking downstream at erosion into the waterside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	4.50	Rating **	U	Issue No.	31 (cont)
LM End	4.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.260150 °	38.259939 °	
			-121.763556 °	-121.764064 °	
DWR ID	LMA-205				

Photo 2 of 2 : SP_2020_RD2060_241_31_20200417_00077.jpg



View looking upstream at erosion into the waterside slope (Spring 2020).

LM Start	4.88	Rating **	M	Issue No.	32
LM End	4.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.261769 °	38.261769 °	
			-121.768504 °	-121.768504 °	
DWR ID	LMA-206				

Photo 1 of 1 : SP_2020_RD2060_241_32_20200417_00078.jpg



View of erosion into the waterside toe (Spring 2020).

LM Start	4.92	Rating **	M	Issue No.	33
LM End	4.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.262128 °	38.262128 °	
			-121.769175 °	-121.769175 °	
DWR ID	LMA-207				

Photo 1 of 2 : SP_2020_RD2060_241_33_20200304_00063.jpg



Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion on the waterside toe. Site ID No:380 Site Designation:LMA-207					

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	4.92	Rating **	M	Issue No.	33 (cont)
LM End	4.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.262128 °	38.262128 °
				-121.769175 °	-121.769175 °
DWR ID	LMA-207				

Photo 2 of 2 : SP_2020_RD2060_241_33_20200304_00064.jpg



LM Start	5.00	Rating **	M	Issue No.	34
LM End	5.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.262636 °	38.262636 °
				-121.770503 °	-121.770503 °
DWR ID	LMA-208				

Photo 1 of 2 : SP_2020_RD2060_241_34_20200304_00066.jpg



Comment Code
E2 : Schedule repair of erosion site prior to the next inspection.

Inspector Comment
This was a 2017 Storm Damage site.
Erosion into the waterside toe.
Site ID No:381
Site Designation:LMA-208

LM Start	5.00	Rating **	M	Issue No.	34 (cont)
LM End	5.00	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2020_RD2060_241_34_20200304_00068.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	04/17/2020 04/17/2020	David Julian

LM Start	5.26	Rating **	M	Issue No.	18
LM End	6.20	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.261398 °	38.266901 °	
			-121.773098 °	-121.788093 °	
DWR ID	DWR_RD2060_01_s_2020_18				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.64	04/17/2020 04/17/2020	David Julian

LM Start	0.22	Rating **	C	Issue No.	6
LM End	0.22	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.277807 °	38.277807 °	
			-121.795928 °	-121.795928 °	
DWR ID	DWR_RD2060_02_f_2019_6				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	0.71	Rating **	U	Issue No.	11
LM End	0.71	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.284945 °	38.284945 °	
			-121.795743 °	-121.795743 °	
DWR ID	DWR_RD2060_02_s_2020_11				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_242_11_20200420_00014.jpg



View of large rut on the crown (Spring 2020).

LM Start	0.74	Rating **	M	Issue No.	10
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.285166 °	38.285203 °	
			-121.795386 °	-121.777111 °	
DWR ID	DWR_RD2060_02_s_2020_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_242_10_20200420_00015.jpg



View looking downstream of annual vegetation on the waterside slope (Spring 2020).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.64	04/17/2020 04/17/2020	David Julian

LM Start	0.74	Rating **	M	Issue No.	7
LM End	1.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.285166 °	38.285204 °	
			-121.795386 °	-121.777111 °	
DWR ID	DWR_RD2060_02_s_2020_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_242_7_20200420_00016.jpg



View looking downstream at annual vegetation on the landside slope (Spring 2020).

LM Start	2.52	Rating **	M	Issue No.	8
LM End	2.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.290866 °	38.290866 °	
			-121.768068 °	-121.768068 °	
DWR ID	DWR_RD2060_02_f_2019_8				
Comment Code					
A2 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					
Cow path is located on the landside slope.					

Photo 1 of 1 : SP_2020_RD2060_242_8_20200304_00004.jpg



View looking downstream at cow path on the landside slope (Fall 2019).

LM Start	2.60	Rating **	M	Issue No.	9
LM End	2.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.291315 °	38.293390 °	
			-121.766569 °	-121.760008 °	
DWR ID	DWR_RD2060_02_f_2019_9				
Comment Code					
A2 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					
Terracing on the levee due to cows.					

Photo 1 of 1 : SP_2020_RD2060_242_9_20200304_00005.jpg



View looking downstream at terracing in the levee due to cows (Fall 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	0.07	Rating **	M	Issue No.	16
LM End	0.07	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		38.296350 °	38.296302 °	
			-121.747642 °	-121.747565 °	
DWR ID	DWR_RD2060_03_s_2017_16				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Sloughing is occurring on the LS slope.					

Photo 1 of 1 : SP_2020_RD2060_243_16_20200304_00009.jpg



Standing on the slope looking upstream at the slough.

LM Start	0.10	Rating **	A/W	Issue No.	71
LM End	0.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		38.296084 °	38.296084 °	
			-121.747052 °	-121.747052 °	
DWR ID	DWR_RD2060_03_s_2018_71				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Minor slump at toe likely due to cattle should be repaired.					

Photo 1 of 1 : SP_2020_RD2060_243_71_20200304_00073.jpg



View looking upstream at minor slump on the lower half of the landside slope (Fall 2019).

LM Start	0.12	Rating **	A/W	Issue No.	13
LM End	0.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		38.295919 °	38.295611 °	
			-121.746700 °	-121.745742 °	
DWR ID	LMA-212				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This was a 2017 Storm Damage site. Sloughing and seepage occurs near the land side toe. Site ID No:385 Site Designation:LMA-212					

Photo 1 of 2 : SP_2020_RD2060_243_13_20200304_00002.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	0.12	Rating **	A/W	Issue No.	13 (cont)
LM End	0.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.295919 °	38.295511 °
				-121.746700 °	-121.745742 °
DWR ID	LMA-212				

Photo 2 of 2 : SP_2020_RD2060_243_13_20200304_00003.jpg



LM Start	0.13	Rating **	M	Issue No.	19
LM End	0.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.295915 °	38.295559 °
				-121.746683 °	-121.745583 °
DWR ID	DWR_RD2060_03_f_2019_19				

Photo 1 of 1 : SP_2020_RD2060_243_19_20200420_00082.jpg



View looking downstream at terracing due to cows on the landside slope (Spring 2020).

Comment Code					
A2 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					
Terracing due to cows walking on the landside slope.					

LM Start	0.20	Rating **	M	Issue No.	6
LM End	0.50	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.295513 °	38.292604 °
				-121.745333 °	-121.741687 °
DWR ID	DWR_RD2060_03_s_2020_6				

No Photos

Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	0.53	Rating **	M	Issue No.	8
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.292196 °	38.290552 °	
			-121.741389 °	-121.731109 °	
DWR ID	DWR_RD2060_03_s_2020_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD2060_243_8_20200420_00083.jpg



View looking downstream at annual vegetation on the landside slope (Spring 2020).

LM Start	0.64	Rating **	U	Issue No.	14
LM End	0.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.292197 °	38.292208 °	
			-121.739661 °	-121.739611 °	
DWR ID	LMA-213				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Relatively deep erosion spot into waterside slope Site ID No:386 Site Designation:LMA-213					

Photo 1 of 1 : SP_2020_RD2060_243_14_20200420_00084.jpg



View looking upstream at erosion into the waterside slope (Spring 2020).

LM Start	0.81	Rating **	A/W	Issue No.	15
LM End	0.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.291633 °	38.291606 °	
			-121.736750 °	-121.736714 °	
DWR ID	LMA-215				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion into waterside berm. Monitor. Site ID No:388 Site Designation:LMA-215					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	1.22	Rating **	U	Issue No.	20
LM End	1.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.290511 °	38.290511 °	
			-121.729828 °	-121.729828 °	
DWR ID	LMA-217				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion about halfway down the waterside slope. Site ID No:390 Site Designation:LMA-217					

Photo 1 of 1 : SP_2020_RD2060_243_20_20200420_00085.jpg



View looking upstream at erosion into the waterside slope (Spring 2020).

LM Start	1.38	Rating **	A/W	Issue No.	21
LM End	1.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.290067 °	38.289608 °	
			-121.726839 °	-121.726344 °	
DWR ID	LMA-320				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. MBK Delta Erosion Sites_6-29-2017 Site ID No:482 Site Designation:LMA-320 Field Date:8/29/2017 4/17/2020 Notes: Did not see any erosion. Do boat inspection to verify. Monitor.					

Photo 1 of 1 : SP_2020_RD2060_243_21_20200304_00016.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	1.45	Rating **	A/W	Issue No.	22
LM End	1.59	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.289256 °	38.287689 °	
			-121.726050 °	-121.724658 °	
DWR ID	LMA-219				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
2017 Storm Damage Site Erosion commences halfway down the slope and results in slippage into the waterside toe. Site ID No:392 Site Designation:LMA-219 4/17/2020 Field Notes: Unable to see erosion. Verify with boat inspection. Monitor.					

Photo 1 of 1 : SP_2020_RD2060_243_22_20200304_00021.jpg



LM Start	1.62	Rating **	A/W	Issue No.	23
LM End	1.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.287336 °	38.287222 °	
			-121.724364 °	-121.724253 °	
DWR ID	LMA-220				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion commences halfway down the slope and results in slippage into the waterside toe. Existing rip rap has sloughed into the water side toe. Site ID No:393 Site Designation:LMA-220 4/17/2020 Notes: Swarm of bees did not allow for inspection. Verify with boat inspection. Monitor.					

Photo 1 of 1 : SP_2020_RD2060_243_23_20200304_00023.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	1.84	Rating **	M	Issue No.	25 (cont)
LM End	1.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.284825 °	38.284467 °
				-121.721764 °	-121.720339 °
DWR ID	LMA-222				

Photo 2 of 2 : SP_2020_RD2060_243_25_20200304_00026.jpg



LM Start	2.02	Rating **	A/W	Issue No.	5
LM End	2.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.284120 °	38.277633 °
				-121.718577 °	-121.711912 °
DWR ID	DWR_RD2060_03_f_2018_5				

No Photos

Comment Code					
Inspector Comment					
<p>2017 Site ID: CHS 22.9 R Status: Eroding 2017 Field Notes: Sites 22.5, 22.6, 22.8, and 22.9 were combined into one long erosion site due to due erosion. Site History: 2007 - Geotechnical failure of midside slope and wave wash/scalloping in toe area. Stone revetment upstream and downstream of site. Similar sites are present all along the right bank downstream of this site, most could be repaired with some maintenance. 2008 - Small scour pockets and mid-slope wave wash. 2010 - Minor new erosion. 2011 - Site extended downstream and new erosion. 2013 - Pockets of erosion behind willows and extending into the levee toe. 2015 - Erosion pockets have increased in size. 2016 - Rock has been placed in some of the pockets. 2020 - erosion extent includes several 2017 storm damage sites. Site Numbers - 396, 397, 398, 399, 400, 401, 402, 403. LMA Site IDs - LMA-223, LMA-224, LMA-225, LMA-226, LMA-227, LMA-228, LMA-229, LMA-230.</p>					

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	2.02	Rating **	M	Issue No.	9
LM End	5.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.283970 °	38.247385 °	
			-121.718709 °	-121.696291 °	
DWR ID	DWR_RD2060_03_s_2020_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	2.02	Rating **	M	Issue No.	10
LM End	5.03	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.283970 °	38.247385 °	
			-121.718709 °	-121.696291 °	
DWR ID	DWR_RD2060_03_s_2020_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	2.64	Rating **	A/W	Issue No.	35
LM End	2.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.277106 °	38.277078 °	
			-121.711489 °	-121.711447 °	
DWR ID	LMA-231				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Erosion at the waterside toe. Site ID No:404 Site Designation:LMA-231 4/17/2020 Field Notes: Unable to observe erosion. Do boat inspection to verify. Monitor.					

Photo 1 of 2 : SP_2020_RD2060_243_35_20200304_00052.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	2.64	Rating **	A/W	Issue No.	35 (cont)
LM End	2.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.277106 °	38.277078 °
				-121.711489 °	-121.711447 °
DWR ID	LMA-231				

Photo 2 of 2 : SP_2020_RD2060_243_35_20200304_00053.jpg



LM Start	2.69	Rating **	A/W	Issue No.	36
LM End	2.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.276608 °	38.276133 °
				-121.710811 °	-121.710394 °
DWR ID	LMA-232				

Photo 1 of 1 : SP_2020_RD2060_243_36_20200304_00057.jpg



Comment Code
E1 : Note and monitor erosion site.

Inspector Comment
This was a 2017 Storm Damage site.
Erosion at the landside toe.
Site ID No:405
Site Designation:LMA-232
4/17/2020 Field Notes: Unable to observe erosion. Do boat inspection to verify. Monitor.

LM Start	3.59	Rating **	M	Issue No.	38
LM End	3.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.266408 °	38.266047 °
				-121.701650 °	-121.701061 °
DWR ID	LMA-322				

Photo 1 of 1 : SP_2020_RD2060_243_38_20200304_00062.jpg



Comment Code
E2 : Schedule repair of erosion site prior to the next inspection.

Inspector Comment
This was a 2017 Storm Damage site.
MBK Delta Erosion Sites_6-29-2017
Site ID No:484
Site Designation:LMA-322

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**


Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	04/17/2020 04/17/2020	David Julian

LM Start	3.66	Rating **	A/W	Issue No.	39
LM End	3.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.265742 °	38.265342 °
				-121.700522 °	-121.699881 °
DWR ID	LMA-321				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
2017 Storm Damage Site MBK Delta Erosion Sites_6-29-2017 Site ID No:483 Site Designation:LMA-321 4/17/2020 Field Notes: Unable to view erosion. Verify with a boat survey. Monitor.					

Photo 1 of 1 : SP_2020_RD2060_243_39_20200304_00063.jpg



LM Start	3.78	Rating **	A/W	Issue No.	4
LM End	4.09	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.264585 °	38.260593 °
				-121.698868 °	-121.696403 °
DWR ID	DWR_RD2060_03_f_2018_4				
Comment Code					
Inspector Comment					
2017 Site ID: CHS 21.1 R Status: Eroding 2017 Field Notes: Significant toe erosion within last year. Site History: 2011 - Several pockets of erosion from rotational failure and slumping toe. 2013 - Site extended downstream to include new erosion pockets. 2016 - New rock in one of the erosion spots. 2020 - erosion extent includes several 2017 storm damage sites. Site Numbers - 410, 411, 412. LMA Site IDs - LMA-237, LMA-238, LMA-239.					

Photo 1 of 1 : SP_2020_RD2060_243_4_20200304_00001.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---