

**Flood Control Project Maintenance
Levee Inspections**

Fall 2019 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR Erosion Survey

San Joaquin River Basin

RD2062 Reclamation District No. 2062 Stewart	Overall LMA Rating	Total LMA Miles						
	U	12.14						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	13.94	2.24	22.90	188.60%				
Trim / Thin Trees	0.11	0.01	0.15	1.24%				
Encroachments	0.01		0.01	0.08%	0.02	0.01		
Animal Control	0.26		0.26	2.14%				
Erosion / Bank Caving	0.13		0.13	1.07%				
Crown Surface / Depressions / Rutting	0.01		0.01	0.08%				
<i>Supplemental</i>								
DWR Erosion Survey	0.14	0.13	0.66	5.44%				
DRAFT DWR UCIP Field Study					0.13	0.03		
<i>LMA Totals:</i>	14.60	2.38	24.12	198.64%	0.15	0.04	0.00	0.00

Unit No. 01 San Joaquin River LB RD2062	Overall Unit Rating	Total Unit Miles						
	U	2.64						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	2.25	0.08	2.57	97.52%				
<i>Supplemental</i>								
DRAFT DWR UCIP Field Study					0.03			
<i>Unit Totals:</i>	2.25	0.08	2.57	97.52%	0.03	0.00	0.00	0.00

Unit No. 02 Paradise Cut RB RD2062	Overall Unit Rating	Total Unit Miles						
	U	3.96						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	3.05		3.05	77.05%				
Trim / Thin Trees		0.01	0.04	1.01%				
Encroachments	0.01		0.01	0.25%	0.02			
Animal Control	0.22		0.22	5.56%				
Crown Surface / Depressions / Rutting	0.01		0.01	0.25%				
<i>Supplemental</i>								
DRAFT DWR UCIP Field Study					0.06	0.02		
<i>Unit Totals:</i>	3.29	0.01	3.33	84.12%	0.08	0.02	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2019 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 03 Old River LB		Overall Unit Rating	Total Unit Miles						
RD2062		U	5.55						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
<i>Earthen Levee</i>									
Vegetation	8.64	2.16	17.28	311.45%					
Trim / Thin Trees	0.11		0.11	1.98%					
Encroachments						0.01			
Animal Control	0.04		0.04	0.72%					
Erosion / Bank Caving	0.13		0.13	2.34%					
<i>Supplemental</i>									
DWR Erosion Survey	0.14	0.13	0.66	11.90%					
DRAFT DWR UCIP Field Study					0.04	0.01			
<i>Unit Totals:</i>	9.06	2.29	18.22	328.39%	0.04	0.02	0.00	0.00	

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Fall 2019 Levee Inspection Results**

Reclamation District No. 2062 Stewart

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			U	

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2019 Levee Inspection Results

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles
Unit No. 01 San Joaquin River	Left	2.64

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	5/21/2019 - 5/21/2019		10/2/2019 - 10/2/2019	
DWR Inspector	Alberto De Leon		Alberto De Leon	
Accompanied By	Tim Mello RD2062		Tim Mello RD2062 Mike Engelmann DWR	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway			Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River			Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	o
				o	o
DWR ID	DWR_RD2062_01_f_2013_2				
Comment Code					
Inspector Comment					
The O&M Manual is available at the LMA's office.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	o
				o	o
DWR ID	DWR_RD2062_01_s_2013_5				
Comment Code					
Inspector Comment					
Adequate flood fight supplies are available on-site.					

No Photos

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	o
				o	o
DWR ID	DWR_RD2062_01_s_2013_8				
Comment Code					
Inspector Comment					
The LMA has a flood fight emergency response plan. LMA has attended DWR flood fight training class.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.00	Rating **	M	Issue No.	11
LM End	0.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.807461°	37.804875°	
			-121.328057°	-121.315880°	
DWR ID	DWR_RD2062_01_f_2019_11				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2019_RD2062_309_11_20191111_00011.jpg



View of vegetation on waterside slope. Fall 2019

LM Start	0.81	Rating **	C	Issue No.	7
LM End	0.81	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		37.804623°	37.804623°	
			-121.314943°	-121.314943°	
DWR ID	DWR_RD2062_01_s_2019_7				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
RD has repaired ruts on crown surface.					

No Photos

LM Start	0.94	Rating **	M	Issue No.	10
LM End	2.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.803317°	37.793050°	
			-121.313639°	-121.310021°	
DWR ID	DWR_RD2062_01_f_2019_10				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	12
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.793521 °	37.793521 °
				-121.315348 °	-121.315348 °
DWR ID	19177				
Comment Code					
Inspector Comment					
DS_ID:19177 FS_ID:22807 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 1 of 3: 16-inch steel irrigation discharge pipe through the levee, 5 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. Installed by USACE in 1961. (Plans to replace rusted portions of two 16-inch irrigation pipes through the levee authorized under Permit No. 16124, 1993 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.65)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_22807_38905.jpg



WS view: pipes, walkway, and dismantled pump house (right).

LM Start	1.64	Rating **	M	Issue No.	12 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_22807_38904.jpg



WS view: 16-inch pipes on both sides of walkway and 10-inch pipe (on right) away from walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	12 (cont)	
LM End	1.64	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DRAFT DWR UCIP Field Study			37.793521°	37.793521°	
				-121.315348°	-121.315348°	
DWR ID	19177					
Comment Code						
Inspector Comment						
DS_ID:19177 FS_ID:22807 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 1 of 3: 16-inch steel irrigation discharge pipe through the levee, 5 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. Installed by USACE in 1961. (Plans to replace rusted portions of two 16-inch irrigation pipes through the levee authorized under Permit No. 16124, 1993 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.65)]. FS Date: 10/22/2013						

Photo 3 of 3 : UCIP_FA_2019_22807_38903.jpg



WS view: two 16-inch pipes. Pumps were removed. Pumphouse dismantled.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	13
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.793510°	37.793510°	
			-121.315345°	-121.315345°	
DWR ID	19183				
Comment Code					
Inspector Comment					
DS_ID:19183 FS_ID:22809 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 2 of 3: 16-inch steel irrigation discharge pipe through the levee, 5 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. Installed by USACE in 1961. (Plans to replace rusted portions of two 16-inch irrigation pipes through the levee authorized under Permit No. 16124, 1993 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.65)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_22809_38913.jpg



WS view: pipes, walkway, and dismantled pump house (right).

LM Start	1.64	Rating **	M	Issue No.	13 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_22809_38912.jpg



WS view: 16-inch pipes on both sides of walkway and 10-inch pipe (on right) away from walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	13 (cont)
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.793510°	37.793510°
				-121.315345°	-121.315345°
DWR ID	19183				
Comment Code					
Inspector Comment					
DS_ID:19183 FS_ID:22809 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 2 of 3: 16-inch steel irrigation discharge pipe through the levee, 5 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. Installed by USACE in 1961. (Plans to replace rusted portions of two 16-inch irrigation pipes through the levee authorized under Permit No. 16124, 1993 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.65)]. FS Date: 10/22/2013					

Photo 3 of 3 : UCIP_FA_2019_22809_38911.jpg



WS view: two 16-inch pipes under walkway; pumps were removed.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	14
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.793497°	37.793497°	
			-121.315340°	-121.315340°	
DWR ID	19184				
Comment Code					
Inspector Comment					
DS_ID:19184 FS_ID:22810 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new. No pump associated with 8-inch pipe.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 3 of 3: 8-inch steel irrigation discharge pipe through the levee, 8 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. (Plans to install a 75-horsepower pump on the bank with a 10-inch steel discharge pipe through the levee authorized under Permit No. 12679, 1979 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_22810_38918.jpg



WS view: pipes, walkway, and dismantled pumphouse (right).

LM Start	1.64	Rating **	M	Issue No.	14 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_22810_38917.jpg



WS view: electric conduit and 10-inch pipe (right). Dismantled/removed pipe and pump house (far right).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	2.64	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	M	Issue No.	14 (cont)
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.793497°	37.793497°
				-121.315340°	-121.315340°
DWR ID	19184				
Comment Code					
Inspector Comment					
DS_ID:19184 FS_ID:22810 EP_NO: 12679 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - All 3 pipes on landside looks new. No pump associated with 8-inch pipe.- Pumps, pump house, and pipes removed from waterside.- Land development activities going on in this area.- Needs to confirm from LMA or DWR Inspector about the crossing. FIELD_STRUCT_DESC: 3 of 3: 8-inch steel irrigation discharge pipe through the levee, 8 feet below the crown. Electrical conduit through the levee. Slant pump in a pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole and concrete gate valve box at the landside (LS) toe. (Plans to install a 75-horsepower pump on the bank with a 10-inch steel discharge pipe through the levee authorized under Permit No. 12679, 1979 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013					

Photo 3 of 3 : UCIP_FA_2019_22810_38916.jpg



LS view: two 16-inch pipes (left) and one 10-inch pipe (right) in ditch. Concrete box removed.

LM Start	2.01	Rating **	U	Issue No.	9
LM End	2.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.793068°	37.794010°
				-121.310008°	-121.309373°
DWR ID	DWR_RD2062_01_f_2019_9				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2019_RD2062_309_9_20191027_00010.jpg



View of vegetation on waterside slope. Fall 2019

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2019 Levee Inspection Results

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles
Unit No. 02 Paradise Cut	Right	3.96

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	5/21/2019 - 5/21/2019		10/2/2019 - 10/2/2019	
DWR Inspector	Alberto De Leon		Alberto De Leon	
Accompanied By	Tim Mello RD2062		Tim Mello RD2062 Mike Engelmann DWR	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.00	Rating **	M	Issue No.	27
LM End	0.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.777815°	37.779984°
				-121.333054°	-121.335088°
DWR ID	DWR_RD2062_02_f_2019_27				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.00	Rating **	M	Issue No.	24
LM End	0.77	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.777815°	37.786367°
				-121.333054°	-121.341881°
DWR ID	DWR_RD2062_02_f_2019_24				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	0.43	Rating **	M	Issue No.	25
LM End	0.43	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.782800°	37.782800°
				-121.337532°	-121.337532°
DWR ID	DWR_RD2062_02_f_2019_25				
Comment Code					
RA : Ramp					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.56	Rating **	M	Issue No.	28 (cont)
LM End	0.56	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.784380°	37.784380°
				-121.338985°	-121.338985°
DWR ID	24697				
Comment Code					
Inspector Comment					
DS_ID:24697 FS_ID:23110 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Found on field with the help of USACE 2012 PI Report. Needs proper abandonment. FIELD_STRUCT_DESC: *ABANDONED* 24-inch steel irrigation discharge pipe through the levee, at an unknown depth. Damaged siphon breaker on the waterside (WS) slope. Pump on a concrete sump in an irrigation ditch on the landside (LS). Service pole on the LS slope. Pump disconnected from the service pole. FS Date: 10/23/2013					

Photo 2 of 3 : UCIP_FA_2019_23110_39397.jpg



WS view: exposed steel pipe and damaged siphon breaker on levee slope.

LM Start	0.56	Rating **	M	Issue No.	28 (cont)
LM End	0.56	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2019_23110_39396.jpg



WS view: exposed steel pipe on channel bank and also immersed into channel water.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.57	Rating **	C	Issue No.	15
LM End	0.57	Issue Type +	En	Location *	CR
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.784488°	37.784488°
				-121.339098°	-121.339098°
DWR ID	DWR_RD2062_02_s_2018_15				
Comment Code					
Inspector Comment					
Unauthorized pipe has been removed. Fall 2019					

No Photos

LM Start	0.75	Rating **	M	Issue No.	29
LM End	0.75	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.786130°	37.786130°
				-121.341564°	-121.341564°
DWR ID	19192				
Comment Code					
Inspector Comment					
DS_ID:19192 FS_ID:23181 EP_NO: 12427 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - no siphon breaker found- levee toe erosion under walkway on waterside.- erosion around concrete standpipe on landside- may be base of the standpipe was leaking. FIELD_STRUCT_DESC: 18-inch irrigation discharge pipe of an unknown material through the levee, 4.4 feet below the crown. Pump house on the waterside (WS) slope. Metal walkway from the pump house to the crown. Service pole on the WS. Flap gate, siphon breaker, and concrete distribution box on the landside (LS) slope. (Emergency plans to replace an existing 18-inch discharge pipe through the levee authorized under Permit No. 12427, 1978 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007, 16-inch pipe referenced. USACE San Joaquin O&M Manual 9, April 1964, (HLM 0.76)]. FS Date: 10/23/2013					

Photo 1 of 3 : UCIP_FA_2019_23181_39792.jpg



WS view: pipe, walkway, service pole, and pumphouse on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.12	Rating **	M	Issue No.	10
LM End	3.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789666°	37.804653°
				-121.346854°	-121.379183°
DWR ID	DWR_RD2062_02_f_2019_10				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	1.37	Rating **	M	Issue No.	30
LM End	1.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.791821°	37.791821°
				-121.350448°	-121.350448°
DWR ID	19193				
Comment Code					
Inspector Comment					
DS_ID:19193 FS_ID:51468 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 04/05/2017:Pipe has been plugged as a flood fight measure and is likely to be replaced under a permit. MBK (Michael Moncrief) is working on the permit. Photo and update courtesy of Max Khashchuk as part of his 2017 Spring Inspection. (K. Fazel - UCIP)10/22/2013:- pumphouse on concrete sump in the channel.- erosion under walkway on waterside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 20-inch steel irrigation discharge pipe through the levee, 8 feet below the crown. Pump house on the waterside (WS) slope. Metal walkway from the pump house to the crown. Flap gate, siphon breaker, and concrete distribution box on the landside (LS) slope. [Additional Reference(s): DWR Levee Log, 2007, 18-inch pipe referenced. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.40), 18-inch pipe referenced]. FS Date: 4/6/2017					

Photo 1 of 3 : UCIP_FA_2019_51468_39195.jpg



WS view: pipe, walkway, and pumphouse on levee berm. Service pole on waterside.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.37	Rating **	M	Issue No.	30 (cont)
LM End	1.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.791821°	37.791821°
				-121.350448°	-121.350448°
DWR ID	19193				
Comment Code					
Inspector Comment					
DS_ID:19193 FS_ID:51468 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 04/05/2017:Pipe has been plugged as a flood fight measure and is likely to be replaced under a permit. MBK (Michael Moncrief) is working on the permit. Photo and update courtesy of Max Khashchuk as part of his 2017 Spring Inspection. (K. Fazel - UCIP)10/22/2013:- pumphouse on concrete sump in the channel.- erosion under walkway on waterside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 20-inch steel irrigation discharge pipe through the levee, 8 feet below the crown. Pump house on the waterside (WS) slope. Metal walkway from the pump house to the crown. Flap gate, siphon breaker, and concrete distribution box on the landside (LS) slope. [Additional Reference(s): DWR Levee Log, 2007, 18-inch pipe referenced. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.40), 18-inch pipe referenced]. FS Date: 4/6/2017					

Photo 2 of 3 : UCIP_FA_2019_51468_39194.jpg



WS view: leaky pump and control box in pumphouse.

LM Start	1.37	Rating **	M	Issue No.	30 (cont)
LM End	1.37	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2019_51468_39193.jpg



WS view: exposed steel pipe under walkway. Soil erosion under walkway. This may be due to leaky pipe joint.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	U	Issue No.	31 (cont)
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.794009°	37.794009°
				-121.354417°	-121.354417°
DWR ID	19194				
Comment Code					
Inspector Comment					
DS_ID:19194 FS_ID:53375 EP_NO: 4305 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/10/2018 Extremely overgrown vegetation did not allow visual inspection of WS levee erosion; however, there are indications based on vegetation growth patterns that the erosion is still present, so keeping crossing as Urgent (D. Sanoski - DWR UCIP).08/31/2016: Heavy sloughing and sink hole remains at the WS slope in alignment with pipe. Though sloughing is not affecting levee prism, it is still an indication of a pipe integrity problem. Oil leak at the pump but does not appear to impact the levee. (K. Fazel - UCIP)10/22/2013:- missing roof in pump house.- no protection for siphon breaker- huge erosion under pumphouse and levee slope on waterside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 1 of 2: 18-inch steel irrigation discharge pipe through the levee, 4.8 feet below the crown. Pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) shoulder. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Plans for installation of two irrigation pumps on the bank to replace an old centrifugal pumping plant at the same location authorized under Permit No. 4305, 1963 - Reclamation District No. 2062) [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.67)]. FS Date: 10/10/2018 11:02:00 AM					

Photo 2 of 3 : UCIP_FA_2019_53375_39186.jpg



WS view: walkway to pumphouse. Walkway in poor condition.

LM Start	1.64	Rating **	U	Issue No.	31 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2019_53375_39185.jpg



WS view: two leaky slant pumps in pumphouse with missing roof.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	U	Issue No.	32
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.794014 °	37.794014 °
				-121.354434 °	-121.354434 °
DWR ID	19197				

Comment Code

Inspector Comment

DS_ID:19197
 FS_ID:53376
 EP_NO: 4305
 Repair Type: Urgent
 Crossing Status: Found
 UCIP Comments: 10/10/2018 Extremely overgrown vegetation did not allow visual inspection of WS levee erosion; however, there are indications based on vegetation growth patterns that the erosion is still present, so keeping crossing as Urgent (D. Sanoski - DWR UCIP).08/31/2016: Heavy sloughing and sink hole remains at the WS slope in alignment with pipes. Though sloughing is not affecting levee prism, it is still an indication of a pipe integrity problem. Oil leak at the pump but does not appear to impact levee. (K. Fazel - UCIP)10/22/2013:- missing roof in pump house.- no protection for siphon breaker- huge erosion under pumphouse and levee slope on waterside. (P. Amatya - DWR)
 FIELD_STRUCT_DESC: 2 of 2: 18-inch steel irrigation discharge pipe through the levee, 4.8 feet below the crown. Pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) shoulder. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Plans for installation of two irrigation pumps on the bank to replace an old centrifugal pumping plant at the same location authorized under Permit No. 4305, 1963 - Reclamation District No. 2062) [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.67)].
 FS Date: 10/10/2018 11:20:00 AM

LM Start	1.64	Rating **	U	Issue No.	32 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_FA_2019_53376_39176.jpg



WS view: pipes, walkway, and pumphouse with missing roof (right).

Photo 2 of 3 : UCIP_FA_2019_53376_39175.jpg



WS view: walkway in poor condition, to pumphouse.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.64	Rating **	U	Issue No.	32 (cont)
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.794014 °	37.794014 °
				-121.354434 °	-121.354434 °
DWR ID	19197				
Comment Code					
Inspector Comment					
DS_ID:19197 FS_ID:53376 EP_NO: 4305 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/10/2018 Extremely overgrown vegetation did not allow visual inspection of WS levee erosion; however, there are indications based on vegetation growth patterns that the erosion is still present, so keeping crossing as Urgent (D. Sanoski - DWR UCIP).08/31/2016: Heavy sloughing and sink hole remains at the WS slope in alignment with pipes. Though sloughing is not affecting levee prism, it is still an indication of a pipe integrity problem. Oil leak at the pump but does not appear to impact levee. (K. Fazel - UCIP)10/22/2013:- missing roof in pump house.- no protection for siphon breaker- huge erosion under pumphouse and levee slope on waterside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 2 of 2: 18-inch steel irrigation discharge pipe through the levee, 4.8 feet below the crown. Pump house on the waterside (WS) slope. Siphon breaker on the landside (LS) shoulder. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Plans for installation of two irrigation pumps on the bank to replace an old centrifugal pumping plant at the same location authorized under Permit No. 4305, 1963 - Reclamation District No. 2062) [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 1.67)]. FS Date: 10/10/2018 11:20:00 AM					

Photo 3 of 3 : UCIP_FA_2019_53376_39174.jpg



WS view: two leaky slant pumps in pumphouse with missing roof.

LM Start	1.79	Rating **	M	Issue No.	14
LM End	1.79	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.795289 °	37.795289 °
				-121.356750 °	-121.356750 °
DWR ID	DWR_RD2062_02_f_2019_14				
Comment Code					
DE : Debris					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.13	Rating **	M	Issue No.	13
LM End	2.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.798103°	37.798103°
				-121.361789°	-121.361789°
DWR ID	DWR_RD2062_02_f_2019_13				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	2.13	Rating **	M	Issue No.	12
LM End	2.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.798104°	37.798104°
				-121.361789°	-121.361789°
DWR ID	DWR_RD2062_02_f_2019_12				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	2.23	Rating **	M	Issue No.	11
LM End	2.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.798909°	37.798909°
				-121.363258°	-121.363258°
DWR ID	DWR_RD2062_02_f_2019_11				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.49	Rating **	C	Issue No.	22
LM End	2.49	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.801227°	37.801227°
				-121.367131°	-121.367131°
DWR ID	DWR_RD2062_02_s_2019_22				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	3.14	Rating **	C	Issue No.	21
LM End	3.14	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.804538°	37.804538°
				-121.377946°	-121.377946°
DWR ID	DWR_RD2062_02_s_2019_21				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.24	Rating **	M	Issue No.	33
LM End	3.24	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.804770°	37.804770°
				-121.379679°	-121.379679°
DWR ID	19199				
Comment Code					
Inspector Comment					
DS_ID:19199 FS_ID:23304 EP_NO: 11524 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - waterside pipe immersed into channel water.- most of the pipe on landside exposed and siphon breaker on waterside not protected. FIELD_STRUCT_DESC: 1 of 3: 24-inch coated steel drainage discharge pipe through the levee, 2 feet below the crown. Siphon breaker on the waterside (WS) slope. Pump on a steel platform in a drainage ditch, 350 feet from the levee centerline off the landward berm. (Plans to install a drainage pump and 24-inch discharge line through the levee at existing main drainage pump authorized under Permit No. 11524, 1976 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 3.29)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23304_40147.jpg



WS view: 24-inch steel pipe (left) with siphon breaker on levee slope. 18-inch pipe on right.

LM Start	3.24	Rating **	M	Issue No.	33 (cont)
LM End	3.24	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_23304_40146.jpg



WS view: leaky siphon breaker on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.24	Rating **	M	Issue No.	33 (cont)
LM End	3.24	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.804770°	37.804770°
				-121.379679°	-121.379679°
DWR ID	19199				
Comment Code					
Inspector Comment					
DS_ID:19199 FS_ID:23304 EP_NO: 11524 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - waterside pipe immersed into channel water.- most of the pipe on landside exposed and siphon breaker on waterside not protected. FIELD_STRUCT_DESC: 1 of 3: 24-inch coated steel drainage discharge pipe through the levee, 2 feet below the crown. Siphon breaker on the waterside (WS) slope. Pump on a steel platform in a drainage ditch, 350 feet from the levee centerline off the landward berm. (Plans to install a drainage pump and 24-inch discharge line through the levee at existing main drainage pump authorized under Permit No. 11524, 1976 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 3.29)]. FS Date: 10/22/2013					

Photo 3 of 3 : UCIP_FA_2019_23304_40148.jpg



LS view: overview of pipes on levee berm and pump platform (marked - right) off the berm 350 ft from the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.24	Rating **	M	Issue No.	34
LM End	3.24	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.804777°	37.804777°	
			-121.379704°	-121.379704°	
DWR ID	19198				
Comment Code					
Inspector Comment					
DS_ID:19198 FS_ID:23023 EP_NO: 11524 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - 18-inch pipe bifurcated near the pump and two gate valves installed.- waterside pipe immersed into channel water.- most of the pipe on landside exposed and siphon breaker on waterside not protected. FIELD_STRUCT_DESC: 2 of 3: 18-inch coated steel drainage discharge pipe through the levee, 4 feet below the crown. Siphon breaker on the waterside (WS) slope. Pump on a steel platform in a drainage ditch, 350 feet from the levee centerline off the landward berm. (Plans to install a drainage pump and 24-inch discharge line through the levee at existing main drainage pump authorized under Permit No. 11524, 1976 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 3.29), 16-inch pipe referenced]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23023_39082.jpg



WS view: exposed 18-inch pipe with siphon breaker on levee slope. Exposed 24-inch pipe (left).

LM Start	3.24	Rating **	M	Issue No.	34 (cont)
LM End	3.24	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_23023_39081.jpg



WS view: closer view of 18-inch pipe with siphon breaker on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.24	Rating **	M	Issue No.	35
LM End	3.24	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.804787°	37.804787°	
			-121.379734°	-121.379734°	
DWR ID	19195				
Comment Code					
Inspector Comment					
DS_ID:19195 FS_ID:23305 EP_NO: 11524 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - no associated pump or any other appurtenances found on landside.- looks abandoned pipe. Needs proper abandonment. FIELD_STRUCT_DESC: 3 of 3: 24-inch coated steel drainage discharge pipe through the levee, 2 feet below the crown. Siphon breaker on the waterside (WS) slope. Pump on a steel platform in a drainage ditch, 350 feet from the levee centerline off the landward berm. (Plans to install a drainage pump and 24-inch discharge line through the levee at existing main drainage pump authorized under Permit No. 11524, 1976 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 3.29)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23305_40153.jpg



WS view: siphon breaker in steel pipe riser on levee slope.

LM Start	3.24	Rating **	M	Issue No.	35 (cont)
LM End	3.24	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_23305_40152.jpg



WS view: closer view of siphon breaker in steel pipe riser on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.24	Rating **	M	Issue No.	35 (cont)
LM End	3.24	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.804787 °	37.804787 °
				-121.379734 °	-121.379734 °
DWR ID	19195				
Comment Code					
Inspector Comment					
DS_ID:19195 FS_ID:23305 EP_NO: 11524 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - no associated pump or any other appurtenances found on landside.- looks abandoned pipe. Needs proper abandonment. FIELD_STRUCT_DESC: 3 of 3: 24-inch coated steel drainage discharge pipe through the levee, 2 feet below the crown. Siphon breaker on the waterside (WS) slope. Pump on a steel platform in a drainage ditch, 350 feet from the levee centerline off the landward berm. (Plans to install a drainage pump and 24-inch discharge line through the levee at existing main drainage pump authorized under Permit No. 11524, 1976 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 3.29)]. FS Date: 10/22/2013					

Photo 3 of 3 : UCIP_FA_2019_23305_40151.jpg



WS view: exposed pipe and steel pipe riser on levee slope.

LM Start	3.30	Rating **	C	Issue No.	20
LM End	3.30	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.805013 °	37.805013 °
				-121.380690 °	-121.380690 °
DWR ID	DWR_RD2062_02_s_2019_20				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.37	Rating **	C	Issue No.	19
LM End	3.37	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.805302°	37.805302°
				-121.381964°	-121.381964°
DWR ID	DWR_RD2062_02_s_2019_19				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	3.48	Rating **	C	Issue No.	18
LM End	3.48	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.805692°	37.805692°
				-121.383837°	-121.383837°
DWR ID	DWR_RD2062_02_s_2019_18				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	3.74	Rating **	M	Issue No.	17
LM End	3.74	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.806798°	37.806798°
				-121.388427°	-121.388427°
DWR ID	DWR_RD2062_02_s_2019_17				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Paradise Cut	Right	3.96	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.77	Rating **	M	Issue No.	9
LM End	3.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.807013°	37.809286°
				-121.388964°	-121.390327°
DWR ID	DWR_RD2062_02_f_2019_9				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

LM Start	3.84	Rating **	C	Issue No.	16
LM End	3.84	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.807703°	37.807703°
				-121.389824°	-121.389824°
DWR ID	DWR_RD2062_02_s_2019_16				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2019 Levee Inspection Results

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles
Unit No. 03 Old River	Left	5.55

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	5/21/2019 - 5/21/2019		10/2/2019 - 10/2/2019	
DWR Inspector	Alberto De Leon		Alberto De Leon	
Accompanied By	Tim Mello RD2062		Tim Mello RD2062 Mike Engelmann DWR	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	-0.03	Rating **	M	Issue No.	1
LM End	0.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.809514 °	37.809514 °
				-121.390125 °	-121.390125 °
DWR ID	RD2062U03RM29.94				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM29.94 08/14/2019: No significant change observed. 09/13/2017: The erosion site has expanded significantly along the river bank. 11/09/2016: No significant change observed. 06/25/2015: The erosion is below a large oak tree. Vegetation is visible around the erosion site.					

Photo 1 of 3 : SJR2019_RD2062U03RM29.94_4.jpg



Front view of the erosion site. Note the large tree above the erosion.

LM Start	-0.03	Rating **	M	Issue No.	1 (cont)
LM End	0.07	Issue Type +	Ma	Location *	

Photo 2 of 3 : SJR2019_RD2062U03RM29.94_10.jpg



Close-up view of the erosion.

LM Start	-0.03	Rating **	M	Issue No.	1 (cont)
LM End	0.07	Issue Type +	Ma	Location *	

Photo 3 of 3 : SJR2019_RD2062U03RM29.94_3.jpg



Close-up view of the erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.09	Rating **	U	Issue No.	2 (cont)
LM End	0.12	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.809932°	37.809932°
				-121.388788°	-121.388788°
DWR ID	RD2062U03RM30.02				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM30.02 08/14/2019: The erosion has extended downstream by approximately 60 ft. 09/13/2017: The erosion site has expanded significantly with the erosion length increased to approximately 90 ft from 40 ft. Signs of animal activities have been found at the site. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: Hard to view the erosion because of the dense vegetation and trees on site. The site is under the bush, close to the tree.					

Photo 3 of 3 : SJR2019_RD2062U03RM30.02_4.jpg



Close-up view of the erosion.

LM Start	0.17	Rating **	M	Issue No.	3
LM End	0.17	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.810268°	37.810268°
				-121.387495°	-121.387495°
DWR ID	RD2062U03RM30.1				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM30.1 08/14/2019: No significant change observed. 09/13/2017: No significant change observed. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: The protection at the levee toe has been washed away.					

Photo 1 of 3 : SJR2019_RD2062U03RM30.10_3.jpg



Direct view of the site.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.22	Rating **	U	Issue No.	4 (cont)
LM End	0.31	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.810609°	37.810609°
				-121.385879°	-121.385879°
DWR ID	RD2062U03RM30.19				
Comment Code					
Inspector Comment					
<p>Site ID: RD2062U03RM30.19 08/14/2019: No significant change observed. 09/13/2017: The erosion has developed vertically. More vegetation at the site. 07/25/2106: No significant change observed. More vegetation observed at the site. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: A new pocket erosion at the upper levee slope has been found directly above a large tree. The erosion might have been caused by internal pipe leakage or surface runoff. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: No significant change observed on site. Dense vegetation is visible along the water line. 09/07/2010: No significant change observed on site. Much of the upper slope was recently cleared of vegetation by spraying. 4- to 6-foot vertical scarp and pocket erosions are lined along a span of 475 feet. In some sections, the vertical scarp encroaches into the levee prism. There is a lack of berm along this reach, exposing the levee slope to high flow velocities during normal and flood events. 08/06/2010: Recommended as local maintenance issue, per CLRO. 03/09/2010: As discussed with Michael Moncrief of MBK Engineers, the site will be 'addressed' later this year. 09/29/2009: No major change observed since last visit; pocket erosion and a vertical scarp forming; this site was combined with Site RM30.13 and 30.02 with a combined total erosion length of 475 feet; recommended as annual assessment and monitoring of the site, per CLRO CES Evaluation 2008 Report; previously rated "M". 11/05/2008: Top of vertical scarp has rip rap that appears to be sliding; rodent holes; existing toe rip rap.</p>					

Photo 3 of 3 : SJR2019_RD2062U03RM30.19_10.jpg



Front view of the site with dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.33	Rating **	M	Issue No.	43
LM End	0.33	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.810952°	37.810952°
				-121.384748°	-121.384748°
DWR ID	DWR_RD2062_03_f_2019_43				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.35	Rating **	M	Issue No.	5
LM End	0.35	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.811101°	37.811101°
				-121.384402°	-121.384402°
DWR ID	RD2062U03RM30.27				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM30.27 08/14/2019: No significant change observed. 09/13/2017: No significant change observed. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: The site is right at the downstream of a river bend.					

Photo 1 of 3 : SJR2019_RD2062U03RM30.27_10.jpg



Front view of the erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.35	Rating **	U	Issue No.	42
LM End	0.35	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.810950°	37.810950°
				-121.384317°	-121.384317°
DWR ID	DWR_RD2062_03_f_2019_42				
Comment Code					
DE : Debris					
Inspector Comment					
PGE utility pole left on the landside slope. LMA will contact PGE for removal.					

Photo 1 of 1 : FA_2019_RD2062_311_42_20191027_00055.jpg



View of utility company debris on landside slope. Fall 2019

LM Start	0.51	Rating **	C	Issue No.	38
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.812552°	37.812552°
				-121.382781°	-121.382781°
DWR ID	DWR_RD2062_03_s_2016_38				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
RD has repaired erosion. Fall 2019					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.51	Rating **	U	Issue No.	44
LM End	0.51	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.812575°	37.812575°	
			-121.382798°	-121.382798°	
DWR ID	19200				
Comment Code					
Inspector Comment					
DS_ID:19200 FS_ID:53377 EP_NO: 2029 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/10/2018 Same as last inspection; erosion still present on LS slope, so keeping as Urgent (D. Sanoski - DWR UCIP).08/31/2016: Sloughing of LS slope beneath exposed section of pipe. Overflow pipe has been replaced on WS, though I could not locate a permit for that work. (K. Fazel - UCIP)10/22/2013:- pits and holes on overflow pipe on waterside.- underpinning at pump support.- slope erosion on both sides of the levee.- 2-inch electric conduit on waterside and power pole on landside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 16-inch coated steel irrigation discharge pipe through the levee, 8 feet below the crown. Siphon breaker on the landside (LS) slope. Pump house on the waterside (WS) slope. Concrete distribution box on the LS. 2-inch electrical conduit on the WS. Service pole on the LS. Newly installed, as of 2016, overflow pipe with shutoff valve on the WS. (Plans for installation of an inclined irrigation pump on the bank authorized under Permit No. 2029, 1954 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 0.52)]. FS Date: 10/10/2018 11:25:00 AM					

Photo 1 of 3 : UCIP_FA_2019_53377_40158.jpg



WS view: pump house on levee slope and soil erosion on levee slope.

LM Start	0.51	Rating **	U	Issue No.	44 (cont)
LM End	0.51	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_53377_40157.jpg



WS view: pump house on levee slope and holes-pits on corroded overflow pipe (left).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.51	Rating **	U	Issue No.	44 (cont)
LM End	0.51	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.812575°	37.812575°
				-121.382798°	-121.382798°
DWR ID	19200				
Comment Code					
Inspector Comment					
DS_ID:19200 FS_ID:53377 EP_NO: 2029 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/10/2018 Same as last inspection; erosion still present on LS slope, so keeping as Urgent (D. Sanoski - DWR UCIP).08/31/2016: Sloughing of LS slope beneath exposed section of pipe. Overflow pipe has been replaced on WS, though I could not locate a permit for that work. (K. Fazel - UCIP)10/22/2013:- pits and holes on overflow pipe on waterside.- underpinning at pump support.- slope erosion on both sides of the levee.- 2-inch electric conduit on waterside and power pole on landside. (P. Amatya - DWR) FIELD_STRUCT_DESC: 16-inch coated steel irrigation discharge pipe through the levee, 8 feet below the crown. Siphon breaker on the landside (LS) slope. Pump house on the waterside (WS) slope. Concrete distribution box on the LS. 2-inch electrical conduit on the WS. Service pole on the LS. Newly installed, as of 2016, overflow pipe with shutoff valve on the WS. (Plans for installation of an inclined irrigation pump on the bank authorized under Permit No. 2029, 1954 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 0.52)]. FS Date: 10/10/2018 11:25:00 AM					

Photo 3 of 3 : UCIP_FA_2019_53377_40156.jpg



WS view: slant pump in pump house on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.55	Rating **	M	Issue No.	7
LM End	0.56	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.813070°	37.813070°
				-121.383100°	-121.383100°
DWR ID	RD2062U03RM30.43				

Comment Code

Inspector Comment

Site ID: RD2062U03RM30.43
 08/14/2019: No significant change observed.
 09/13/2017: No significant change observed.
 07/25/2016: No significant change observed.
 06/25/2015: No significant change observed.
 07/02/2014: No significant change observed.
 08/13/2013: No significant change observed.
 08/07/2012: The site has been visited by boat survey. No significant change observed.
 08/23/2011: No significant change observed on site.
 09/07/2010: No significant change observed on site. Much of the placed rip rap revetment has slid. It is no longer adequately protecting the slope.
 08/06/2010: Recommended as local maintenance issue, per CLRO Report.
 03/09/2010: As discussed with Michael Moncrief of MBK, site will be 'addressed' this year.
 09/29/2009: No major change observed since last visit; a section of the rip rap has slipped, exposing a levee section that has eroded; recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; Site # is the same as RM30.43,LM0.63; previously rated "U".
 11/05/2008: Site is located inside of a bend; scarp looks to be into the levee prism; piles of concrete chunks placed on the slope, with some of them already starting to slide.

LM Start	0.55	Rating **	M	Issue No.	7 (cont)
LM End	0.56	Issue Type +	Ma	Location *	

Photo 1 of 3 : SJR2019_RD2062U03RM30.43_3.jpg



Close-up view of the site.

Photo 2 of 3 : SJR2019_RD2062U03RM30.43_2.jpg



Front view of the site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	0.55	Rating **	M	Issue No.	7 (cont)
LM End	0.56	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.813070°	37.813070°
				-121.383100°	-121.383100°
DWR ID	RD2062U03RM30.43				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM30.43 08/14/2019: No significant change observed. 09/13/2017: No significant change observed. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed. 08/23/2011: No significant change observed on site. 09/07/2010: No significant change observed on site. Much of the placed rip rap revetment has slid. It is no longer adequately protecting the slope. 08/06/2010: Recommended as local maintenance issue, per CLRO Report. 03/09/2010: As discussed with Michael Moncrief of MBK, site will be 'addressed' this year. 09/29/2009: No major change observed since last visit; a section of the rip rap has slipped, exposing a levee section that has eroded; recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; Site # is the same as RM30.43,LM0.63; previously rated "U". 11/05/2008: Site is located inside of a bend; scarp looks to be into the levee prism; piles of concrete chunks placed on the slope, with some of them already starting to slide.					

Photo 3 of 3 : SJR2019_RD2062U03RM30.43_4.jpg



Front view of the site.

LM Start	0.75	Rating **	M	Issue No.	41
LM End	0.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.815440°	37.815440°
				-121.381511°	-121.381511°
DWR ID	DWR_RD2062_03_f_2019_41				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	N/A : Not Applicable A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.03	Rating **	M	Issue No.	40
LM End	1.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.817750 °	37.817750 °
				-121.378604 °	-121.378604 °
DWR ID	DWR_RD2062_03_f_2019_40				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.18	Rating **	M	Issue No.	8
LM End	1.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.819290 °	37.819290 °
				-121.378880 °	-121.378880 °
DWR ID	RD2062U03RM31.12				
Comment Code					
Inspector Comment					
<p>Site ID: RD2062U03RM31.12 08/14/2019: No significant change observed. 09/13/2017: No significant change observed. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: No significant change observed on site. 09/07/2010: No significant change observed on site. Much of the seasonal grass along the slope was cleared. Site consists of an existing scalloped erosion approximately 30 feet long by 5 feet wide at its widest opening. The lateral crack is extended outwards along the middle slope. There is a 1 to 2 feet of differential settlement that could further develop into a shallow slide. 08/06/2010: Recommended as local maintenance issue, per CLRO. 03/09/2010: As discussed with Michael Moncrief of MBK Engineer, site will be 'addressed' this year. 09/28/2009: No major change observed; section of rip rap has slipped, creating a terraced effect; dense vegetation growth; recommended as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Site # is the same as RM31.12,LM1.25; previously rated "U". 09/14/2006: 1-2' into prism.</p>					

Photo 1 of 3 : SJR2019_RD2062U03RM31.12_5.jpg



Front view of the site.

<p>* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.18	Rating **	M	Issue No.	8 (cont)
LM End	1.19	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR Erosion Survey		37.819290 °	37.819290 °	
			-121.378880 °	-121.378880 °	
DWR ID	RD2062U03RM31.12				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM31.12 08/14/2019: No significant change observed. 09/13/2017: No significant change observed. 07/25/2016: No significant change observed. 06/25/2015: No significant change observed. 07/02/2014: No significant change observed. 08/13/2013: No significant change observed. 08/07/2012: The site has been visited by boat survey. No significant change observed 08/23/2011: No significant change observed on site. 09/07/2010: No significant change observed on site. Much of the seasonal grass along the slope was cleared. Site consists of an existing scalloped erosion approximately 30 feet long by 5 feet wide at its widest opening. The lateral crack is extended outwards along the middle slope. There is a 1 to 2 feet of differential settlement that could further develop into a shallow slide. 08/06/2010: Recommended as local maintenance issue, per CLRO. 03/09/2010: As discussed with Michael Moncrief of MBK Engineer, site will be 'addressed' this year. 09/28/2009: No major change observed; section of rip rap has slipped, creating a terraced effect; dense vegetation growth; recommended as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Site # is the same as RM31.12,LM1.25; previously rated "U". 09/14/2006: 1-2' into prism.					

LM Start	1.18	Rating **	M	Issue No.	8 (cont)
LM End	1.19	Issue Type +	Ma	Location *	

Photo 2 of 3 : SJR2019_RD2062U03RM31.12_2.jpg



Front view of the site.

Photo 3 of 3 : SJR2019_RD2062U03RM31.12_1.jpg



Close-up view of the site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.31	Rating **	U	Issue No.	22
LM End	1.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.820322°	37.821072°
				-121.377146°	-121.377031°
DWR ID	DWR_RD2062_03_s_2018_22				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2019_RD2062_311_22_20191111_00058.jpg



View of vegetation on waterside slope. Fall 2019

LM Start	1.32	Rating **	M	Issue No.	37
LM End	1.32	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.820459°	37.820459°
				-121.377109°	-121.377109°
DWR ID	DWR_RD2062_03_f_2019_37				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	1.36	Rating **	M	Issue No.	15
LM End	5.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.821032°	37.807536°
				-121.377046°	-121.328314°
DWR ID	DWR_RD2062_03_s_2019_15				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2019_RD2062_311_15_20190830_00032.jpg



Typical view of vegetation on waterside slope. (Spring 2019)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	1.46	Rating **	M	Issue No.	34
LM End	1.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.821657°	37.821657°
				-121.375657°	-121.375657°
DWR ID	DWR_RD2062_03_f_2019_34				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	1.70	Rating **	M	Issue No.	33
LM End	1.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.820938°	37.820938°
				-121.371534°	-121.371534°
DWR ID	DWR_RD2062_03_f_2019_33				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.95	Rating **	M	Issue No.	32
LM End	1.95	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.819118°	37.819118°
				-121.367894°	-121.367894°
DWR ID	DWR_RD2062_03_f_2019_32				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.03	Rating **	M	Issue No.	30
LM End	2.03	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.818647°	37.818647°
				-121.366502°	-121.366502°
DWR ID	DWR_RD2062_03_f_2019_30				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	2.16	Rating **	M	Issue No.	29
LM End	2.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.818687°	37.818687°
				-121.364138°	-121.364138°
DWR ID	DWR_RD2062_03_f_2019_29				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	2.18	Rating **	M	Issue No.	25
LM End	2.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.818748°	37.818748°
				-121.363716°	-121.363716°
DWR ID	DWR_RD2062_03_s_2019_25				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.77	Rating **	M	Issue No.	45
LM End	2.77	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.816362°	37.816362°	
			-121.354339°	-121.354339°	
DWR ID	19202				
Comment Code					
Inspector Comment					
DS_ID:19202 FS_ID:23311 EP_NO: 2505 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pumphouse roof missing.- siphon breaker buried by dirt in CMP riser.- 2.25 inch electric conduit and power pole on landside. FIELD_STRUCT_DESC: 2 of 2: 16-inch irrigation discharge pipe of an unknown material through the levee, 6.5 feet below the crown. Pump in a pump house on a pile structure in the stream. Timber walkway to the pump. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Concrete distribution box at the LS toe. Timber bulkhead and slab on the waterside (WS) slope. Installed by USACE in 1963. (Plans for the installation of two irrigation pumps on the bank to replace an existing pumping plant at this location authorized under Permit No. 2505, 1959 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 2.81)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23311_40175.jpg



WS view: wooden walkway to pumphouse, pumphouse on wooden pile structure in the stream.

LM Start	2.77	Rating **	M	Issue No.	45 (cont)
LM End	2.77	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_23311_40174.jpg



WS view: exposed steel pipes and an electric conduit on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.77	Rating **	M	Issue No.	46
LM End	2.77	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DRAFT DWR UCIP Field Study		37.816362 °	37.816362 °	
			-121.354334 °	-121.354334 °	
DWR ID	19205				
Comment Code					
Inspector Comment					
DS_ID:19205 FS_ID:23312 EP_NO: 2505 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pumphouse roof missing.- siphon breaker buried by dirt in CMP riser.- 2.25 inch electric conduit and power pole on landside. FIELD_STRUCT_DESC: 1 of 2: 14-inch irrigation discharge pipe of an unknown material through the levee, 6.5 feet below the crown. Pump in a pump house on a pile structure in the stream. Timber walkway to the pump. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Concrete distribution box at the LS toe. Timber bulkhead and slab on the waterside (WS) slope. Installed by USACE in 1963. (Plans for the installation of two irrigation pumps on the bank to replace an existing pumping plant at this location authorized under Permit No. 2505, 1959 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 2.81)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23312_40181.jpg



WS view: wooden walkway to pumphouse, pumphouse on wooden pile structure in the stream.

LM Start	2.77	Rating **	M	Issue No.	46 (cont)
LM End	2.77	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_FA_2019_23312_40179.jpg



WS view: exposed steel pipes and a electric conduit on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	2.77	Rating **	M	Issue No.	46 (cont)
LM End	2.77	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.816362 °	37.816362 °
				-121.354334 °	-121.354334 °
DWR ID	19205				
Comment Code					
Inspector Comment					
<p>DS_ID:19205 FS_ID:23312 EP_NO: 2505 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pumphouse roof missing.- siphon breaker buried by dirt in CMP riser.- 2.25 inch electric conduit and power pole on landside. FIELD_STRUCT_DESC: 1 of 2: 14-inch irrigation discharge pipe of an unknown material through the levee, 6.5 feet below the crown. Pump in a pump house on a pile structure in the stream. Timber walkway to the pump. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Concrete distribution box at the LS toe. Timber bulkhead and slab on the waterside (WS) slope. Installed by USACE in 1963. (Plans for the installation of two irrigation pumps on the bank to replace an existing pumping plant at this location authorized under Permit No. 2505, 1959 - Reclamation District No. 2062). [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 2.81)]. FS Date: 10/22/2013</p>					

Photo 3 of 3 : UCIP_FA_2019_23312_40180.jpg



LS view: two CMP risers on levee slope, concrete distribution box, and service pole across the dirt road, off the levee toe.

LM Start	2.85	Rating **	A/W	Issue No.	21
LM End	4.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.816313 °	37.818882 °
				-121.352848 °	-121.334412 °
DWR ID	DWR_RD2062_03_s_2018_21				
Comment Code					
<p>A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.</p>					
Inspector Comment					

No Photos

<p>* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.05	Rating **	M	Issue No.	28
LM End	3.05	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.817885 °	37.817885 °
				-121.349956 °	-121.349956 °
DWR ID	DWR_RD2062_03_f_2019_28				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	3.31	Rating **	U	Issue No.	19
LM End	5.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.819898 °	37.807428 °
				-121.346864 °	-121.330299 °
DWR ID	DWR_RD2062_03_f_2019_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2019_RD2062_311_19_20191111_00057.jpg



View of vegetation on landside slope and easement. Fall 2019

LM Start	3.61	Rating **	M	Issue No.	31
LM End	3.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.816982 °	37.816541 °
				-121.342939 °	-121.342191 °
DWR ID	DWR_RD2062_03_s_2015_31				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
There is about a 3 ft vertical cut at the levee toe into the levee prism.					

Photo 1 of 1 : FA_2019_RD2062_311_31_20190830_00037.jpg



View of the eroded landside levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.83	Rating **	M	Issue No.	24
LM End	3.83	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.818245°	37.818245°
				-121.340564°	-121.340564°
DWR ID	DWR_RD2062_03_s_2019_24				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	3.91	Rating **	M	Issue No.	26
LM End	3.91	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.819465°	37.819465°
				-121.340375°	-121.340375°
DWR ID	DWR_RD2062_03_f_2019_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	3.99	Rating **	A/W	Issue No.	10
LM End	4.01	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.820834°	37.820834°
				-121.340314°	-121.340314°
DWR ID	RD2062U03RM33.92				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM33.92 08/14/2019: No significant change observed. 09/13/2017: The erosion site is immediately downstream of a sharp river bend.					

Photo 1 of 3 : SJR2019_RD2062U03RM33.92_1.JPG



Close-up view of the erosion located at the inside of a sharp river bend.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	3.99	Rating **	A/W	Issue No.	10 (cont)
LM End	4.01	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.820834 °	37.820834 °
				-121.340314 °	-121.340314 °
DWR ID	RD2062U03RM33.92				
Comment Code					
Inspector Comment					
Site ID: RD2062U03RM33.92 08/14/2019: No significant change observed. 09/13/2017: The erosion site is immediately downstream of a sharp river bend.					

Photo 2 of 3 : SJR2019_RD2062U03RM33.92_3.JPG



Close-up view of the erosion.

LM Start	3.99	Rating **	A/W	Issue No.	10 (cont)
LM End	4.01	Issue Type +	Ma	Location *	

Photo 3 of 3 : SJR2019_RD2062U03RM33.92_6.JPG



Close-up view of the erosion. Note the sandy material of the river bank at the erosion site.

LM Start	4.83	Rating **	M	Issue No.	35
LM End	4.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.812849 °	37.811682 °
				-121.336116 °	-121.336271 °
DWR ID	DWR_RD2062_03_f_2014_35				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
There is a 2 to 3 feet vertical cut at the landside toe.					

Photo 1 of 1 : FA_2019_RD2062_311_35_20190830_00038.jpg



View of a 2-3 feet vertical cut at the landside levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	4.91	Rating **	M	Issue No.	20
LM End	4.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.811729°	37.811729°
				-121.336117°	-121.336117°
DWR ID	DWR_RD2062_03_f_2019_20				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	5.18	Rating **	C	Issue No.	18
LM End	5.18	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.808167°	37.808167°
				-121.334530°	-121.334530°
DWR ID	DWR_RD2062_03_s_2019_18				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	5.28	Rating **	M	Issue No.	16
LM End	5.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.807519°	37.807519°
				-121.332921°	-121.332921°
DWR ID	DWR_RD2062_03_s_2019_16				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	5.37	Rating **	M	Issue No.	47 (cont)
LM End	5.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.807305°	37.807305°
				-121.331290°	-121.331290°
DWR ID	19203				
Comment Code					
Inspector Comment					
DS_ID:19203 FS_ID:23142 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - siphon breakers not protected.- flow meter and gage station on waterside.- pump house on wooden pile structure. Walkway to the pumphouse. FIELD_STRUCT_DESC: 1 of 2: 16-inch irrigation discharge pipe of an unknown material through the levee, 4 feet below the crown. Pump in a pump house on a pile structure in the stream. Walkway to the pump house. Siphon breaker on the landside (LS) slope. Concrete distribution box on the LS berm. [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 5.45)]. FS Date: 10/22/2013					

Photo 3 of 3 : UCIP_FA_2019_23142_39547.jpg



WS view: pump house on wooden pipe structure in the stream. Two steel pipes under the walkway.

LM Start	5.37	Rating **	M	Issue No.	48
LM End	5.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.807305°	37.807305°
				-121.331276°	-121.331276°
DWR ID	19206				
Comment Code					
Inspector Comment					
DS_ID:19206 FS_ID:23140 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - siphon breakers not protected.- flow meter and gage station on waterside.- pump house on wooden pile structure. Walkway to the pumphouse. FIELD_STRUCT_DESC: 2 of 2: 16-inch irrigation discharge pipe of an unknown material through the levee, 4 feet below the crown. Pump in a pump house on a pile structure in the stream. Walkway to the pump house. Siphon breaker on the landside (LS) slope. Concrete distribution box on the LS berm. [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 5.45)]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_FA_2019_23140_39531.jpg



WS view: steel walkway to pump house in the stream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2019

Reclamation District No. 2062 Stewart

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Old River	Left	5.55	10/02/2019 10/02/2019	Alberto De Leon

LM Start	5.37	Rating **	M	Issue No.	48 (cont)
LM End	5.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DRAFT DWR UCIP Field Study			37.807305°	37.807305°
				-121.331276°	-121.331276°
DWR ID	19206				
Comment Code					
Inspector Comment					
DS_ID:19206 FS_ID:23140 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - siphon breakers not protected.- flow meter and gage station on waterside.- pump house on wooden pile structure. Walkway to the pumphouse. FIELD_STRUCT_DESC: 2 of 2: 16-inch irrigation discharge pipe of an unknown material through the levee, 4 feet below the crown. Pump in a pump house on a pile structure in the stream. Walkway to the pump house. Siphon breaker on the landside (LS) slope. Concrete distribution box on the LS berm. [Additional Reference(s): DWR Levee Log, 2007. USACE San Joaquin O&M Manual 9, April 1964, (HLM 5.45)]. FS Date: 10/22/2013					

Photo 2 of 3 : UCIP_FA_2019_23140_39530.jpg



WS view: two 16-inch pipes under walkway. Gate valve without handle on one of the pipes.

LM Start	5.37	Rating **	M	Issue No.	48 (cont)
LM End	5.37	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_FA_2019_23140_39529.jpg



WS view: pump house on wooden pipe structure in the stream. Two steel pipes under the walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---