

# Appendix **C**

## **Miscellaneous Summary Reports**


This Appendix includes reporting of a Non Project Levee in the San Joaquin River Flood Control Project. It also includes channels in areas that are outside of the the Sacramento and San Joaquin River Flood Control Project. Appendix C includes:

- Miscellaneous Index
- Map
- Individual local area Summary Profiles

This page is intentionally left blank

Local Agencies & Areas	County	Tab Name	Short Name	Page
<b>Reclamation Districts</b>				
Reclamation District No. 2074 Sargent-Barnhart Tract	San Joaquin	RD 2074	RD2074	5
<b>Named Areas</b>				
Adin Community Service District	Modoc	Adin	NA0030	9
Fairfield Suisun Sewer District	Solano	FSSD	NA0035	13
Placer County	Placer	Truckee River	NA0045	17

This page is intentionally left blank



 Map of LMAs (Other Flood Control Systems)



# Reclamation District No. 2074 Sargent-Barnhart Tract

**San Joaquin County**

**Contact**

Nelson Bahler  
President  
PO Box 7576  
Stockton CA 95267  
Phone: (209) 473-6024



LMA Short Name : RD2074	Bank	Unit Length (Miles)
-------------------------	------	---------------------

No Units Associated with this District.

**Threat Assessment & Recommendations**

- DWR does not inspect this area and no threat assessment or recommendations were done.

**DWR Levee Inspection Summary**

Levees in this District are not Inspected.

**DWR Structure Inspection Summary**

No Structures Inspected in this District.

**DWR Channel Inspection Summary**

No Channels Inspected in this District.

**DWR San Joaquin River Erosion Summary**

No Supplemental Erosion Sites.

**DWR Flood System Repair Project Summary**

No POI Repair Sites.

**DWR Summary of Local Maintaining Agency Report**

**Part 1 Information known to the Local Agency that is relevant to the condition or performance of the Project Levee (or jurisdictional Non-Project Levee)**

The Agency reported existing encroachments are regularly inspected and new encroachments will meet CVFPB, DWR, and USACE standards. The Agency also reported all access gates are locked. The Agency mentioned all erosion, vegetation, and rodent issues are maintained regularly and levees are in good condition.

**Part 2 Information identifying known conditions that might impair or compromise the level of flood protection provided by the Project Levee (or jurisdictional Non-Project Levee)**

No information was provided by the Agency for Part 2.

**Part 3 A summary of maintenance performed by the Local Agency during the previous fiscal year**

The Agency provided a summary of maintenance activities accomplished for all levee units. Activities include encroachment control, erosion repair, gate repair, inspection, road maintenance, rodent control, and vegetation control.

**Part 4 A statement of work and estimated cost for operation and maintenance of the Project Levee (or jurisdictional Non-Project Levee) for the current fiscal year, as approved by the Local Agency**

The Agency provided a summary of expenses and maintenance activities planned for all levee units. Expenses include costs of encroachment control, erosion repair including riprap revetment, gate repair, installation of flap gates on the storm drain pipe, rodent control, and vegetation control. The reported total estimated cost for the current fiscal year is \$610,000.

**Part 5 Any other readily available information contained in the records of the Local Agency relevant to the condition or performance of the Project Levee (or jurisdictional Non-Project Levee), as determined by the CVFPB or DWR**

The Agency reported the Five Year Plan, Emergency Procedures Manual, Existing Encroachment Permits, and Operation and Maintenance Activity Logs are available upon request.


This page is intentionally left blank

# Adin Community Service District

## Modoc County

### **Contact**

Katie Bidwell  
President  
PO Box 258  
Adin CA 96006  
Phone: (530) 260-6396



**LMA Short Name :** NA0030

**Bank Unit Length (Miles)**

No Units Associated with this District.

**Threat Assessment & Recommendations**

- The LMA should continue to maintain the area at the high level seen during the last Channel inspection.

**DWR Levee Inspection Summary**

Levees in this District are not Inspected.

**DWR Structure Inspection Summary**

No Structures Inspected in this District.

**DWR Channel Inspection Summary**

Channel Name	Overall Rating
Ash Creek	A
Dry Creek	A

**DWR San Joaquin River Erosion Summary**

No Supplemental Erosion Sites.

**DWR Flood System Repair Project Summary**

No POI Repair Sites.

**DWR Summary of Local Maintaining Agency Report**

No Reporting by this District.


This page is intentionally left blank

# Fairfield Suisun Sewer District

## Solano County

### **Contact**

Kevin Cullen  
Senior Environmental Engineer  
1010 Chadbourne Road  
Fairfield CA 94534-9700  
Phone: (707) 429-8930



LMA Short Name : NA0035	Bank	Unit Length (Miles)
-------------------------	------	---------------------

No Units Associated with this District.

**Threat Assessment & Recommendations**

- Soil and vegetation exist that may significantly impact the capacity of channels in this Area.
- The LMA should ensure that the capacity of the channel as designed and constructed is maintained.

**DWR Levee Inspection Summary**

Levees in this District are not Inspected.

**DWR Structure Inspection Summary**

No Structures Inspected in this District.

**DWR Channel Inspection Summary**

Channel Name	Overall Rating
Laurel Creek	M
Ledgewood Creek	A
McCoy Creek	A
Union Avenue Diversion	A

**DWR San Joaquin River Erosion Summary**

No Supplemental Erosion Sites.

**DWR Flood System Repair Project Summary**

No POI Repair Sites.

**DWR Summary of Local Maintaining Agency Report**

No Reporting by this District.

This page is intentionally left blank

# Placer County

## Placer County

### **Contact**

Brian Keating  
District Manager  
3091 County Center Drive Suite 220  
Auburn CA 95603  
Phone: (530) 745-7592



LMA Short Name : NA0045	Bank	Unit Length (Miles)
-------------------------	------	---------------------

No Units Associated with this District.

**Threat Assessment & Recommendations**

- The LMA should continue to maintain the area at the high level seen during the last Channel inspection.

**DWR Levee Inspection Summary**

Levees in this District are not Inspected.

Truckee  
River

**DWR Structure Inspection Summary**

No Structures Inspected in this District.

**DWR Channel Inspection Summary**

Channel Name	Overall Rating
Truckee River	A

**DWR San Joaquin River Erosion Summary**

No Supplemental Erosion Sites.

**DWR Flood System Repair Project Summary**

No POI Repair Sites.

**DWR Summary of Local Maintaining Agency Report**

No Reporting by this District.

This page is intentionally left blank