

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
0.00		Feather River right bank levee at upstream boundary of Maintenance Area No. 3. The crown is 20 feet wide and Graveled. The mileage runs upstream. The access road is Cypress Avenue 0.31 miles downstream. (M.A. 3, L.M.4.80).	1/1/2005
0.00		Ramp on both slopes. Pipe gate across landward ramp. Metal drive gate across waterward ramp	1/1/2005
0.00	0.35	Fence along the waterward slope.	1/1/2005
0.02		Power pole anchor in the landward slope.	1/1/2005
0.16		Ramp on waterward slope.	1/1/2005
0.35		Overhead-power line crosses levee. Power pole with two anchors on the landward slope.	1/1/2005
0.35		54-inch corrugated metal through levee, 25.5-feet below crown. Slide gate in 66-inch corrugated metal riser on waterward slope. Discharges into 13.5-foot concrete box at landward toe. (App. 1679).	1/1/2005
0.35		Ramp on waterward slope.	1/1/2005
0.36		Cross fence, pipe gate.	1/1/2005
0.42		Ramp on landward slope with metal drive gate.	1/1/1990
0.42		Ramp on landward slope with pipe gate welded shut.	1/1/2005
0.51		Wing levee on the waterward side.	1/1/2005
0.82		Cross fence, pipe gate.	1/1/2005
0.83		Ramp on landward slope to Central Avenue. Pipe gate across ramp.	1/1/2005
1.00		Milepost on landward shoulder.	1/1/2005
1.10		Wing levee on the waterward side.	1/1/2005
1.18		Ramp on landward slope with metal drive gate.	1/1/1990
1.18		Ramp on landward slope with pipe gate welded shut.	1/1/2005
1.47		Ramp on landward slope with metal drive gate.	1/1/2005
1.51		Abandoned 8-inch pipe through the levee, 4.8-feet below crown. Siphon breaker in 24-inch corrugated metal riser on landward shoulder. Well, submersible pump, and service pole at landward toe.	1/1/2005
1.65		Ramp on landward slope with pipe gate.	1/1/2005
1.65		Ramp on landward slope with metal drive gate.	1/1/1990
1.71		Wing levee on the waterward side.	1/1/2005
1.71		Ramp on waterward slope.	1/1/2005
1.84		Abandoned 8-inch pipe through the levee, 4.6 feet below crown. Siphon breaker in 24-inch corrugated metal riser on landward shoulder.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
2.00		Milepost on landward shoulder	1/1/2005
2.02		Concrete standpipe at landward toe.	1/1/2005
2.21		8-inch pipe through levee, 4.6-feet below the crown. Pump and gate valve at landward toe. Siphon breaker in corrugated metal riser on landward slope.	1/1/2005
2.21		Cross fence, pipe gate.	1/1/2005
2.33		10-foot PVC standpipe on landward toe.	1/1/2005
2.34		Concrete standpipe at landward toe.	1/1/2005
2.42		Ramp on landward slope to Wilke Avenue. Metal drive gate across ramp.	1/1/2005
2.42		Concrete retaining wall at landward toe. Concrete standpipe at landward toe.	1/1/2005
2.42		Wing levee on the waterward side with pipe gate.	1/1/2005
2.47		Three 18-inch steel pipes through the levees, 2.5-feet below the crown. Siphon breakers in steel risers on the landward shoulder. Pumps mounted on steel structure in the intake channel. Walkway to pumps. Discharges into large concrete sump on the landside.	1/1/2005
2.47		18-inch pipe-through the levee, 2.8-feet below crown. Siphon breaker on the landward shoulder. Discharges into concrete sump on landward side. Vertical pump mounted on the downstream side of the pump platform.	1/1/2005
2.47		14-inch pipe through the levee, 2.4-feet below the crown. Siphon breaker on the landward shoulder. Gate valve and slant pump on waterward side. Discharges into concrete sump on the landward side.	1/1/2005
2.47		1-1/4-inch electrical conduit through the levee, 2-feet below crown.	1/1/2005
2.48		Overhead power line crosses levee, power pole on waterward slope. (ABO No. 4464).	1/1/2005
2.54		Ramp on both slopes gate on landward ramp.	1/1/2005
2.72		Cross fence, pipe gate.	1/1/2005
2.85		USED benchmark on landward berm.	1/1/2005
2.90		Ramp on landward slope with metal drive gate.	1/1/1990
2.90		Ramp on landward slope with pipe gate.	1/1/2005
2.90		Wing levee on waterward side.	1/1/2005
3.00		Milepost on landward shoulder.	1/1/2005
3.09		Abandoned 8-inch pipe through levee, 4.3-feet below crown.	1/1/2005
3.09		8-inch pipe through levee, 4.3-feet below crown.	1/1/1990
3.19		Ramp on waterward slope.	1/1/2005
3.21		Ramp on landward slope.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
3.42		Abandoned steel drainpipe through levee, 4.1 feet below crown. Siphon breaker on landward slope. Butterfly shutoff valve on landward slope, concrete stand pipe and pump at toe of landward slope. Discharges into borrow pit on waterward side.	1/1/2005
3.69		Cross fence, pipe gate.	1/1/2005
3.70		Ramp on landward slope with pipe gate.	1/1/2005
3.90		Ramp on waterward slope.	1/1/2005
3.93	4.17	Filter trench along landward levee toe. (App. 14781- L.D. No.1 Sutter)	1/1/2005
4.15		Abandoned 14-inch pipe through levee, 4.1 feet below The crown. Siphon breaker on the landward slope. Open on waterward slope.	1/1/2005
4.19		Overhead power line crosses levee. (App. 10552)	1/1/2005
4.20	4.26	waterward slope cobble revetted.	1/1/2005
4.20		Ramp on waterward slope	1/1/2005
4.23		Two 24-inch, one 16-inch, and one 26-inch pipe through levee, 3.0 feet below crown. Siphon breakers on landward shoulder. Vertical pump units on pile structure in channel. Walkway to concrete distribution box at landward toe. Concrete stand pipe at landward toe.	1/1/2005
4.23		Overhead power line crosses levee. Service pole on the landward slope.	1/1/2005
4.24		Ramp on landward slope with cable gate.	1/1/1990
4.24		Ramp on landward slope with pipe gate.	1/1/2005
4.53		Cross fence, pipe gate.	1/1/1990
4.53		Steel posts on both shoulders.	1/1/2005
4.54		Ramp on landward slope to Star Bend road. Pipe gate across ramp.	1/1/2005
4.54		Ramp on the waterward slope.	1/1/2005
4.91		Abandoned 6-inch pipe through the levee, 4 feet below the crown. Steel plate on waterward end. Siphon breaker in corrugated metal pipe riser on the landward shoulder. 5-foot by 5-foot concrete distribution box at landward toe.	1/1/2005
4.98		Milepost on the landward shoulder.	1/1/2005
5.05		5-inch steel drainage pipe through the levee, 3 feet below the crown. Siphon breaker in corrugated metal riser on landward shoulder. Discharges into borrow pit on waterward side	1/1/2005
5.12	5.75	Fence along landward toe.	1/1/1990
5.17		Ramp on waterward slope.	1/1/2005
5.22		Abandoned 8-inch pipe through the levee, 4.2 feet below crown. Siphon breaker in corrugated metal riser on landward slope. Pipe capped on landward side.	1/1/2005
5.51		Ramp on waterward slope, with pipe gate.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
5.98		Milepost on the landward shoulder.	1/1/2005
6.00		Wing levee on the waterward side. (App. 4254)	1/1/2005
6.10		Overhead power line crosses levee.	1/1/2005
6.20		Ramp on waterward slope.	1/1/2005
6.22		Ramp on landward slope with pipe gate.	1/1/2005
6.62		Ramp on waterward slope.	1/1/2005
6.69		Milepost on the landward shoulder.	1/1/2005
7.12		Ramp on both slopes. Chain link gate on landward ramp.	1/1/2005
7.13	7.18	Fence along the landward shoulder.	1/1/2005
7.16		Four 26-inch pipes through the levee, 3 feet below Crown. Siphon breakers on landward shoulder, Pumps mounted on steel structure in intake on waterward side. Walkway to pumps, Discharge in concrete sump on landward side.	1/1/2005
7.18	7.28	Wing levee on waterward side.	1/1/2005
7.18		Cross fence, pipe gate.	1/1/2005
7.18		Overhead power line crosses levee.	1/1/2005
7.22		Ramp on landward slope.	1/1/2005
7.26	7.70	Waterward slope cobble revetted by district (App. 2421)	1/1/2005
7.28		Wing levee on waterward side.	1/1/2005
7.47		8-inch pipe through levee, 4 feet below crown. Siphon breaker in riser on landward Shoulder. Pipe to be used as a storm drain with a pump Structure on landward side. (App. 13980 - Sierra Nursery)	1/1/2005
7.50	7.94	Walnut trees along landward toe.	1/1/2005
7.70	7.93	Waterward slope and berm cobble revetted.	1/1/2005
7.91		Ramp on landward slope.	1/1/2005
7.93	7.97	Fence along waterward shoulder.	1/1/2005
7.94		24-inch pipe through the levee 31 feet below crown. Gate valve in pumphouse on waterward side. Concrete distribution box at the landward toe.	1/1/1990
7.94		Overhead telephone Line crosses levee. (App. 11610)	1/1/2005
7.94		24-inch pipe through the levee 31 feet below crown. Pump on waterward side. Concrete distribution box at landward toe.	1/1/2005
7.96	8.06	Department of Fish and Game boat launching ramp and Parking area on waterward side. (App. 2675A & 14083-Sutter Co.)	1/1/2005
7.97		Cross fence, pipe gate.	1/1/2005
7.98	8.23	Paved crown roadway.	1/1/2005
7.99		Ramp on waterward slope.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
7.99		Ramp on waterward slope to boat launching facility.	1/1/1990
8.00		Milepost on landward shoulder.	1/1/2005
8.23		Ramp on landward slope to Oswald Avenue.	1/1/2005
8.27		Cross fence, pipe gate.	1/1/2005
8.27	8.34	Cable fence at landward toe.	1/1/2005
9.00		Milepost on landward shoulder.	1/1/2005
9.10	9.28	Power poles along landward toe.	1/1/2005
9.10		Overhead power line crosses levee.	1/1/2005
9.11		High power line crosses levee.	1/1/2005
9.55		DWR water stage recorder on waterward side. (App. 4033)	1/1/1990
9.56		Cross fence.	1/1/2005
9.56		Cross fence, pipe gate.	1/1/1990
9.57		Ramp on landward slope to Barry Road. Pipe gate across ramp.	1/1/2005
9.57	9.61	Cable fence on the landward shoulder.	1/1/2005
9.61		Cross fence, pipe gate.	1/1/2005
10.00	10.42	Waterward slope cobble revetted by USCE 1966, Unit 8, River Mile 24.5	1/1/2005
10.00		Milepost on the landward shoulder.	1/1/2005
10.45	10.50	6-foot chain link fence 10 feet off landward toe.	1/1/2005
10.47		Proposed 18-inch steel pipe through the levee, 3 feet below levee crown. Siphon breaker on landward shoulder. (App. 7151)	1/1/1990
10.48		Ramp on landward slope to parking lot. (Star Bend fishing Area)	1/1/2005
10.64		Concrete steps with hand rails on landward slope (App. 11767 - Sutter Co.)	1/1/2005
10.70	10.90	Rock revetment on waterward slope (District, 1983).	1/1/2005
10.81		Concrete steps with handrails on the landward slope. (App. 11767 - Sutter Co.)	1/1/2005
10.90	11.12	Chain link fence 10 feet to 25 feet of landward levee toe.	1/1/2005
11.00	11.07	Bank rock revetted, 1962 and 1964.	1/1/2005
11.04		Ramp on waterward slope.	1/1/2005
11.07	11.23	Fence along the waterward shoulder.	1/1/2005
11.08		Mile marker on landward shoulder.	1/1/2005
11.08		Mile marker on landward shoulder. (11.0)	1/1/1990
11.23	11.26	Cable-fence on landward shoulder	1/1/2005
11.23	11.25	Fence along the waterward shoulder.	1/1/1990
11.23	11.26	Cable fence in landward shoulder.	1/1/1990
11.24		Ramp on landward slope with pipe gate.	1/1/2005
11.25		Cross fence, pipe gate.	1/1/1990

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
11.26	11.76	Relief wells (55) along landward toe, USCE, 1956.	1/1/2005
11.31	11.87	Waterward slope and berm cobble revetted. Site of 1955 levee break.	1/1/2005
11.43		Two 24-inch storm discharge pipelines thru levee, 2.6 Feet below crown (App 15565 - City of Yuba City).	1/1/2005
11.55		Ramp on waterward slope with pipe gate.	1/1/1990
11.64		Ramp on landward slope.	1/1/2005
11.90		6-inch and 24-inch-pipes through levee, 6.0 feet below crown. Flap gates on waterward end. Siphon breakers in corrugated metal pipe risers on waterward shoulder. Pump house at landward toe.	1/1/2005
12.00		Milepost on landward shoulder.	1/1/2005
12.14		2-inch steel pipe through levee, 3.5 feet below crown. Siphon breaker in corrugated metal pipe riser on landward Slope. (App. 12827 Nevis Industries)	1/1/2005
12.15		12kv cable through levee, 2 feet below crown. (App. 12407 - PG&E)	1/1/2005
12.21		Ramp on landward slope.	1/1/2005
12.51		Two 16-inch gas lines through levee, 3 feet below crown. PG&E gas line-crossing sign on waterward shoulder.	1/1/2005
12.73		Cross fence, pipe gate.	1/1/1990
12.75		Paved ramp on both slopes.	1/1/2005
12.78		Cross fence, pipe gate.	1/1/1990
12.90		Ramp on waterward slope.	1/1/2005
13.00		Milepost on landward shoulder.	1/1/2005
13.44	13.46	Fence along waterward shoulder.	1/1/2005
13.46		Cross fence, pipe gate.	1/1/2005
13.47		Ramp on waterward slope.	1/1/2005
13.53		Paved ramp on both slopes to Fish and Game parking area. Launching ramp and related facilities.	1/1/2005
13.61		Overhead power line crosses levee. Power pole and guy wire anchor on waterward shoulder.	1/1/2005
13.61		Overhead telephone line crosses levee.	1/1/2005
13.63		Ramp on landward slope.	1/1/2005
13.64	13.69	Residences, fences, trees- along landward toe.	1/1/2005
13.64		Cross fence, pipe gate.	1/1/2005
13.72	14.03	Landscaping along landward slope.	1/1/1990
13.81	14.31	Waterward slope cobble revetted. (App. 2377)	1/1/2005
13.84		Cross fence, chain link gate.	1/1/2005
13.85	13.87	Various trees on landward slope. Fence along landward shoulder.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
13.88		Concrete stairway on landward slope.	1/1/2005
13.90	13.92	Cyclone fence on landward shoulder.	1/1/2005
14.00	14.02	Fence posts on landward shoulder.	1/1/2005
14.02	14.03	Cyclone fence on landward slope.	1/1/2005
14.03	14.06	Reinforced concrete block retaining wall within landward toe. 95 feet in length, 5 feet high. (App. 13951 - Sutter Co.)	1/1/2005
14.03		Cross fence, metal drive gate.	1/1/2005
14.04	14.06	Reinforced concrete block retaining wall within landward toe. 95 feet in length, 5 feet high. (App. 13951 - Sutter Co.)	1/1/1990
14.06	14.08	Cinder block building at landward toe.	1/1/2005
14.10		Ramp on waterward slope.	1/1/2005
14.13	14.16	Concrete building at landward toe.	1/1/2005
14.26	14.28	Landscaping on landward slope	1/1/2005
14.26		Power pole, meter, and anchor on landward shoulder.	1/1/2005
14.27	14.28	Wire fence on landward shoulder.	1/1/2005
14.27		Concrete steps on landward slope.	1/1/2005
14.28		Overhead telephone Line crosses levee.	1/1/2005
14.28		Overhead power line crosses levee.	1/1/2005
14.28		SNRR crosses levee at crown elevation. No vehicular crossing provided. Go back to ramp on landward slope at L.M. 13.63, turn right and go north on 2nd Street for 0.70 mile to ramp on landward slope at 14.33.	1/1/2005
14.30		Fifth street crosses levee at crown elevation. Concrete stairway on landward slope at upstream. side of bridge. Bridge across channel.	1/1/2005
14.31		Overhead power line crosses levee. Power pole and Anchor at toe of landward slope. High power pole on waterward slope with 2 anchors.	1/1/2005
14.33		Ramp on landward slope to Sutter Street.	1/1/2005
14.34	14.37	Landscaping on landward slope.	1/1/2005
14.37	14.43	Concrete retaining wall along landward slope.	1/1/2005
14.42	14.63	Landscaping on the waterward slope consisting of shrubs and trees.	1/1/2005
14.47	15.26	Filter trench along landward slope (15034-District 1)	1/1/2005
14.51		Cross fence, pipe gate on landward berm.	1/1/1990
14.52		Cross fence, pipe gate and pipe gate on landward berm.	1/1/2005
14.53		Paved ramp on both slopes.	1/1/2005
14.54		Paved ramp on both slopes.	1/1/1990
14.54	14.56	Cable fence on waterward shoulder.	1/1/2005
14.55		Abandoned 4-inch pipe through levee, 15-inches below crown. Open on waterward end.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
14.60	14.61	Concrete retaining wall on landward slope. (App. 15133 - District)	1/1/2005
14.61		Overhead power line crosses levee. Two power poles on waterward berm.	1/1/2005
14.62	16.63	Landscaping on the waterward slope consisting of Shrubs and trees.	1/1/2005
14.63	14.65	Landscaping on the waterward slope. Trees on the landward slope with sprinkler system.	1/1/2005
14.65		State Highway 20 (Tenth Street Bridge) crosses levee, 11 feet above crown elevation. No vehicular crossing Provided. Go back to ramp at L.M. 14.54, turn left and proceed under bridge to ramp at L.M. 14.77.	1/1/2005
14.71		Underground telephone cable through the levee, 2 feet below the crown.	1/1/2005
14.73		Underground telephone cable through the levee, 5 feet below the crown.	1/1/2005
14.75		Cross fence, pipe gate.	1/1/2005
14.77		Ramp on both slopes.	1/1/2005
14.85		Mile marker on the landward shoulder. (14.00)	1/1/2005
14.85		Cross fence, pipe gate.	1/1/2005
14.98		16-inch sewer pipe through the levee, 5 feet below the Crown. Siphon breaker in steel riser on waterward slope. Flap gate and 4-foot by 4-foot concrete outlet box at waterward toe.	1/1/2005
14.98		24-inch sewer pipe through the levee, 2 feet below the crown. (App. 120741)	1/1/2005
14.98		24-inch steel drainage pipe through the levee, 4 feet below crown. Siphon breaker in steel riser on waterward shoulder.	1/1/2005
14.98		36-inch steel pipeline through levee, 5 feet below crown. Siphon breaker on waterward shoulder. (App-13930-Gilsizer Co. Drainage District)	1/1/2005
14.98		Abandoned 36-inch pipe through the levee, 30 feet below crown. Slide gate in corrugated metal riser on the waterward Slope.	1/1/2005
14.99		Ramp on waterward slope.	1/1/2005
15.21		Ramp on landward slope with pipe gate.	1/1/2005
15.32		Ramp on landward slope with pipe gate.	1/1/2005
15.56		16-inch gas line through levee, 3.5 feet below the crown.	1/1/2005
15.65		Cross fence, pipe gate.	1/1/2005
15.69		Ramp on both slopes.	1/1/2005
15.70		Cross fence, pipe gate on crown and at landward toe.	1/1/2005
15.75		Cross fence with pipe gate at landward toe.	1/1/2005
15.94		Milepost on the landward shoulder	1/1/2005
16.01		Ramp on waterward slope.	1/1/2005
16.01		Ramp on landward slope, pipe fence at toe.	1/1/2005
16.01		Overhead power line crosses levee.	1/1/2005

AGENCY NAME: Levee District No. 0001 (Sutter County)

LMA NAME: Levee District No. 0001 (Sutter County)

LMA SHORT NAME: LD0001S

This is a general report and
contains all levee logs years.

PLATE NO. 1
Key No.

Draft

Channel Bank, Unit, and Channel Name: **Right Bank of Unit No. 01 Feather River**

FPIIB Integrity Section A Channel Sub Unit and Channel Designations: **1.1 Feather River**

Begin Mile	End Mile	Description	Log Date
16.01		(2) 24-inch pipes through the levee, 5.8 feet below crown. Both pipes concrete encased through levee. Pumping plant in floodway. Siphon breakers in concrete box on landward shoulder. Discharges on west side of State Highway 99. (App. 6016 & 13957-Yuba City)	1/1/2005
16.01		Installation of inertia pipelines 4 feet below crown in overflow area. Abandon 30 feet of 24-inch pipeline (above) (App. 15331 - Yuba City, 10/89). (2) 3-inch air relief valves with (2) 6-inch valves, install valve box on landward shoulder. (App. 15330-City)	1/1/2005
16.21		Overhead power line crosses levee. Power pole on waterward slope.	1/1/2005
16.29		24-inch steel pipe through levee, Siphon breaker on waterward shoulder in corrugated metal riser. (App. 14420-Yuba City)	1/1/2005
16.58		Cross fence, pipe gate.	1/1/2005
16.59		Ramp on waterward slope with chain link gate. (App.10525)	1/1/2005
16.60		10-inch pipe through levee, 2 feet below crown. Siphon breaker on the waterward shoulder. (App. 13754- Sargent & Morton) 11/83 Not completed as of 1/90.	1/1/2005
16.63		Cross fence, pipe gate.	1/1/2005
16.65		SPRR crosses the levee, 6 feet below crown.	1/1/2005
16.65		End of Levee District No. 1, Sutter at downstream boundary of Levee District No. 9, Sutter County.	1/1/2005

Subtotal Count: **233**

Total Count: **233**

File and Object: DWR_UCIP.accdb/RPT_QRY_H_LL_GENERAL

Output Location Object: S:\FPIIBA\UCIP\REPORTS\L_LOG\DRAFT\RPT_QRY_H_LL_GENERAL(LMA_ID= 258).PDF

End of report.