

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	11/12/2014 11/12/2014	Matthew Hoffman

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0001S_01_s _ 2013_4				
Action/Comments					
Inspector Comments: Bill Hampton stated that the O&M manuals are stored at the district office at 243 2nd st, Yuba City, CA.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0001S_01_s _ 2013_5				
Action/Comments					
Inspector Comments: Supplies and flood fight equipment are stored at the district office. They also went in with RD784 in their large stockpile of flood fight supplies located in their district.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_LD0001S_01_s _ 2013_6				
Action/Comments					
Inspector Comments: Bill stated that he and the district employees attend the Flood Fight class put on by DWR and RD784 annually.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	11/12/2014 11/12/2014	Matthew Hoffman

LM Start	0.05	Rating **	A	Issue No.	13
LM End	0.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.951881 °	38.951881 °
				-121.585589 °	-121.585589 °
DWR ID	DWR_LD0001S_01_f _ 2014_13				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : FA_2014_LD0001S_433_13_20141124_00011.jpg



This photo was taken from the crown facing north looking down the landward levee slope at acceptable vegetation maintenance. Fall 2014.

LM Start	1.84	Rating **	M	Issue No.	487
LM End	1.84	Issue Type +	Ma	Location *	LS
Category	Interior Drainage & Piping Systems			GPS Latitude/Longitude	
				Start	End
Item	Metal Pipes			38.976927 °	38.976927 °
				-121.591210 °	-121.591210 °
DWR ID	DWR_LD0001S_01_s_2012_487				
Action/Comments					
Inspector Comments: Abandoned pipe. This pipe is listed in our levee log as an abandoned pipe, no date listed. No permit number. Corp pipe.					

No Photos

LM Start	3.22	Rating **	C	Issue No.	19
LM End	3.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.996261 °	38.996261 °
				-121.595939 °	-121.595939 °
DWR ID	DWR_LD0001S_01_f_2013_19				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	11/12/2014 11/12/2014	Matthew Hoffman

LM Start	13.65	Rating **	C	Issue No.	21
LM End	14.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.130209 °	39.135551 °
				-121.602451 °	-121.604932 °
DWR ID	DWR_LD0001S_01_f_2013_21				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Due to fires in the valley the district was unable to burn this section. District stated that they will drag the area to control vegetation.					

No Photos

LM Start	13.65	Rating **	C	Issue No.	22
LM End	14.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.130209 °	39.135551 °
				-121.602451 °	-121.604932 °
DWR ID	DWR_LD0001S_01_f_2013_22				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Due to fires in the valley the district was unable to burn this section. District stated that they will drag the area to control vegetation.					

No Photos

LM Start	15.66	Rating **	C	Issue No.	23
LM End	15.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.156036 °	39.159377 °
				-121.616960 °	-121.620682 °
DWR ID	DWR_LD0001S_01_f_2013_23				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Vegetation from the crown down the slope approx. 15'.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	11/12/2014 11/12/2014	Matthew Hoffman

LM Start	15.66	Rating **	M	Issue No.	24
LM End	15.97	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.156036 °	39.159377 °
				-121.616960 °	-121.620682 °
DWR ID	DWR_LD0001S_01_f_2013_24				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Vegetation from the crown down the slope approx. 15'.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---