

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2022

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	10/27/2022 10/27/2022	Brooks Weisser

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_LD0001S_01_s_2013_4				
Comment Code					
OM : O&M Manuals					
Inspector Comment					
O&M manuals are stored at the district office at 243 2nd St, Yuba City, CA.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_LD0001S_01_s_2013_5				
Comment Code					
ES : Emergency Supplies & Equipment					
Inspector Comment					
Supplies and flood fight equipment are stored at the district office. They also went in with RD784 in their large stockpile of flood fight supplies located in their district.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_LD0001S_01_s_2013_6				
Comment Code					
FP : Flood Preparedness & Training					
Inspector Comment					
The district employees attend the Flood Fight class put on by DWR and RD784 annually. Pending RxR closure structure training LM 16.10.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2022

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	10/27/2022 10/27/2022	Brooks Weisser

LM Start	0.20	Rating **	A	Issue No.	69
LM End	16.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.953742 °	39.168732 °
				-121.585547 °	-121.622687 °
DWR ID	DWR_LD0001S_01_f_2022_69				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is well maintained, Fall 2022.					

Photo 1 of 1 : FA_2022_LD0001S_433_69_20221028_00004.jpg



View of well maintained vegetation on the landside slope, Fall 2022.

LM Start	0.20	Rating **	A	Issue No.	70
LM End	16.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.953743 °	39.168732 °
				-121.585545 °	-121.622687 °
DWR ID	DWR_LD0001S_01_f _ 2022_70				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual Vegetation is well maintained, Fall 2022.					

Photo 1 of 1 : FA_2022_LD0001S_433_70_20221028_00005.jpg



View of annual vegetation on the waterside slope, Fall 2022.

LM Start	2.56	Rating **	A/W	Issue No.	24
LM End	2.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.987277 °	38.987277 °
				-121.591992 °	-121.591992 °
DWR ID	DWR_LD0001S_01_s_2021_24				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry bush blocking access and visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2022

Levee District No. 0001 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	16.11	10/27/2022 10/27/2022	Brooks Weisser

LM Start	5.43	Rating **	C	Issue No.	26
LM End	5.43	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.023753 °	39.023753 °
				-121.613171 °	-121.613171 °
DWR ID	DWR_LD0001S_01_s_2021_26				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

No Photos

LM Start	7.69	Rating **	A/W	Issue No.	19
LM End	7.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.055986 °	39.056710 °
				-121.611301 °	-121.611331 °
DWR ID	LD1-S-03				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This was a 2017 Storm Damage site for erosion.					
Site ID No:146					
Site Designation:LD1-S-03					

Photo 1 of 1 : LEVAL_FA_2022_146_4051.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---