

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

**Sacramento River Basin**

---

LD0002 Levee District No. 0002 (Glenn County)	Overall LMA Rating	Total LMA Miles				
	<b>A</b>	<b>4.89</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.14		0.14	2.86%		
Encroachments					0.01	
Animal Control	0.14		0.14	2.86%		
<i>LMA Totals:</i>	0.28	0.00	0.28	5.73%	0.01	0.00

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Fall 2010 Levee Inspection Results**

**Levee District No. 0002 (Glenn County)**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>A</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2010 Levee Inspection Results**

**Levee District No. 0002 (Glenn County)**

Waterway	Bank	Unit Miles
Unit No. 01 Glenn County Sacramento River	Right	4.89

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	3/22/2010		9/21/2010	
DWR Inspector	Bob Duffey		Bob Duffey	
Accompanied By	Dennis Clark		Dennis Clark	

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.
- (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Levee District No. 0002 (Glenn County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Right	4.89	10/13/2010 10/13/2010	Bob Duffey

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.66	0.80	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	39.422844 ° -122.011637 °	39.424829 ° -122.011467 °	1 Y
2	1.04	1.04	Earthen Levee	Encroachments	WS	PO	Buildings	39.428322 ° -122.010973 °	39.428322 ° -122.010973 °	8 Y
3	1.09	1.09	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.454387 ° -122.014835 °	39.428972 ° -122.010887 °	4
4	2.95	3.00	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.453595 ° -122.016273 °	39.454003 ° -122.015503 °	2
5	3.08	3.08	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.454957 ° -122.014460 °	39.454959 ° -122.014454 °	5
6	3.10	3.18	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.455145 ° -122.014287 °	39.455813 ° -122.013205 °	3
7	3.24	3.26	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	39.456158 ° -122.012036 °	39.456181 ° -122.011783 °	6

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p> <p>C : Corrected W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Levee District No. 0002 (Glenn County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Right	4.89	10/13/2010 10/13/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.66
End Levee Mile	0.80
Location	Water Side
Category	Earthen Levee
Item	Vegetation
View of the vegetation on the w/s slope.	
rduffey_f_20101101_242.jpg	



Levee Mile Report Line	2
Start Levee Mile	1.04
End Levee Mile	1.04
Location	Water Side
Category	Earthen Levee
Item	Encroachments
View of house along w/s toe.	
rduffey_f_20101101_238.jpg	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor U : Unacceptable      N : Not Inspected/Rated</p>
---	---