

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|----------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|----------------------------------------|----------------------------------|--------------|----|------------------------|-----|
| LM Start | | Rating ** | A | Issue No. | 14 |
| LM End | | Issue Type + | Ma | Location * | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Operations & Maintenance Manuals | | | ° | ° |
| | | | | ° | ° |
| DWR ID | DWR_LD0002_01_s_2013_14 | | | | |
| Comment Code | | | | | |
| | | | | | |
| Inspector Comment | | | | | |
| The LMA has copies of the O&M manuals. | | | | | |

No Photos

| | | | | | |
|----------------------------------------------------------|--------------------------------|--------------|----|------------------------|-----|
| LM Start | | Rating ** | A | Issue No. | 17 |
| LM End | | Issue Type + | Ma | Location * | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Emergency Supplies & Equipment | | | ° | ° |
| | | | | ° | ° |
| DWR ID | DWR_LD0002_01_s_2013_17 | | | | |
| Comment Code | | | | | |
| | | | | | |
| Inspector Comment | | | | | |
| The LMA has adequate flood fight supplies and equipment. | | | | | |

No Photos

| | | | | | |
|----------------------------------------|-------------------------------|--------------|----|------------------------|-----|
| LM Start | | Rating ** | M | Issue No. | 18 |
| LM End | | Issue Type + | Ma | Location * | |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Flood Preparedness & Training | | | ° | ° |
| | | | | ° | ° |
| DWR ID | DWR_LD0002_01_s_2013_18 | | | | |
| Comment Code | | | | | |
| | | | | | |
| Inspector Comment | | | | | |
| Recommend taking flood fight training. | | | | | |

No Photos

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.07 | Rating ** | M | Issue No. | 6 |
| LM End | 0.28 | Issue Type + | Ma | Location * | WS |
| Category | Supplemental | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | 2017 USACE Erosion Survey | | | 39.414649 ° | 39.417689 ° |
| | | | | -122.009853 ° | -122.010369 ° |
| DWR ID | DWR_ST0010_02_f_2022_4 | | | | |
| Comment Code | | | | | |
| | | | | | |
| Inspector Comment | | | | | |
| 2017 Site ID: SAC 164.7 R | | | | | |
| Status: Eroding | | | | | |
| 2017 Field Notes: New erosion along entire site. | | | | | |
| Site History: 2009 - Very slow retreat, hard toe, encroaching into the levee projection. 2010 - Slowly eroding. 2011 - Site extended downstream. | | | | | |

Photo 1 of 2 : FA_2020_LD0002_28_6_20200915_00002.jpg



USACE 2013 Photo #1

| | | | | | |
|----------|-------------|--------------|----|------------|-----------------|
| LM Start | 0.07 | Rating ** | M | Issue No. | 6 (cont) |
| LM End | 0.28 | Issue Type + | Ma | Location * | WS |

Photo 2 of 2 : FA_2020_LD0002_28_6_20200915_00003.jpg



USACE 2013 Photo #2

| | | | | | |
|------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.64 | Rating ** | M | Issue No. | 35 |
| LM End | 0.77 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.422805 ° | 39.424597 ° |
| | | | | -122.011640 ° | -122.011527 ° |
| DWR ID | DWR_LD0002_01_s_2018_35 | | | | |
| Comment Code | | | | | |
| V2 : Remove the wild growth other than native grasses from the levee slopes. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_35_20200915_00013.jpg



View of the vegetation along the waterside slope.

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|-------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 1.25 | Rating ** | N | Issue No. | 31 |
| LM End | 1.25 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 39.431524 ° | 39.431524 ° |
| | | | | -122.010790 ° | -122.010790 ° |
| DWR ID | DWR_LD0002_01_s_2019_31 | | | | |
| Comment Code | | | | | |
| T5 : Tree stumps. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | | | |
|--------------------------------------------------------|---------------------------------------|--------------|----|------------------------|---------------|
| LM Start | 1.40 | Rating ** | M | Issue No. | 34 |
| LM End | 1.40 | Issue Type + | Ma | Location * | CR |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Crown Surface / Depressions / Rutting | | | 39.433809 ° | 39.433809 ° |
| | | | | -122.010814 ° | -122.010814 ° |
| DWR ID | DWR_LD0002_01_f_2016_34 | | | | |
| Comment Code | | | | | |
| C2 : Repair depressions or ruts in the crown or slope. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_34_20200915_00012.jpg



View of a depression on the levee crown looking upstream.

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 1.56 | Rating ** | U | Issue No. | 15 |
| LM End | 1.60 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.436609 ° | 39.436643 ° |
| | | | | -122.010524 ° | -122.010498 ° |
| DWR ID | DWR_LD0002_01_f_2012_15 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_15_20201105_00050.jpg



View of the rodent activity along the landside slope. Fall 2020.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|-------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 2.01 | Rating ** | N | Issue No. | 41 |
| LM End | 2.01 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 39.441698 ° | 39.441698 ° |
| | | | | -122.012794 ° | -122.012794 ° |
| DWR ID | DWR_LD0002_01_s_2019_41 | | | | |
| Comment Code | | | | | |
| T5 : Tree stumps. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | | | |
|-----------------------------------------------------------------------------------------------------|------------------------|--------------|----|------------------------|---------------|
| LM Start | 2.91 | Rating ** | M | Issue No. | 2 |
| LM End | 2.96 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.453595 ° | 39.454003 ° |
| | | | | -122.016273 ° | -122.015503 ° |
| DWR ID | DWR_LD0002_01_f_2015_2 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_2_20200915_00001.jpg



View of the rodent holes along the landside slope.

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.08 | Rating ** | M | Issue No. | 23 |
| LM End | 3.09 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.455394 ° | 39.455501 ° |
| | | | | -122.013990 ° | -122.013879 ° |
| DWR ID | DWR_LD0002_01_f_2020_23 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|---------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.11 | Rating ** | U | Issue No. | 12 |
| LM End | 3.13 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.455647 ° | 39.455805 ° |
| | | | | -122.013623 ° | -122.013286 ° |
| DWR ID | DWR_LD0002_01_s_2013_12 | | | | |
| Comment Code | | | | | |
| A1 : Exterminate rodents and backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_12_20200915_00004.jpg



View of rodent activity on the landside slope. Fall 2019.

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.24 | Rating ** | U | Issue No. | 16 |
| LM End | 3.30 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.456222 ° | 39.456272 ° |
| | | | | -122.011266 ° | -122.010163 ° |
| DWR ID | DWR_LD0002_01_f_2012_16 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_16_20200915_00006.jpg



View of the rodent holes along the landside slope. Spring 2019.

| | | | | | |
|------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.40 | Rating ** | M | Issue No. | 47 |
| LM End | 3.40 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.457095 ° | 39.457095 ° |
| | | | | -122.009469 ° | -122.009469 ° |
| DWR ID | DWR_LD0002_01_s_2019_47 | | | | |
| Comment Code | | | | | |
| V2 : Remove the wild growth other than native grasses from the levee slopes. | | | | | |
| Inspector Comment | | | | | |
| The berry vines should be removed from the waterside slope. | | | | | |

No Photos

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|------------------------|---------------|-----------|
| LM Start | 3.54 | Rating ** | M | Issue No. | 27 |
| LM End | 3.59 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | GPS Latitude/Longitude | | |
| | | | Start | End | |
| Item | Animal Control | | 39.458930 ° | 39.459614 ° | |
| | | | -122.010150 ° | -122.010741 ° | |
| DWR ID | DWR_LD0002_01_s_2014_27 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_27_20200915_00008.jpg



View of the rodent holes along the landside slope.

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|------------------------|---------------|-----------|
| LM Start | 3.62 | Rating ** | M | Issue No. | 25 |
| LM End | 3.62 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | GPS Latitude/Longitude | | |
| | | | Start | End | |
| Item | Animal Control | | 39.459888 ° | 39.459888 ° | |
| | | | -122.010970 ° | -122.010970 ° | |
| DWR ID | DWR_LD0002_01_f_2020_25 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | | | |
|-------------------|-------------------------|--------------|------------------------|---------------|-----------|
| LM Start | 3.68 | Rating ** | M | Issue No. | 26 |
| LM End | 3.68 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | GPS Latitude/Longitude | | |
| | | | Start | End | |
| Item | Encroachments | | 39.460837 ° | 39.460837 ° | |
| | | | -122.011323 ° | -122.011323 ° | |
| DWR ID | DWR_LD0002_01_f_2020_26 | | | | |
| Comment Code | | | | | |
| TR : Tree or limb | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.79 | Rating ** | M | Issue No. | 50 |
| LM End | 3.79 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.462358 ° | 39.462358 ° |
| | | | | -122.011623 ° | -122.011623 ° |
| DWR ID | DWR_LD0002_01_s_2019_50 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_50_20200915_00014.jpg



View of the rodent holes on the landside slope. Spring 2019.

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.85 | Rating ** | M | Issue No. | 53 |
| LM End | 3.85 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.463261 ° | 39.463261 ° |
| | | | | -122.011613 ° | -122.011613 ° |
| DWR ID | DWR_LD0002_01_s_2019_53 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.93 | Rating ** | M | Issue No. | 29 |
| LM End | 3.93 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Animal Control | | | 39.464409 ° | 39.464409 ° |
| | | | | -122.011455 ° | -122.011455 ° |
| DWR ID | DWR_LD0002_01_f_2020_29 | | | | |
| Comment Code | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | | | | | | | | |
|-----------------------------------------------------------------------------------------------------|-------------------------|--------------|------------------------|---------------|-----------|--|--|--|--|--|--|--|
| LM Start | 4.00 | Rating ** | M | Issue No. | 28 | | | | | | | |
| LM End | 4.02 | Issue Type + | Ma | Location * | LS | | | | | | | |
| Category | Earthen Levee | | GPS Latitude/Longitude | | | | | | | | | |
| | | | Start | End | | | | | | | | |
| Item | Animal Control | | 39.465418 ° | 39.465657 ° | | | | | | | | |
| | | | -122.011235 ° | -122.011237 ° | | | | | | | | |
| DWR ID | DWR_LD0002_01_f_2018_28 | | | | | | | | | | | |
| Comment Code | | | | | | | | | | | | |
| A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | | | | | | | | | | | | |
| Inspector Comment | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_28_20200915_00010.jpg



View of the rodent holes along the landside slope.

| | | | | | | | | | | | | |
|-------------------|-------------------------|--------------|------------------------|---------------|-----------|--|--|--|--|--|--|--|
| LM Start | 4.05 | Rating ** | M | Issue No. | 32 | | | | | | | |
| LM End | 4.05 | Issue Type + | Ma | Location * | WS | | | | | | | |
| Category | Earthen Levee | | GPS Latitude/Longitude | | | | | | | | | |
| | | | Start | End | | | | | | | | |
| Item | Encroachments | | 39.466030 ° | 39.466030 ° | | | | | | | | |
| | | | -122.011324 ° | -122.011324 ° | | | | | | | | |
| DWR ID | DWR_LD0002_01_f_2020_32 | | | | | | | | | | | |
| Comment Code | | | | | | | | | | | | |
| TR : Tree or limb | | | | | | | | | | | | |
| Inspector Comment | | | | | | | | | | | | |
| | | | | | | | | | | | | |

No Photos

| | | | | | | | | | | | | |
|-------------------|-------------------------|--------------|------------------------|---------------|-----------|--|--|--|--|--|--|--|
| LM Start | 4.61 | Rating ** | N | Issue No. | 54 | | | | | | | |
| LM End | 4.61 | Issue Type + | Ma | Location * | WS | | | | | | | |
| Category | Earthen Levee | | GPS Latitude/Longitude | | | | | | | | | |
| | | | Start | End | | | | | | | | |
| Item | Trim / Thin Trees | | 39.473414 ° | 39.473414 ° | | | | | | | | |
| | | | -122.015340 ° | -122.015340 ° | | | | | | | | |
| DWR ID | DWR_LD0002_01_s_2019_54 | | | | | | | | | | | |
| Comment Code | | | | | | | | | | | | |
| T5 : Tree stumps. | | | | | | | | | | | | |
| Inspector Comment | | | | | | | | | | | | |
| | | | | | | | | | | | | |

No Photos

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2020

Levee District No. 0002 (Glenn County)

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Glenn County Sacramento River | Right | 4.90 | 11/04/2020 11/04/2020 | Makar Sokol |

| | | | | | |
|-------------------|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 4.64 | Rating ** | N | Issue No. | 55 |
| LM End | 4.64 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trim / Thin Trees | | | 39.473680 ° | 39.473680 ° |
| | | | | -122.015618 ° | -122.015618 ° |
| DWR ID | DWR_LD0002_01_s _ 2019_55 | | | | |
| Comment Code | | | | | |
| T5 : Tree stumps. | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

No Photos

| | | | | | |
|-------------------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 4.90 | Rating ** | M | Issue No. | 57 |
| LM End | 4.90 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Encroachments | | | 39.477096 ° | 39.477096 ° |
| | | | | -122.017607 ° | -122.017607 ° |
| DWR ID | DWR_LD0002_01_s_2019_57 | | | | |
| Comment Code | | | | | |
| TR : Tree or limb | | | | | |
| Inspector Comment | | | | | |
| | | | | | |

Photo 1 of 1 : FA_2020_LD0002_28_57_20200915_00015.jpg



View of the tree and branches on the waterside slope. Spring 2020.

| | | | |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|