

**Flood Control Project Maintenance  
Levee Inspections  
Fall 2024 Levee Maintenance Deficiency Summary Report**

**Sacramento River Basin**

LD0009	Overall LMA Rating	Total LMA Miles							
Levee District No. 0009 (Sutter County)	A	6.25							
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
Earthen Levee									
Encroachments					0.34				
LMA Totals:	0.00	0.00	0.00	0.00%	0.34	0.00	0.00	0.00	
Unit No. 01 Sutter County, Feather River RB	Overall Unit Rating	Total Unit Miles							
LD0009	A	6.25							
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
Earthen Levee									
Encroachments					0.34				
Unit Totals:	0.00	0.00	0.00	0.00%	0.34	0.00	0.00	0.00	







**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet**

**Levee District No. 0009 (Sutter County)**

Waterway			Bank	Unit Miles
Unit No. 01 Sutter County, Feather River			Right	6.25
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	4/16/2024 - 4/16/2024		10/30/2024 - 10/30/2024	
DWR Inspector	Brooks Weisser		Brooks Weisser	
Accompanied By	Andrew Stresser LD0001S		Andrew Stresser LD0001S	

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*



**Flood Control Project Maintenance  
Levee Inspections****Levee Inspection Report By Mile - Fall 2024****Levee District No. 0009 (Sutter County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/30/2024 10/30/2024	Brooks Weisser

LM Start		Rating **	A	Issue No.	3					
LM End		Issue Type +	Ma	Location *	N/A					
Category	Earthen Levee		GPS Latitude/Longitude							
			Start	End						
Item	Emergency Supplies & Equipment			°	°					
				°	°					
DWR ID	DWR_LD0009_01_s _ 2024_3									
Comment Code										
ES : Emergency Supplies & Equipment										
Inspector Comment										
LD 9 has flood fight supplies on hand and coordinates with other local levee districts in the flood fight supply staging program.										

No Photos

LM Start		Rating **	A	Issue No.	4					
LM End		Issue Type +	Ma	Location *	N/A					
Category	Earthen Levee		GPS Latitude/Longitude							
			Start	End						
Item	Flood Preparedness & Training			°	°					
				°	°					
DWR ID	DWR_LD0009_01_s _ 2024_4									
Comment Code										
FP : Flood Preparedness & Training										
Inspector Comment										
The district has attended the Flood Fight class put on by RD 784 and DWR.										

No Photos

LM Start		Rating **	A	Issue No.	5					
LM End		Issue Type +	Ma	Location *	N/A					
Category	Earthen Levee		GPS Latitude/Longitude							
			Start	End						
Item	Operations & Maintenance Manuals			°	°					
				°	°					
DWR ID	DWR_LD0009_01_s _ 2024_5									
Comment Code										
OM : O&M Manuals										
Inspector Comment										
The levee district has stated in the past that they have a copy of the O&M manuals.										

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---



**Flood Control Project Maintenance  
Levee Inspections****Levee Inspection Report By Mile - Fall 2024****Levee District No. 0009 (Sutter County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/30/2024 10/30/2024	Brooks Weisser

LM Start	0.09	Rating **	A	Issue No.	1
LM End	6.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.170043 °	39.255811 °
				-121.622574 °	-121.636381 °
DWR ID	DWR_LD0009_01_f_2024_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is well maintained, Fall 2024.					

Photo 1 of 1 : FA\_2024\_LD0009\_202\_1\_20241031\_00003.jpg



View of maintained vegetation on the landside slope, Fall 2024.

LM Start	0.09	Rating **	A	Issue No.	2
LM End	6.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.170048 °	39.255814 °
				-121.622574 °	-121.636381 °
DWR ID	DWR_LD0009_01_f_2024_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is well maintained, Fall 2024.					

Photo 1 of 1 : FA\_2024\_LD0009\_202\_2\_20241031\_00004.jpg



View of maintained vegetation on the waterside slope, Fall 2024.

LM Start	5.66	Rating **	M	Issue No.	20
LM End	6.00	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.247349 °	39.252258 °
				-121.637341 °	-121.637077 °
DWR ID	DWR_LD0009_01_f_2016_20				
Comment Code					
DT : Ditch					
Inspector Comment					
A ditch is located at the toe of the levee on the landside.					

Photo 1 of 1 : FA\_2024\_LD0009\_202\_20\_20241031\_00002.jpg



View looking upstream of ditch at the toe of the levee on the landside, Fall 2024.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	



Flood Control Project Maintenance  
Levee Inspections

Levee Inspection Report By Mile - Fall 2024

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/30/2024 10/30/2024	Brooks Weisser

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---