

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2007 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**Sacramento River Basin**

Maintenance Area 0009	Overall LMA Rating	Total LMA Miles				
	<b>M</b>	<b>19.60</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.75		0.75	3.83%		
Trim / Thin Trees	0.01		0.01	0.05%		
Encroachments	0.02		0.02	0.10%	1.08	0.17
Slope Stability	0.01		0.01	0.05%		
Erosion / Bank Caving	0.01	0.29	1.17	5.97%		
<i>LMA Totals:</i>	0.80	0.29	1.96	10.00%	1.08	0.17

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2007 Levee Inspection Results**  
**Maintenance Area 0009**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>M</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Fall 2007 Levee Inspection Results  
Maintenance Area 0009**

Waterway		Bank	Unit Miles
Unit No. 01 Sacramento River		Left	19.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			<b>M</b>	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**Maintenance Area 0009**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River				Left	19.60		Not Assigned

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	19.61	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		1
2	0.00	19.61	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2
3	0.42	0.46	Earthen Levee	Erosion / Bank Caving	WS	U	Schedule repair of erosion site prior to the next inspection.	°	°		3
4	0.49	0.63	Earthen Levee	Encroachments	LS	PO	Buildings	°	°		4
5	0.65	0.70	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		5
6	0.75	0.88	Earthen Levee	Erosion / Bank Caving	WS	U	Schedule repair of erosion site prior to the next inspection.	°	°		6
7	0.88	0.89	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		7
8	0.91	0.93	Earthen Levee	Encroachments	LS	CO	Buildings	°	°		8
9	0.97	0.98	Earthen Levee	Encroachments	LS	CO	Landscaping	°	°		9
10	1.02	1.04	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		10
11	1.21	1.21	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		11
12	1.24	1.28	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		12
13	1.31	1.33	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		13
14	1.34	1.39	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		14
15	1.49	1.49	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		15
16	1.57	1.57	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		16
17	1.59	1.61	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		17
18	1.64	1.64	Earthen Levee	Encroachments	LS	CO	Buildings	°	°		18
19	1.65	1.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	°	°		19

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**Maintenance Area 0009**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River				Left	19.60		Not Assigned

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	1.68	1.71	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		20
21	1.88	1.89	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		21
22	2.78	2.78	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		40
23	2.80	2.81	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		41
24	3.21	3.24	Earthen Levee	Encroachments	LS	CO	Landscaping	°	°		42
25	3.80	3.80	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		43
26	3.82	3.82	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		44
27	3.85	3.85	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		45
28	3.89	3.89	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		46
29	3.96	3.96	Earthen Levee	Encroachments	LS	CO	Landscaping	°	°		47
30	4.06	4.06	Earthen Levee	Encroachments	LS	M	Debris	°	°		48
31	4.24	4.24	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	°	°		49
32	4.25	4.25	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		50
33	4.30	4.32	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		51
34	4.61	4.67	Earthen Levee	Encroachments	LS	CO	Fences	°	°		52
35	4.97	4.97	Earthen Levee	Encroachments	LS	CO	Buildings	°	°		53
36	5.50	5.52	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		54
37	6.20	6.32	Earthen Levee	Erosion / Bank Caving	WS	U	Schedule repair of erosion site prior to the next inspection.	°	°		55
38	6.88	6.89	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		56

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**Maintenance Area 0009**

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 01 Sacramento River				Left	19.60		Not Assigned				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	7.35	7.37	Earthen Levee	Encroachments	LS	CO	Fences	°	°		57
40	7.37	7.37	Earthen Levee	Encroachments	LS	M	Debris	°	°		58
41	9.14	9.14	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	°	°		59
42	9.16	9.65	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		60
43	10.90	11.00	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		22
44	11.17	11.26	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		23
45	11.39	11.49	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		24
46	11.59	11.61	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		25
47	11.62	11.62	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		26
48	12.26	12.30	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		27
49	12.80	12.90	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		28
50	14.49	14.54	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		29
51	15.50	15.50	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		30
52	15.75	15.75	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		31
53	16.20	16.30	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		32
54	16.30	16.30	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	°	°		33
55	17.50	17.50	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		34
56	17.80	17.80	Earthen Levee	Encroachments	LS	PO	Buildings	°	°		35
57	19.00	19.10	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	°	°		36

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**Maintenance Area 0009**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River				Left	19.60		Not Assigned

  

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	19.06	19.06	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	°	°		37
59	19.10	19.12	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	°	°		38
60	19.20	19.20	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	°	°		39

<p><b>* Location</b></p> <p>LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing                  M : Minimally Acceptable      CO : Completely Obstructing                  U : Unacceptable      N : Not Inspected</p>
---	---