

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2013 Levee Inspection Results**

**Sutter Maintenance Yard Maintenance Area 0016**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway		Bank	Unit Miles
Unit No. 01 Feather River		Right	4.09

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	03/26/2013 - 03/26/2013			
DWR Inspector	Rick Burnett			
Accompanied By	Jason Cooper Sutter Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.09	03/26/2013 03/26/2013	Rick Burnett

LMR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1				Operations & Maintenance Manuals	LS	A Ma		°	°	3
DWR ID: DWR_MA0016_01_s_2013_3										
2				Flood Preparedness & Training	LS	A Ma		°	°	4
DWR ID: DWR_MA0016_01_s_2013_4										
3				Emergency Supplies & Equipment	LS	A Ma		°	°	5
DWR ID: DWR_MA0016_01_s_2013_5										
4	0.06	0.10		Vegetation	LS	M En	V6 : Landscaping	39.256618 ° -121.636442 °	39.257228 ° -121.636462 °	2 Y
DWR ID: DWR_MA0016_01_s_2012_2										
5	0.18	0.18		Encroachments	LS	M En	BU : Building	39.258437 ° -121.636613 °	39.258437 ° -121.636613 °	15 Y
DWR ID: DWR_MA0016_01_s_2012_15										
6	0.45	0.49		Encroachments	LS	U En	BU : Building	39.262213 ° -121.636545 °	39.262825 ° -121.636430 °	7 Y
DWR ID: DWR_MA0016_01_s_2012_7										
7	0.76	0.76		Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard has sprayed both slopes.	39.266693 ° -121.635600 °	39.266693 ° -121.635600 °	1
DWR ID: DWR_MA0016_01_s_2013_1										
8	2.85	3.08		Encroachments	LS	M En	DT : Ditch	39.293675 ° -121.636615 °	39.296748 ° -121.638192 °	14 Y
DWR ID: DWR_MA0016_01_s_2012_14										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.09	03/26/2013 03/26/2013	Rick Burnett

Levee Mile Report Line	4
Start Levee Mile	0.06
End Levee Mile	0.10
Location	Land Side
Category	
Item	Vegetation
Levee mile 0.10. This photo shows the landscaping on the landside slope and toe.	
jhirabay_s_20130314_023.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.18
End Levee Mile	0.18
Location	Land Side
Category	
Item	Encroachments
Levee mile 0.18. This photo shows the building on the landside shoulder and toe.	
jhirabay_s_20130314_027.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.45
End Levee Mile	0.49
Location	Land Side
Category	
Item	Encroachments
Levee mile 0.49. This photo shows the building and landscaping on the landside slope and toe.	
jhirabay_s_20130314_024.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.09	03/26/2013 03/26/2013	Rick Burnett

Levee Mile Report Line	8
Start Levee Mile	2.85
End Levee Mile	3.08
Location	Land Side
Category	
Item	Encroachments
Land side ditch levee mile 3.08.	
jhirabay_s_20130314_025.jpg	



Levee Mile Report Line	8
Start Levee Mile	2.85
End Levee Mile	3.08
Location	Land Side
Category	
Item	Encroachments
AG ditch land side slope and toe.	
jhirabay_s_20130314_026.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---