

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	11/19/2014 11/19/2014	Matthew Hoffman

LM Start		Rating **	A	Issue No.	<b>3</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_MA0016_01_s_2013_3				
Action/Comments					
Inspector Comments: The O&M manuals are located at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	<b>4</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_MA0016_01_s_2013_4				
Action/Comments					
Inspector Comments: Sutter maintenance yard employees attend the annual Flood Fight class put on by DWR inspector Bob Duffy.					

No Photos

LM Start		Rating **	A	Issue No.	<b>5</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_MA0016_01_s_2013_5				
Action/Comments					
Inspector Comments: Emergency supplies and equipment are stored at the Sutter Maintenance Yard.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	11/19/2014 11/19/2014	Matthew Hoffman

LM Start	<b>0.00</b>	Rating **	A/W	Issue No.	<b>13</b>
LM End	<b>4.09</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		°	°	
			°	°	
DWR ID	DWR_MA0016_01_f_2014_13				
Action/Comments					
Material					

Photo 1 of 1 : FA\_2014\_MA0016\_302\_13\_20141124\_00008.jpg



This photo was taken from the crown facing north looking at the levee currently under construction and unable to inspect. Fall 2014.

LM Start	<b>0.24</b>	Rating **	M	Issue No.	<b>20</b>
LM End	<b>0.24</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.259173 °	39.259173 °	
			-121.636667 °	-121.636667 °	
DWR ID	DWR_MA0016_01_f_2013_20				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---