

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2008 Levee Inspection Results**

American River Flood Control District

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 01 Arcade Creek	Left	2.10

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Arcade Creek				Left	2.10	05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.78	0.78	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.624010 ° -121.455138 °	38.624010 ° -121.455138 °		25
2	1.14	1.14	Earthen Levee	Encroachments	LS	CO	Fences	38.624800 ° -121.448808 °	38.624800 ° -121.448808 °		24
3	1.16	1.16	Earthen Levee	Encroachments	LS	CO	Fences	38.624832 ° -121.448607 °	38.624832 ° -121.448607 °		23
4	1.17	1.17	Earthen Levee	Encroachments	LS	CO	Fences	38.624850 ° -121.448428 °	38.624850 ° -121.448428 °		22
5	1.18	1.18	Earthen Levee	Encroachments	LS	CO	Fences	38.624877 ° -121.448248 °	38.624877 ° -121.448248 °		21
6	1.19	1.19	Earthen Levee	Encroachments	LS	CO	Fences	38.624900 ° -121.448037 °	38.624900 ° -121.448037 °		20
7	1.20	1.20	Earthen Levee	Encroachments	LS	CO	Fences	38.624942 ° -121.447825 °	38.624942 ° -121.447825 °		19
8	1.26	1.26	Earthen Levee	Encroachments	LS	CO	Buildings	38.625300 ° -121.446767 °	38.625300 ° -121.446767 °		18
9	1.35	1.35	Earthen Levee	Encroachments	LS	CO	Fences	38.625827 ° -121.445395 °	38.625827 ° -121.445395 °		17
10	1.37	1.37	Earthen Levee	Encroachments	LS	CO	Fences	38.626000 ° -121.444978 °	38.626000 ° -121.444978 °		16
11	1.38	1.38	Earthen Levee	Encroachments	LS	CO	Fences	38.626048 ° -121.444785 °	38.626048 ° -121.444785 °		15
12	1.39	1.39	Earthen Levee	Encroachments	LS	CO	Fences	38.626085 ° -121.444580 °	38.626085 ° -121.444580 °		14
13	1.41	1.41	Earthen Levee	Encroachments	LS	CO	Fences	38.626155 ° -121.444250 °	38.626155 ° -121.444250 °		13
14	1.42	1.42	Earthen Levee	Encroachments	LS	CO	Fences	38.626212 ° -121.444082 °	38.626212 ° -121.444082 °		12
15	1.43	1.43	Earthen Levee	Encroachments	LS	CO	Landscaping	38.626325 ° -121.443928 °	38.626325 ° -121.443928 °		11
16	1.55	1.55	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627267 ° -121.442138 °	38.627267 ° -121.442138 °		10
17	1.83	1.83	Earthen Levee	Encroachments	LS	CO	Fences	38.627880 ° -121.437368 °	38.627880 ° -121.437368 °		9
18	1.87	1.87	Earthen Levee	Encroachments	LS	CO	Landscaping	38.627827 ° -121.436633 °	38.627827 ° -121.436633 °		8
19	1.88	1.88	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627837 ° -121.436393 °	38.627837 ° -121.436393 °		7

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 01 Arcade Creek				Left	2.10	05/08/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	1.92	1.92	Earthen Levee	Encroachments	LS CO	Fences		38.627725 ° -121.435715 °	38.627725 ° -121.435715 °		6
21	1.93	1.93	Earthen Levee	Encroachments	LS CO	Fences		38.627680 ° -121.435555 °	38.627680 ° -121.435555 °		5
22	1.94	1.94	Earthen Levee	Encroachments	LS CO	Fences		38.627640 ° -121.435378 °	38.627640 ° -121.435378 °		4
23	1.95	1.95	Earthen Levee	Encroachments	LS CO	Fences		38.627595 ° -121.435218 °	38.627595 ° -121.435218 °		3
24	1.99	1.99	Earthen Levee	Encroachments	LS CO	Fences		38.627377 ° -121.434383 °	38.627377 ° -121.434383 °		2
25	2.00	2.00	Earthen Levee	Encroachments	LS PO	Landscaping		38.627318 ° -121.434208 °	38.627318 ° -121.434208 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway		Bank	Unit Miles
Unit No. 02 Natomas E Canal		Left	4.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/7/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Natomas E Canal	Left	4.00	05/07/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 03 American River	Right	3.42

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 American River			Right	3.42	05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 04 American River	Left	11.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/16/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.31	0.47	Earthen Levee	Encroachments	LS CO	Landscaping		38.599835 ° -121.503448 °	38.600762 ° -121.500833 °		1
2	2.68	2.68	Earthen Levee	Encroachments	LS CO	Buildings		38.588913 ° -121.467210 °	38.588913 ° -121.467210 °		2
3	2.82	2.82	Earthen Levee	Encroachments	LS CO	Debris		38.587442 ° -121.465170 °	38.587442 ° -121.465170 °		3
4	2.84	2.84	Earthen Levee	Encroachments	WS PO	Debris		38.587272 ° -121.464768 °	38.587272 ° -121.464768 °		4
5	2.93	2.93	Earthen Levee	Encroachments	LS CO	Buildings		38.587250 ° -121.463138 °	38.587250 ° -121.463138 °		5
6	3.91	3.91	Earthen Levee	Encroachments	LS PO	Fences		38.586105 ° -121.447622 °	38.586105 ° -121.447622 °		8
7	3.92	3.92	Earthen Levee	Encroachments	LS CO	Fences		38.586327 ° -121.447382 °	38.586327 ° -121.447382 °		6
8	3.92	3.92	Earthen Levee	Encroachments	LS CO	Landscaping		38.586118 ° -121.447540 °	38.586118 ° -121.447540 °		7
9	3.94	3.94	Earthen Levee	Encroachments	LS CO	Fences		38.585888 ° -121.447172 °	38.585888 ° -121.447172 °		9
10	3.97	3.97	Earthen Levee	Encroachments	LS CO	Landscaping		38.585655 ° -121.446793 °	38.585655 ° -121.446793 °		10
11	4.01	4.01	Earthen Levee	Encroachments	LS CO	Fences		38.585367 ° -121.446262 °	38.585367 ° -121.446262 °		11
12	4.02	4.02	Earthen Levee	Encroachments	LS CO	Fences		38.585180 ° -121.445988 °	38.585180 ° -121.445988 °		12
13	4.05	4.05	Earthen Levee	Encroachments	LS CO	Fences		38.584923 ° -121.445655 °	38.584923 ° -121.445655 °		13
14	4.07	4.07	Earthen Levee	Encroachments	LS PO	Fences		38.584713 ° -121.445385 °	38.584713 ° -121.445385 °		14
15	4.10	4.10	Earthen Levee	Encroachments	LS CO	Fences		38.584485 ° -121.445042 °	38.584485 ° -121.445042 °		15
16	4.11	4.11	Earthen Levee	Encroachments	LS PO	Landscaping		38.584347 ° -121.444855 °	38.584347 ° -121.444855 °		16
17	4.12	4.12	Earthen Levee	Encroachments	LS CO	Fences		38.584237 ° -121.444680 °	38.584237 ° -121.444680 °		17
18	4.13	4.13	Earthen Levee	Encroachments	LS CO	Fences		38.584133 ° -121.444545 °	38.584133 ° -121.444545 °		18
19	4.14	4.14	Earthen Levee	Encroachments	LS CO	Fences		38.584063 ° -121.444428 °	38.584063 ° -121.444428 °		19

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Levee Inspection Report By Mile - Spring 2008**

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	4.15	4.15	Earthen Levee	Encroachments	LS CO	Fences		38.583980 ° -121.444267 °	38.583980 ° -121.444267 °		20
21	4.16	4.16	Earthen Levee	Encroachments	LS CO	Landscaping		38.583858 ° -121.444070 °	38.583858 ° -121.444070 °		21
22	4.20	4.20	Earthen Levee	Encroachments	LS CO	Fences		38.583563 ° -121.443533 °	38.583563 ° -121.443533 °		22
23	4.22	4.22	Earthen Levee	Encroachments	LS PO	Fences		38.583367 ° -121.443205 °	38.583367 ° -121.443205 °		23
24	4.23	4.23	Earthen Levee	Encroachments	LS PO	Fences		38.583270 ° -121.443067 °	38.583270 ° -121.443067 °		24
25	4.28	4.28	Earthen Levee	Encroachments	LS PO	Fences		38.582802 ° -121.442387 °	38.582802 ° -121.442387 °		25
26	4.32	4.32	Earthen Levee	Encroachments	LS PO	Fences		38.582480 ° -121.441865 °	38.582480 ° -121.441865 °		26
27	4.35	4.35	Earthen Levee	Encroachments	LS CO	Fences		38.582218 ° -121.441345 °	38.582218 ° -121.441345 °		27
28	4.36	4.36	Earthen Levee	Encroachments	LS CO	Fences		38.582160 ° -121.441207 °	38.582160 ° -121.441207 °		28
29	4.41	4.41	Earthen Levee	Encroachments	LS CO	Landscaping		38.581868 ° -121.440340 °	38.581868 ° -121.440340 °		29
30	4.42	4.42	Earthen Levee	Encroachments	LS PO	Fences		38.581792 ° -121.440138 °	38.581792 ° -121.440138 °		30
31	4.43	4.43	Earthen Levee	Encroachments	LS PO	Fences		38.581747 ° -121.440003 °	38.581747 ° -121.440003 °		31
32	4.48	4.48	Earthen Levee	Encroachments	LS PO	Fences		38.581512 ° -121.439188 °	38.581512 ° -121.439188 °		32
33	4.49	4.49	Earthen Levee	Encroachments	LS PO	Landscaping		38.581478 ° -121.439018 °	38.581478 ° -121.439018 °		33
34	4.51	4.51	Earthen Levee	Encroachments	LS PO	Landscaping		38.581375 ° -121.438588 °	38.581375 ° -121.438588 °		34
35	4.55	4.55	Earthen Levee	Encroachments	LS PO	Fences		38.581207 ° -121.437998 °	38.581207 ° -121.437998 °		35
36	4.56	4.56	Earthen Levee	Encroachments	LS PO	Fences		38.581197 ° -121.437815 °	38.581197 ° -121.437815 °		36
37	4.68	4.68	Earthen Levee	Encroachments	LS PO	Landscaping		38.580957 ° -121.435645 °	38.580957 ° -121.435645 °		37
38	4.69	4.69	Earthen Levee	Encroachments	LS PO	Landscaping		38.580900 ° -121.435367 °	38.580900 ° -121.435367 °		38

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	4.72	4.72	Earthen Levee	Encroachments	LS CO	Landscaping		38.580833 ° -121.434918 °	38.580833 ° -121.434918 °		39
40	4.75	4.75	Earthen Levee	Encroachments	LS PO	Fences		38.580742 ° -121.434305 °	38.580742 ° -121.434305 °		40
41	4.77	4.77	Earthen Levee	Encroachments	LS CO	Fences		38.580733 ° -121.433932 °	38.580733 ° -121.433932 °		41
42	4.79	4.79	Earthen Levee	Encroachments	LS CO	Fences		38.580720 ° -121.433587 °	38.580720 ° -121.433587 °		42
43	4.84	4.84	Earthen Levee	Encroachments	LS PO	Fences		38.580725 ° -121.432613 °	38.580725 ° -121.432613 °		43
44	4.91	4.91	Earthen Levee	Encroachments	LS PO	Landscaping		38.580813 ° -121.431345 °	38.580813 ° -121.431345 °		44
45	4.94	4.94	Earthen Levee	Encroachments	LS PO	Fences		38.580848 ° -121.430753 °	38.580848 ° -121.430753 °		45
46	5.10	5.10	Earthen Levee	Encroachments	LS CO	Fences		38.581032 ° -121.427927 °	38.581032 ° -121.427927 °		46
47	5.15	5.15	Earthen Levee	Encroachments	LS PO	Fences		38.580912 ° -121.427042 °	38.580912 ° -121.427042 °		47
48	5.19	5.19	Earthen Levee	Encroachments	LS CO	Fences		38.580660 ° -121.426403 °	38.580660 ° -121.426403 °		48
49	5.46	5.46	Earthen Levee	Encroachments	LS PO	Fences		38.577595 ° -121.423347 °	38.577595 ° -121.423347 °		49
50	5.56	5.56	Earthen Levee	Encroachments	LS CO	Landscaping		38.576208 ° -121.423152 °	38.576208 ° -121.423152 °		50
51	5.58	5.58	Earthen Levee	Encroachments	LS CO	Landscaping		38.576005 ° -121.423150 °	38.576005 ° -121.423150 °		51
52	5.62	5.62	Earthen Levee	Encroachments	LS CO	Landscaping		38.575390 ° -121.423207 °	38.575390 ° -121.423207 °		52
53	5.63	5.63	Earthen Levee	Encroachments	LS CO	Landscaping		38.575250 ° -121.423240 °	38.575250 ° -121.423240 °		53
54	5.64	5.64	Earthen Levee	Encroachments	LS PO	Fences		38.575093 ° -121.423263 °	38.575093 ° -121.423263 °		54
55	5.66	5.66	Earthen Levee	Encroachments	LS PO	Fences		38.574837 ° -121.423297 °	38.574837 ° -121.423297 °		55
56	5.67	5.67	Earthen Levee	Encroachments	LS CO	Buildings		38.574648 ° -121.423348 °	38.574648 ° -121.423348 °		56
57	5.72	5.72	Earthen Levee	Encroachments	LS CO	Fences		38.573927 ° -121.423480 °	38.573927 ° -121.423480 °		57

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	5.75	5.75	Earthen Levee	Encroachments	LS	PO	Landscaping	38.573547 ° -121.423583 °	38.573547 ° -121.423583 °		58
59	5.76	5.76	Earthen Levee	Encroachments	LS	PO	Fences	38.573403 ° -121.423642 °	38.573403 ° -121.423642 °		59
60	5.77	5.77	Earthen Levee	Encroachments	LS	PO	Landscaping	38.573240 ° -121.423697 °	38.573240 ° -121.423697 °		60
61	5.79	5.79	Earthen Levee	Encroachments	LS	CO	Landscaping	38.572918 ° -121.423760 °	38.572918 ° -121.423760 °		61
62	5.81	5.81	Earthen Levee	Encroachments	LS	PO	Landscaping	38.572748 ° -121.423818 °	38.572748 ° -121.423818 °		62
63	5.83	5.83	Earthen Levee	Encroachments	LS	CO	Buildings	38.572325 ° -121.423913 °	38.572325 ° -121.423913 °		63
64	5.85	5.85	Earthen Levee	Encroachments	LS	CO	Landscaping	38.572117 ° -121.423987 °	38.572117 ° -121.423987 °		64
65	5.87	5.87	Earthen Levee	Encroachments	LS	PO	Fences	38.571783 ° -121.424080 °	38.571783 ° -121.424080 °		65
66	5.88	5.88	Earthen Levee	Encroachments	LS	PO	Material	38.571685 ° -121.424115 °	38.571685 ° -121.424115 °		67
67	5.88	5.88	Earthen Levee	Encroachments	LS	CO	Buildings	38.571688 ° -121.424112 °	38.571688 ° -121.424112 °		66
68	5.89	5.89	Earthen Levee	Encroachments	LS	CO	Landscaping	38.571525 ° -121.424152 °	38.571525 ° -121.424152 °		68
69	5.91	5.91	Earthen Levee	Encroachments	LS	PO	Landscaping	38.571305 ° -121.424183 °	38.571305 ° -121.424183 °		69
70	5.92	5.92	Earthen Levee	Encroachments	LS	PO	Landscaping	38.571145 ° -121.424192 °	38.571145 ° -121.424192 °		70
71	5.97	5.97	Earthen Levee	Encroachments	LS	PO	Landscaping	38.570450 ° -121.424237 °	38.570450 ° -121.424237 °		71
72	6.00	6.00	Earthen Levee	Encroachments	LS	PO	Fences	38.569973 ° -121.424282 °	38.569973 ° -121.424282 °		72
73	6.61	6.61	Earthen Levee	Encroachments	LS	CO	Buildings	38.561643 ° -121.421262 °	38.561643 ° -121.421262 °		73
74	7.73	7.73	Earthen Levee	Encroachments	LS	CO	Fences	38.559172 ° -121.402947 °	38.559172 ° -121.402947 °		74
75	7.75	7.75	Earthen Levee	Encroachments	LS	CO	Fences	38.559227 ° -121.402647 °	38.559227 ° -121.402647 °		75
76	7.80	7.80	Earthen Levee	Encroachments	LS	CO	Fences	38.559308 ° -121.401717 °	38.559308 ° -121.401717 °		76

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
77	7.85	7.85	Earthen Levee	Encroachments	LS CO	Fences		38.559367 ° -121.400938 °	38.559367 ° -121.400938 °		77
78	7.88	7.88	Earthen Levee	Encroachments	LS CO	Fences		38.559408 ° -121.400242 °	38.559408 ° -121.400242 °		78
79	7.97	7.97	Earthen Levee	Encroachments	LS CO	Fences		38.559833 ° -121.398785 °	38.559833 ° -121.398785 °		79
80	8.01	8.01	Earthen Levee	Encroachments	LS CO	Fences		38.560070 ° -121.398128 °	38.560070 ° -121.398128 °		80
81	8.05	8.05	Earthen Levee	Encroachments	LS CO	Fences		38.560340 ° -121.397388 °	38.560340 ° -121.397388 °		81
82	8.09	8.09	Earthen Levee	Encroachments	LS CO	Fences		38.560563 ° -121.396818 °	38.560563 ° -121.396818 °		82
83	8.10	8.10	Earthen Levee	Encroachments	LS CO	Fences		38.560647 ° -121.396660 °	38.560647 ° -121.396660 °		83
84	8.11	8.11	Earthen Levee	Encroachments	LS CO	Fences		38.560725 ° -121.396470 °	38.560725 ° -121.396470 °		84
85	8.13	8.13	Earthen Levee	Encroachments	LS CO	Fences		38.560837 ° -121.396220 °	38.560837 ° -121.396220 °		85
86	8.14	8.14	Earthen Levee	Encroachments	LS CO	Fences		38.560907 ° -121.396043 °	38.560907 ° -121.396043 °		86
87	8.15	8.15	Earthen Levee	Encroachments	LS CO	Fences		38.561008 ° -121.395817 °	38.561008 ° -121.395817 °		87
88	8.20	8.20	Earthen Levee	Encroachments	LS CO	Fences		38.561325 ° -121.395067 °	38.561325 ° -121.395067 °		88
89	8.22	8.22	Earthen Levee	Encroachments	LS CO	Fences		38.561467 ° -121.394728 °	38.561467 ° -121.394728 °		89
90	8.23	8.23	Earthen Levee	Encroachments	LS CO	Fences		38.561540 ° -121.394513 °	38.561540 ° -121.394513 °		90
91	8.25	8.25	Earthen Levee	Encroachments	LS PO	Landscaping		38.561658 ° -121.394157 °	38.561658 ° -121.394157 °		92
92	8.25	8.25	Earthen Levee	Encroachments	LS CO	Fences		38.561593 ° -121.394315 °	38.561593 ° -121.394315 °		91
93	8.26	8.26	Earthen Levee	Encroachments	LS CO	Fences		38.561658 ° -121.394152 °	38.561658 ° -121.394152 °		93
94	8.27	8.27	Earthen Levee	Encroachments	LS CO	Fences		38.561732 ° -121.393928 °	38.561732 ° -121.393928 °		94
95	8.28	8.28	Earthen Levee	Encroachments	LS CO	Fences		38.561802 ° -121.393697 °	38.561802 ° -121.393697 °		95

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
96	8.29	8.29	Earthen Levee	Encroachments	LS CO	Fences		38.561872 ° -121.393537 °	38.561872 ° -121.393537 °		96
97	8.31	8.31	Earthen Levee	Encroachments	LS PO	Fences		38.561972 ° -121.393323 °	38.561972 ° -121.393323 °		97
98	8.32	8.32	Earthen Levee	Encroachments	LS CO	Fences		38.562045 ° -121.393148 °	38.562045 ° -121.393148 °		98
99	8.33	8.33	Earthen Levee	Encroachments	LS CO	Fences		38.562120 ° -121.392983 °	38.562120 ° -121.392983 °		99
100	8.34	8.34	Earthen Levee	Encroachments	LS CO	Fences		38.562182 ° -121.392778 °	38.562182 ° -121.392778 °		100
101	8.38	8.38	Earthen Levee	Encroachments	LS CO	Fences		38.562430 ° -121.392083 °	38.562430 ° -121.392083 °		101
102	8.45	8.45	Earthen Levee	Encroachments	LS CO	Landscaping		38.562840 ° -121.391040 °	38.562840 ° -121.391040 °		102
103	8.47	8.47	Earthen Levee	Encroachments	LS CO	Fences		38.562998 ° -121.390647 °	38.562998 ° -121.390647 °		103
104	8.48	8.48	Earthen Levee	Encroachments	LS PO	Fences		38.563108 ° -121.390452 °	38.563108 ° -121.390452 °		104
105	8.51	8.51	Earthen Levee	Encroachments	LS PO	Landscaping		38.563238 ° -121.390073 °	38.563238 ° -121.390073 °		105
106	8.52	8.52	Earthen Levee	Encroachments	LS PO	Fences		38.563308 ° -121.389885 °	38.563308 ° -121.389885 °		106
107	8.54	8.54	Earthen Levee	Encroachments	LS CO	Landscaping		38.563438 ° -121.389528 °	38.563438 ° -121.389528 °		107
108	8.55	8.55	Earthen Levee	Encroachments	LS CO	Landscaping		38.563508 ° -121.389347 °	38.563508 ° -121.389347 °		108
109	8.57	8.57	Earthen Levee	Encroachments	LS PO	Fences		38.563580 ° -121.389140 °	38.563580 ° -121.389140 °		109
110	8.58	8.58	Earthen Levee	Encroachments	LS PO	Fences		38.563678 ° -121.388938 °	38.563678 ° -121.388938 °		110
111	8.60	8.60	Earthen Levee	Encroachments	LS CO	Fences		38.563820 ° -121.388518 °	38.563820 ° -121.388518 °		111
112	8.61	8.61	Earthen Levee	Encroachments	LS CO	Landscaping		38.563877 ° -121.388343 °	38.563877 ° -121.388343 °		113
113	8.61	8.61	Earthen Levee	Encroachments	LS CO	Landscaping		38.563877 ° -121.388345 °	38.563877 ° -121.388345 °		112
114	8.63	8.63	Earthen Levee	Encroachments	LS CO	Landscaping		38.563945 ° -121.388137 °	38.563945 ° -121.388137 °		114

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Levee Inspection Report By Mile - Spring 2008**

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
115	8.65	8.65	Earthen Levee	Encroachments	LS CO	Fences		38.563998 ° -121.387725 °	38.563998 ° -121.387725 °		115
116	8.66	8.66	Earthen Levee	Encroachments	LS CO	Fences		38.564035 ° -121.387572 °	38.564035 ° -121.387572 °		116
117	8.66	8.66	Earthen Levee	Encroachments	LS CO	Fences		38.564033 ° -121.387572 °	38.564033 ° -121.387572 °		117
118	8.68	8.68	Earthen Levee	Encroachments	LS CO	Fences		38.564133 ° -121.387092 °	38.564133 ° -121.387092 °		118
119	8.68	8.68	Earthen Levee	Encroachments	LS CO	Fences		38.564135 ° -121.387088 °	38.564135 ° -121.387088 °		119
120	9.54	9.54	Earthen Levee	Encroachments	LS PO	Landscaping		38.566835 ° -121.372048 °	38.566835 ° -121.372048 °		120
121	9.61	9.61	Earthen Levee	Encroachments	LS CO	Landscaping		38.567007 ° -121.370918 °	38.567007 ° -121.370918 °		121
122	9.64	9.64	Earthen Levee	Encroachments	LS PO	Landscaping		38.567115 ° -121.370330 °	38.567115 ° -121.370330 °		122
123	9.66	9.66	Earthen Levee	Encroachments	LS PO	Landscaping		38.567208 ° -121.370003 °	38.567208 ° -121.370003 °		123
124	9.67	9.67	Earthen Levee	Encroachments	LS PO	Landscaping		38.567242 ° -121.369858 °	38.567242 ° -121.369858 °		124
125	9.69	9.69	Earthen Levee	Encroachments	LS CO	Landscaping		38.567330 ° -121.369462 °	38.567330 ° -121.369462 °		125
126	9.70	9.70	Earthen Levee	Encroachments	LS PO	Landscaping		38.567352 ° -121.369293 °	38.567352 ° -121.369293 °		126
127	9.72	9.72	Earthen Levee	Encroachments	LS PO	Landscaping		38.567423 ° -121.368910 °	38.567423 ° -121.368910 °		127
128	9.74	9.74	Earthen Levee	Encroachments	LS CO	Fences		38.567493 ° -121.368633 °	38.567493 ° -121.368633 °		128
129	9.75	9.75	Earthen Levee	Encroachments	LS PO	Landscaping		38.567505 ° -121.368415 °	38.567505 ° -121.368415 °		129
130	9.78	9.78	Earthen Levee	Encroachments	LS CO	Landscaping		38.567598 ° -121.367890 °	38.567598 ° -121.367890 °		130
131	9.79	9.79	Earthen Levee	Encroachments	LS PO	Landscaping		38.567628 ° -121.367612 °	38.567628 ° -121.367612 °		131
132	9.82	9.82	Earthen Levee	Encroachments	LS PO	Landscaping		38.567722 ° -121.367085 °	38.567722 ° -121.367085 °		132
133	9.84	9.84	Earthen Levee	Encroachments	LS PO	Landscaping		38.567887 ° -121.366793 °	38.567887 ° -121.366793 °		133

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway						Bank	Unit Miles	Inspection Date	Inspector		
Unit No. 04 American River						Left	11.00	05/16/2008	Clay Thomas		
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
134	9.86	9.86	Earthen Levee	Encroachments	LS PO	Landscaping		38.567873 ° -121.366410 °	38.567873 ° -121.366410 °		134
135	10.02	10.02	Earthen Levee	Encroachments	LS PO	Landscaping		38.568542 ° -121.363643 °	38.568542 ° -121.363643 °		135
136	10.03	10.03	Earthen Levee	Encroachments	LS CO	Landscaping		38.568620 ° -121.363453 °	38.568620 ° -121.363453 °		136
137	10.07	10.07	Earthen Levee	Encroachments	LS PO	Landscaping		38.568822 ° -121.362768 °	38.568822 ° -121.362768 °		137
138	10.08	10.08	Earthen Levee	Encroachments	LS CO	Fences		38.568712 ° -121.362663 °	38.568712 ° -121.362663 °		138
139	10.11	10.11	Earthen Levee	Encroachments	LS PO	Landscaping		38.569077 ° -121.362168 °	38.569077 ° -121.362168 °		139
140	10.16	10.16	Earthen Levee	Encroachments	LS PO	Landscaping		38.569177 ° -121.361218 °	38.569177 ° -121.361218 °		140
141	10.36	10.36	Earthen Levee	Encroachments	LS CO	Fences		38.570000 ° -121.357767 °	38.570000 ° -121.357767 °		141
142	10.40	10.40	Earthen Levee	Encroachments	LS CO	Fences		38.570147 ° -121.357073 °	38.570147 ° -121.357073 °		142
143	10.43	10.43	Earthen Levee	Encroachments	LS CO	Fences		38.570225 ° -121.356510 °	38.570225 ° -121.356510 °		143
144	10.47	10.47	Earthen Levee	Encroachments	LS CO	Fences		38.570312 ° -121.355938 °	38.570312 ° -121.355938 °		144
145	10.47	10.47	Earthen Levee	Encroachments	LS CO	Fences		38.570315 ° -121.355938 °	38.570315 ° -121.355938 °		145
146	10.50	10.50	Earthen Levee	Encroachments	LS CO	Fences		38.570433 ° -121.355342 °	38.570433 ° -121.355342 °		146
147	10.53	10.53	Earthen Levee	Encroachments	LS PO	Fences		38.570510 ° -121.354758 °	38.570510 ° -121.354758 °		147
148	10.56	10.56	Earthen Levee	Encroachments	LS PO	Fences		38.570503 ° -121.354352 °	38.570503 ° -121.354352 °		148
149	10.59	10.59	Earthen Levee	Encroachments	LS PO	Fences		38.570243 ° -121.353918 °	38.570243 ° -121.353918 °		149
150	10.60	10.60	Earthen Levee	Encroachments	LS PO	Fences		38.570095 ° -121.353807 °	38.570095 ° -121.353807 °		150
151	10.61	10.61	Earthen Levee	Encroachments	LS CO	Fences		38.569990 ° -121.353758 °	38.569990 ° -121.353758 °		151
152	10.63	10.63	Earthen Levee	Encroachments	LS PO	Fences		38.569707 ° -121.353633 °	38.569707 ° -121.353633 °		152

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 American River				Left	11.00	05/16/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
153	10.67	10.67	Earthen Levee	Encroachments	LS CO	Fences		38.569158 ° -121.353370 °	38.569158 ° -121.353370 °		153
154	10.68	10.68	Earthen Levee	Encroachments	LS PO	Fences		38.569020 ° -121.353313 °	38.569020 ° -121.353313 °		154
155	10.69	10.69	Earthen Levee	Encroachments	LS PO	Landscaping		38.568870 ° -121.353245 °	38.568870 ° -121.353245 °		155
156	10.71	10.71	Earthen Levee	Encroachments	LS PO	Landscaping		38.568713 ° -121.353150 °	38.568713 ° -121.353150 °		156
157	10.72	10.72	Earthen Levee	Encroachments	LS PO	Landscaping		38.568512 ° -121.353078 °	38.568512 ° -121.353078 °		157
158	10.73	10.73	Earthen Levee	Encroachments	LS PO	Fences		38.568355 ° -121.353033 °	38.568355 ° -121.353033 °		158
159	10.74	10.74	Earthen Levee	Encroachments	LS PO	Fences		38.568227 ° -121.352997 °	38.568227 ° -121.352997 °		159
160	10.75	10.75	Earthen Levee	Encroachments	LS PO	Fences		38.568112 ° -121.352942 °	38.568112 ° -121.352942 °		160
161	10.76	10.76	Earthen Levee	Encroachments	LS CO	Fences		38.567993 ° -121.352852 °	38.567993 ° -121.352852 °		161
162	10.81	10.81	Earthen Levee	Encroachments	LS PO	Fences		38.567328 ° -121.352478 °	38.567328 ° -121.352478 °		162
163	10.82	10.82	Earthen Levee	Encroachments	LS CO	Fences		38.567145 ° -121.352380 °	38.567145 ° -121.352380 °		163
164	10.86	10.86	Earthen Levee	Encroachments	LS CO	Landscaping		38.566788 ° -121.351777 °	38.566788 ° -121.351777 °		164
165	10.90	10.90	Earthen Levee	Encroachments	LS PO	Fences		38.554763 ° -121.346112 °	38.554763 ° -121.346112 °		170
166	10.97	10.97	Earthen Levee	Encroachments	LS PO	Fences		38.565930 ° -121.350028 °	38.565930 ° -121.350028 °		165
167	10.97	10.97	Earthen Levee	Encroachments	LS PO	Landscaping		38.564645 ° -121.349090 °	38.564645 ° -121.349090 °		167
168	10.97	10.97	Earthen Levee	Encroachments	LS CO	Fences		38.564995 ° -121.348150 °	38.564995 ° -121.348150 °		168
169	10.97	10.97	Earthen Levee	Encroachments	LS CO	Landscaping		38.561302 ° -121.348837 °	38.561302 ° -121.348837 °		169
170	10.97	10.97	Earthen Levee	Encroachments	LS PO	Fences		38.563338 ° -121.350295 °	38.563338 ° -121.350295 °		171
171	10.97	10.97	Earthen Levee	Encroachments	LS PO	Fences		38.564960 ° -121.348975 °	38.564960 ° -121.348975 °		166

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway		Bank	Unit Miles
Unit No. 05 Sacramento River		Left	0.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/16/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Sacramento River				Left	0.40	05/16/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.11	0.11	Earthen Levee	Encroachments	LS	PO	Landscaping	38.594850 ° -121.506452 °	38.594850 ° -121.506452 °		2
2	0.15	0.15	Earthen Levee	Encroachments	LS	PO	Landscaping	38.594310 ° -121.506360 °	38.594310 ° -121.506360 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway		Bank	Unit Miles
Unit No. 06 Linda Creek		Left	1.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 06 Linda Creek				Left	1.30	05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.15	0.93	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.657242 °	38.661953 °		1
								-121.471915 °	-121.459010 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 07 Arcade Creek	Right	1.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Arcade Creek				Right	1.90	05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.04	0.78	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.620638 ° -121.466987 °	38.624787 ° -121.455618 °		1
2	1.54	1.54	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627680 ° -121.442342 °	38.627680 ° -121.442342 °		2
3	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences	38.627707 ° -121.441965 °	38.627707 ° -121.441965 °		4
4	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences	38.627682 ° -121.442113 °	38.627682 ° -121.442113 °		3
5	1.65	1.65	Earthen Levee	Encroachments	LS	CO	Fences	38.627620 ° -121.440467 °	38.627620 ° -121.440467 °		5
6	1.68	1.68	Earthen Levee	Encroachments	LS	CO	Fences	38.627868 ° -121.439962 °	38.627868 ° -121.439962 °		6
7	1.69	1.69	Earthen Levee	Encroachments	LS	CO	Buildings	38.627935 ° -121.439758 °	38.627935 ° -121.439758 °		7
8	1.72	1.72	Earthen Levee	Encroachments	LS	CO	Buildings	38.628102 ° -121.439283 °	38.628102 ° -121.439283 °		8
9	1.74	1.74	Earthen Levee	Encroachments	LS	CO	Fences	38.628197 ° -121.438863 °	38.628197 ° -121.438863 °		9
10	1.77	1.77	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628273 ° -121.438255 °	38.628273 ° -121.438255 °		10
11	1.79	1.79	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628297 ° -121.437995 °	38.628297 ° -121.437995 °		11
12	1.80	1.80	Earthen Levee	Encroachments	LS	PO	Fences	38.628307 ° -121.437842 °	38.628307 ° -121.437842 °		12
13	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences	38.628303 ° -121.437530 °	38.628303 ° -121.437530 °		14
14	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences	38.628303 ° -121.437693 °	38.628303 ° -121.437693 °		13
15	1.83	1.83	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628295 ° -121.437282 °	38.628295 ° -121.437282 °		15
16	1.84	1.84	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628262 ° -121.436985 °	38.628262 ° -121.436985 °		16

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 08 Magpie Creek Diversion	Left	1.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Magpie Creek Diversion				Left	1.50	05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.07	1.48	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This levee is a patrol road. Limited access.	38.665677 °	38.660740 °		2
								-121.431967 °	-121.429255 °		
2	1.07	1.48	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This levee is a patrol road. Limited access.	38.665668 °	38.660728 °		1
								-121.431955 °	-121.429247 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 09 American River	Right	4.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 09 American River				Right	4.50	05/14/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.13	1.13	Earthen Levee	Encroachments	LS	PO	Landscaping	38.563040 ° -121.402168 °	38.563040 ° -121.402168 °		3
2	3.11	3.24	Earthen Levee	Encroachments	LS	CO	Fences	38.576423 ° -121.419117 °	38.578248 ° -121.418475 °		2
3	3.24	3.32	Earthen Levee	Encroachments	LS	PO	Fences	38.578258 ° -121.418475 °	38.579363 ° -121.418100 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 10 American River	Right	4.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 10 American River				Right	4.00	05/14/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

American River Flood Control District

Waterway	Bank	Unit Miles
Unit No. 11 New Arcade Creek		

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/8/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 11 New Arcade Creek			05/08/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.74	Earthen Levee	Vegetation			Control annual grass and weeds on the levee slopes and easements. Inspector Comments: L/M 0.00 starts at bike trail,going D/S. L/M 0.00 going U/S is unit 8 magpie crk. The V 1 does not apply, this is for GPS.	38.667982 °	38.662538 °		1
								-121.447555 °	-121.457848 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---