

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway	Bank	Unit Miles
Unit No. 01 Mud Creek	Right	7.29

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Dave Herfi Butte Co.			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	7.29	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	1.32	1.32	Earthen Levee	Encroachments	LS	C	Prunings	39.741257 ° -121.927585 °	39.741257 ° -121.927585 °	1
2	1.75	1.75	Earthen Levee	Encroachments	LS	M	Prunings	39.746137 ° -121.923162 °	39.746137 ° -121.923162 °	2
3	1.92	1.92	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.747462 ° -121.920537 °	39.747462 ° -121.920537 °	27 Y
4	2.06	2.10	Earthen Levee	Encroachments	LS	CO	Fences	39.748330 ° -121.918685 °	39.748867 ° -121.918533 °	3
5	2.16	2.16	Earthen Levee	Encroachments	LS	CO	Buildings	39.749732 ° -121.918270 °	39.749732 ° -121.918270 °	24
6	2.18	2.25	Earthen Levee	Encroachments	LS	PO	Fences	39.749917 ° -121.917738 °	39.753355 ° -121.922915 °	4
7	2.50	2.50	Earthen Levee	Encroachments	LS	C	Prunings	39.753695 ° -121.914863 °	39.753695 ° -121.914863 °	28
8	2.83	2.83	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.757982 ° -121.912880 °	39.757982 ° -121.912880 °	29
9	3.10	3.10	Earthen Levee	Encroachments	LS	M	Prunings	39.761085 ° -121.911048 °	39.761085 ° -121.911048 °	25
10	3.20	3.20	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.762213 ° -121.909962 °	39.762213 ° -121.909962 °	30
11	3.98	3.98	Earthen Levee	Encroachments	LS	M	Prunings	39.770351 ° -121.901349 °	39.770351 ° -121.901349 °	5
12	4.05	4.05	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.771120 ° -121.900330 °	39.771120 ° -121.900330 °	26
13	4.14	4.14	Earthen Levee	Encroachments	LS	C	Prunings	39.771787 ° -121.899065 °	39.771787 ° -121.899065 °	19
14	4.58	4.58	Earthen Levee	Encroachments	LS	M	Prunings	39.775908 ° -121.893947 °	39.775908 ° -121.893947 °	21
15	4.72	4.76	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.778007 ° -121.893537 °	39.778405 ° -121.893283 °	31
16	4.92	4.92	Earthen Levee	Encroachments	LS	M	Prunings	39.780133 ° -121.891385 °	39.780133 ° -121.891385 °	6
17	4.96	4.96	Earthen Levee	Encroachments	LS	M	Prunings	39.780550 ° -121.890952 °	39.780550 ° -121.890952 °	22

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected
 W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	7.29	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	3
Start Levee Mile	1.92
End Levee Mile	1.92
Location	Land Side
Category	Earthen Levee
Item	Animal Control
View of squirrel holes along the slope of land side levee and a bait station feeder.	
rduffey_s_20100607_022.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 02 Mud Creek		Left	8.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Dave Herfi Butte Co.			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	8.20	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	1.58	1.90	Earthen Levee	Encroachments	LS	CO	Fences	39.782773 ° -121.888178 °	39.778972 ° -121.891563 °	3 Y
2	2.90	2.90	Earthen Levee	Encroachments	LS	M	Firewood	39.767985 ° -121.901493 °	39.767985 ° -121.901493 °	11
3	4.69	4.69	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.749917 ° -121.917195 °	39.749917 ° -121.917195 °	16
4	5.10	5.10	Earthen Levee	Encroachments	LS	M	Prunings	39.745932 ° -121.921553 °	39.745932 ° -121.921553 °	15
5	6.63	6.63	Earthen Levee	Encroachments	LS	M	Prunings	39.728864 ° -121.932545 °	39.728864 ° -121.932545 °	1
6	7.38	7.38	Earthen Levee	Encroachments	LS	M	Prunings	39.719695 ° -121.938189 °	39.719695 ° -121.938189 °	2

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	8.20	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	1.58
End Levee Mile	1.90
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the fence along the landside toe of the levee.	
rduffey_s_20100628_093.jpg	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway	Bank	Unit Miles
Unit No. 02A Channel Slough	Left	0.30

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Dave Herfi Butte Co.			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Channel Slough	Left	0.30	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.30	Earthen Levee	Vegetation	CR	W	Remove the wild growth other than native grasses from the levee slopes.	39.733565 ° -121.929807 °	39.733565 ° -121.929807 °	3 Y

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Channel Slough	Left	0.30	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.30
Location	Crown
Category	Earthen Levee
Item	Vegetation
View of the sprayed vegetation on both slopes of the levee.	
rduffey_s_20100628_094.jpg	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway	Bank	Unit Miles
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.13

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks				Right	4.13	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.06	0.06	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	39.786068 ° -121.881828 °	39.786068 ° -121.881828 °	3 Y

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.13	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.06
End Levee Mile	0.06
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
View of the motorcycle erosion on the landside slope of the levee.	
rduffey_s_20100607_025.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 04 Sycamore and Dry Creeks		Right	2.94

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.94	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.98	1.05	Earthen Levee	Encroachments	LS	CO	Fences	39.776013 ° -121.851175 °	39.776595 ° -121.852005 °	1 Y
2	1.16	1.27	Earthen Levee	Encroachments	LS	CO	Fences	39.776760 ° -121.854022 °	39.777650 ° -121.855687 °	3
3	1.80	1.80	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	° °	° °	2 Y

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.94	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.98
End Levee Mile	1.05
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the fence and trees along the landside toe of the levee.

rduffey_s_20100628_092.jpg



Levee Mile Report Line	3
Start Levee Mile	1.80
End Levee Mile	1.80
Location	Land Side
Category	Earthen Levee
Item	Vegetation

View of Levee without grass on it.

rduffey_s_20100630_100.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>	<p>C : Corrected W : Watch/Monitor</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 05 Big Chico Diversion		Left	1.85

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2010 - 5/5/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Dave Herfi Butte Co.			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	05/05/2010 05/05/2010	Bob Duffey

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.22	0.45	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	39.761921 ° -121.792929 °	39.761110 ° -121.796950 °	2 Y
2	0.22	0.45	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	39.761920 ° -121.792930 °	39.761110 ° -121.796951 °	1

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Butte County Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	05/05/2010 05/05/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.22
End Levee Mile	0.45
Location	Water Side
Category	Earthen Levee
Item	Vegetation
View of the noxious weeds on both slopes of the levee.	
rduffey_s_20100607_027.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---