

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Butte County Public Works

Big Chico Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A

Lindo Channel Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Lindo Channel Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Flood Control Project Maintenance

Unit Cover Sheet

2008 Structure Inspection Results

Butte County Public Works

Structure
Big Chico Creek Diversion Structure

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Structure Rating	A

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure		Inspection Date	Inspector
Big Chico Creek Diversion Structure		09/17/2008	Bob Duffey

Roll Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Vegetation & Obstructions		A		39.761950 ° 121.792730 °	Y	2
2	Structures & Concrete Lined Channels	Vegetation & Obstructions		A		39.761950 ° 121.792730 °	Y	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure	Inspection Date	Inspector
Big Chico Creek Diversion Structure	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Vegetation & Obstructions
Downstream at discharge end of the structure from the right bank.	



Report Line	2
Location	
Category	Structures & Concrete Lined Channels
Item	Vegetation & Obstructions
View of the upstream side of the structure.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	--

Flood Control Project Maintenance

Unit Cover Sheet

2008 Structure Inspection Results

Butte County Public Works

Structure
Lindo Channel Control Structure

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Structure Rating	A

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure		Inspection Date	Inspector
Lindo Channel Control Structure		09/17/2008	Bob Duffey

RptLine	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Concrete Foundations		A		39.761670 ° 121.797130 °	Y	1
2	Structures & Concrete Lined Channels	Concrete Foundations		A		39.761670 ° 121.797130 °	Y	2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure	Inspection Date	Inspector
Lindo Channel Control Structure	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

View of the upstream side of structure.



Report Line	2
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

View of the downstream side of structure.



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	--

Flood Control Project Maintenance

Unit Cover Sheet

2008 Structure Inspection Results

Butte County Public Works

Structure
Lindo Channel Diversion Weir

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Structure Rating	A

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure		Inspection Date	Inspector
Lindo Channel Diversion Weir		09/17/2008	Bob Duffey

RptLine	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Concrete Foundations		A		39.761960 ° 121.797330 °	Y	2
2	Structures & Concrete Lined Channels	Concrete Foundations		A		39.761960 ° 121.797330 °	Y	1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	--

**Flood Control Project Maintenance
Inspection Report - Structure 2008**

Butte County Public Works

Structure	Inspection Date	Inspector
Lindo Channel Diversion Weir	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

The velocity dissipaters on the downstream side of structure from the left bank.



Report Line	2
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

Upstream side of the structure from the left bank.



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	--