

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	10/27/2014 10/27/2014	Matthew Hoffman

LM Start		Rating **	A	Issue No.	<b>4</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals		°	°	°
DWR ID	DWR_NA0004_01_s_2013_4				
Action/Comments					
Inspector Comments: Frank Miller stated that he has a couple copies of the O&M manuals and they are located at the district office.					

No Photos

LM Start		Rating **	A	Issue No.	<b>5</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment		°	°	°
DWR ID	DWR_NA0004_01_s_2013_5				
Action/Comments					
Inspector Comments: LMA stated that most of the emergency flood fight supplies are located at 214 1st St.					

No Photos

LM Start		Rating **	A	Issue No.	<b>6</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training		°	°	°
DWR ID	DWR_NA0004_01_s_2013_6				
Action/Comments					
Inspector Comments: Frank Miller stated that he and his employees were able to participate in a flood fight training exercise recently with Emergency Services and Yuba County OES.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	10/27/2014 10/27/2014	Matthew Hoffman

LM Start	<b>1.85</b>	Rating **	A	Issue No.	<b>10</b>
LM End	<b>1.85</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.164735 °	39.164735 °	
			-121.583859 °	-121.583859 °	
DWR ID	DWR_NA0004_01_f_2014_10				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : FA\_2014\_NA0004\_104\_10\_20141103\_00002.jpg



This photo was taken from the levee crown facing west looking down the landward slope at acceptable vegetation maintenance. Fall 2014.

LM Start	<b>3.21</b>	Rating **	A/W	Issue No.	<b>1</b>
LM End	<b>3.21</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		39.163590 °	39.163590 °	
			-121.559495 °	-121.559495 °	
DWR ID	DWR_NA0004_01_s_2012_1				
Action/Comments					
Repair slope instability. Inspector Comments: This drain pipe has been added to the site on the Corps PI.					

Photo 1 of 1 : FA\_2014\_NA0004\_104\_1\_20141023\_00001.jpg



This site is on the Corps PI.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	10/27/2014 10/27/2014	Matthew Hoffman

LM Start	<b>0.43</b>	Rating **	A	Issue No.	<b>5</b>
LM End	<b>0.43</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.143573 °	39.143573 °	
			-121.600375 °	-121.600375 °	
DWR ID	DWR_NA0004_02_f_2014_5				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : FA\_2014\_NA0004\_105\_5\_20141103\_00002.jpg



This photo was taken from the levee crown facing south looking down the waterward slope at acceptable vegetation maintenance. Fall 2014.

LM Start	<b>0.72</b>	Rating **	M	Issue No.	<b>9</b>
LM End	<b>0.72</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.139752 °	39.139752 °	
			-121.600637 °	-121.600637 °	
DWR ID	DWR_NA0004_02_f_2013_9				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Blackberries on waterward levee slope.					

Photo 1 of 1 : FA\_2014\_NA0004\_105\_9\_20141023\_00001.jpg



This photo was taken from the access road going under the 5th street bridge of blackberries growing on the waterward levee slope. Fall 2013.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	10/27/2014 10/27/2014	Matthew Hoffman

LM Start	<b>0.87</b>	Rating **	A	Issue No.	<b>25</b>
LM End	<b>0.87</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.139990 °	39.139990 °	
			-121.583184 °	-121.583184 °	
DWR ID	DWR_NA0004_03_f_2014_25				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : FA\_2014\_NA0004\_106\_25\_20141103\_00007.jpg



This photo was taken from the levee crown facing east looking down the waterward slope at acceptable vegetation maintenance. Fall 2014.

LM Start	<b>4.64</b>	Rating **	M	Issue No.	<b>34</b>
LM End	<b>4.64</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.182347 °	39.182347 °	
			-121.542744 °	-121.542744 °	
DWR ID	DWR_NA0004_03_f_2013_34				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Blackberries on landward levee slope.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------