

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	11/04/2015 11/04/2015	Jai Lor

LM Start		Rating **	A	Issue No.	<b>4</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_NA0004_01_s_2013_4				
Action/Comments					
Inspector Comments: Frank Miller stated that he has a couple copies of the O&M manuals and they are located at the district office.					

No Photos

LM Start		Rating **	A	Issue No.	<b>5</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_NA0004_01_s_2013_5				
Action/Comments					
Inspector Comments: LMA stated that most of the emergency flood fight supplies are located at 214 1st St.					

No Photos

LM Start		Rating **	A	Issue No.	<b>6</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_NA0004_01_s_2013_6				
Action/Comments					
Inspector Comments: Frank Miller stated that he and his employees were able to participate in a flood fight training exercise recently with Emergency Services and Yuba County OES.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	11/04/2015 11/04/2015	Jai Lor

LM Start	<b>0.01</b>	Rating **	A	Issue No.	<b>7</b>
LM End	<b>1.23</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149387 °	39.134755 °
				-121.601125 °	-121.594040 °
DWR ID	DWR_NA0004_02_f_2015_7				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Levee slope has been maintained.					

No Photos

LM Start	<b>0.01</b>	Rating **	A	Issue No.	<b>5</b>
LM End	<b>1.23</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149387 °	39.134750 °
				-121.601125 °	-121.594045 °
DWR ID	DWR_NA0004_02_f_2015_5				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Levee slope has been burned and dragged.					

Photo 1 of 1 : FA\_2015\_NA0004\_105\_5\_20151112\_00002.jpg



View of the vegetation on the waterward side of the levee looking downstream. Fall 2015.

LM Start	<b>0.31</b>	Rating **	A/W	Issue No.	<b>6</b>
LM End	<b>0.31</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.144990 °	39.144990 °
				-121.600576 °	-121.600576 °
DWR ID	DWR_NA0004_02_s_2015_6				
Action/Comments					
Note and monitor erosion site.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	11/04/2015 11/04/2015	Jai Lor

LM Start	<b>0.70</b>	Rating **	C	Issue No.	<b>9</b>
LM End	<b>0.70</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.139752 °	39.139752 °	
			-121.600637 °	-121.600637 °	
DWR ID	DWR_NA0004_02_f_2013_9				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Blackberries on waterward levee slope.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	11/04/2015 11/04/2015	Jai Lor

LM Start	<b>0.01</b>	Rating **	A	Issue No.	<b>25</b>
LM End	<b>0.27</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134850 °	39.135147 °
				-121.593650 °	-121.588987 °
DWR ID	DWR_NA0004_03_f_2015_25				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: LMA has burned and dragged the levee.					

Photo 1 of 1 : FA\_2015\_NA0004\_106\_25\_20151112\_00007.jpg



View of the vegetation on the waterward side of the levee looking upstream. Fall 2015.

LM Start	<b>0.01</b>	Rating **	A	Issue No.	<b>26</b>
LM End	<b>0.27</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134850 °	39.135147 °
				-121.593650 °	-121.588987 °
DWR ID	DWR_NA0004_03_f_2015_26				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>0.27</b>	Rating **	M	Issue No.	<b>30</b>
LM End	<b>0.59</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135147 °	39.136647 °
				-121.588987 °	-121.583490 °
DWR ID	DWR_NA0004_03_f_2015_30				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<p><b>* Location</b>                  LS : Land Side    N/A : Not Applicable                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable</p>	<p>N : Not Inspected/Rated                  C : Corrected                  A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b>                  Ma : Maintenance Deficiency                  Ob : Design &amp; System Obsolescence                  En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	11/04/2015 11/04/2015	Jai Lor

LM Start	<b>0.27</b>	Rating **	M	Issue No.	<b>29</b>
LM End	<b>2.15</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.135147 °	39.154462 °	
			-121.588987 °	-121.569858 °	
DWR ID	DWR_NA0004_03_f_2015_29				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>2.15</b>	Rating **	M	Issue No.	<b>32</b>
LM End	<b>3.31</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.154462 °	39.167685 °	
			-121.569858 °	-121.556858 °	
DWR ID	DWR_NA0004_03_f_2015_32				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>2.70</b>	Rating **	M	Issue No.	<b>33</b>
LM End	<b>3.43</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.160072 °	39.169147 °	
			-121.562475 °	-121.555802 °	
DWR ID	DWR_NA0004_03_f_2015_33				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	11/04/2015 11/04/2015	Jai Lor

LM Start	<b>4.58</b>	Rating **	M	Issue No.	<b>34</b>
LM End	<b>4.58</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.182347 °	39.182347 °	
			-121.542744 °	-121.542744 °	
DWR ID	DWR_NA0004_03_f_2013_34				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Blackberries on landward levee slope.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---