

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2009 Levee Inspection Results

City of Sacramento

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
City of Sacramento**

Waterway		Bank	Unit Miles
Unit No. 01 City of Sacramento		Left	3.60

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/5/2009 - 5/5/2009			
DWR Inspector	John Williamson			
Accompanied By	Jeff Heard City of Sac.			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 City of Sacramento	Left	3.60	05/05/2009 05/05/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.14	0.14	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: state recorder can(DWR) fenced area	38.588715 ° -121.504885 °	38.588715 ° -121.504885 °	Y	1
2	0.16	0.16	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: historical building	38.588425 ° -121.504860 °	38.588425 ° -121.504860 °	Y	2
3	0.78	0.78	Earthen Levee	Encroachments	CR	PO	Buildings Inspector Comments: Embassy Suites	38.579712 ° -121.507347 °	38.579712 ° -121.507347 °	Y	4
4	0.78	0.93	Earthen Levee	Encroachments	CR	PO	Landscaping Inspector Comments: River walk along the water front	38.579705 ° -121.507360 °	38.577740 ° -121.508147 °	Y	5
5	1.73	1.96	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: Levee is oversize with railroad tracks and paved parking this area is Miller Park	38.568172 ° -121.516042 °	38.564882 ° -121.516265 °	Y	6
6	1.96	2.34	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: Railroad tracks run on crown of levee, paved roadway runs along toe on waterside this is Miller Park Marina area.	38.564900 ° -121.516253 °	38.559460 ° -121.515085 °	Y	7
7	2.45	2.45	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.557937 ° -121.514237 °	38.557937 ° -121.514237 °		8
8	2.90	2.90	Earthen Levee	Encroachments	CR	PO	Buildings	38.551810 ° -121.511838 °	38.551810 ° -121.511838 °	Y	10
9	2.92	3.58	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Waterside slope cannot be mowed until June 15, requirements by Fish & Game. Sacramento City will comply with requirements and mow after that date.	38.551453 ° -121.511738 °	38.541792 ° -121.510987 °		12

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 City of Sacramento	Left	3.60	05/05/2009 05/05/2009	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.14
End Levee Mile	0.14
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Recorder can (DWR)	



Levee Mile Report Line	2
Start Levee Mile	0.16
End Levee Mile	0.16
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Historical Building : State Parks & Recreations	



Levee Mile Report Line	3
Start Levee Mile	0.78
End Levee Mile	0.78
Location	Crown
Category	Earthen Levee
Item	Encroachments
Embassy Suites	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 City of Sacramento	Left	3.60	05/05/2009 05/05/2009	John Williamson

Levee Mile Report Line	4
Start Levee Mile	0.78
End Levee Mile	0.93
Location	Crown
Category	Earthen Levee
Item	Encroachments
River walk crown with landscaping	



Levee Mile Report Line	5
Start Levee Mile	1.73
End Levee Mile	1.96
Location	Crown
Category	Earthen Levee
Item	Encroachments
Miller Park at Broadway rail road track and parking area on levee	



Levee Mile Report Line	6
Start Levee Mile	1.96
End Levee Mile	2.34
Location	Crown
Category	Earthen Levee
Item	Encroachments
Rail road tracks on levee crown street to boat ramp	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 City of Sacramento	Left	3.60	05/05/2009 05/05/2009	John Williamson

Levee Mile Report Line	8
Start Levee Mile	2.90
End Levee Mile	2.90
Location	Crown
Category	Earthen Levee
Item	Encroachments
pump station city of Sacramento crown of levee waterside	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected