

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2011 Levee Inspection Results**

**Solano County Public Works Mellin Levee**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Solano County Public Works Mellin Levee**

<b>Waterway</b>	<b>Bank</b>	<b>Unit Miles</b>
Unit No. 01 Mellin Levee	Right	0.59

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/18/2011 - 4/18/2011			
DWR Inspector	Richard Willoughby			
Accompanied By	Thomas Pate Solano County Water Agency			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000


**X** \_\_\_\_\_ Date

Signature of LMA Representative

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mellin Levee	Right	0.59	04/18/2011 04/18/2011	Richard Willoughby

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Vegetation	WS	W	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Bamboo on waterside slope	38.174051 ° -121.674220 °	38.174051 ° -121.674221 °	1 Y
2	0.00	0.59	Earthen Levee	Encroachments	WS	CO	Fences	38.174167 ° -121.674312 °	38.178960 ° -121.680600 °	3 Y
3	0.00	0.59	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.174083 ° -121.674265 °	38.180032 ° -121.681958 °	5 Y
4	0.00	0.59	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.174087 ° -121.674262 °	38.180032 ° -121.681962 °	11
5	0.02	0.59	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	° °	38.180033 ° -121.681957 °	12
6	0.04	0.04	Earthen Levee	Encroachments	LS	M	Abandoned vehicles	38.174470 ° -121.674730 °	38.174470 ° -121.674730 °	8 Y
7	0.08	0.08	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	38.174948 ° -121.675263 °	38.174948 ° -121.675263 °	2 Y
8	0.10	0.28	Earthen Levee	Encroachments	LS	PO	Fences	38.175115 ° -121.675463 °	38.176805 ° -121.677893 °	4
9	0.36	0.51	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.177743 ° -121.678998 °	38.179212 ° -121.680873 °	6

<b>* Location</b> LS : Landside WS : Waterside CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mellin Levee	Right	0.59	04/18/2011 04/18/2011	Richard Willoughby

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking northeast at bamboo on waterside at the entrance to levee.	
richard_s_20110215_099.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.59
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Fence along the waterside shoulder.	
richard_s_20110215_103.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.00
End Levee Mile	0.59
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking at typical view of levee.	
richard_s_20110606_107.jpg	



<b>* Location</b> LS : Landside WS : Waterside CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--	--	--	------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mellin Levee	Right	0.59	04/18/2011 04/18/2011	Richard Willoughby

Levee Mile Report Line	6
Start Levee Mile	0.04
End Levee Mile	0.04
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking southwest at dilapidated vehicles on landside toe.	
richard_s_20110215_106.jpg	



Levee Mile Report Line	7
Start Levee Mile	0.08
End Levee Mile	0.08
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
Looking downstream (east) at slope damage on waterside slope and shoulder.	
richard_s_20110215_100.jpg	



Levee Mile Report Line	7
Start Levee Mile	0.08
End Levee Mile	0.08
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
Looking east at slope damage on waterside shoulder.	
richard_s_20110215_101.jpg	



<p><b>* Location</b></p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---	---	---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mellin Levee	Right	0.59	04/18/2011 04/18/2011	Richard Willoughby

Levee Mile Report Line	7
Start Levee Mile	0.08
End Levee Mile	0.08
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

Looking upstream (west) at slope damage on waterside slope and shoulder.

richard\_s\_20110215\_102.jpg



<p><b>* Location</b></p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor U : Unacceptable      N : Not Inspected/Rated</p>
---	---