

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2008 Levee Inspection Results**

**Sacramento River West Side Levee District**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2008 Levee Inspection Results**

**Sacramento River West Side Levee District**

Waterway	Bank	Unit Miles
Unit No. 01 Sacramento River	Right	50.24

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/13/2008			
DWR Inspector	John Williamson			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Sacramento River West Side Levee District**

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	50.24	05/13/2008	John Williamson

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.27	50.02	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: no gps tracking at end	38.802618 ° -121.724020 °	39.142295 ° -121.763328 °		1
2	0.27	50.02	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: no gps tracking at end	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		2
3	2.44	2.44	Earthen Levee	Encroachments	LS	PO	Equipment	38.832537 ° -121.729542 °	38.832537 ° -121.729542 °		3
4	2.83	2.83	Earthen Levee	Encroachments	LS	PO	Landscaping	38.837405 ° -121.731717 °	38.837405 ° -121.731717 °		4
5	3.02	3.02	Earthen Levee	Encroachments	LS	PO	Equipment	38.840057 ° -121.731012 °	38.840057 ° -121.731012 °		5
6	3.06	3.06	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.840495 ° -121.730600 °	38.840495 ° -121.730600 °		6
7	4.66	4.66	Earthen Levee	Encroachments	LS	PO	Debris	38.857245 ° -121.731100 °	38.857245 ° -121.731100 °		7
8	4.76	4.76	Earthen Levee	Encroachments	LS	PO	Abandoned vehicles	38.858718 ° -121.731490 °	38.858718 ° -121.731490 °		8
9	4.87	4.87	Earthen Levee	Encroachments	LS	PO	Pipe	38.859443 ° -121.733005 °	38.859443 ° -121.733005 °		9
10	5.82	5.82	Earthen Levee	Encroachments	WS	PO	Firewood	38.866078 ° -121.747460 °	38.866078 ° -121.747460 °		10
11	8.87	8.87	Earthen Levee	Encroachments	LS	PO	Buildings	38.855498 ° -121.783998 °	38.855498 ° -121.783998 °		11
12	10.86	10.86	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.867778 ° -121.803512 °	38.867778 ° -121.803512 °		12
13	11.87	11.87	Earthen Levee	Encroachments	WS	PO	Crops	38.877333 ° -121.816183 °	38.877333 ° -121.816183 °		13
14	12.35	12.35	Earthen Levee	Encroachments	CR	PO	Buildings	38.883807 ° -121.817543 °	38.883807 ° -121.817543 °		14
15	18.23	18.23	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.944225 ° -121.837500 °	38.944225 ° -121.837500 °		15
16	18.75	18.75	Earthen Levee	Encroachments	CR	PO	Buildings	38.951400 ° -121.838255 °	38.951400 ° -121.838255 °		16
17	18.75	18.75	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.951458 ° -121.838242 °	38.951458 ° -121.838242 °		17
18	18.89	18.89	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.952923 ° -121.839797 °	38.952923 ° -121.839797 °		19
19	18.89	18.89	Earthen Levee	Encroachments	LS	PO	Landscaping	38.952923 ° -121.839797 °	38.952923 ° -121.839797 °		18

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Sacramento River West Side Levee District**

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River			Right	50.24	05/13/2008	John Williamson

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	18.98	18.98	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.953975 ° -121.840833 °	38.953975 ° -121.840833 °		20
21	19.11	19.11	Earthen Levee	Encroachments	LS	PO	Debris	38.955608 ° -121.841057 °	38.955608 ° -121.841057 °		21
22	19.16	19.16	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	38.955913 ° -121.840282 °	38.955913 ° -121.840282 °		22
23	19.22	19.22	Earthen Levee	Encroachments	CR	PO	Buildings	38.956330 ° -121.839277 °	38.956330 ° -121.839277 °		23
24	19.31	19.31	Earthen Levee	Encroachments	CR	PO	Debris	38.956932 ° -121.837822 °	38.956932 ° -121.837822 °		24
25	19.34	19.34	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.957183 ° -121.837323 °	38.957183 ° -121.837323 °		25
26	21.86	21.86	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: arundo two bunches on levee slope	38.984707 ° -121.821457 °	38.984707 ° -121.821457 °		26
27	22.93	22.93	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.989943 ° -121.805900 °	38.989943 ° -121.805900 °		27
28	23.00	23.00	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.989785 ° -121.804702 °	38.989785 ° -121.804702 °		28
29	23.14	23.14	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.990035 ° -121.802152 °	38.990035 ° -121.802152 °		30
30	23.14	23.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.990040 ° -121.802152 °	38.990040 ° -121.802152 °		29
31	23.48	23.48	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.993465 ° -121.797585 °	38.993465 ° -121.797585 °		31
32	24.57	24.57	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	39.003777 ° -121.808377 °	39.003777 ° -121.808377 °		32
33	25.10	25.10	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	39.005197 ° -121.817618 °	39.005197 ° -121.817618 °		33
34	25.13	25.13	Earthen Levee	Encroachments	LS	CO	Landscaping	39.005240 ° -121.818123 °	39.005240 ° -121.818123 °		34
35	26.00	26.00	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees over roadway to at least 12 feet above ground level.	39.013830 ° -121.826678 °	39.013830 ° -121.826678 °		35
36	27.00	27.00	Earthen Levee	Encroachments	WS	PO	Firewood	39.027085 ° -121.823585 °	39.027085 ° -121.823585 °		36
37	27.85	27.85	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	39.034620 ° -121.833378 °	39.034620 ° -121.833378 °		37
38	28.25	28.51	Earthen Levee	Crown Surface / Depressions / Rutting	CR	A	Keep the crown roadway free of vegetation.	39.039675 ° -121.833748 °	39.042103 ° -121.837288 °		38

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Sacramento River West Side Levee District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River				Right	50.24	05/13/2008	John Williamson

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	28.97	28.97	Earthen Levee	Encroachments	WS	PO	Debris	39.048017 ° -121.841027 °	39.048017 ° -121.841027 °		39
40	32.30	32.30	Earthen Levee	Encroachments	WS	PO	Pipe	39.068557 ° -121.874700 °	39.068557 ° -121.874700 °		40
41	32.42	32.42	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	39.069130 ° -121.876638 °	39.069130 ° -121.876638 °		41
42	32.45	32.45	Earthen Levee	Encroachments	WS	PO	Buildings	39.069257 ° -121.877278 °	39.069257 ° -121.877278 °		42
43	32.64	32.64	Earthen Levee	Encroachments	WS	PO	Abandoned vehicles	39.069860 ° -121.880545 °	39.069860 ° -121.880545 °		43
44	34.79	34.79	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	39.092297 ° -121.894930 °	39.092297 ° -121.894930 °		44
45	34.85	34.85	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	39.093155 ° -121.894928 °	39.093155 ° -121.894928 °		45
46	36.06	36.06	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	39.104502 ° -121.907095 °	39.104502 ° -121.907095 °		46
47	36.41	36.86	Earthen Levee	Crown Surface / Depressions / Rutting	CR	A	Keep the crown roadway free of vegetation.	39.109028 ° -121.909543 °	39.114543 ° -121.913895 °		47
48	36.72	36.72	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	39.112628 ° -121.912662 °	39.112628 ° -121.912662 °		48
49	42.66	42.66	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		49
50	43.34	43.63	Earthen Levee	Crown Surface / Depressions / Rutting	CR	A	Keep the crown roadway free of vegetation. Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		50
51	43.70	43.70	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		51
52	44.80	44.80	Earthen Levee	Encroachments	WS	PO	Prunings Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		52
53	46.35	46.35	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		53
54	47.48	47.48	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		54
55	48.65	48.65	Earthen Levee	Encroachments	LS	PO	Prunings Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		55
56	48.98	48.98	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		56

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Sacramento River West Side Levee District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River				Right	50.24	05/13/2008	John Williamson

  

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
57	49.91	49.91	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		57
58	49.96	49.96	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: no gps tracking	39.142295 ° -121.763328 °	39.142295 ° -121.763328 °		58

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---