

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

San Joaquin River Basin

NA0017	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
San Joaquin County Flood Control District	M *	104.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	2.52		2.52	2.41%		
Trim / Thin Trees	0.60		0.60	0.57%		
Encroachments	1.59	0.25	2.59	2.48%	4.37	0.62
Animal Control	0.29		0.29	0.28%		
Slope Stability	0.03		0.03	0.03%		
Erosion / Bank Caving	0.05		0.05	0.05%		
Crown Surface / Depressions / Rutting	0.81		0.81	0.78%		
Flap Gates		0.01	0.04	0.04%		
Boat Survey Erosion	0.06	0.81	3.30	3.16%		
<i>LMA Totals:</i>	5.95	1.07	10.23	9.79% *	4.37	0.62

Unit No. 01 Littlejohn Creek	Overall Unit Rating	Total Unit Miles				
	A	2.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Encroachments	0.01		0.01	0.35%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.35%	0.00	0.00

Unit No. 02 Littlejohn Creek	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
	M *	3.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.20		0.20	5.71%		
Animal Control	0.01		0.01	0.29%		
Erosion / Bank Caving	0.01		0.01	0.29%		
Flap Gates		0.01	0.04	1.14%		
<i>Unit Totals:</i>	0.22	0.01	0.26	7.43% *	0.00	0.00

Unit No. 06 SPRR Drain	Overall Unit Rating	Total Unit Miles				
	A	0.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 07 Bear Creek	Overall Unit Rating	Total Unit Miles				
	A	16.80				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.31		0.31	1.85%		
Trim / Thin Trees	0.01		0.01	0.06%		
Encroachments	0.20		0.20	1.19%	0.21	0.01
Slope Stability	0.02		0.02	0.12%		
Boat Survey Erosion	0.02		0.02	0.12%		
<i>Unit Totals:</i>	0.56	0.00	0.56	3.33%	0.21	0.01

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

San Joaquin River Basin (cont.)

Unit No. 08 Bear Creek	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
	M *	16.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.36		0.36	2.18%		
Trim / Thin Trees	0.20		0.20	1.21%		
Encroachments	0.16	0.08	0.48	2.91%	0.39	
Animal Control	0.18		0.18	1.09%		
Slope Stability	0.01		0.01	0.06%		
Crown Surface / Depressions / Rutting	0.11		0.11	0.67%		
Boat Survey Erosion	0.04		0.04	0.24%		
<i>Unit Totals:</i>	1.06	0.08	1.38	8.36% *	0.39	0.00

Unit No. 09 Paddy Creek	Overall Unit Rating	Total Unit Miles				
	A	1.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 10 Paddy Creek	Overall Unit Rating	Total Unit Miles				
	U	1.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.34		0.34	24.29%		
<i>Unit Totals:</i>	0.34	0.00	0.34	24.29%	0.00	0.00

Unit No. 11 North Paddy Creek	Overall Unit Rating	Total Unit Miles				
	A	3.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Encroachments	0.25		0.25	6.94%	0.32	
<i>Unit Totals:</i>	0.25	0.00	0.25	6.94%	0.32	0.00

Unit No. 12 North Paddy Creek	Overall Unit Rating	Total Unit Miles				
	M	3.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.47		0.47	12.05%		
<i>Unit Totals:</i>	0.47	0.00	0.47	12.05%	0.00	0.00

Unit No. 13 Middle Paddy Creek	Overall Unit Rating	Total Unit Miles				
	A	1.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

San Joaquin River Basin (cont.)

Unit No. 14 Middle Paddy Creek	Overall Unit Rating	Total Unit Miles				
	U	1.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Crown Surface / Depressions / Rutting	0.70		0.70	50.00%		
<i>Unit Totals:</i>	0.70	0.00	0.70	50.00%	0.00	0.00

Unit No. 15 Mormon Slough	Overall Unit Rating	Total Unit Miles				
	U	25.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.32		0.32	1.25%		
Trim / Thin Trees	0.39		0.39	1.52%		
Encroachments	0.58	0.17	1.26	4.92%	1.98	0.43
Animal Control	0.08		0.08	0.31%		
Erosion / Bank Caving	0.03		0.03	0.12%		
Boat Survey Erosion		0.81	3.24	12.66%		
<i>Unit Totals:</i>	1.40	0.98	5.32	20.78%	1.98	0.43

Unit No. 16 Mormon Slough	Overall Unit Rating	Total Unit Miles				
	A	23.70				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.52		0.52	2.19%		
Encroachments	0.38		0.38	1.60%	1.47	0.18
Animal Control	0.02		0.02	0.08%		
Erosion / Bank Caving	0.01		0.01	0.04%		
<i>Unit Totals:</i>	0.93	0.00	0.93	3.92%	1.47	0.18

Unit No. 17 Potter Creek	Overall Unit Rating	Total Unit Miles				
	A	0.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.01		0.01	1.11%		
<i>Unit Totals:</i>	0.01	0.00	0.01	1.11%	0.00	0.00

Unit No. 18 Potter Creek	Overall Unit Rating	Total Unit Miles				
	A	0.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Fall 2008 Levee Inspection Results**

San Joaquin County Flood Control District

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			M	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 01 Littlejohn Creek	Left	2.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008		11/7/2008	
DWR Inspector	Clay Thomas		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Littlejohn Creek			Left	2.90	11/07/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Vegetation		A	Inspector Comments: GPS local only	37.873793 °	37.873793 °	Y	1
								-121.226660 °	-121.226660 °		
2	0.30	0.30	Earthen Levee	Encroachments		M	Prunings	37.873874 °	37.873874 °	Y	2
								-121.233557 °	-121.233557 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Littlejohn Creek	Left	2.90	11/07/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Earthen Levee
Item	Vegetation
Example of good vegetation control along this unit.	



Levee Mile Report Line	2
Start Levee Mile	0.30
End Levee Mile	0.30
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings pile from within 10 feet of landside toe of levee at LM 0.30.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 02 Littlejohn Creek	Right	3.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008		11/7/2008	
DWR Inspector	Clay Thomas		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Littlejohn Creek	Right	3.50	11/07/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue	
	Start	End						Start	End			
1	0.00	0.00	Earthen Levee	Vegetation	CR	A	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: GPS local only.	37.875075 ° -121.219897 °			Y	1
2	1.20	1.20	Interior Drainage & Piping Systems	Flap Gates	WS	U	Inspector Comments: Unable to see flap gate, slide gate does nhot appear operational.	37.879379 ° -121.240164 °	37.879379 ° -121.240164 °		Y	2
3	1.90	1.90	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection. Inspector Comments: Erosion caused by farmer irrigation discharge.	37.882203 ° -121.249972 °	37.882203 ° -121.249972 °		Y	3
4	2.50	2.70	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	37.888830 ° -121.258192 °	37.889058 ° -121.259798 °		Y	5
5	2.60	2.60	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.888800 ° -121.258035 °	37.888800 ° -121.258035 °		Y	4

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Littlejohn Creek	Right	3.50	11/07/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Earthen Levee
Item	Vegetation
Example of good vegetation control on this unit.	



Levee Mile Report Line	2
Start Levee Mile	1.20
End Levee Mile	1.20
Location	
Category	Interior Drainage & Piping Systems
Item	Flap Gates
Unable to see waterside end of culvert at LM 1.20- Cannot confirm if it has a flapgate.	



Levee Mile Report Line	2
Start Levee Mile	1.20
End Levee Mile	1.20
Location	
Category	Interior Drainage & Piping Systems
Item	Flap Gates
Screwgate located at waterward shoulder at LM 1.20. Close gate to ensure that the culvert cannot carry drainage.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Littlejohn Creek	Right	3.50	11/07/2008	David Pesavento

Levee Mile Report Line	3
Start Levee Mile	1.90
End Levee Mile	1.90
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Repair & compact errosion caused by farmer on waterward slope at LM 1.90	



Levee Mile Report Line	3
Start Levee Mile	1.90
End Levee Mile	1.90
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Repair & compact errosion caused by farmer on waterward slope at LM 1.90.	



Levee Mile Report Line	4
Start Levee Mile	2.50
End Levee Mile	2.70
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow wild growth within 10 feet of landside toe from LM 2.50 to LM 2.70.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Littlejohn Creek	Right	3.50	11/07/2008	David Pesavento

Levee Mile Report Line	5
Start Levee Mile	2.60
End Levee Mile	2.60
Location	
Category	Earthen Levee
Item	Animal Control
Exterminate rodents and backfill/grout along waterward slope at LM 2.60.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 06 SPRR Drain	Left	0.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008		10/22/2008	
DWR Inspector	Clay Thomas		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 06 SPRR Drain			Left	0.50	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.14	0.14	Earthen Levee	Erosion / Bank Caving	WS	A	Note and monitor erosion site.	37.979185 ° -121.097563 °	37.979185 ° -121.097563 °		2

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 07 Bear Creek	Right	16.80

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/23/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek				Right	16.80	10/23/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.18	1.18	Earthen Levee	Encroachments	LS	PO	Tree or limb Inspector Comments: Fruit trees within 10' from toe	38.043332 ° -121.356323 °	38.043327 ° -121.356207 °		2
2	1.40	1.40	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.043249 ° -121.352352 °	38.043249 ° -121.352352 °	Y	22
3	1.45	1.45	Earthen Levee	Encroachments	LS	PO	Landscaping	38.043197 ° -121.351508 °	38.043190 ° -121.351393 °	Y	3
4	2.15	2.15	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.043243 ° -121.338958 °	38.043243 ° -121.338958 °	Y	23
5	2.28	2.28	Earthen Levee	Encroachments	LS	PO	Landscaping	38.043223 ° -121.336505 °	38.043223 ° -121.336505 °	Y	24
6	2.41	2.41	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.043204 ° -121.334254 °	38.043204 ° -121.334254 °		25
7	2.66	2.67	Earthen Levee	Encroachments	LS	CO	Fences	38.043182 ° -121.329790 °	38.043179 ° -121.329613 °	Y	26
8	5.57	5.57	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.052566 ° -121.282609 °	38.052566 ° -121.282609 °		27
9	7.50	7.61	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.064035 ° -121.254713 °	38.064893 ° -121.253196 °		28
10	8.87	8.87	Earthen Levee	Encroachments	LS	M	Prunings	38.068319 ° -121.231559 °	38.068319 ° -121.231559 °		29
11	8.99	8.99	Earthen Levee	Encroachments	LS	M	Prunings	38.068989 ° -121.229659 °	38.068989 ° -121.229659 °		30
12	9.18	9.18	Earthen Levee	Encroachments	LS	M	Prunings	38.070231 ° -121.226677 °	38.070231 ° -121.226677 °		31
13	9.91	9.91	Earthen Levee	Encroachments	LS	M	Prunings	38.073359 ° -121.215305 °	38.073359 ° -121.215305 °		9
14	9.95	9.95	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	38.073594 ° -121.214688 °	38.073594 ° -121.214688 °	Y	32
15	10.03	10.03	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	38.073917 ° -121.213257 °	38.073917 ° -121.213257 °		33
16	10.05	10.05	Earthen Levee	Encroachments	LS	M	Prunings	38.073972 ° -121.212985 °	38.073972 ° -121.212985 °		34
17	10.44	10.46	Earthen Levee	Encroachments	LS	PO	Landscaping	38.076352 ° -121.208700 °	38.076617 ° -121.208598 °	Y	35
18	10.95	10.96	Earthen Levee	Encroachments	LS	M	Debris	38.079807 ° -121.201170 °	38.079960 ° -121.201075 °	Y	14
19	12.65	12.74	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.093103 ° -121.177440 °	38.094166 ° -121.176840 °	Y	36

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek				Right	16.80	10/23/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	12.89	12.97	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.096326 ° -121.176625 °	38.097470 ° -121.176471 °		37
21	13.22	13.29	Earthen Levee	Encroachments	LS	M	Tree or limb	38.100882 ° -121.177485 °	38.101833 ° -121.177763 °		17
22	13.39	13.51	Earthen Levee	Encroachments	LS	PO	Crops	38.103297 ° -121.177588 °	38.104991 ° -121.177134 °	Y	38
23	13.58	13.60	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: Directly across Site 16	38.105895 ° -121.176424 °	° °		961
24	14.08	14.08	Earthen Levee	Encroachments	LS	M	Firewood	38.111902 ° -121.172685 °	38.111902 ° -121.172685 °	Y	39
25	14.09	14.13	Earthen Levee	Encroachments	LS	PO	Landscaping	38.112076 ° -121.172668 °	38.112631 ° -121.172596 °	Y	40
26	14.93	14.93	Earthen Levee	Encroachments	LS	M	Debris	38.123575 ° -121.169653 °	38.123575 ° -121.169653 °	Y	41
27	15.58	15.63	Earthen Levee	Encroachments	WS	M	Debris	38.128933 ° -121.160514 °	38.129459 ° -121.159899 °	Y	42

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek	Right	16.80	10/23/2008	David Pesavento

Levee Mile Report Line	2
Start Levee Mile	1.40
End Levee Mile	1.40
Location	
Category	Earthen Levee
Item	Vegetation
<p>Landscaping located within 10' from landside toe of levee at LM 1.40. Landscaping should be removed and controlled.</p>	



Levee Mile Report Line	3
Start Levee Mile	1.45
End Levee Mile	1.45
Location	
Category	Earthen Levee
Item	Encroachments
<p>Landscaping located within 10' from landside toe of levee at LM 1.45.</p>	



Levee Mile Report Line	4
Start Levee Mile	2.15
End Levee Mile	2.15
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
<p>Fruit trees planted within 10' from landside toe of levee at LM 2.15. Remove or prune to 5' from levee surface to allow for visibility and ability to flood fight.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek	Right	16.80	10/23/2008	David Pesavento

Levee Mile Report Line	5
Start Levee Mile	2.28
End Levee Mile	2.28
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping located within 10' of landside toe of levee at LM 2.28.	



Levee Mile Report Line	7
Start Levee Mile	2.66
End Levee Mile	2.67
Location	
Category	Earthen Levee
Item	Encroachments
Newer fence built within landside toe of levee at from LM 2.66 to LM 2.67.	



Levee Mile Report Line	14
Start Levee Mile	9.95
End Levee Mile	9.95
Location	
Category	Earthen Levee
Item	Slope Stability
Significant amount of landside levee slope removed and damaged by farm equipment at LM 9.95. Repair levee and attempt to prevent future damage.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek	Right	16.80	10/23/2008	David Pesavento

Levee Mile Report Line	17
Start Levee Mile	10.44
End Levee Mile	10.46
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping located within 10' from landside toe of levee from LM 10.44 to LM 10.46.	



Levee Mile Report Line	18
Start Levee Mile	10.95
End Levee Mile	10.96
Location	
Category	Earthen Levee
Item	Encroachments
Debris located along landside toe of levee from LM 10.95 to LM 10.96.	



Levee Mile Report Line	19
Start Levee Mile	12.65
End Levee Mile	12.74
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation along landside slope of levee to 10' from toe from LM 12.65 to 12.74.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek	Right	16.80	10/23/2008	David Pesavento

Levee Mile Report Line	22
Start Levee Mile	13.39
End Levee Mile	13.51
Location	
Category	Earthen Levee
Item	Encroachments
Grape vines within 10' from landside toe of levee from LM 13.39 to 13.51.	



Levee Mile Report Line	24
Start Levee Mile	14.08
End Levee Mile	14.08
Location	
Category	Earthen Levee
Item	Encroachments
Move firewood to outside of 10' from landside toe of levee at LM 14.08.	



Levee Mile Report Line	25
Start Levee Mile	14.09
End Levee Mile	14.13
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping on landside of levee from LM 14.09 to LM 14.13.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek	Right	16.80	10/23/2008	David Pesavento

Levee Mile Report Line	26
Start Levee Mile	14.93
End Levee Mile	14.93
Location	
Category	Earthen Levee
Item	Encroachments
Remove debris located on waterside of levee at LM 14.93.	



Levee Mile Report Line	27
Start Levee Mile	15.58
End Levee Mile	15.63
Location	
Category	Earthen Levee
Item	Encroachments
Debris located on waterside shoulder of access road next to golf course maintenance yard from LM 15.58 to 15.63. Debris should be moved to allow for patrolling next to channel and for visibility.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 08 Bear Creek	Left	16.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/16/2008		11/25/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek			Left	16.50	11/25/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.21	1.21	Earthen Levee	Encroachments	LS	M	Prunings	38.042964 ° -121.362157 °	38.042964 ° -121.362157 °	Y	19
2	1.27	1.27	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042932 ° -121.361084 °	38.042932 ° -121.361084 °	Y	20
3	1.34	1.34	Earthen Levee	Encroachments	LS	M	Prunings	38.042898 ° -121.359906 °	38.042898 ° -121.359906 °	Y	21
4	1.37	1.37	Earthen Levee	Encroachments	LS	M	Prunings	38.042880 ° -121.359389 °	38.042880 ° -121.359389 °	Y	22
5	1.48	1.48	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042842 ° -121.357402 °	38.042842 ° -121.357402 °	Y	23
6	1.67	1.67	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042774 ° -121.353840 °	38.042774 ° -121.353840 °	Y	24
7	1.71	1.71	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.042758 ° -121.353196 °	38.042758 ° -121.353196 °	Y	25
8	1.77	1.77	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042732 ° -121.352034 °	38.042732 ° -121.352034 °	Y	26
9	2.06	2.17	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042788 ° -121.347117 °	38.042767 ° -121.345148 °	Y	27
10	2.18	2.18	Earthen Levee	Encroachments	LS	M	Prunings	38.042767 ° -121.344936 °	38.042767 ° -121.344936 °	Y	28
11	2.20	2.20	Earthen Levee	Encroachments	LS	M	Prunings	38.042766 ° -121.344585 °	38.042766 ° -121.344585 °	Y	29
12	2.22	2.22	Earthen Levee	Encroachments	LS	M	Prunings	38.042758 ° -121.344109 °	38.042758 ° -121.344109 °	Y	30
13	2.27	2.27	Earthen Levee	Encroachments	LS	M	Prunings	38.042750 ° -121.343243 °	38.042750 ° -121.343243 °	Y	31
14	2.32	2.32	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.042751 ° -121.342273 °	38.042751 ° -121.342272 °	Y	32
15	2.32	2.35	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042750 ° -121.342272 °	38.042749 ° -121.341897 °	Y	33
16	2.37	2.37	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.042744 ° -121.341523 °	38.042744 ° -121.341523 °	Y	34
17	2.40	2.42	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.042740 ° -121.340838 °	38.042736 ° -121.340505 °	Y	35
18	2.40	2.42	Earthen Levee	Encroachments	WS	M	Prunings	38.042740 ° -121.340838 °	38.042737 ° -121.340506 °	Y	36
19	2.47	2.47	Earthen Levee	Encroachments	LS	M	Firewood	38.042729 ° -121.339659 °	38.042729 ° -121.339659 °	Y	37

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek				Left	16.50	11/25/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	2.48	2.48	Earthen Levee	Encroachments	LS	M	Prunings	38.042727 ° -121.339476 °	38.042727 ° -121.339476 °	Y	38
21	2.48	2.52	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042832 ° -121.339403 °	38.042805 ° -121.338695 °	Y	14
22	2.58	2.61	Earthen Levee	Encroachments	LS	PO	Fences	38.042718 ° -121.337506 °	38.042713 ° -121.337074 °	Y	39
23	2.62	2.63	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042762 ° -121.336925 °	38.042717 ° -121.336690 °	Y	13
24	2.67	2.71	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.042715 ° -121.336125 °	38.042701 ° -121.335392 °	Y	40
25	2.73	2.73	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042715 ° -121.335123 °	38.042715 ° -121.335123 °	Y	41
26	2.78	2.78	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042710 ° -121.334235 °	38.042710 ° -121.334235 °	Y	42
27	2.87	2.89	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042697 ° -121.332416 °	38.042694 ° -121.332199 °	Y	43
28	2.96	2.96	Earthen Levee	Encroachments	LS	M	Prunings	38.042689 ° -121.331021 °	38.042689 ° -121.331021 °	Y	44
29	3.00	3.00	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	38.042701 ° -121.330282 °	38.042701 ° -121.330282 °	Y	45
30	3.01	3.01	Earthen Levee	Encroachments	LS	M	Prunings	38.042689 ° -121.330133 °	38.042689 ° -121.330133 °	Y	46
31	3.12	3.12	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042658 ° -121.328104 °	38.042658 ° -121.328104 °	Y	47
32	3.18	3.18	Earthen Levee	Encroachments	LS	M	Firewood	38.042652 ° -121.326923 °	38.042652 ° -121.326923 °	Y	48
33	3.18	3.18	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042646 ° -121.326923 °	38.042646 ° -121.326923 °	Y	49
34	3.35	3.37	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.042653 ° -121.323728 °	38.042657 ° -121.323378 °	Y	50
35	4.09	4.09	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.042493 ° -121.310813 °	38.042493 ° -121.310813 °	Y	51
36	4.50	4.66	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.042434 ° -121.303504 °	38.042808 ° -121.300632 °	Y	52
37	7.28	7.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.057837 ° -121.261500 °	38.059753 ° -121.260282 °	Y	53
38	7.57	7.62	Earthen Levee	Encroachments	LS	PO	Landscaping	38.061125 ° -121.258760 °	38.061611 ° -121.258137 °	Y	54

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 08 Bear Creek				Left	16.50	11/25/2008	David Pesavento				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	9.52	9.52	Earthen Levee	Encroachments	LS	M	Prunings	38.069625 ° -121.226987 °	38.069625 ° -121.226987 °	Y	55
40	12.62	12.62	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.091417 ° -121.183735 °	38.091417 ° -121.183735 °	Y	56
41	13.51	13.59	Earthen Levee	Encroachments	LS	PO	Landscaping	38.100559 ° -121.176544 °	38.101535 ° -121.177154 °	Y	6
42	13.54	13.59	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.100930 ° -121.176942 °	38.101585 ° -121.177188 °	Y	5
43	14.50	14.54	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: Near agricultural inlet	38.113730 ° -121.172040 °	° °	Y	956
44	14.90	14.90	Earthen Levee	Encroachments	WS	M	Prunings	38.119066 ° -121.170735 °	38.119066 ° -121.170735 °	Y	57
45	15.00	15.08	Earthen Levee	Encroachments	WS	U	Prunings	38.120349 ° -121.169745 °	38.121368 ° -121.169199 °	Y	4
46	15.01	15.18	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.120385 ° -121.169760 °	38.122757 ° -121.169193 °	Y	1
47	15.14	15.15	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.122173 ° -121.169083 °	38.122293 ° -121.169075 °	Y	3
48	15.17	15.17	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.122682 ° -121.169116 °	38.122682 ° -121.169116 °	Y	58
49	15.64	15.74	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.126705 ° -121.163299 °	38.127221 ° -121.161765 °	Y	59

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	1.21
End Levee Mile	1.21
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings on landside of levee slope at LM 1.21	



Levee Mile Report Line	2
Start Levee Mile	1.27
End Levee Mile	1.27
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside toe of levee at LM 1.27	



Levee Mile Report Line	3
Start Levee Mile	1.34
End Levee Mile	1.34
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings along toe of landside of levee at LM 1.34	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	4
Start Levee Mile	1.37
End Levee Mile	1.37
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings along toe of landside of levee at LM 1.37	



Levee Mile Report Line	5
Start Levee Mile	1.48
End Levee Mile	1.48
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along toe of landside of levee at LM 1.48	



Levee Mile Report Line	6
Start Levee Mile	1.67
End Levee Mile	1.67
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along toe of landside of levee at LM 1.67	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	7
Start Levee Mile	1.71
End Levee Mile	1.71
Location	
Category	Earthen Levee
Item	Vegetation
Remove vegetation from landside of levee at LM 1.71	



Levee Mile Report Line	8
Start Levee Mile	1.77
End Levee Mile	1.77
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside toe of levee at LM 1.77	



Levee Mile Report Line	9
Start Levee Mile	2.06
End Levee Mile	2.17
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside of levee from LM 2.06 to LM 2.17	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	10
Start Levee Mile	2.18
End Levee Mile	2.18
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside toe of levee at LM 2.18	



Levee Mile Report Line	11
Start Levee Mile	2.20
End Levee Mile	2.20
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings and logs from landside of levee at LM 2.20	



Levee Mile Report Line	12
Start Levee Mile	2.22
End Levee Mile	2.22
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 2.22	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	13
Start Levee Mile	2.27
End Levee Mile	2.27
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 2.27	



Levee Mile Report Line	14
Start Levee Mile	2.32
End Levee Mile	2.32
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim/thin trees on landside of levee to allow for visibility at LM 2.32	



Levee Mile Report Line	15
Start Levee Mile	2.32
End Levee Mile	2.35
Location	
Category	Earthen Levee
Item	Encroachments
Garden located on landside slope of levee from LM 2.32 to LM 2.35	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	16
Start Levee Mile	2.37
End Levee Mile	2.37
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim and thin trees on landside slope of levee to provide visibility at LM 2.37	



Levee Mile Report Line	17
Start Levee Mile	2.40
End Levee Mile	2.42
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim/thin trees along landside of levee from LM 2.40 to LM 2.42	



Levee Mile Report Line	18
Start Levee Mile	2.40
End Levee Mile	2.42
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from waterside of levee from LM 2.40 to LM 2.42	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	19
Start Levee Mile	2.47
End Levee Mile	2.47
Location	
Category	Earthen Levee
Item	Encroachments
Remove firewood from landside of levee slope at LM 2.47	



Levee Mile Report Line	20
Start Levee Mile	2.48
End Levee Mile	2.48
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 2.48	



Levee Mile Report Line	21
Start Levee Mile	2.48
End Levee Mile	2.52
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees along landside of levee to allow for visibility from LM 2.48 to LM 2.52	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	22
Start Levee Mile	2.58
End Levee Mile	2.61
Location	
Category	Earthen Levee
Item	Encroachments
Fence located to sholder of landside of levee from LM 2.58 to LM 5.61	



Levee Mile Report Line	23
Start Levee Mile	2.62
End Levee Mile	2.63
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping on landside of levee slope from LM 2.62 to LM 2.63	



Levee Mile Report Line	24
Start Levee Mile	2.67
End Levee Mile	2.71
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees along landside of levee slope from LM 2.67 to LM 2.71	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	25
Start Levee Mile	2.73
End Levee Mile	2.73
Location	
Category	Earthen Levee
Item	Encroachments
Century plant located at landside toe of levee at LM 2.73	



Levee Mile Report Line	26
Start Levee Mile	2.78
End Levee Mile	2.78
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside toe of levee at LM 2.78	



Levee Mile Report Line	27
Start Levee Mile	2.87
End Levee Mile	2.89
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside toe of levee from LM 2.87 to LM 2.89	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	28
Start Levee Mile	2.96
End Levee Mile	2.96
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 2.96	



Levee Mile Report Line	29
Start Levee Mile	3.00
End Levee Mile	3.00
Location	
Category	Earthen Levee
Item	Slope Stability
Repair landside slope of levee where damaged by foot traffic at LM 3.00	



Levee Mile Report Line	30
Start Levee Mile	3.01
End Levee Mile	3.01
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 3.01	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	31
Start Levee Mile	3.12
End Levee Mile	3.12
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees along landside slope of levee to allow for visibility at LM 3.12	



Levee Mile Report Line	32
Start Levee Mile	3.18
End Levee Mile	3.18
Location	
Category	Earthen Levee
Item	Encroachments
Remove firewood from landside of levee at LM 3.18	



Levee Mile Report Line	33
Start Levee Mile	3.18
End Levee Mile	3.18
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees along landside toe of levee at LM 3.18	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	34
Start Levee Mile	3.35
End Levee Mile	3.37
Location	
Category	Earthen Levee
Item	Vegetation
Remove vegetation along landside toe of levee from LM 3.35 to LM 3.37	



Levee Mile Report Line	35
Start Levee Mile	4.09
End Levee Mile	4.09
Location	
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Regrade crown of levee to provide proper drainage at LM 4.09. Repair minor erosion at this location from concentrated runoff from the depression.	



Levee Mile Report Line	36
Start Levee Mile	4.50
End Levee Mile	4.66
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation within 10' of landside toe of levee from LM 4.50 to LM 4.66	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	37
Start Levee Mile	7.28
End Levee Mile	7.44
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation along landside of levee out to at least 10' from levee toe.	



Levee Mile Report Line	38
Start Levee Mile	7.57
End Levee Mile	7.62
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside slope of levee at from LM 7.57 to 7.62	



Levee Mile Report Line	39
Start Levee Mile	9.52
End Levee Mile	9.52
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from landside of levee at LM 9.52	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	40
Start Levee Mile	12.62
End Levee Mile	12.62
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation along landside of levee at LM 12.62	



Levee Mile Report Line	41
Start Levee Mile	13.51
End Levee Mile	13.59
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping along landside of levee from LM 13.51 to LM 13.59. Trim trees along landside of levee slope to allow for visibility from LM 13.54 to 13.59.	



Levee Mile Report Line	44
Start Levee Mile	14.90
End Levee Mile	14.90
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from waterside of levee at LM 14.90	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	45
Start Levee Mile	15.00
End Levee Mile	15.08
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings from waterside of levee from LM 15.00 to LM 15.08	



Levee Mile Report Line	46
Start Levee Mile	15.01
End Levee Mile	15.18
Location	
Category	Earthen Levee
Item	Animal Control
Example of rodent activity needing to be repaired along landside of levee from LM 15.01 to LM 15.18	



Levee Mile Report Line	47
Start Levee Mile	15.14
End Levee Mile	15.15
Location	
Category	Earthen Levee
Item	Animal Control
Example of rodent hole needing to be repaired along waterside of levee from LM 15.14 to LM 15.15	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Bear Creek	Left	16.50	11/25/2008	David Pesavento

Levee Mile Report Line	48
Start Levee Mile	15.17
End Levee Mile	15.17
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees to at least 5' from surface of levee to allow for visibility at LM 15.17	



Levee Mile Report Line	49
Start Levee Mile	15.64
End Levee Mile	15.74
Location	
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Regrade crown of levee to provide proper drainage and prevent ponding from LM 15.64 to LM 15.74	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 09 Paddy Creek		Left	1.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		11/25/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 09 Paddy Creek			Left	1.50	11/25/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								o	o		
								o	o		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 10 Paddy Creek	Right	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/24/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 10 Paddy Creek			Right	1.40	10/24/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.53	0.66	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.095278 ° -121.166519 °	38.094692 ° -121.164345 °		4
2	0.70	0.76	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.094537 ° -121.163707 °	38.094539 ° -121.162617 °		3
3	1.11	1.26	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.094680 ° -121.156136 °	38.094344 ° -121.153539 °	Y	2

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 10 Paddy Creek	Right	1.40	10/24/2008	David Pesavento

Levee Mile Report Line	3
Start Levee Mile	1.11
End Levee Mile	1.26
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation on landside slope to allow for visibility and ability to flood fight from LM 1.11 to 1.26.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 11 North Paddy Creek	Right	3.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/24/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 11 North Paddy Creek			Right	3.60	10/24/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.17	0.41	Earthen Levee	Encroachments	LS	M	Crops Inspector Comments: Newly planted trees within 10' from landside toe	38.097342 °	38.100685 °		3
								-121.169262 °	-121.169112 °		
2	0.17	0.49	Earthen Levee	Encroachments	LS	PO	Fences	38.097243 °	38.101853 °	Y	2
								-121.169258 °	-121.168563 °		
3	3.15	3.15	Earthen Levee	Encroachments	WS	M	Debris	38.127167 °	38.127167 °		8
								-121.142205 °	-121.142205 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 11 North Paddy Creek	Right	3.60	10/24/2008	David Pesavento

Levee Mile Report Line	2
Start Levee Mile	0.17
End Levee Mile	0.49
Location	
Category	Earthen Levee
Item	Encroachments
Fence located from LM 0.17 to LM 0.49 and crops located from LM 0.17 to LM 0.41 within 10' from landside toe of levee.	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 12 North Paddy Creek	Left	3.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/24/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 12 North Paddy Creek				Left	3.90	10/24/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.01	1.05	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.108667 ° -121.165703 °	38.109056 ° -121.165291 °	Y	4
2	1.03	1.07	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.108938 ° -121.165476 °	38.109184 ° -121.164961 °		5
3	3.53	3.92	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes.	38.131755 ° -121.138425 °	38.131756 ° -121.138425 °	Y	6

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 12 North Paddy Creek	Left	3.90	10/24/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	1.01
End Levee Mile	1.05
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation on waterside of levee to 20' from shoulder from LM 1.01 to LM 1.05.	



Levee Mile Report Line	3
Start Levee Mile	3.53
End Levee Mile	3.92
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation from access road to allow for access to upper portion of unit from LM 3.53 to LM 3.92.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 13 Middle Paddy Creek		Left	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/24/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 13 Middle Paddy Creek				Left	1.40	10/24/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								o	o		
								o	o		

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 14 Middle Paddy Creek	Right	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008		10/24/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 14 Middle Paddy Creek			Right	1.40	10/24/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.62	1.32	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.111753 ° -121.150038 °	38.110943 ° -121.140063 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 15 Mormon Slough		Right	25.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/28/2008		10/21/2008	
DWR Inspector	Clay Thomas		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough				Right	25.60	10/21/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.75	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: Lots of rodent holes; stakes are placed to track erosion; wide levee crown	38.049410 °	-121.015130 °		952
2	1.55	1.61	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: Near weir, no berm downstream; 10 ft wide berm upstream of site	38.040170 °	-121.033800 °		953
3	2.41	2.41	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.032993 °	-121.045130 °	Y	63
4	2.41	2.41	Earthen Levee	Encroachments	LS	M	Prunings	38.032994 °	-121.045130 °		62
5	2.54	2.54	Earthen Levee	Encroachments	LS	PO	Equipment	38.031739 °	-121.046711 °		64
6	2.68	2.68	Earthen Levee	Encroachments	LS	M	Prunings	38.030223 °	-121.048407 °	Y	2
7	2.68	2.71	Earthen Levee	Encroachments	LS	PO	Buildings Inspector Comments: retaining wall at toe of slope & irrigation recently placed	38.030173 °	-121.048432 °	Y	66
8	2.73	2.73	Earthen Levee	Encroachments	LS	PO	Landscaping	38.030185 °	-121.049397 °		3
9	2.73	2.73	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.029727 °	-121.049051 °		67
10	2.88	2.88	Earthen Levee	Encroachments	LS	M	Prunings	38.028572 °	-121.051137 °		4
11	2.99	2.99	Earthen Levee	Encroachments	LS	M	Prunings	38.027547 °	-121.052728 °		5
12	3.04	3.04	Earthen Levee	Encroachments	LS	M	Prunings	38.027270 °	-121.053565 °		6
13	3.11	3.11	Earthen Levee	Encroachments	LS	M	Prunings	38.026527 °	-121.054547 °		7
14	3.19	3.19	Earthen Levee	Encroachments	LS	M	Prunings	38.025712 °	-121.055480 °		8
15	3.26	3.26	Earthen Levee	Encroachments	LS	M	Prunings	38.025053 °	-121.056457 °		9
16	3.30	3.30	Earthen Levee	Encroachments	LS	M	Prunings	38.024735 °	-121.056947 °		10
17	3.34	3.34	Earthen Levee	Encroachments	LS	M	Prunings	38.024362 °	-121.057635 °		11
18	3.40	3.40	Earthen Levee	Encroachments	LS	M	Prunings	38.023913 °	-121.058410 °		12

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough				Right	25.60	10/21/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
19	3.61	3.61	Earthen Levee	Encroachments	LS	M	Prunings	38.021818 ° -121.061112 °	38.021818 ° -121.061112 °		13
20	3.92	3.92	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: pipes & trash on labdside levee	38.018513 ° -121.064775 °	38.018513 ° -121.064775 °		15
21	3.97	3.97	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.017897 ° -121.065348 °	38.017897 ° -121.065348 °		68
22	4.05	4.07	Earthen Levee	Animal Control	WS	A	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Rodent holes grouted	38.017077 ° -121.066214 °	38.016870 ° -121.066440 °	Y	69
23	4.10	4.10	Earthen Levee	Encroachments	LS	M	Prunings	38.016536 ° -121.066775 °	38.016536 ° -121.066775 °		70
24	4.14	4.14	Earthen Levee	Encroachments	LS	PO	Landscaping	38.016115 ° -121.067187 °	38.016115 ° -121.067187 °		16
25	4.22	4.22	Earthen Levee	Encroachments	LS	M	Material	38.014948 ° -121.067553 °	38.014948 ° -121.067553 °		17
26	4.27	4.27	Earthen Levee	Encroachments	LS	M	Prunings	38.014370 ° -121.067759 °	38.014370 ° -121.067759 °		71
27	4.29	4.29	Earthen Levee	Encroachments	LS	M	Prunings	38.014025 ° -121.067983 °	38.014025 ° -121.067983 °	Y	19
28	4.59	4.59	Earthen Levee	Encroachments	LS	M	Prunings	38.010054 ° -121.069471 °	38.010054 ° -121.069471 °		72
29	4.72	4.72	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.008289 ° -121.070059 °	38.008289 ° -121.070059 °		73
30	4.96	4.96	Earthen Levee	Encroachments	LS	M	Equipment	38.005302 ° -121.071867 °	38.005302 ° -121.071867 °		20
31	4.96	4.96	Earthen Levee	Encroachments	WS	M	Equipment	38.005300 ° -121.071863 °	38.005300 ° -121.071863 °		21
32	5.11	5.11	Earthen Levee	Encroachments	WS	M	Prunings	38.003357 ° -121.073378 °	38.003357 ° -121.073378 °		74
33	5.27	5.27	Earthen Levee	Encroachments	WS	M	Debris	38.001543 ° -121.075012 °	38.001543 ° -121.075012 °		22
34	5.31	5.31	Earthen Levee	Encroachments	WS	M	Prunings	38.001152 ° -121.075354 °	38.001152 ° -121.075354 °		75
35	5.34	5.34	Earthen Levee	Encroachments	WS	M	Prunings	38.000793 ° -121.075643 °	38.000793 ° -121.075643 °		23
36	5.36	5.36	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.000568 ° -121.075891 °	38.000568 ° -121.075891 °		76
37	5.38	5.45	Earthen Levee	Encroachments	LS	CO	Buildings	38.000308 ° -121.076133 °	37.999502 ° -121.076835 °	Y	24

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 15 Mormon Slough				Right	25.60	10/21/2008	David Pesavento				
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
38	5.77	5.91	Earthen Levee	Encroachments	WS	U	Debris	37.995733 ° -121.080102 °	37.994185 ° -121.081587 °		25
39	6.03	6.03	Earthen Levee	Encroachments	WS	M	Debris	37.992920 ° -121.082949 °	37.992920 ° -121.082949 °		77
40	6.37	6.37	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.988920 ° -121.086368 °	37.988920 ° -121.086368 °	Y	27
41	6.38	6.43	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.988817 ° -121.086478 °	37.988274 ° -121.086999 °	Y	78
42	6.61	6.61	Earthen Levee	Encroachments	LS	M	Prunings	37.986128 ° -121.088882 °	37.986128 ° -121.088882 °		29
43	6.90	6.90	Earthen Levee	Erosion / Bank Caving	LS	M	Note and monitor erosion site. Inspector Comments: Farmer tilling & driving onto levee, causing erosion	37.983156 ° -121.092199 °	37.983156 ° -121.092199 °	Y	79
44	6.92	7.06	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.982961 ° -121.092519 °	37.981745 ° -121.094580 °		80
45	7.45	7.55	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.978855 ° -121.100406 °	37.978464 ° -121.102124 °		81
46	7.60	7.60	Earthen Levee	Encroachments	WS	M	Debris	37.978238 ° -121.102960 °	37.978238 ° -121.102960 °		31
47	7.69	7.90	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.977442 ° -121.104267 °	37.975731 ° -121.107247 °		82
48	7.90	7.90	Earthen Levee	Encroachments	WS	M	Debris	37.975723 ° -121.107205 °	37.975723 ° -121.107205 °		32
49	8.05	8.05	Earthen Levee	Encroachments	WS	M	Debris	37.974337 ° -121.109453 °	37.974337 ° -121.109453 °		33
50	8.26	8.26	Earthen Levee	Encroachments	LS	M	Debris	37.972738 ° -121.112553 °	37.972738 ° -121.112553 °		34
51	8.58	8.58	Earthen Levee	Encroachments	LS	M	Prunings	37.969813 ° -121.116218 °	37.969813 ° -121.116218 °		36
52	8.68	8.70	Earthen Levee	Encroachments	LS	U	Equipment	37.969550 ° -121.117927 °	37.969391 ° -121.118277 °	Y	37
53	8.72	8.72	Earthen Levee	Encroachments	LS	CO	Buildings	37.969305 ° -121.118664 °	37.969305 ° -121.118664 °	Y	83
54	8.80	8.80	Earthen Levee	Encroachments	LS	M	Equipment	37.969133 ° -121.119957 °	37.969133 ° -121.119957 °		38
55	8.84	8.84	Earthen Levee	Encroachments	LS	M	Garbage	37.968730 ° -121.120660 °	37.968730 ° -121.120660 °		39
56	8.94	8.98	Earthen Levee	Encroachments	WS	M	Prunings	37.968565 ° -121.122254 °	37.968360 ° -121.122937 °		84

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
57	9.03	9.13	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	37.967905 ° -121.123797 °	37.967043 ° -121.125132 °	Y	85
58	9.63	9.63	Earthen Levee	Encroachments	WS	U	Buildings	37.967017 ° -121.133863 °	37.967017 ° -121.133863 °	Y	40
59	9.69	9.74	Earthen Levee	Encroachments	WS	M	Prunings	37.966662 ° -121.134905 °	37.966385 ° -121.135801 °		41
60	9.80	9.80	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.965997 ° -121.136616 °	37.965997 ° -121.136616 °	Y	86
61	10.35	10.35	Earthen Levee	Encroachments	LS	M	Prunings	37.965055 ° -121.146293 °	37.965055 ° -121.146293 °		87
62	10.61	10.68	Earthen Levee	Encroachments	WS	M	Prunings	37.964942 ° -121.150981 °	37.964792 ° -121.152154 °		88
63	10.76	10.76	Earthen Levee	Encroachments	LS	M	Prunings	37.964580 ° -121.153504 °	37.964580 ° -121.153504 °		89
64	11.05	11.05	Earthen Levee	Encroachments	LS	M	Debris	37.962858 ° -121.158358 °	37.962858 ° -121.158358 °		43
65	11.10	11.10	Earthen Levee	Encroachments	WS	M	Prunings	37.962556 ° -121.159035 °	37.962556 ° -121.159035 °		42
66	11.12	11.12	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.962299 ° -121.159348 °	37.962299 ° -121.159348 °		90
67	11.57	11.57	Earthen Levee	Encroachments	LS	M	Equipment	37.960826 ° -121.166873 °	37.960826 ° -121.166873 °		91
68	12.09	12.09	Earthen Levee	Encroachments	LS	M	Prunings	37.961838 ° -121.176018 °	37.961838 ° -121.176018 °		44
69	12.21	12.21	Earthen Levee	Encroachments	LS	M	Prunings	37.961945 ° -121.178268 °	37.961945 ° -121.178268 °		45
70	12.82	12.82	Earthen Levee	Encroachments	WS	M	Prunings	37.961012 ° -121.189067 °	37.961012 ° -121.189067 °		46
71	13.30	13.30	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.961264 ° -121.197068 °	37.961264 ° -121.197068 °		92
72	13.54	13.54	Earthen Levee	Encroachments	LS	M	Equipment	37.960547 ° -121.201300 °	37.960547 ° -121.201300 °		47
73	15.71	15.71	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.975922 ° -121.234967 °	37.975922 ° -121.234967 °		93
74	17.79	18.05	Earthen Levee	Encroachments	LS	PO	Fences	37.990067 ° -121.267757 °	37.991645 ° -121.271827 °		48
75	17.83	18.04	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.990052 ° -121.268448 °	37.991428 ° -121.271701 °	Y	94

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 15 Mormon Slough				Right	25.60	10/21/2008	David Pesavento				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
76	19.71	19.71	Earthen Levee	Encroachments	LS	PO	Landscaping	37.995272 ° -121.277625 °	37.995272 ° -121.277625 °		50
77	19.80	19.89	Earthen Levee	Encroachments	LS	CO	Landscaping	37.994785 ° -121.279202 °	37.994752 ° -121.280733 °		51
78	20.80	20.91	Earthen Levee	Encroachments	LS	CO	Fences	37.992300 ° -121.296665 °	37.992008 ° -121.298688 °		52
79	20.91	21.01	Earthen Levee	Encroachments	LS	CO	Buildings	37.992015 ° -121.298692 °	37.992103 ° -121.300505 °		53
80	21.05	21.10	Earthen Levee	Encroachments	LS	CO	Fences	37.992163 ° -121.301308 °	37.992170 ° -121.302212 °		55
81	21.56	21.75	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987718 ° -121.307630 °	37.985305 ° -121.309322 °		56
82	22.27	22.32	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980533 ° -121.316473 °	37.980285 ° -121.317410 °		57
83	22.36	22.37	Earthen Levee	Encroachments	LS	PO	Fences	37.979996 ° -121.318045 °	37.979969 ° -121.318236 °	Y	95
84	24.22	25.62	Earthen Levee	Encroachments	LS	PO	Landscaping	37.974485 ° -121.347958 °	37.975337 ° -121.372153 °		58

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	3
Start Levee Mile	2.41
End Levee Mile	2.41
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees to provide visibility of landside of levee at LM 2.41.	



Levee Mile Report Line	6
Start Levee Mile	2.68
End Levee Mile	2.68
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings pile from landside of levee at LM 2.68.	



Levee Mile Report Line	7
Start Levee Mile	2.68
End Levee Mile	2.71
Location	
Category	Earthen Levee
Item	Encroachments
Recently built retaining wall at toe of landside levee at LM 2.68.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	22
Start Levee Mile	4.05
End Levee Mile	4.07
Location	
Category	Earthen Levee
Item	Animal Control
Good example of grouting rodent holes	



Levee Mile Report Line	27
Start Levee Mile	4.29
End Levee Mile	4.29
Location	
Category	Earthen Levee
Item	Encroachments
Example of a prunings pile immediately adjacent to access road at LM 4.29. Evidence of habitual burnings at this site.	



Levee Mile Report Line	37
Start Levee Mile	5.38
End Levee Mile	5.45
Location	
Category	Earthen Levee
Item	Encroachments
Building located immediately adjacent to access road approximately from LM 5.38 to 5.45	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	40
Start Levee Mile	6.37
End Levee Mile	6.37
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
<p>Minor erosion occurring locate at LM 6.37. Evidence present that is facilitated by rodent holes in the area. This site should be monitored and repaired</p>	



Levee Mile Report Line	40
Start Levee Mile	6.37
End Levee Mile	6.37
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
<p>Additional view of erosion facilitated by rodent holes located at LM 6.37.</p>	



Levee Mile Report Line	41
Start Levee Mile	6.38
End Levee Mile	6.43
Location	
Category	Earthen Levee
Item	Animal Control
<p>Rodent holes located from LM 6.38 to 6.43. Backfill and compact or grout the hole.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	43
Start Levee Mile	6.90
End Levee Mile	6.90
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
<p>Farming equipment grading into the landside toe of the levee located at LM 6.90. Backfill and compact to design shape and attempt to prevent future damage.</p>	



Levee Mile Report Line	52
Start Levee Mile	8.68
End Levee Mile	8.70
Location	
Category	Earthen Levee
Item	Encroachments
<p>Remove equipment from landside slope of levee at from LM 8.68 to LM 8.70.</p>	



Levee Mile Report Line	53
Start Levee Mile	8.72
End Levee Mile	8.72
Location	
Category	Earthen Levee
Item	Encroachments
<p>Building, fence and landscaping immediately adjacent to the access road at LM 8.72.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	57
Start Levee Mile	9.03
End Levee Mile	9.13
Location	
Category	Earthen Levee
Item	Vegetation
<p>Good control of vegetation on waterside of levee. Proper visibility maintained within 20' of waterside shoulder from LM 9.03 to LM 9.13.</p>	



Levee Mile Report Line	58
Start Levee Mile	9.63
End Levee Mile	9.63
Location	
Category	Earthen Levee
Item	Encroachments
<p>Building located at LM 9.63 on waterside of access road. This building appears to be recently constructed and does not currently contain anything.</p>	



Levee Mile Report Line	58
Start Levee Mile	9.63
End Levee Mile	9.63
Location	
Category	Earthen Levee
Item	Encroachments
<p>Additional view of building at LM 9.63.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 15 Mormon Slough	Right	25.60	10/21/2008	David Pesavento

Levee Mile Report Line	60
Start Levee Mile	9.80
End Levee Mile	9.80
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
<p>Minor erosion occurring at LM 9.80. This erosion appears to be active as evidenced by cracking. Monitor and repair to prevent larger erosion.</p>	



Levee Mile Report Line	75
Start Levee Mile	17.83
End Levee Mile	18.04
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
<p>Trim trees from LM 17.83 to LM 18.04 to at least 5 feet from levee surface to allow visibility and ability to conduct flood fight.</p>	



Levee Mile Report Line	83
Start Levee Mile	22.36
End Levee Mile	22.37
Location	
Category	Earthen Levee
Item	Encroachments
<p>Fence located from LM 22.36 to LM 22.37 significantly encroaches onto landside levee slope.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 16 Mormon Slough		Left	23.70

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/3/2008		10/22/2008	
DWR Inspector	Clay Thomas		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough				Left	23.70	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.32	0.32	Earthen Levee	Encroachments	CR	M	Prunings	38.048055 ° -121.016667 °	38.048055 ° -121.016667 °	Y	50
2	1.48	1.48	Earthen Levee	Encroachments	WS	M	Debris	38.039640 ° -121.033262 °	38.039640 ° -121.033262 °		51
3	2.07	2.07	Earthen Levee	Encroachments	WS	M	Debris	38.034930 ° -121.041238 °	38.034930 ° -121.041238 °		49
4	3.35	3.35	Earthen Levee	Encroachments	WS	M	Prunings	38.023257 ° -121.058158 °	38.023257 ° -121.058158 °		52
5	3.52	3.52	Earthen Levee	Encroachments	WS	M	Prunings	38.021650 ° -121.060312 °	38.021650 ° -121.060312 °		53
6	3.78	3.78	Earthen Levee	Encroachments	WS	M	Prunings	38.018975 ° -121.063469 °	38.018975 ° -121.063469 °		54
7	5.55	5.84	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.997402 ° -121.077988 °	37.994141 ° -121.080976 °	Y	55
8	5.83	5.83	Earthen Levee	Encroachments	WS	M	Debris	37.994268 ° -121.080850 °	37.994268 ° -121.080850 °		56
9	5.89	5.94	Earthen Levee	Encroachments	WS	M	Equipment	37.993593 ° -121.081493 °	37.993030 ° -121.082014 °		57
10	5.95	5.95	Earthen Levee	Encroachments	WS	M	Firewood	37.992846 ° -121.082221 °	37.992846 ° -121.082221 °	Y	58
11	6.32	6.32	Earthen Levee	Encroachments	WS	M	Prunings	37.988708 ° -121.085845 °	37.988708 ° -121.085845 °		59
12	6.36	6.36	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.988240 ° -121.086358 °	37.988240 ° -121.086358 °		47
13	7.30	7.30	Earthen Levee	Encroachments	WS	M	Prunings	37.979522 ° -121.098305 °	37.979522 ° -121.098305 °		60
14	7.37	7.37	Earthen Levee	Encroachments	WS	M	Debris	37.978850 ° -121.099325 °	37.978850 ° -121.099325 °		61
15	8.60	8.65	Earthen Levee	Encroachments	WS	M	Prunings	37.969108 ° -121.117254 °	37.969107 ° -121.117261 °		62
16	8.93	8.93	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.968148 ° -121.121846 °	37.968148 ° -121.121846 °		63
17	9.64	9.64	Earthen Levee	Encroachments	WS	M	Prunings	37.966512 ° -121.133739 °	37.966512 ° -121.133739 °		64
18	11.04	11.04	Earthen Levee	Encroachments	CR	M	Debris	37.962841 ° -121.157669 °	37.962841 ° -121.157669 °		65
19	11.20	11.20	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.961511 ° -121.159973 °	37.961511 ° -121.159973 °		66

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough				Left	23.70	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	13.46	13.61	Earthen Levee	Encroachments	LS	M	Prunings	37.960399 ° -121.199377 °	37.959543 ° -121.201851 °		67
21	16.38	16.41	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	37.979260 ° -121.245131 °	37.979550 ° -121.245595 °	Y	68
22	16.46	16.65	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	37.979877 ° -121.246258 °	37.981158 ° -121.249358 °		69
23	17.44	17.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	37.986540 ° -121.261922 °	37.986540 ° -121.261922 °		70
24	19.64	19.64	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991060 ° -121.298593 °	37.991060 ° -121.298593 °		42
25	19.75	19.75	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991008 ° -121.300550 °	37.991008 ° -121.300550 °		41
26	19.76	19.76	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991000 ° -121.300860 °	37.991000 ° -121.300860 °		40
27	19.79	19.79	Earthen Levee	Encroachments	LS	CO	Landscaping	37.991067 ° -121.301430 °	37.991067 ° -121.301430 °		39
28	19.90	19.90	Earthen Levee	Encroachments	LS	PO	Landscaping	37.990975 ° -121.303375 °	37.990975 ° -121.303375 °		38
29	20.02	20.02	Earthen Levee	Encroachments	LS	CO	Fences	37.989660 ° -121.304837 °	37.989660 ° -121.304837 °		37
30	20.05	20.05	Earthen Levee	Encroachments	LS	CO	Fences	37.989382 ° -121.305158 °	37.989382 ° -121.305158 °		36
31	20.08	20.08	Earthen Levee	Encroachments	LS	PO	Landscaping	37.989032 ° -121.305465 °	37.989032 ° -121.305465 °		35
32	20.09	20.09	Earthen Levee	Encroachments	LS	CO	Landscaping	37.988942 ° -121.305548 °	37.988942 ° -121.305548 °		34
33	20.11	20.11	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988632 ° -121.305733 °	37.988632 ° -121.305733 °		33
34	20.15	20.15	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988215 ° -121.305940 °	37.988215 ° -121.305940 °		32
35	20.16	20.16	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988035 ° -121.306035 °	37.988035 ° -121.306035 °		31
36	20.17	20.17	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987907 ° -121.306102 °	37.987907 ° -121.306102 °		30
37	20.18	20.18	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987723 ° -121.306157 °	37.987723 ° -121.306157 °		29
38	20.19	20.19	Earthen Levee	Encroachments	LS	CO	Landscaping	37.987622 ° -121.306230 °	37.987622 ° -121.306230 °		28

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough				Left	23.70	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	20.23	20.23	Earthen Levee	Encroachments	LS CO	Fences		37.987093 ° -121.306495 °	37.987093 ° -121.306495 °		27
40	20.25	20.25	Earthen Levee	Encroachments	LS CO	Fences		37.986857 ° -121.306602 °	37.986857 ° -121.306602 °		26
41	21.17	21.17	Earthen Levee	Encroachments	LS CO	Fences		37.978855 ° -121.319108 °	37.978855 ° -121.319108 °		25
42	21.18	21.18	Earthen Levee	Encroachments	LS CO	Fences		37.978958 ° -121.319258 °	37.978958 ° -121.319258 °		24
43	21.20	21.20	Earthen Levee	Encroachments	LS CO	Fences		37.979107 ° -121.319415 °	37.979107 ° -121.319415 °		23
44	21.58	21.58	Earthen Levee	Encroachments	WS PO	Landscaping		37.980918 ° -121.325630 °	37.980918 ° -121.325630 °		22
45	21.64	21.64	Earthen Levee	Encroachments	LS CO	Landscaping		37.981132 ° -121.326753 °	37.981132 ° -121.326753 °		21
46	21.71	21.71	Earthen Levee	Encroachments	LS CO	Landscaping		37.981185 ° -121.327822 °	37.981185 ° -121.327822 °		20
47	21.73	21.73	Earthen Levee	Encroachments	LS PO	Landscaping		37.980972 ° -121.328217 °	37.980972 ° -121.328217 °		19
48	21.74	21.74	Earthen Levee	Encroachments	LS PO	Landscaping		37.980932 ° -121.328380 °	37.980932 ° -121.328380 °		18
49	21.85	21.85	Earthen Levee	Encroachments	LS PO	Landscaping		37.980288 ° -121.330173 °	37.980288 ° -121.330173 °		17
50	21.88	21.88	Earthen Levee	Encroachments	LS PO	Landscaping		37.980178 ° -121.330588 °	37.980178 ° -121.330588 °		16
51	21.90	21.90	Earthen Levee	Encroachments	WS PO	Landscaping		37.980042 ° -121.330953 °	37.980042 ° -121.330953 °		15
52	21.90	21.90	Earthen Levee	Encroachments	LS CO	Fences		37.980040 ° -121.330955 °	37.980040 ° -121.330955 °		14
53	21.92	21.92	Earthen Levee	Encroachments	LS CO	Landscaping		37.979905 ° -121.331390 °	37.979905 ° -121.331390 °		12
54	21.92	21.92	Earthen Levee	Encroachments	WS CO	Landscaping		37.979908 ° -121.331383 °	37.979908 ° -121.331383 °		13
55	21.97	21.97	Earthen Levee	Encroachments	LS PO	Landscaping		37.979652 ° -121.332265 °	37.979652 ° -121.332265 °		11
56	22.01	22.01	Earthen Levee	Encroachments	LS CO	Landscaping		37.979715 ° -121.332972 °	37.979715 ° -121.332972 °		10
57	22.05	22.05	Earthen Levee	Encroachments	LS PO	Landscaping		37.979780 ° -121.333647 °	37.979780 ° -121.333647 °		9

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough				Left	23.70	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	22.08	22.08	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979820 ° -121.334107 °	37.979820 ° -121.334107 °		8
59	22.13	22.13	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979717 ° -121.335107 °	37.979717 ° -121.335107 °		7
60	22.15	22.15	Earthen Levee	Encroachments	LS	PO	Fences	37.979598 ° -121.335428 °	37.979598 ° -121.335428 °		6
61	22.16	22.16	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979528 ° -121.335620 °	37.979528 ° -121.335620 °		5
62	22.18	22.20	Earthen Levee	Encroachments	LS	CO	Fences	37.979420 ° -121.335815 °	37.979360 ° -121.336188 °		4
63	22.20	22.33	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979367 ° -121.336195 °	37.979368 ° -121.338632 °		3
64	22.57	23.05	Earthen Levee	Encroachments	LS	PO	Urban	37.978012 ° -121.342420 °	37.973158 ° -121.348577 °		2
65	23.06	23.70	Earthen Levee	Encroachments	WS	PO	Urban	37.973135 ° -121.348730 °	37.970950 ° -121.351928 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough	Left	23.70	10/22/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.32
End Levee Mile	0.32
Location	
Category	Earthen Levee
Item	Encroachments
<p>Prunings pile located at LM 0.32 on waterside shoulder of access road. The pile impedes access and forces vehicles to drive through orchard.</p>	



Levee Mile Report Line	7
Start Levee Mile	5.55
End Levee Mile	5.84
Location	
Category	Earthen Levee
Item	Vegetation
<p>Remove/mow vegetation 20' from waterside shoulder to allow visibility of waterside slope from LM 5.55 to LM 5.84.</p>	



Levee Mile Report Line	10
Start Levee Mile	5.95
End Levee Mile	5.95
Location	
Category	Earthen Levee
Item	Encroachments
<p>Firewood piles located on waterside of shoulder at LM 5.95. These piles should be moved away from landside of access road.</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 16 Mormon Slough	Left	23.70	10/22/2008	David Pesavento

Levee Mile Report Line	21
Start Levee Mile	16.38
End Levee Mile	16.41
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation to 10' from landside toe to maintain visibility from LM 16.38 to LM 16.41 and LM 16.46 to LM 16.65.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 17 Potter Creek	Right	0.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/12/2008		10/22/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 17 Potter Creek			Right	0.90	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.50	0.50	Earthen Levee	Encroachments		M	Prunings	37.958565 ° -121.154819 °	37.958565 ° -121.154819 °		1

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 18 Potter Creek	Left	0.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/12/2008		10/22/2008	
DWR Inspector	Herman Phillips		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 18 Potter Creek			Left	0.90	10/22/2008	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.10	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	37.958490 °	37.958490 °	Y	1
								-121.151937 °	-121.151937 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 18 Potter Creek	Left	0.90	10/22/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.10
Location	
Category	Earthen Levee
Item	Vegetation
Good vegetation maintenance on Unit 18 of Potter Creek.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---