

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2014 Levee Inspection Results**

**California Department of Fish and Game Shea Levee**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2014 Levee Inspection Results**

**California Department of Fish and Game Shea Levee**

Waterway		Bank	Unit Miles	
Unit No. 01 Sacramento River		Left	0.30	
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	03/27/2014 - 03/27/2014			
DWR Inspector	Bob Duffey			
Accompanied By	Michael Harris Department of Fish and Game			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**California Department of Fish and Game Shea Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	03/27/2014 03/27/2014	Bob Duffey

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
				°	°
DWR ID	DWR_NA0018_01_s_2013_7				
Action/Comments					

No Photos

LM Start		Rating **	M	Issue No.	8
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
				°	°
DWR ID	DWR_NA0018_01_s_2012_8				
Action/Comments					
Inspector Comments: LMA has not completed any training and does not have an available flood plan.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
				°	°
DWR ID	DWR_NA0018_01_s_2013_10				
Action/Comments					

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**California Department of Fish and Game Shea Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	03/27/2014 03/27/2014	Bob Duffey

LM Start	<b>0.00</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>0.28</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.511276 °	40.507907 °	
			-122.360355 °	-122.363620 °	
DWR ID	DWR_NA0018_01_f_2013_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : rduffey\_s\_20140428\_230.jpg



The Dept. of Fish and wildlife services has not done any maintenance.

LM Start	<b>0.02</b>	Rating **	M	Issue No.	<b>1</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.511185 °	40.510670 °	
			-122.360553 °	-122.361203 °	
DWR ID	DWR_NA0018_01_s_2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : rduffey\_s\_20140428\_231.jpg



View of the blackberry and other vegetation along the landside slope.

LM Start	<b>0.02</b>	Rating **	M	Issue No.	<b>6</b>
LM End	<b>0.08</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		40.511185 °	40.510671 °	
			122.360553 °	122.360944 °	
DWR ID	DWR_NA0018_01_s_2013_6				
Action/Comments					
Repair the levee slope damaged by livestock and prevent large animal access. Inspector Comments: The livestock damaged the L/S slope.					

Photo 1 of 1 : rduffey\_s\_20140428\_232.jpg



View of the livestock erosion along the landside slope.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**California Department of Fish and Game Shea Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	03/27/2014 03/27/2014	Bob Duffey

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>9</b>
LM End	<b>0.20</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		40.510649 °	40.509012 °	
			-122.360945 °	-122.362609 °	
DWR ID	DWR_NA0018_01_f_2012_9				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 2 : rduffey\_s\_20140304\_593.jpg



Remove the small trees along the landside slope.

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>9 (cont)</b>
LM End	<b>0.20</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : rduffey\_s\_20140428\_233.jpg



Remove the small trees along the landside slope.

LM Start	<b>0.08</b>	Rating **	M	Issue No.	<b>5</b>
LM End	<b>0.21</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.510671 °	40.509146 °	
			-122.360944 °	-122.362499 °	
DWR ID	DWR_NA0018_01_s_2012_5				
Action/Comments					
Remove the wild growth other than native grasses from the levee					

Photo 1 of 1 : rduffey\_s\_20140428\_234.jpg



The Dept. of Fish and wildlife service has done no maintenance this

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**California Department of Fish and Game Shea Levee**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	03/27/2014 03/27/2014	Bob Duffey

LM Start	<b>0.25</b>	Rating **	M	Issue No.	<b>2</b>
LM End	<b>0.30</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.508138 °	40.508138 °
				-122.363480 °	-122.363480 °
DWR ID	DWR_NA0018_01_s_2012_2				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : rduffey\_s\_20140428\_235.jpg



View of the vegetation along the landside slope.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---