

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

California Department of Fish and Game Shea Levee

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	04/08/2015 04/08/2015	Bob Duffey

LM Start		Rating **	M	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	o
DWR ID	DWR_NA0018_01_s_2013_7				
Action/Comments					
Inspector Comments: Fish and Wildlife Service will not call me back and I was unable to verify the manual.					

No Photos

LM Start		Rating **	M	Issue No.	8
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	o
DWR ID	DWR_NA0018_01_s_2012_8				
Action/Comments					
Inspector Comments: The LMA has not completed any training and does not have an available flood plan.					

No Photos

LM Start		Rating **	M	Issue No.	10
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	o
DWR ID	DWR_NA0018_01_s_2013_10				
Action/Comments					
Inspector Comments: The Fish and Wildlife Service will not call me back and I was unable to verify their supplies.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

California Department of Fish and Game Shea Levee

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	04/08/2015 04/08/2015	Bob Duffey

LM Start	0.00	Rating **	M	Issue No.	2
LM End	0.07	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.508138 °	40.508138 °	
			-122.363480 °	-122.363480 °	
DWR ID	DWR_NA0018_01_s_2012_2				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : SP_2015_NA0018_269_2_20150420_00006.jpg



View of the levee with no maintenance done.

LM Start	0.00	Rating **	M	Issue No.	9
LM End	0.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		40.509012 °	40.510649 °	
			-122.362609 °	-122.360945 °	
DWR ID	DWR_NA0018_01_f_2012_9				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: Fish and Wildlife Service has not completed any maintenance.					

Photo 1 of 1 : SP_2015_NA0018_269_9_20150420_00007.jpg



Remove the small trees along the landside slope.

LM Start	0.10	Rating **	M	Issue No.	1
LM End	0.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.511185 °	40.510670 °	
			-122.360553 °	-122.361203 °	
DWR ID	DWR_NA0018_01_s_2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Fish and Wildlife Service has not completed any maintenance.					

Photo 1 of 1 : SP_2015_NA0018_269_1_20150420_00008.jpg



View of the blackberries and other vegetation along the landside slope.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

