

**Flood Control Project Maintenance
Levee Inspections**
2014 Channel Summary Report
Overall Unit and Item Ratings

Tehama County Flood Control and Water Conservation District

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	M

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2014 Channel Inspection Results****Tehama County Flood Control and Water Conservation District**

Channel
McClure Creek

Channel Rating	M
Date of Inspection	07/15/2014
DWR Inspector	Bob Duffey
Accompanied By	Gary Antone Tehama Co.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Truckee Avenue / Up			
Rating **	A	Issue No. 1	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_3_c_2012_1		
Action/Comments			
Inspector Comments: No vegetation in the channel.			

No Photos

Rating **	A	Issue No. 2	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_3_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0019_3_c_2012_5		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Truckee Avenue / Up (cont)			
Rating **	N	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Revetments		
DWR ID	DWR_NA0019_3_c_2012_4		
Action/Comments			
Inspector Comments: No riprap along the banks of the channel.			

No Photos

Rating **	A	Issue No. 3	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Encroachments		
DWR ID	DWR_NA0019_3_c_2012_3		
Action/Comments			
Inspector Comments: No erosion in the channel.			

Photo 1 of 1 : CH_2014_NA0019_3_3_20140829_00008.jpg



Upstream from extension of Truckee Avenue.

Check Point / View			
Truckee Avenue / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	40.009840 °
Category	Rivers, Channels & Designated Flood		-122.200180 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_3_c_2012_6		
Action/Comments			
Inspector Comments: No vegetation in the channel.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View

Truckee Avenue / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_9			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Truckee Avenue / Down (cont)			
Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.009840 °
Item	Encroachments		-122.200180 °
DWR ID	DWR_NA0019_3_c_2012_10		
Action/Comments			
Inspector Comments: No encroachments in the channel			

Photo 1 of 1 : CH_2014_NA0019_3_10_20140829_00009.jpg



Downstream of the extension of Truckee Avenue.

Check Point / View			
Highway 99 W / Up			
Rating **	M	Issue No.	11
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.007430 °
Item	Vegetation & Obstructions		-122.171780 °
DWR ID	DWR_NA0019_3_c_2012_11		
Action/Comments			
Inspector Comments: Remove all vegetation from channel before winter.			

Photo 1 of 1 : CH_2014_NA0019_3_11_20140829_00010.jpg



Upstream from Highway 99 W. vegetation in the channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
Highway 99 W / Up (cont)					
Rating **	A	Issue No.	12		
Issue Type +	Ma	Location *		40.007430 °	
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0019_3_c_2012_12				
Action/Comments					
Inspector Comments: No shoaling or sedimentation present.					

Rating **	A	Issue No.	13	GPS Lat/Long	
Issue Type +	Ma	Location *		40.007430 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_3_c_2012_13				
Action/Comments					
Inspector Comments: No erosion along the banks of the channel.					

Rating **	N	Issue No.	14	GPS Lat/Long	
Issue Type +	Ma	Location *		40.007430 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Revetments				
DWR ID	DWR_NA0019_3_c_2012_14				
Action/Comments					
Inspector Comments: No riprap along the bank of the channel.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Highway 99 W / Up (cont)			
Rating **	A	Issue No. 15	GPS Lat/Long
Issue Type +	Ma	Location *	40.007430 °
Category	Rivers, Channels & Designated Flood		-122.171780 °
Item	Encroachments		
DWR ID	DWR_NA0019_3_c_2012_15		
Action/Comments			
Inspector Comments: No trash or debris in the channel.			

No Photos

Check Point / View			
Highway 99 W / Down			
Rating **	M	Issue No. 16	GPS Lat/Long
Issue Type +	Ma	Location *	40.007430 °
Category	Rivers, Channels & Designated Flood		-122.171780 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_3_c_2012_16		
Action/Comments			
Inspector Comments: Remove all vegetation from channel before winter.			

Photo 1 of 1 : CH_2014_NA0019_3_16_20140829_00011.jpg



Downstream from Highway 99 W. Vegetation in the channel.

Rating **	A	Issue No. 17	GPS Lat/Long
Issue Type +	Ma	Location *	40.007430 °
Category	Rivers, Channels & Designated Flood		-122.171780 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_3_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling present.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
Highway 99 W / Down (cont)					
Rating **	A	Issue No.	18		
Issue Type +	Ma	Location *		40.007430 °	
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_3_c_2012_18				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank.					

Rating **	N	Issue No.	19	GPS Lat/Long	
Issue Type +	Ma	Location *		40.007430 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Revetments				
DWR ID	DWR_NA0019_3_c_2012_19				
Action/Comments					
Inspector Comments: No riprap along the banks of the channel.					

Rating **	A	Issue No.	20	GPS Lat/Long	
Issue Type +	Ma	Location *		40.007430 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.171780 °	
Item	Encroachments				
DWR ID	DWR_NA0019_3_c_2012_20				
Action/Comments					
Inspector Comments: There is an irrigation pipeline going across the channel.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				
Hamilton Road / Up				
Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_41			
Action/Comments				
Inspector Comments: Remove all vegetation from the channel before winter.				

Photo 1 of 1 : CH_2014_NA0019_3_41_20140829_00012.jpg



Upstream From Hamilton Rd. Dense vegetation in the channel.

Rating **	M	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_42			
Action/Comments				
Inspector Comments: Remove the sediment from the channel.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_43			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Hamilton Road / Up (cont)			
Rating **	N	Issue No. 44	GPS Lat/Long
Issue Type +	Ma	Location *	40.017400 °
Category	Rivers, Channels & Designated Flood		-122.146540 °
Item	Revetments		
DWR ID	DWR_NA0019_3_c_2012_44		
Action/Comments			
Inspector Comments: No riprap along the banks of the channel.			

No Photos

Rating **	M	Issue No. 45	GPS Lat/Long
Issue Type +	Ma	Location *	40.017400 °
Category	Rivers, Channels & Designated Flood		-122.146540 °
Item	Encroachments		
DWR ID	DWR_NA0019_3_c_2012_45		
Action/Comments			
Inspector Comments: There is debris built-up in the vegetation.			

No Photos

Check Point / View			
Hamilton Road / Down			
Rating **	M	Issue No. 46	GPS Lat/Long
Issue Type +	Ma	Location *	40.017400 °
Category	Rivers, Channels & Designated Flood		-122.146540 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_3_c_2012_46		
Action/Comments			
Inspector Comments: Remove all vegetation from the channel before winter.			

Photo 1 of 1 : CH_2014_NA0019_3_46_20140829_00013.jpg



Downstream from Hamilton RD. Vegetation in the channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
Hamilton Road / Down (cont)					
Rating **	M	Issue No.	47		
Issue Type +	Ma	Location *		40.017400 °	
Category	Rivers, Channels & Designated Flood			-122.146540 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0019_3_c_2012_47				
Action/Comments					
Inspector Comments: There is sediment in the channel.					

Rating **	A	Issue No.	48	GPS Lat/Long	
Issue Type +	Ma	Location *		40.017400 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.146540 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_3_c_2012_48				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank.					

Rating **	N	Issue No.	49	GPS Lat/Long	
Issue Type +	Ma	Location *		40.017400 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.146540 °	
Item	Revetments				
DWR ID	DWR_NA0019_3_c_2012_49				
Action/Comments					
Inspector Comments: No riprap along the banks of the channel.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Hamilton Road / Down (cont)			
Rating **	M	Issue No.	50
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.017400 °
Item	Encroachments		-122.146540 °
DWR ID	DWR_NA0019_3_c_2012_50		
Action/Comments			
Inspector Comments: There is debris in the channel.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance**Unit Cover Sheet****2014 Channel Inspection Results****Tehama County Flood Control and Water Conservation District**

Channel
Salt Creek

Channel Rating	A
Date of Inspection	07/15/2014
DWR Inspector	Bob Duffey
Accompanied By	Gary Antone Tehama Co.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				
Upstream Limit / Up				
Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0019_4_1_20140829_00005.jpg



View of Salt Creek from the new railroad car bridge.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_3			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Upstream Limit / Up (cont)			
Rating **	A	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		-122.164250 °
Item	Revetments		
DWR ID	DWR_NA0019_4_c_2012_4		
Action/Comments			
Inspector Comments: Revetment appeared to be in good condition.			
No Photos			

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		-122.164250 °
Item	Encroachments		
DWR ID	DWR_NA0019_4_c_2012_5		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			
No Photos			

Check Point / View			
Upstream Limit / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		122.164250 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_6		
Action/Comments			
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.			
No Photos			

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
Upstream Limit / Down (cont)					
Rating **	A	Issue No.	7		
Issue Type +	Ma	Location *		40.157120 °	
Category	Rivers, Channels & Designated Flood			-122.164250 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0019_4_c_2012_7				
Action/Comments					
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.					

Rating **	A	Issue No.	8	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		40.157120 °	
Category	Rivers, Channels & Designated Flood			-122.164250 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_4_c_2012_8				
Action/Comments					
Inspector Comments: No erosion that would affect the capacity was noted.					

Rating **	A	Issue No.	9	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		40.157120 °	
Category	Rivers, Channels & Designated Flood			-122.164250 °	
Item	Revetments				
DWR ID	DWR_NA0019_4_c_2012_9				
Action/Comments					
Inspector Comments: Revetment appeared to be in good condition or not needed.					

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Upstream Limit / Down (cont)			
Rating **	A	Issue No. 10	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		122.164250 °
Item	Encroachments		
DWR ID	DWR_NA0019_4_c_2012_10		
Action/Comments			
Inspector Comments: New railroad car bridge being constructed at the low water crossing by PG&E.			

No Photos

Check Point / View			
Extension of Salt Creek Road / Up			
Rating **	A	Issue No. 11	GPS Lat/Long
Issue Type +	Ma	Location *	40.156770 °
Category	Rivers, Channels & Designated Flood		122.163670 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_11		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

No Photos

Rating **	A	Issue No. 12	GPS Lat/Long
Issue Type +	Ma	Location *	40.156770 °
Category	Rivers, Channels & Designated Flood		-122.163670 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_4_c_2012_12		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				
Extension of Salt Creek Road / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_13			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

Photo 1 of 1 : CH_2014_NA0019_4_14_20140829_00006.jpg



The landowner has placed rip rap along all erosion sites.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_15			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Extension of Salt Creek Road / Down			
Rating **	A	Issue No. 16	GPS Lat/Long
Issue Type +	Ma	Location *	40.156770 °
Category	Rivers, Channels & Designated Flood		122.163670 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.			

No Photos

Rating **	A	Issue No. 17	GPS Lat/Long
Issue Type +	Ma	Location *	40.156770 °
Category	Rivers, Channels & Designated Flood		-122.163670 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_4_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

Rating **	A	Issue No. 18	GPS Lat/Long
Issue Type +	Ma	Location *	40.156770 °
Category	Rivers, Channels & Designated Flood		-122.163670 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0019_4_c_2012_18		
Action/Comments			
Inspector Comments: No erosion that would affect the capacity was noted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
Extension of Salt Creek Road / Down (cont)			
Rating **	A	Issue No.	19
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.156770 °
Item	Revetments		-122.163670 °
DWR ID	DWR_NA0019_4_c_2012_19		
Action/Comments			
Inspector Comments: Revetment appeared to be in good condition or not needed.			

No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.156770 °
Item	Encroachments		-122.163670 °
DWR ID	DWR_NA0019_4_c_2012_20		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

Check Point / View			
2,800' upstream of downstream limit / Up			
Rating **	A	Issue No.	21
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.151480 °
Item	Vegetation & Obstructions		-122.157590 °
DWR ID	DWR_NA0019_4_c_2012_21		
Action/Comments			
Inspector Comments: The property owner has removed the debris from the channel.			

Photo 1 of 1 : CH_2014_NA0019_4_21_20140829_00007.jpg



Channel has been cleared of logs and vegetation by landowner.

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
2,800' upstream of downstream limit / Up (cont)			
Rating **	A	Issue No. 22	GPS Lat/Long
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		-122.157590 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_4_c_2012_22		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

Rating **	A	Issue No. 23	GPS Lat/Long
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		122.157590 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0019_4_c_2012_23		
Action/Comments			
Inspector Comments: Landowner has repaired all erosions sites.			

No Photos

Rating **	A	Issue No. 24	GPS Lat/Long
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		-122.157590 °
Item	Revetments		
DWR ID	DWR_NA0019_4_c_2012_24		
Action/Comments			
Inspector Comments: Revetment appeared to be in good condition.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
2,800' upstream of downstream limit / Up (cont)			
Rating **	A	Issue No.	25
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		-122.157590 °
Item	Encroachments		
DWR ID	DWR_NA0019_4_c_2012_25		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

Check Point / View			
2,800' upstream of downstream limit / Down			
Rating **	A	Issue No.	26
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		122.157590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_26		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.			

No Photos

Rating **	A	Issue No.	27
Issue Type +	Ma	Location *	40.151480 °
Category	Rivers, Channels & Designated Flood		-122.157590 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_4_c_2012_27		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
2,800' upstream of downstream limit / Down (cont)					
Rating **	A	Issue No.	28		
Issue Type +	Ma	Location *		40.151480 °	
Category	Rivers, Channels & Designated Flood			-122.157590 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_4_c_2012_28				
Action/Comments					
Inspector Comments: No erosion that would affect the capacity was noted.					

Rating **	A	Issue No.	29	GPS Lat/Long	
Issue Type +	Ma	Location *		40.151480 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.157590 °	
Item	Revetments				
DWR ID	DWR_NA0019_4_c_2012_29				
Action/Comments					
Inspector Comments: Revetment appeared to be in good condition or not needed.					

Rating **	A	Issue No.	30	GPS Lat/Long	
Issue Type +	Ma	Location *		40.151480 °	No Photos
Category	Rivers, Channels & Designated Flood			-122.157590 °	
Item	Encroachments				
DWR ID	DWR_NA0019_4_c_2012_30				
Action/Comments					
Inspector Comments: No encroachments were observed that would affect the flow.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
100' upstream of confluence with Sac. R. / Up			
Rating **	A	Issue No.	31
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.147230 °
Item	Vegetation & Obstructions		122.154420 °
DWR ID	DWR_NA0019_4_c_2012_31		
Action/Comments			
Inspector Comments: Logs and vegetation have been removed from the channel.			

Photo 1 of 1 : CH_2014_NA0019_4_31_20140829_00008.jpg



Logs and vegetation has been removed from the channel at the confluence of the Sacramento River.

Rating **	A	Issue No.	32
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.147230 °
Item	Shoaling / Sedimentation		-122.154420 °
DWR ID	DWR_NA0019_4_c_2012_32		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

Rating **	A	Issue No.	33
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.147230 °
Item	Erosion / Bank Caving		-122.154420 °
DWR ID	DWR_NA0019_4_c_2012_33		
Action/Comments			
Inspector Comments: No erosion that would affect the capacity was noted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
100' upstream of confluence with Sac. R. / Up (cont)			
Rating **	A	Issue No. 34	GPS Lat/Long
Issue Type +	Ma	Location *	40.147230 °
Category	Rivers, Channels & Designated Flood		-122.154420 °
Item	Revetments		
DWR ID	DWR_NA0019_4_c_2012_34		
Action/Comments			
Inspector Comments: Revetment appeared to be in good condition or not needed.			

No Photos

Rating **	A	Issue No. 35	GPS Lat/Long
Issue Type +	Ma	Location *	40.147230 °
Category	Rivers, Channels & Designated Flood		-122.154420 °
Item	Encroachments		
DWR ID	DWR_NA0019_4_c_2012_35		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

Check Point / View			
100' upstream of confluence with Sac. R. / Down			
Rating **	A	Issue No. 36	GPS Lat/Long
Issue Type +	Ma	Location *	40.147230 °
Category	Rivers, Channels & Designated Flood		122.154420 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_36		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
100' upstream of confluence with Sac. R. / Down (cont)			
Rating **	A	Issue No.	37
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0019_4_c_2012_37		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

Rating **	A	Issue No.	38
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0019_4_c_2012_38		
Action/Comments			
Inspector Comments: No erosion that would affect the capacity was noted.			

No Photos

Rating **	N	Issue No.	39
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0019_4_c_2012_39		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/15/2014 07/15/2014	Bob Duffey

Check Point / View			
100' upstream of confluence with Sac. R. / Down (cont)			
Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.147230 °
Item	Encroachments		-122.154420 °
DWR ID	DWR_NA0019_4_c_2012_40		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
--	--	---