

**Flood Control Project Maintenance
Levee Inspections**
2015 Channel Summary Report
Overall Unit and Item Ratings

Tehama County Flood Control and Water Conservation District

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	M

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2015 Channel Inspection Results****Tehama County Flood Control and Water Conservation District**

Channel
McClure Creek

Channel Rating	M
Date of Inspection	07/09/2015
DWR Inspector	Bob Duffey
Accompanied By	Gary Antone Tehama Co.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View			
Truckee Avenue / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.009840 °
Item	-122.200180 °		
DWR ID	Vegetation & Obstructions		
DWR_NA0019_3_c_2012_1			
Action/Comments			
Inspector Comments: No vegetation in the channel.			

No Photos

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.009840 °
Item	-122.200180 °		
DWR ID	Shoaling / Sedimentation		
DWR_NA0019_3_c_2012_2			
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No.	5
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.009840 °
Item	-122.200180 °		
DWR ID	Erosion / Bank Caving		
DWR_NA0019_3_c_2012_5			
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Truckee Avenue / Up (cont)				
Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_4			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_3			
Action/Comments				
Inspector Comments: No erosion in the channel.				

Photo 1 of 1 : CH_2015_NA0019_3_3_20150729_00007.jpg



Upstream extension of Truckee Avenue.

Check Point / View				
Truckee Avenue / Down				
Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_6			
Action/Comments				
Inspector Comments: No vegetation in the channel.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				No Photos	
Truckee Avenue / Down (cont)					
Rating **	A	Issue No.	7		GPS Lat/Long
Issue Type +	Ma	Location *			40.009840 °
Category	Rivers, Channels & Designated Flood				-122.200180 °
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0019_3_c_2012_7				
Action/Comments					
Inspector Comments: No shoaling present.					

Rating **	A	Issue No.	8	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		40.009840 °	
Category	Rivers, Channels & Designated Flood			-122.200180 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0019_3_c_2012_8				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank.					

Rating **	N	Issue No.	9	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		40.009840 °	
Category	Rivers, Channels & Designated Flood			-122.200180 °	
Item	Revetments				
DWR ID	DWR_NA0019_3_c_2012_9				
Action/Comments					
Inspector Comments: No riprap along the banks of the channel.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View			
Truckee Avenue / Down (cont)			
Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.009840 °
Item	Encroachments		-122.200180 °
DWR ID	DWR_NA0019_3_c_2012_10		
Action/Comments			
Inspector Comments: No encroachments in the channel			

Photo 1 of 1 : CH_2015_NA0019_3_10_20150729_00008.jpg



Downstream extension of Truckee Avenue.

Check Point / View			
Highway 99 W / Up			
Rating **	M	Issue No.	11
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.007430 °
Item	Vegetation & Obstructions		-122.171780 °
DWR ID	DWR_NA0019_3_c_2012_11		
Action/Comments			
Inspector Comments: Remove all vegetation from channel before winter.			

Photo 1 of 1 : CH_2015_NA0019_3_11_20150729_00009.jpg



Upstream from Highway 99 W. vegetation in the channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Highway 99 W / Up (cont)				
Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_13			
Action/Comments				
Inspector Comments: No erosion along the banks of the channel.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_14			
Action/Comments				
Inspector Comments: No riprap along the bank of the channel.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Highway 99 W / Up (cont)				
Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_15			
Action/Comments				
Inspector Comments: No trash or debris in the channel.				

No Photos

Check Point / View				
Highway 99 W / Down				
Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_16			
Action/Comments				
Inspector Comments: Remove all vegetation from channel before winter.				

Photo 1 of 1 : CH_2015_NA0019_3_16_20150729_00010.jpg



Downstream view from Highway 99 W. There is an irrigation pipe going across the channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling present.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View
Highway 99 W / Down (cont)

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_19			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

Rating **	M	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_20			
Action/Comments				
Inspector Comments: There is an irrigation pipeline going across the channel.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Hamilton Road / Up				
Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_41			
Action/Comments				
Inspector Comments: Remove all vegetation from the channel before winter.				



Upstream from Hamilton Rd. Dense vegetation in the channel.

Rating **	M	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_42			
Action/Comments				
Inspector Comments: Remove the sediment from the channel.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_43			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Hamilton Road / Up (cont)				
Rating **	N	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_44			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

Rating **	M	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_45			
Action/Comments				
Inspector Comments: There is debris built-up in the vegetation.				

No Photos

Check Point / View				
Hamilton Road / Down				
Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_46			
Action/Comments				
Inspector Comments: Remove all vegetation from the channel before winter.				

Photo 1 of 1 : CH_2015_NA0019_3_46_20150729_00012.jpg



Downstream from Hamilton Rd. Dense vegetation in the channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Hamilton Road / Down (cont)				
Rating **	M	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_47			
Action/Comments				
Inspector Comments: There is sediment in the channel.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_48			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_49			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Hamilton Road / Down (cont)				
Rating **	M	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_50			
Action/Comments				
Inspector Comments: There is debris in the channel.				

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

Flood Control Project Maintenance

Unit Cover Sheet

2015 Channel Inspection Results

Tehama County Flood Control and Water Conservation District

Channel
Salt Creek

Channel Rating	A
Date of Inspection	07/09/2015
DWR Inspector	Bob Duffey
Accompanied By	Gary Antone Tehama Co.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Upstream Limit / Up				
Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0019_4_1_20150805_00005.jpg



View of Salt Creek from the railroad car bridge.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_3			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View			
Upstream Limit / Up (cont)			
Rating **	A	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		-122.164250 °
Item	Revetments		
DWR ID	DWR_NA0019_4_c_2012_4		
Action/Comments			
Inspector Comments: Revetment appeared to be in good condition.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		-122.164250 °
Item	Encroachments		
DWR ID	DWR_NA0019_4_c_2012_5		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

Check Point / View			
Upstream Limit / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	40.157120 °
Category	Rivers, Channels & Designated Flood		-122.164250 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0019_4_c_2012_6		
Action/Comments			
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Upstream Limit / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_8			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_9			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition or not needed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Upstream Limit / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_10			
Action/Comments				
Inspector Comments: New railroad car bridge being constricted at the low water crossing by PG&E.				

No Photos

Check Point / View				
Extension of Salt Creek Road / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

No Photos

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Extension of Salt Creek Road / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_13			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

Photo 1 of 1 : CH_2015_NA0019_4_14_20150805_00006.jpg



The landowner has placed rip rap along all erosion sites.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_15			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View			
Extension of Salt Creek Road / Down			
Rating **	A	Issue No.	16
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.156770 °
Item	Vegetation & Obstructions		-122.163670 °
DWR ID	DWR_NA0019_4_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.			

No Photos

Rating **	A	Issue No.	17
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.156770 °
Item	Shoaling / Sedimentation		-122.163670 °
DWR ID	DWR_NA0019_4_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.			

No Photos

Rating **	A	Issue No.	18
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.156770 °
Item	Erosion / Bank Caving		-122.163670 °
DWR ID	DWR_NA0019_4_c_2012_18		
Action/Comments			
Inspector Comments: No erosion that would affect the capacity was noted.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
Extension of Salt Creek Road / Down (cont)				
Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_19			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition or not needed.				

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_20			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

Check Point / View				
2,800' upstream of downstream limit / Up				
Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_21			
Action/Comments				
Inspector Comments: The property owner has removed the debris from the channel.				

Photo 1 of 1 : CH_2015_NA0019_4_21_20150805_00007.jpg



Channel has been cleared of logs and vegetation by landowner.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
2,800' upstream of downstream limit / Up (cont)				
Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_23			
Action/Comments				
Inspector Comments: Landowner has repaired all erosion sites.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_24			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition.				

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
2,800' upstream of downstream limit / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_25			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

Check Point / View				
2,800' upstream of downstream limit / Down				
Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.				

No Photos

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
2,800' upstream of downstream limit / Down (cont)				
Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_28			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_29			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition or not needed.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_30			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
100' upstream of confluence with Sac. R. / Up				
Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_31			
Action/Comments				
Inspector Comments: Logs and vegetation have been removed from the channel.				

No Photos

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_33			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
100' upstream of confluence with Sac. R. / Up (cont)				
Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_34			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition or not needed.				

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_35			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

Check Point / View				
100' upstream of confluence with Sac. R. / Down				
Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.				

Photo 1 of 1 : CH_2015_NA0019_4_36_20150827_00008.jpg



View of the confluence of the Sacramento River.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View				
100' upstream of confluence with Sac. R. / Down (cont)				
Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_38			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

Tehama County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	07/09/2015 07/09/2015	Bob Duffey

Check Point / View			
100' upstream of confluence with Sac. R. / Down (cont)			
Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		40.147230 °
Item	Encroachments		-122.154420 °
DWR ID	DWR_NA0019_4_c_2012_40		
Action/Comments			
Inspector Comments: No encroachments were observed that would affect the flow.			

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--