

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2008 Levee Inspection Results**

**Tehama County Flood Control and Water Conservation District**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2008 Levee Inspection Results**

**Tehama County Flood Control and Water Conservation District**

Waterway	Bank	Unit Miles
Unit No. 01 Deer Creek	Left	4.11

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Bob Duffey			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Tehama County Flood Control and Water Conservation District**

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Deer Creek			Left	4.11	03/20/2008	Bob Duffey

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.47	1.55	Earthen Levee	Encroachments	LS	M	Debris	39.969862 ° -122.006667 °	39.969388 ° -122.008142 °		1
2	2.82	2.82	Earthen Levee	Animal Control	LS	A	Repair the levee slope damaged by livestock and prevent large animal access.	39.964678 ° -122.029288 °	39.964678 ° -122.029288 °		2
3	2.85	2.85	Earthen Levee	Encroachments	LS	M	Tree or limb	39.964293 ° -122.029725 °	39.964293 ° -122.029725 °		3
4	3.54	3.59	Earthen Levee	Encroachments	LS	M	Tree or limb	39.946370 ° -122.053412 °	39.945963 ° -122.054308 °		4
5	3.79	3.79	Earthen Levee	Encroachments	LS	M	Prunings	39.944135 ° -122.054788 °	39.944135 ° -122.054788 °		5
6	3.99	3.99	Earthen Levee	Encroachments	LS	M	Prunings	39.941922 ° -122.057228 °	39.941910 ° -122.057238 °		6

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2008 Levee Inspection Results**

**Tehama County Flood Control and Water Conservation District**

Waterway		Bank	Unit Miles
Unit No. 02 Deer Creek		Right	1.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Bob Duffey			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Tehama County Flood Control and Water Conservation District**

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Deer Creek			Right	1.50	03/20/2008	Bob Duffey

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.22	0.22	Earthen Levee	Encroachments	LS	M	Tree or limb	39.970628 ° -122.012717 °	39.970628 ° -122.012717 °		1
2	0.31	0.31	Earthen Levee	Encroachments	LS	M	Debris	39.970305 ° -122.014465 °	39.970305 ° -122.014465 °		2
3	0.74	0.74	Earthen Levee	Encroachments	LS	M	Material	39.968832 ° -122.021802 °	39.968832 ° -122.021802 °		3
4	0.84	0.84	Earthen Levee	Encroachments	LS	M	Material	39.968557 ° -122.023477 °	39.968557 ° -122.023477 °		4
5	1.01	1.30	Earthen Levee	Encroachments	LS	M	Material	39.967177 ° -122.026250 °	39.964953 ° -122.030640 °		5
6	1.30	1.30	Earthen Levee	Encroachments	WS	A	Firewood	39.964883 ° -122.030655 °	39.964883 ° -122.030655 °		6

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2008 Levee Inspection Results**

**Tehama County Flood Control and Water Conservation District**

Waterway	Bank	Unit Miles
Unit No. 04 Elder Creek	Left	4.07

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Bob Duffey			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Tehama County Flood Control and Water Conservation District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 Elder Creek				Left	4.07	03/20/2008	Bob Duffey				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.08	0.11	Earthen Levee	Encroachments	LS	M	Firewood	40.051737 ° -122.187700 °	40.051720 ° -122.187103 °		1
2	0.65	0.65	Earthen Levee	Encroachments	LS	M	Garbage	40.051673 ° -122.177185 °	40.051673 ° -122.177185 °		2
3	1.60	1.71	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.052607 ° -122.161418 °	40.053558 ° -122.159903 °		3
4	2.32	2.63	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.052325 ° -122.149125 °	40.054197 ° -122.144262 °		4
5	2.75	3.18	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.054843 ° -122.142522 °	40.057537 ° -122.137093 °		5
6	2.80	2.84	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.055035 ° -122.141605 °	40.055525 ° -122.141343 °		6
7	2.91	2.91	Earthen Levee	Encroachments	WS	M	Abandoned vehicles	40.056507 ° -122.141175 °	40.056507 ° -122.141175 °		7
8	2.96	3.17	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.056618 ° -122.140442 °	40.057492 ° -122.137253 °		8
9	2.98	3.05	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	40.056562 ° -122.139963 °	40.056332 ° -122.138667 °		9
10	3.03	3.03	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.056388 ° -122.139168 °	40.056388 ° -122.139168 °		10
11	3.33	3.33	Earthen Levee	Encroachments	LS	M	Garbage	40.057538 ° -122.134442 °	40.057538 ° -122.134442 °		11
12	3.36	3.46	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	40.057267 ° -122.133947 °	40.055840 ° -122.133313 °		12
13	3.62	3.80	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.055468 ° -122.130567 °	40.055147 ° -122.127717 °		13
14	3.71	3.80	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	40.055868 ° -122.128948 °	40.055148 ° -122.127718 °		14
15	3.82	3.83	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	40.054965 ° -122.127537 °	40.054867 ° -122.127432 °		15
16	3.83	3.88	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.054867 ° -122.127432 °	40.054445 ° -122.126612 °		16
17	3.85	3.86	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.054622 ° -122.126980 °	40.054563 ° -122.126863 °		17
18	3.93	3.99	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.054028 ° -122.125748 °	40.053747 ° -122.124685 °		18

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2008 Levee Inspection Results**

**Tehama County Flood Control and Water Conservation District**

Waterway	Bank	Unit Miles
Unit No. 05 Elder Creek	Right	3.96

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Bob Duffey			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Tehama County Flood Control and Water Conservation District**

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elder Creek			Right	3.96	03/20/2008	Bob Duffey

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.83	0.83	Earthen Levee	Encroachments	WS	M	Garbage	40.050868 ° -122.177215 °	40.050868 ° -122.177215 °		1
2	2.70	2.76	Earthen Levee	Encroachments	LS	M	Landscaping	40.051778 ° -122.145745 °	40.052243 ° -122.144825 °		2
3	2.97	3.07	Earthen Levee	Encroachments	WS	M	Prunings	40.054162 ° -122.142298 °	40.054725 ° -122.140552 °		3
4	3.01	3.01	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.054272 ° -122.141492 °	40.054272 ° -122.141492 °		4
5	3.18	3.22	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.055548 ° -122.139058 °	40.055482 ° -122.138320 °		5
6	3.37	3.94	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	40.056815 ° -122.136403 °	40.054137 ° -122.127988 °		6
7	3.45	3.45	Earthen Levee	Erosion / Bank Caving	LS	M	Schedule repair of erosion site prior to the next inspection.	40.056727 ° -122.134888 °	40.056727 ° -122.134888 °		7

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---