

**Flood Control Project Maintenance  
Levee Inspections**  
**2014 Channel Summary Report**  
**Overall Unit and Item Ratings**

**Adin Community Service District**

---

**Ash Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Dry Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

**Flood Control Project Maintenance**

**Unit Cover Sheet**

**2014 Channel Inspection Results**

**Adin Community Service District**

Channel
Ash Creek

Channel Rating	<b>A</b>
Date of Inspection	08/13/2014
DWR Inspector	Bob Duffey
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View

**Main Street / Up**

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_1			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				

Photo 1 of 1 : CH\_2014\_NA0030\_1\_1\_20140821\_00007.jpg



View from Main Street (Highway 299) towards the gaging station.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Main Street / Up (cont)</b>			
Rating **	A	Issue No. <b>4</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Revetments		
DWR ID	DWR_NA0030_1_c_2012_4		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained.			

No Photos

Rating **	A	Issue No. <b>5</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
<b>Main Street / Down</b>			
Rating **	A	Issue No. <b>6</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_6		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 1 : CH\_2014\_NA0030\_1\_6\_20140821\_00008.jpg



View from Main Street (Highway 299) towards the Ash St. low water crossing.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View
<a href="#">Main Street / Down (cont)</a>

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_9			
Action/Comments				
Inspector Comments: Riprap clearly visible.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View				
<b>Main Street / Down (cont)</b>				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

Check Point / View				
<b>Ash Street / Up</b>				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.197660 °
Category	Rivers, Channels & Designated Flood			-120.944220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_11			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				

Photo 1 of 1 : CH\_2014\_NA0030\_1\_11\_20140821\_00009.jpg



View of the channel from Ash Street low water crossing.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.197660 °
Category	Rivers, Channels & Designated Flood			-120.944220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Ash Street / Up (cont)</b>			
Rating **	A	Issue No. <b>13</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_1_c_2012_13		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.			

No Photos

Rating **	A	Issue No. <b>14</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Revetments		
DWR ID	DWR_NA0030_1_c_2012_14		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.			

No Photos

Rating **	A	Issue No. <b>15</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_15		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Ash Street / Down</b>			
Rating **	A	Issue No. <b>16</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

No Photos

Rating **	A	Issue No. <b>17</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0030_1_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	M	Issue No. <b>18</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_1_c_2012_18		
Action/Comments			
Inspector Comments: Monitor erosion during high flows.			

Photo 1 of 1 : CH\_2014\_NA0030\_1\_18\_20140821\_00012.jpg



View of the moderate erosion on both banks.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Ash Street / Down (cont)</b>			
Rating **	A	Issue No. <b>19</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Revetments		
DWR ID	DWR_NA0030_1_c_2012_19		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained.			

No Photos

Rating **	A	Issue No. <b>20</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.197660 °
Category	Rivers, Channels & Designated Flood		-120.944220 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement			

No Photos

Check Point / View			
<b>Downstream limit/fish ladder &amp; walkway / Up</b>			
Rating **	A	Issue No. <b>31</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.192990 °
Category	Rivers, Channels & Designated Flood		-120.954530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_31		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 1 : CH\_2014\_NA0030\_1\_31\_20140821\_00011.jpg



View of the upstream side of the weir.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View

**Downstream limit/fish ladder & walkway / Up (cont)**

Rating **	A	Issue No.	<b>32</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>33</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_33			
Action/Comments				
Inspector Comments: There is minor erosion along both sides of the structure.				

No Photos

Rating **	A	Issue No.	<b>34</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_34			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.				

No Photos

<p><b>* Location</b>                  LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable</p>	<p>N : Not Inspected/Rated                  C : Corrected                  A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b>                  Ma : Maintenance Deficiency                  Ob : Design &amp; System Obsolescence                  En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Downstream limit/fish ladder &amp; walkway / Up (cont)</b>			
Rating **	A	Issue No.	35
Issue Type +	Ma	Location *	41.192990 °
Category	Rivers, Channels & Designated Flood		-120.954530 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_35		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
<b>Downstream limit/fish ladder &amp; walkway / Down</b>			
Rating **	A	Issue No.	36
Issue Type +	Ma	Location *	41.192990 °
Category	Rivers, Channels & Designated Flood		-120.954530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_36		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 1 : CH\_2014\_NA0030\_1\_36\_20140821\_00010.jpg



View of the downstream side of the dam, fish ladder constructed by Dept. of Fish and Game in October 1999.

Rating **	A	Issue No.	37
Issue Type +	Ma	Location *	41.192990 °
Category	Rivers, Channels & Designated Flood		-120.954530 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0030_1_c_2012_37		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	08/13/2014 08/13/2014	Bob Duffey

Check Point / View

**Downstream limit/fish ladder & walkway / Down (cont)**

Rating **	A	Issue No.	<b>38</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.				

No Photos

Rating **	A	Issue No.	<b>39</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_39			
Action/Comments				
Inspector Comments: Placed more riprap on both sides of weir to prevent erosion.				

No Photos

Rating **	A	Issue No.	<b>40</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_40			
Action/Comments				
Inspector Comments: Remove all debris from both sides of weir.				

No Photos

<p><b>* Location</b> LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
--	--	---

**Flood Control Project Maintenance**

**Unit Cover Sheet**

**2014 Channel Inspection Results**

**Adin Community Service District**

Channel
Dry Creek

Channel Rating	<b>A</b>
Date of Inspection	08/13/2014
DWR Inspector	Bob Duffey
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Adin Street / Up</b>			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_2_c_2012_1		
Action/Comments			
Inspector Comments: Remove all vegetation in channel before winter. Mike Williamson said they will remove the vegetation before winter.			

Photo 1 of 1 : CH\_2014\_NA0030\_2\_1\_20140821\_00007.jpg



Upstream at Adin Street. Minor vegetation in channel.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0030_2_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_2_c_2012_3		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Adin Street / Up (cont)</b>			
Rating **	N	Issue No. <b>4</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_4		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No. <b>5</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
<b>Adin Street / Down</b>			
Rating **	A	Issue No. <b>6</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_2_c_2012_6		
Action/Comments			
Inspector Comments: Remove all vegetation in channel before winter.			

Photo 1 of 1 : CH\_2014\_NA0030\_2\_6\_20140821\_00008.jpg



Downstream from Adin street. Minor vegetation in channel.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View				GPS Lat/Long	No Photos
<b>Adin Street / Down (cont)</b>					
Rating **	A	Issue No.	7		
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0030_2_c_2012_7				
Action/Comments					
Inspector Comments: No shoaling or sedimentation present.					

Rating **	A	Issue No.	8	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0030_2_c_2012_8				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank.					

Rating **	N	Issue No.	9	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Revetments				
DWR ID	DWR_NA0030_2_c_2012_9				
Action/Comments					
Inspector Comments: No revetments were observed.					

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View				
<b>Adin Street / Down (cont)</b>				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.196370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

Check Point / View				
<b>Main Street / Up</b>				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_11			
Action/Comments				
Inspector Comments: Remove all vegetation in channel before winter.				

Photo 1 of 1 : CH\_2014\_NA0030\_2\_11\_20140821\_00009.jpg



Upstream from Main Street. Minor vegetation in channel.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Main Street / Up (cont)</b>			
Rating **	A	Issue No. <b>13</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_2_c_2012_13		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

Rating **	N	Issue No. <b>14</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_14		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No. <b>15</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_15		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View				
<b>Main Street / Down</b>				
Rating **	A	Issue No.	<b>16</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_16			
Action/Comments				
Inspector Comments: Remove all vegetation from channel before winter.				

Photo 1 of 2 : CH\_2014\_NA0030\_2\_16\_20140821\_00010.jpg



View of the minor vegetation in channel.

Rating **	A	Issue No.	<b>16 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_16			

Photo 2 of 2 : CH\_2014\_NA0030\_2\_16\_20140714\_00006.jpg



View of the minimal vegetation in channel.

Rating **	A	Issue No.	<b>17</b>	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2014**

**Adin Community Service District**

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	08/13/2014 08/13/2014	Bob Duffey

Check Point / View			
<b>Main Street / Down (cont)</b>			
Rating **	A	Issue No. <b>18</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_2_c_2012_18		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

Rating **	N	Issue No. <b>19</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_19		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No. <b>20</b>	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---