

**Flood Control Project Maintenance
Levee Inspections**

2016 Channel Summary Report

Overall Unit and Item Ratings

Adin Community Service District

Ash Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Dry Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****Adin Community Service District**

Channel
Ash Creek

Channel Rating	A
Date of Inspection	7/13/2016
DWR Inspector	Maksim Khashchuk
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View

Main Street / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_1			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				

Photo 1 of 1 : CH_2016_NA0030_1_1_20160726_00009.jpg



View from Main Street(highway 299) towards the gaging station.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Main Street / Up (cont)			
Rating **	A	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Revetments		
DWR ID	DWR_NA0030_1_c_2012_4		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
Main Street / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	41.197770 °
Category	Rivers, Channels & Designated Flood		-120.944100 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_6		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 1 : CH_2016_NA0030_1_6_20160726_00010.jpg



View from Main Street (highway 299) towards the Ash Street low water crossing.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View
Main Street / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_9			
Action/Comments				
Inspector Comments: Riprap clearly visible.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				
Main Street / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

Check Point / View				
Ash Street / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_11			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				

Photo 1 of 1 : CH_2016_NA0030_1_11_20160726_00011.jpg



View of the channel from Ash Street low water crossing.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				GPS Lat/Long	No Photos
Ash Street / Up (cont)					
Rating **	A	Issue No.	13		
Issue Type +	Ma	Location *		41.197138 °	
Category	Rivers, Channels & Designated Flood			-120.945271 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0030_1_c_2012_13				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.					

Check Point / View				GPS Lat/Long	No Photos
Ash Street / Up (cont)					
Rating **	A	Issue No.	14		
Issue Type +	Ma	Location *		41.197138 °	
Category	Rivers, Channels & Designated Flood			-120.945271 °	
Item	Revetments				
DWR ID	DWR_NA0030_1_c_2012_14				
Action/Comments					
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.					

Check Point / View				GPS Lat/Long	No Photos
Ash Street / Up (cont)					
Rating **	A	Issue No.	15		
Issue Type +	Ma	Location *		41.197138 °	
Category	Rivers, Channels & Designated Flood			-120.945271 °	
Item	Encroachments				
DWR ID	DWR_NA0030_1_c_2012_15				
Action/Comments					
Inspector Comments: No trash, debris or other obstructions present within the easement.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Ash Street / Down			
Rating **	A	Issue No. 16	GPS Lat/Long
Issue Type +	Ma	Location *	41.197138 °
Category	Rivers, Channels & Designated Flood		-120.945271 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

No Photos

Rating **	A	Issue No. 17	GPS Lat/Long
Issue Type +	Ma	Location *	41.197138 °
Category	Rivers, Channels & Designated Flood		-120.945271 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0030_1_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	M	Issue No. 18	GPS Lat/Long
Issue Type +	Ma	Location *	41.197138 °
Category	Rivers, Channels & Designated Flood		-120.945271 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_1_c_2012_18		
Action/Comments			
Inspector Comments: Monitor erosion during high flows.			

Photo 1 of 1 : CH_2016_NA0030_1_18_20160726_00012.jpg



View of the moderate erosion on both banks.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Ash Street / Down (cont)			
Rating **	A	Issue No. 19	GPS Lat/Long
Issue Type +	Ma	Location *	41.197138 °
Category	Rivers, Channels & Designated Flood		-120.945271 °
Item	Revetments		
DWR ID	DWR_NA0030_1_c_2012_19		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained.			

No Photos

Rating **	A	Issue No. 20	GPS Lat/Long
Issue Type +	Ma	Location *	41.197138 °
Category	Rivers, Channels & Designated Flood		-120.945271 °
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
Downstream limit/fish ladder & walkway / Up			
Rating **	A	Issue No. 31	GPS Lat/Long
Issue Type +	Ma	Location *	41.192990 °
Category	Rivers, Channels & Designated Flood		-120.954530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_31		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 1 : CH_2016_NA0030_1_31_20160726_00013.jpg



View of the upstream side of the weir.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View

Downstream limit/fish ladder & walkway / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_33			
Action/Comments				
Inspector Comments: There is minor erosion along both sides of the structure.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_34			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Downstream limit/fish ladder & walkway / Up (cont)			
Rating **	A	Issue No.	35
Issue Type +	Ma	Location *	41.192990°
Category	Rivers, Channels & Designated Flood		-120.954530°
Item	Encroachments		
DWR ID	DWR_NA0030_1_c_2012_35		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
Downstream limit/fish ladder & walkway / Down			
Rating **	A	Issue No.	36
Issue Type +	Ma	Location *	41.192990°
Category	Rivers, Channels & Designated Flood		-120.954530°
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_1_c_2012_36		
Action/Comments			
Inspector Comments: The channel is clear of vegetation & obstructions.			

Photo 1 of 2 : CH_2016_NA0030_1_36_20160726_00014.jpg



View of the downstream side of the dam.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---


**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				
Downstream limit/fish ladder & walkway / Down (cont)				
Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_36			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				



View of the downstream side of the dam, fish ladder constructed by Dept. of Fish and Game in October 1999.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Downstream limit/fish ladder & walkway / Down (cont)			
Rating **	A	Issue No.	39
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		41.192990 °
DWR ID	DWR_NA0030_1_c_2012_39		-120.954530 °
Action/Comments			
Inspector Comments: Placed more riprap on both sides of weir to prevent erosion.			

No Photos

Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Encroachments		41.192990 °
DWR ID	DWR_NA0030_1_c_2012_40		-120.954530 °
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance

Unit Cover Sheet

2016 Channel Inspection Results

Adin Community Service District

Channel
Dry Creek

Channel Rating	A
Date of Inspection	7/13/2016
DWR Inspector	Maksim Khashchuk
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Adin Street / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_2_c_2012_1		
Action/Comments			
Inspector Comments: Remove all vegetation in channel before winter. Mike Williamson said they will remove the vegetation before winter.			



Upstream at Adin Street. Minimal vegetation in channel.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0030_2_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_2_c_2012_3		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Adin Street / Up (cont)			
Rating **	N	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_4		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

Check Point / View			
Adin Street / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	41.195370 °
Category	Rivers, Channels & Designated Flood		-120.943190 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0030_2_c_2012_6		
Action/Comments			
Inspector Comments: Remove volunteer woody vegetation in channel before blockage occurs.			

Photo 1 of 1 : CH_2016_NA0030_2_6_20160726_00006.jpg



Downstream from Adin Street. Minimal vegetation in channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				GPS Lat/Long	No Photos
Adin Street / Down (cont)					
Rating **	A	Issue No.	7		
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0030_2_c_2012_7				
Action/Comments					
Inspector Comments: No shoaling or sedimentation present.					

Rating **	A	Issue No.	8	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0030_2_c_2012_8				
Action/Comments					
Inspector Comments: No erosion encroaching into the channel bank.					

Rating **	N	Issue No.	9	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		41.195370 °	
Category	Rivers, Channels & Designated Flood			-120.943190 °	
Item	Revetments				
DWR ID	DWR_NA0030_2_c_2012_9				
Action/Comments					
Inspector Comments: No revetments were observed.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				
Adin Street / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

Check Point / View				
Main Street / Up				
Rating **	M	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_11			
Action/Comments				
Inspector Comments: Remove all woody vegetation in channel before winter.				

Photo 1 of 1 : CH_2016_NA0030_2_11_20160726_00007.jpg



Upstream from Main Street. Minimal vegetation in channel.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Main Street / Up (cont)			
Rating **	A	Issue No. 13	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0030_2_c_2012_13		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank.			

No Photos

Rating **	N	Issue No. 14	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_14		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No. 15	GPS Lat/Long
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_15		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View				
Main Street / Down				
Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_16			
Action/Comments				
Inspector Comments: Remove volunteer woody vegetation in channel before blockage occurs. The grass should be mowed before flood season.				

Photo 1 of 1 : CH_2016_NA0030_2_16_20160726_00008.jpg



View from Main Street looking downstream at minimal vegetation in channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_2_c_2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	07/13/2016 07/13/2016	Maksim Khashchuk

Check Point / View			
Main Street / Down (cont)			
Rating **	N	Issue No.	19
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Revetments		
DWR ID	DWR_NA0030_2_c_2012_19		
Action/Comments			
Inspector Comments: No revetments were observed.			

No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	41.196350 °
Category	Rivers, Channels & Designated Flood		-120.944250 °
Item	Encroachments		
DWR ID	DWR_NA0030_2_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris or other obstructions present within the easement.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---