

**Flood Control Project Maintenance  
Levee Inspections**

**2015 Channel Summary Report**

**Overall Unit and Item Ratings**

**Placer County**

---

**Truckee River**

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**Unit Cover Sheet**  
**2015 Channel Inspection Results**

**Placer County**

Channel
Truckee River

Channel Rating	A
Date of Inspection	08/13/2015
DWR Inspector	Jai Lor
Accompanied By	

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Outlet Structure / Up</b>				
Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0045\_13\_1\_20150817\_00020.jpg



Looking upstream from the outlet structure. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0045\_13\_1\_20150612\_00001.jpg



Standing on the walkway looking upstream at Lake Tahoe. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0045\_13\_1\_20150612\_00003.jpg



Looking upstream at the very low flow out of Lake Tahoe. Summer 2014

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				GPS Lat/Long	No Photos
<b>Outlet Structure / Up (cont)</b>					
Rating **	A	Issue No.	2		
Issue Type +	Ma	Location *		39.167101 °	
Category	Rivers, Channels & Designated Flood			-120.144002 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0045_13_c_2012_2				
Action/Comments					
Inspector Comments: No shoaling or sedimentation present.					

Rating **	A	Issue No.	3	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.167101 °	
Category	Rivers, Channels & Designated Flood			-120.144002 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0045_13_c_2012_3				
Action/Comments					
Inspector Comments: No head cutting or horizontal deviation observed.					

Rating **	N	Issue No.	4	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.167101 °	
Category	Rivers, Channels & Designated Flood			-120.144002 °	
Item	Revetments				
DWR ID	DWR_NA0045_13_c_2012_4				
Action/Comments					
Inspector Comments: This item does not apply to this inspection.					

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Outlet Structure / Up (cont)</b>				
Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_5			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
<b>Outlet Structure / Down</b>				
Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0045\_13\_6\_20150817\_00021.jpg



Looking downstream from the outlet structure. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0045\_13\_6\_20150612\_00004.jpg



Looking at the outlet structure from Highway 89. Summer 2014

Check Point / View				
Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Outlet Structure / Down (cont)</b>				
Rating **	A	Issue No.	<b>6 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 3 of 3 : CH\_2015\_NA0045\_13\_6\_20150612\_00005.jpg



A side view of the downstream side of the structure. Summer 2013

Rating **	A	Issue No.	<b>7</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>8</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_8			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>Outlet Structure / Down (cont)</b>			
Rating **	N	Issue No.	9
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.167101 °
Item	Revetments		-120.144002 °
DWR ID	DWR_NA0045_13_c _ 2012_9		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.167101 °
Item	Encroachments		-120.144002 °
DWR ID	DWR_NA0045_13_c _ 2012_10		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
<b>Hwy 89 / Up</b>			
Rating **	A	Issue No.	11
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.166845 °
Item	Vegetation & Obstructions		-120.144424 °
DWR ID	DWR_NA0045_13_c _ 2012_11		
Action/Comments			
Inspector Comments: The flow going out the control structure is very low. Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 2 : CH\_2015\_NA0045\_13\_11\_20150817\_00022.jpg



Looking upstream from Highway 89. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---


**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Hwy 89 / Up (cont)</b>				
Rating **	A	Issue No.	<b>11 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			
Action/Comments				
Inspector Comments: The flow going out the control structure is very low. Minimal, scattered obstructions or vegetation. The flow is not impeded.				



Looking upstream from Highway 89 at the outlet structure. Summer 2014

Rating **	A	Issue No.	<b>12</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>13</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>Hwy 89 / Up (cont)</b>			
Rating **	A	Issue No. <b>14</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.166845 °
Category	Rivers, Channels & Designated Flood		-120.144424 °
Item	Revetments		
DWR ID	DWR_NA0045_13_c _ 2012_14		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No. <b>15</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.166845 °
Category	Rivers, Channels & Designated Flood		-120.144424 °
Item	Encroachments		
DWR ID	DWR_NA0045_13_c _ 2012_15		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
<b>Hwy 89 / Down</b>			
Rating **	A	Issue No. <b>16</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.166845 °
Category	Rivers, Channels & Designated Flood		-120.144424 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0045_13_c _ 2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 2 : CH\_2015\_NA0045\_13\_16\_20150817\_00023.jpg



Looking downstream from Highway 89. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Hwy 89 / Down (cont)</b>				
Rating **	A	Issue No.	<b>16 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 2 of 2 : CH\_2015\_NA0045\_13\_16\_20150612\_00008.jpg



Looking downstream from Highway 89. Summer 2014

Rating **	A	Issue No.	<b>17</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>18</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_18			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>Hwy 89 / Down (cont)</b>			
Rating **	N	Issue No.	19
Issue Type +	Ma	Location *	39.166845 °
Category	Rivers, Channels & Designated Flood		-120.144424 °
Item	Revetments		
DWR ID	DWR_NA0045_13_c_2012_19		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	39.166845 °
Category	Rivers, Channels & Designated Flood		-120.144424 °
Item	Encroachments		
DWR ID	DWR_NA0045_13_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
<b>bike bridge / Up</b>			
Rating **	A	Issue No.	21
Issue Type +	Ma	Location *	39.165170 °
Category	Rivers, Channels & Designated Flood		120.147590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0045_13_c_2012_21		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 2 : CH\_2015\_NA0045\_13\_21\_20150817\_00024.jpg



Looking upstream from the bike bridge. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>bike bridge / Up (cont)</b>			
Rating **	A	Issue No.	<b>21 (cont)</b>
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.165170 °
Item	Vegetation & Obstructions		120.147590 °
DWR ID	DWR_NA0045_13_c _ 2012_21		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 2 of 2 : CH\_2015\_NA0045\_13\_21\_20150612\_00010.jpg



Looking upstream from the bike bridge. Summer 2014

Rating **	A	Issue No.	<b>22</b>
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.165170 °
Item	Shoaling / Sedimentation		120.147590 °
DWR ID	DWR_NA0045_13_c _ 2012_22		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No.	<b>23</b>
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.165170 °
Item	Erosion / Bank Caving		120.147590 °
DWR ID	DWR_NA0045_13_c _ 2012_23		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>bike bridge / Up (cont)</b>			
Rating **	N	Issue No. <b>24</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.165170 °
Category	Rivers, Channels & Designated Flood		120.147590 °
Item	Revetments		
DWR ID	DWR_NA0045_13_c_2012_24		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No. <b>25</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.165170 °
Category	Rivers, Channels & Designated Flood		-120.147590 °
Item	Encroachments		
DWR ID	DWR_NA0045_13_c_2012_25		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
<b>bike bridge / Down</b>			
Rating **	A	Issue No. <b>26</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.165170 °
Category	Rivers, Channels & Designated Flood		120.147590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0045_13_c_2012_26		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 2 : CH\_2015\_NA0045\_13\_26\_20150817\_00025.jpg



Looking downstream from the bike bridge. Summer 2015.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement


**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>bike bridge / Down (cont)</b>				
Rating **	A	Issue No.	<b>26 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				



Looking downstream from the bike bridge. Summer 2014

Rating **	A	Issue No.	<b>27</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>28</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_28			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>bike bridge / Down (cont)</b>				
Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_29			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
<b>Tahoe City lumber yard / Up</b>				
Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0045\_13\_31\_20150817\_00026.jpg



Looking upstream from Tahoe City Lumber Yard ( 39.162628, - 120.151856). Summer 2015.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**


Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Tahoe City lumber yard / Up (cont)</b>				
Rating **	A	Issue No.	<b>31 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				



Looking upstream from Tahoe City Lumber Yard ( 39.162634, -120.152646). Summer 2015.

Rating **	A	Issue No.	<b>31 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			



Looking upstream from Tahoe City Lumber Yard. Summer 2014

Rating **	A	Issue No.	<b>32</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>Tahoe City lumber yard / Up (cont)</b>			
Rating **	A	Issue No. <b>33</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.162480 °
Category	Rivers, Channels & Designated Flood		-120.151900 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0045_13_c_2012_33		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	N	Issue No. <b>34</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.162480 °
Category	Rivers, Channels & Designated Flood		-120.151900 °
Item	Revetments		
DWR ID	DWR_NA0045_13_c_2012_34		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No. <b>35</b>	GPS Lat/Long
Issue Type +	Ma	Location *	39.162480 °
Category	Rivers, Channels & Designated Flood		-120.151900 °
Item	Encroachments		
DWR ID	DWR_NA0045_13_c_2012_35		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View				
<b>Tahoe City lumber yard / Down</b>				
Rating **	A	Issue No.	<b>36</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0045\_13\_36\_20150817\_00030.jpg



Alternate view of downstream from Tahoe City Lumber Yard (39.162634, -120.152646). Summer 2015.

Rating **	A	Issue No.	<b>36 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Photo 2 of 3 : CH\_2015\_NA0045\_13\_36\_20150817\_00029.jpg



Looking downstream from Tahoe City Lumber Yard (39.162628, -120.151856). Summer 2015.

Rating **	A	Issue No.	<b>36 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Photo 3 of 3 : CH\_2015\_NA0045\_13\_36\_20150612\_00018.jpg



Looking downstream From Tahoe City Lumber Yard. Summer 2014

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View
<b>Tahoe City lumber yard / Down (cont)</b>

Rating **	A	Issue No.	<b>37</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	<b>38</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	<b>39</b>	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Placer County**

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	08/13/2015 08/13/2015	Jai Lor

Check Point / View			
<b>Tahoe City lumber yard / Down (cont)</b>			
Rating **	A	Issue No.	<b>40</b>
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.162480 °
Item	Encroachments		
DWR ID	DWR_NA0045_13_c _ 2012_40		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---