

Flood Control Project Maintenance
2009 Structure Summary Report
Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard

Cache Creek Setting Basin Weir And Drainage Structure

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|----------------------------|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments | A |
| | Encroachments | A |
| | Culverts: Inlets / Outlets | A |
| | Manual Gate Operators | A |
| | Concrete Surfaces | A |
| | Concrete Foundations | A |
| | Security Fencing | A |
| | Safety | A |

Fremont Weir

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|-------------------------------|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments | A |
| | Encroachments | A |
| | Sluice/Slide Gates | A |
| | Concrete Surfaces | A |
| | Concrete Tilting / Settlement | A |
| | Concrete Foundations | A |
| | Security Fencing | A |
| | Monolith Joints | A |
| | Safety | A |

Knights Landing Outfall Structure

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---------------------------|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Encroachments | A |
| | Trash Racks | A |
| | Flap Gates | A |
| | Sluice/Slide Gates | A |
| | Electric Gate Operators | M |
| | Manual Gate Operators | A |
| | Concrete Surfaces | A |
| | Concrete Foundations | A |
| | Security Fencing | A |
| | Closure Structures | A |
| | Other Metallic Items | M |
| | Safety | A |

Flood Control Project Maintenance
2009 Structure Summary Report
Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard (cont.)

Paradise Dam

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|-------------------------------|-------------|
| M | Photo Documentation | A |
| | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments | A |
| | Encroachments | A |
| | Concrete Surfaces | A |
| | Concrete Tilting / Settlement | A |
| | Concrete Foundations | M |
| | Safety | M |

Sacramento Weir

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---------------------------|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Encroachments | M |
| | Concrete Foundations | A |
| | Security Fencing | A |
| | Other Metallic Items | A |
| | Monolith Joints | A |
| | Safety | A |

Flood Control Project Maintenance
Unit Cover Sheet
2009 Structure Inspection Results

DWR Sacramento Maintenance Yard

| Structure |
|---|
| Cache Creek Setting Basin Weir And Drainage Structure |

| | |
|--------------------|---------------------------------------|
| Structure Rating | A |
| Date of Inspection | 7/7/2009 |
| DWR Inspector | John Williamson |
| Accompanied By | Larry Kline Sacramento Maintenance |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|---|------------------|--------------------------|--------------------|
| Cache Creek Setting Basin Weir And Drainage Structure | | 07/15/2009 07/15/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location* | Rating** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-----------------------------------|-----------|----------|---|-----------------------------|-----------------------------|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 1 | 0.00 | 0.00 | Structures | Photo Documentation | | | Inspector Comments: Intake structure, gates out flow 38.67848 -121.67294, s. end Cache weir 38.68246 - 121.67293, n. end Cache weir 38.68735 -121.67374 all GPS readings are from top of levee | 38.682460 ° 121.672930 ° | 38.687350 ° 121.673740 ° | Y | 1 |
| 2 | 0.00 | 0.00 | Structures | Vegetation & Obstructions | | A | | ° ° | ° ° | | 2 |
| 3 | 0.00 | 0.00 | Structures | Shoaling / Sedimentation | | A | | ° ° | ° ° | | 3 |
| 4 | 0.00 | 0.00 | Structures | Erosion / Bank Caving | | A | | ° ° | ° ° | | 4 |
| 5 | 0.00 | 0.00 | Structures | Revetments | | A | | ° ° | ° ° | | 5 |
| 6 | 0.00 | 0.00 | Structures | Encroachments | | A | | ° ° | ° ° | | 6 |
| 7 | 0.00 | 0.00 | Structures | Culverts: Inlets / Outlets | | A | | ° ° | ° ° | | 7 |
| 8 | 0.00 | 0.00 | Structures | Culverts: Breaks / Holes / Cracks | | N | | ° ° | ° ° | | 8 |
| 9 | 0.00 | 0.00 | Structures | Metal Pipes | | N | | ° ° | ° ° | | 9 |
| 10 | 0.00 | 0.00 | Structures | Trash Racks | | N | | ° ° | ° ° | | 10 |
| 11 | 0.00 | 0.00 | Structures | Flap Gates | | N | | ° ° | ° ° | | 11 |
| 12 | 0.00 | 0.00 | Structures | Sluice/Slide Gates | | N | | ° ° | ° ° | | 12 |
| 13 | 0.00 | 0.00 | Structures | Electric Gate Operators | | N | | ° ° | ° ° | | 13 |
| 14 | 0.00 | 0.00 | Structures | Manual Gate Operators | | A | Inspector Comments: 38.67848 -121.67294 gates are tested once a year with safety and dams. Gates are open for the flood season every year. | 38.678480 ° 121.672940 ° | 38.678480 ° 121.672940 ° | Y | 14 |
| 15 | 0.00 | 0.00 | Structures | Concrete Surfaces | | A | | ° ° | ° ° | | 15 |

| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|---|------------------|--------------------------|--------------------|
| Cache Creek Setting Basin Weir And Drainage Structure | | 07/15/2009 07/15/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location* | Rating** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-------------------------------|-----------|----------|----------------|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 16 | 0.00 | 0.00 | Structures | Concrete Tilting / Settlement | | N | | ° | ° | | 16 |
| 17 | 0.00 | 0.00 | Structures | Concrete Foundations | | A | | ° | ° | | 17 |
| 18 | 0.00 | 0.00 | Structures | Security Fencing | | A | | ° | ° | | 18 |
| 19 | 0.00 | 0.00 | Structures | Closure Structures | | N | | ° | ° | | 19 |
| 20 | 0.00 | 0.00 | Structures | Trash Rakes | | N | | ° | ° | | 20 |
| 21 | 0.00 | 0.00 | Structures | Other Metallic Items | | N | | ° | ° | | 21 |
| 22 | 0.00 | 0.00 | Structures | Monolith Joints | | N | | ° | ° | | 22 |
| 23 | 0.00 | 0.00 | Structures | Safety | | A | | ° | ° | | 23 |

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|---|------------------|--------------------------|--------------------|
| Cache Creek Setting Basin Weir And Drainage Structure | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| Look from the southern end Cache Weir 38.68246 -121.67293 | |
| johngw_20090716_10.jpg | |



| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| Another view southern end with recorder can 38.68246 -121.67293 | |
| johngw_20090716_11.jpg | |



| | |
|---|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| view from the northern end of Cache Weir 38.68735 -121.67374 | |
| johngw_20090716_12.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|---|------------------|--------------------------|--------------------|
| Cache Creek Setting Basin Weir And Drainage Structure | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|------------------------|-----------------------|
| Levee Mile Report Line | 14 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Manual Gate Operators |
| Manual gates | 38.67848 121.67294 |
| johngw_20090716_13.jpg | |



| | |
|--|-----------------------|
| Levee Mile Report Line | 14 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Manual Gate Operators |
| out flow structure gates on top of levee | |
| johngw_20090716_14.jpg | |



| | |
|------------------------|-----------------------|
| Levee Mile Report Line | 14 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Manual Gate Operators |
| intake structure | |
| johngw_20090716_15.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|---|------------------|--------------------------|--------------------|
| Cache Creek Setting Basin Weir And Drainage Structure | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|--------------------------------|-----------------------|
| Levee Mile Report Line | 14 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Manual Gate Operators |
| intake structure and stop logs | |
| johngw_20090716_16.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

DWR Sacramento Maintenance Yard

| |
|--------------|
| Structure |
| Fremont Weir |

| | |
|--------------------|-----------------|
| Structure Rating | A |
| Date of Inspection | 7/7/2009 |
| DWR Inspector | John Williamson |
| Accompanied By | |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|--------------------------|--------------------|
| Fremont Weir | | 07/09/2009 07/09/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location* | Rating** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-----------------------------------|-----------|----------|---|------------------------|-------------|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 1 | | | Structures | Photo Documentation | | | Inspector Comments: west end 38.75888 -121.66538, fish ladder center 38.76431 -121.64669 east end 38.76468 -121.63543 | 38.758883 ° | 38.758883 ° | Y | 1 |
| 2 | 0.00 | 0.00 | Structures | Vegetation & Obstructions | | A | | ° | ° | | 2 |
| 3 | 0.00 | 0.00 | Structures | Shoaling / Sedimentation | | A | | ° | ° | | 3 |
| 4 | 0.00 | 0.00 | Structures | Erosion / Bank Caving | | A | | ° | ° | | 4 |
| 5 | 0.00 | 0.00 | Structures | Revetments | | A | | ° | ° | | 5 |
| 6 | 0.00 | 0.00 | Structures | Encroachments | | A | | ° | ° | | 6 |
| 7 | 0.00 | 0.00 | Structures | Culverts: Inlets / Outlets | | N | | ° | ° | | 7 |
| 8 | 0.00 | 0.00 | Structures | Culverts: Breaks / Holes / Cracks | | N | | ° | ° | | 8 |
| 9 | 0.00 | 0.00 | Structures | Metal Pipes | | N | | ° | ° | | 9 |
| 10 | 0.00 | 0.00 | Structures | Trash Racks | | N | | ° | ° | | 10 |
| 11 | 0.00 | 0.00 | Structures | Flap Gates | | N | | ° | ° | | 11 |
| 12 | 0.00 | 0.00 | Structures | Sluice/Slide Gates | | A | | ° | ° | | 12 |
| 13 | 0.00 | 0.00 | Structures | Electric Gate Operators | | N | | ° | ° | | 13 |
| 14 | 0.00 | 0.00 | Structures | Manual Gate Operators | | N | | ° | ° | | 14 |
| 15 | 0.00 | 0.00 | Structures | Concrete Surfaces | | A | | ° | ° | | 15 |
| 16 | 0.00 | 0.00 | Structures | Concrete Tilting / Settlement | | A | | ° | ° | | 16 |

| | | |
|---|---|---|
| <p>* Location LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|--------------------------|-----------------|
| Fremont Weir | | 07/09/2009 07/09/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|----------------------|------------|-----------|--|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 17 | 0.00 | 0.00 | Structures | Concrete Foundations | | A | | ° | ° | | 17 |
| 18 | 0.00 | 0.00 | Structures | Security Fencing | | A | | ° | ° | | 18 |
| 19 | 0.00 | 0.00 | Structures | Closure Structures | | N | | ° | ° | | 19 |
| 20 | 0.00 | 0.00 | Structures | Trash Rakes | | N | | ° | ° | | 20 |
| 21 | 0.00 | 0.00 | Structures | Other Metallic Items | | N | | ° | ° | | 21 |
| 22 | 0.00 | 0.00 | Structures | Monolith Joints | | A | | ° | ° | | 22 |
| 23 | 0.00 | 0.00 | Structures | Safety | | A | Inspector Comments: this item does not apply N/A | ° | ° | | 23 |

| | | |
|---|---|---|
| <p>* Location LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|--------------------------|--------------------|
| Fremont Weir | | 07/09/2009 07/09/2009 | John Williamson |

| | |
|--------------------------------------|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | |
| End Levee Mile | |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| west end of weir 38.75888 -121.66538 | |
| johngw_20090709_6.jpg | |



| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | |
| End Levee Mile | |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| standing at fish ladder looking west 38.764318 - 121.64669 | |
| johngw_20090709_7.jpg | |



| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | |
| End Levee Mile | |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| standing at fish ladder looking east 38.764318 - 121.64669 | |
| johngw_20090709_8.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|--------------------------|--------------------|
| Fremont Weir | | 07/09/2009 07/09/2009 | John Williamson |

| | |
|--------------------------------------|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | |
| End Levee Mile | |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| east end of weir 38.76468 -121.63543 | |
| johngw_20090709_9.jpg | |



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p> |
|---|---|

Flood Control Project Maintenance
Unit Cover Sheet
2009 Structure Inspection Results

DWR Sacramento Maintenance Yard

| |
|-----------------------------------|
| Structure |
| Knights Landing Outfall Structure |

| | |
|--------------------|---------------------------------------|
| Structure Rating | A |
| Date of Inspection | 7/7/2009 |
| DWR Inspector | John Williamson |
| Accompanied By | Larry Kline Sacramento Maintenance |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------------------------|------------------|--------------------------|-----------------|
| Knights Landing Outfall Structure | | 07/16/2009 07/16/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location* | Rating** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-----------------------------------|-----------|----------|---|-----------------------------|-----------------------------|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 1 | 0.00 | 0.00 | Structures | Photo Documentation | | | Inspector Comments: North end 38.79956 -121.72553, South end 38.79932 -121.72485, all GPS readings are on levee at the gates. | 38.799560 ° 121.725530 ° | 38.799320 ° 121.724850 ° | Y | 1 |
| 2 | 0.00 | 0.00 | Structures | Vegetation & Obstructions | | A | | ° ° | ° ° | | 2 |
| 3 | 0.00 | 0.00 | Structures | Shoaling / Sedimentation | | A | | ° ° | ° ° | | 3 |
| 4 | 0.00 | 0.00 | Structures | Erosion / Bank Caving | | A | | ° ° | ° ° | | 4 |
| 5 | 0.00 | 0.00 | Structures | Revetments | | N | | ° ° | ° ° | | 5 |
| 6 | 0.00 | 0.00 | Structures | Encroachments | | A | | ° ° | ° ° | | 6 |
| 7 | 0.00 | 0.00 | Structures | Culverts: Inlets / Outlets | | N | | ° ° | ° ° | | 7 |
| 8 | 0.00 | 0.00 | Structures | Culverts: Breaks / Holes / Cracks | | N | | ° ° | ° ° | | 8 |
| 9 | 0.00 | 0.00 | Structures | Metal Pipes | | N | | ° ° | ° ° | | 9 |
| 10 | 0.00 | 0.00 | Structures | Trash Racks | | A | | ° ° | ° ° | | 10 |
| 11 | 0.00 | 0.00 | Structures | Flap Gates | | A | Inspector Comments: scheduled for up grade in 2010-2011 | ° ° | ° ° | | 11 |
| 12 | 0.00 | 0.00 | Structures | Sluice/Slide Gates | | A | Inspector Comments: scheduled for up grade in 2010-2011 | ° ° | ° ° | | 12 |
| 13 | 0.00 | 0.00 | Structures | Electric Gate Operators | | M | Inspector Comments: bays 3 & 5 are not in operation at this time can be open manually. Telephone service which operates gates is laying on the ground for about 500' and is subject to vandals. Scheduled to be up graded in 2010-2011. | ° ° | ° ° | Y | 13 |
| 14 | 0.00 | 0.00 | Structures | Manual Gate Operators | | A | Inspector Comments: scheduled for up grade in 2010-2011 | ° ° | ° ° | | 14 |

| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------------------------|------------------|--------------------------|-----------------|
| Knights Landing Outfall Structure | | 07/16/2009 07/16/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location* | Rating** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-------------------------------|-----------|----------|---|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 15 | 0.00 | 0.00 | Structures | Concrete Surfaces | | A | Inspector Comments: vertical crack on north side has not changed from pass year continue to monitor and repair as necessary. Small vertical crack south side continue to monitor. | ° | ° | ° | Y 15 |
| 16 | 0.00 | 0.00 | Structures | Concrete Tilting / Settlement | | N | | ° | ° | ° | 16 |
| 17 | 0.00 | 0.00 | Structures | Concrete Foundations | | A | | ° | ° | ° | 17 |
| 18 | 0.00 | 0.00 | Structures | Security Fencing | | A | | ° | ° | ° | 18 |
| 19 | 0.00 | 0.00 | Structures | Closure Structures | | A | | ° | ° | ° | 19 |
| 20 | 0.00 | 0.00 | Structures | Trash Rakes | | N | | ° | ° | ° | 20 |
| 21 | 0.00 | 0.00 | Structures | Other Metallic Items | | M | | ° | ° | ° | Y 21 |
| 22 | 0.00 | 0.00 | Structures | Monolith Joints | | N | | ° | ° | ° | 22 |
| 23 | 0.00 | 0.00 | Structures | Safety | | A | | ° | ° | ° | 23 |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009


DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------------------------|------------------|--------------------------|--------------------|
| Knights Landing Outfall Structure | | 07/16/2009 07/16/2009 | John Williamson |

| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| view from the north side of Syamore Slough | |
| johngw_20090720_31.jpg | |



| | |
|--------------------------|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| view from the South side | |
| johngw_20090720_32.jpg | |



| | |
|----------------------------------|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| Backside view from the Southside | |
| johngw_20090720_33.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------------------------|------------------|--------------------------|--------------------|
| Knights Landing Outfall Structure | | 07/16/2009 07/16/2009 | John Williamson |

| | |
|---|-------------------------|
| Levee Mile Report Line | 13 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Electric Gate Operators |
| Telephone cable laying on ground running towards control room | |
| johngw_20090720_34.jpg | |



| | |
|---|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| vertical crack Northside has not changed from pervious inspection | |
| johngw_20090720_36.jpg | |



| | |
|----------------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| vertical crack Southside montior | |
| johngw_20090720_37.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------------------------|------------------|--------------------------|--------------------|
| Knights Landing Outfall Structure | | 07/16/2009 07/16/2009 | John Williamson |

| | |
|-------------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| view from the bank downstream | |
| johngw_20090720_38.jpg | |



| | |
|---|----------------------|
| Levee Mile Report Line | 21 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Other Metallic Items |
| flap gate outlet side some rust on metal surfaces | |
| johngw_20090720_35.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

DWR Sacramento Maintenance Yard

| |
|--------------|
| Structure |
| Paradise Dam |

| | |
|--------------------|-------------|
| Structure Rating | M |
| Date of Inspection | 7/15/2009 |
| DWR Inspector | John Paasch |
| Accompanied By | |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|----------------------|-------------|
| Paradise Dam | | 07/21/2009 | John Paasch |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-----------------------------------|----------|--------|---|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 1 | 0.00 | 0.00 | Structures | Photo Documentation | | C | | ° | ° | | 1 |
| 2 | 0.00 | 0.00 | Structures | Vegetation & Obstructions | | M | Inspector Comments: Dense vegetation exists on San Joaquin River side of earthen dam. | ° | ° | Y | 2 |
| 3 | 0.00 | 0.00 | Structures | Shoaling / Sedimentation | | A | Inspector Comments: No shoaling or sedimentation present. | ° | ° | | 3 |
| 4 | 0.00 | 0.00 | Structures | Erosion / Bank Caving | | A | Inspector Comments: No active erosion or bank caving observed that would threaten function of the dam. | ° | ° | | 4 |
| 5 | 0.00 | 0.00 | Structures | Revetments | | A | Inspector Comments: Additional riprap stockpiled onsite. | ° | ° | | 5 |
| 6 | 0.00 | 0.00 | Structures | Encroachments | | A | Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area. | ° | ° | | 6 |
| 7 | 0.00 | 0.00 | Structures | Culverts: Inlets / Outlets | | N | | ° | ° | | 7 |
| 8 | 0.00 | 0.00 | Structures | Culverts: Breaks / Holes / Cracks | | N | | ° | ° | | 8 |
| 9 | 0.00 | 0.00 | Structures | Metal Pipes | | N | | ° | ° | | 9 |
| 10 | 0.00 | 0.00 | Structures | Trash Racks | | N | | ° | ° | | 10 |
| 11 | 0.00 | 0.00 | Structures | Flap Gates | | N | | ° | ° | | 11 |
| 12 | 0.00 | 0.00 | Structures | Sluice/Slide Gates | | N | | ° | ° | | 12 |
| 13 | 0.00 | 0.00 | Structures | Electric Gate Operators | | N | | ° | ° | | 13 |
| 14 | 0.00 | 0.00 | Structures | Manual Gate Operators | | N | | ° | ° | | 14 |
| 15 | 0.00 | 0.00 | Structures | Concrete Surfaces | | A | Inspector Comments: Negligible spalling, scaling or cracking. | ° | ° | | 15 |

| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|----------------------|-------------|
| Paradise Dam | | 07/21/2009 | John Paasch |

| LMR No. | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-------------------------------|------------|-----------|---|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 16 | 0.00 | 0.00 | Structures | Concrete Tilting / Settlement | | A | Inspector Comments: There are no significant areas of tilting, sliding or settlement that would endanger the integrity of the project. | ° | ° | | 16 |
| 17 | 0.00 | 0.00 | Structures | Concrete Foundations | | M | Inspector Comments: Minor scouring beneath asphalt dam surface evident. | ° | ° | Y | 17 |
| 18 | 0.00 | 0.00 | Structures | Security Fencing | | N | | ° | ° | | 18 |
| 19 | 0.00 | 0.00 | Structures | Closure Structures | | N | | ° | ° | | 19 |
| 20 | 0.00 | 0.00 | Structures | Trash Rakes | | N | | ° | ° | | 20 |
| 21 | 0.00 | 0.00 | Structures | Other Metallic Items | | N | | ° | ° | | 21 |
| 22 | 0.00 | 0.00 | Structures | Monolith Joints | | N | | ° | ° | | 22 |
| 23 | 0.00 | 0.00 | Structures | Safety | | M | Inspector Comments: Minor safety hazards are present, but do not pose an immediate threat to the structure or personnel at the structure. | ° | ° | | 23 |

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|--------------|------------------|----------------------|-------------|
| Paradise Dam | | 07/21/2009 | John Paasch |

| | |
|--|---------------------------|
| Levee Mile Report Line | 2 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Vegetation & Obstructions |
| Paradise Dam as viewed from RD 2107. Paradise Cut to right, San Joaquin River to left (beyond extents of photo). | |
| jpaasch_20090722_8.jpg | |



| | |
|--|----------------------|
| Levee Mile Report Line | 17 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Foundations |
| Close up of dam surface shows asphalt and large granite rip-rap. | |
| jpaasch_20090722_9.jpg | |



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p> |
|---|---|

Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

DWR Sacramento Maintenance Yard

| |
|-----------------|
| Structure |
| Sacramento Weir |

| | |
|--------------------|-----------------|
| Structure Rating | A |
| Date of Inspection | 7/7/2009 |
| DWR Inspector | John Williamson |
| Accompanied By | |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|-----------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|-----------------------------------|------------|-----------|---|------------------------|-------------|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 1 | 0.00 | 0.00 | Structures | Photo Documentation | | | Inspector Comments: north end of Sac. Weir 38.60712 - 121.56010, south end of Sac. Weir 38.60285 -121.55579 | 38.607120 ° | 38.602850 ° | Y | 1 |
| 2 | 0.00 | 0.00 | Structures | Vegetation & Obstructions | | A | | ° | ° | | 2 |
| 3 | 0.00 | 0.00 | Structures | Shoaling / Sedimentation | | A | Inspector Comments: from weir to waters edge is scheduled for removal of sediment this year if budget will allow. | ° | ° | | 3 |
| 4 | 0.00 | 0.00 | Structures | Erosion / Bank Caving | | A | | ° | ° | | 4 |
| 5 | 0.00 | 0.00 | Structures | Revetments | | N | | ° | ° | | 5 |
| 6 | 0.00 | 0.00 | Structures | Encroachments | | M | Inspector Comments: encroachment is a homeless person living during the summer | ° | ° | Y | 6 |
| 7 | 0.00 | 0.00 | Structures | Culverts: Inlets / Outlets | | N | | ° | ° | | 7 |
| 8 | 0.00 | 0.00 | Structures | Culverts: Breaks / Holes / Cracks | | N | | ° | ° | | 8 |
| 9 | 0.00 | 0.00 | Structures | Metal Pipes | | N | | ° | ° | | 9 |
| 10 | 0.00 | 0.00 | Structures | Trash Racks | | N | | ° | ° | | 10 |
| 11 | 0.00 | 0.00 | Structures | Flap Gates | | N | | ° | ° | | 11 |
| 12 | 0.00 | 0.00 | Structures | Sluice/Slide Gates | | N | | ° | ° | | 12 |
| 13 | 0.00 | 0.00 | Structures | Electric Gate Operators | | N | | ° | ° | | 13 |
| 14 | 0.00 | 0.00 | Structures | Manual Gate Operators | | N | | ° | ° | | 14 |
| 15 | 0.00 | 0.00 | Structures | Concrete Surfaces | | | Inspector Comments: bay 24 has two defusers all other bays have three | ° | ° | Y | 15 |
| 16 | 0.00 | 0.00 | Structures | Concrete Tilting / Settlement | | N | | ° | ° | | 16 |

| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|-----------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| LMR No. | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Photo | Issue No. |
|---------|------------|------|------------|----------------------|------------|-----------|---|------------------------|-----|-------|-----------|
| | Start | End | | | | | | Start | End | | |
| 17 | 0.00 | 0.00 | Structures | Concrete Foundations | | A | | ° | ° | | 17 |
| 18 | 0.00 | 0.00 | Structures | Security Fencing | | A | | ° | ° | | 18 |
| 19 | 0.00 | 0.00 | Structures | Closure Structures | | N | | ° | ° | | 19 |
| 20 | 0.00 | 0.00 | Structures | Trash Rakes | | N | | ° | ° | | 20 |
| 21 | 0.00 | 0.00 | Structures | Other Metallic Items | | A | | ° | ° | | 21 |
| 22 | 0.00 | 0.00 | Structures | Monolith Joints | | A | | ° | ° | | 22 |
| 23 | 0.00 | 0.00 | Structures | Safety | | A | Inspector Comments: all safety equipment is kept at yard and brought out every time work is to be preformed. There is no place to store safety equipment at site. | ° | ° | | 23 |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|--------------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|--|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| view downstream north side of weie bays 1-10, 38.60712 -121.56010 | |
| johngw_20090716_17.jpg | |



| | |
|---|---------------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Photo Documentation |
| view south end bays 39-47 38.60285 - 121.55579 | |
| johngw_20090716_18.jpg | |



| | |
|----------------------------------|---------------|
| Levee Mile Report Line | 6 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Encroachments |
| propane bottles and trash bay 10 | |
| johngw_20090716_19.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|--------------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 6 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Encroachments |
| homeless camp bay 9 | |
| johngw_20090716_20.jpg | |



| | |
|------------------------|---------------|
| Levee Mile Report Line | 6 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Encroachments |
| garden on water side | |
| johngw_20090716_21.jpg | |



| | |
|------------------------------|---------------|
| Levee Mile Report Line | 6 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Encroachments |
| more of the garden waterside | |
| johngw_20090716_22.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|--------------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 48 | |
| johngw_20090716_23.jpg | |



| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 33 | |
| johngw_20090716_24.jpg | |



| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 31 | |
| johngw_20090716_25.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009

DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|--------------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 31 | |
| johngw_20090716_26.jpg | |



| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 20 | |
| johngw_20090716_27.jpg | |



| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 14 | |
| johngw_20090716_28.jpg | |



| | | |
|--|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected |
|--|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2009


DWR Sacramento Maintenance Yard

| Structure | Structure Length | Inspection Start/End | Inspector |
|-----------------|------------------|--------------------------|--------------------|
| Sacramento Weir | | 07/15/2009 07/15/2009 | John Williamson |

| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay 14 | |
| johngw_20090716_29.jpg | |



| | |
|------------------------|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 0.00 |
| Location | |
| Category | Structures |
| Item | Concrete Surfaces |
| bay14 | |
| johngw_20090716_30.jpg | |



| | | |
|---|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> |
|---|---|---|