

**Flood Control Project Maintenance
Levee Inspections**

2015 Channel Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	M *
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

Flood Control Project Maintenance

Unit Cover Sheet

2015 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Big Chico Creek

Channel Rating	A
Date of Inspection	06/10/2015 - 06/11/2015
DWR Inspector	Michael Pitta
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Big Chico Creek Control Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_1_20150728_00013.jpg



View of the channel from the structure facing upstream.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_3		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Big Chico Creek Control Structure / Up (cont)			
Rating **	A	Issue No.	4
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_4		
Action/Comments			
Inspector Comments: Riprap is visible and appears properly maintained.			

No Photos

Rating **	A	Issue No.	5
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Big Chico Creek Control Structure / Down			
Rating **	A	Issue No.	6
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_6		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_6_20150728_00014.jpg



View of the downstream side of the channel from the structure.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Big Chico Creek Control Structure / Down (cont)			
Rating **	A	Issue No.	7
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_7		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	8
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_8		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	A	Issue No.	9
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_9		
Action/Comments			
Inspector Comments: Riprap is visible and appears properly maintained.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Big Chico Creek Control Structure / Down (cont)			
Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_10		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Manzanita Ave. / Up			
Rating **	A	Issue No.	11
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_11		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_11_20150610_00003.jpg



This photo is looking upstream on Manzanita Ave.

Rating **	A	Issue No.	12
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_12		
Action/Comments			
Inspector Comments: Shoaling or sedimentation was observed. Does not seem to impede flow.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Manzanita Ave. / Up (cont)				
Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_14			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Manzanita Ave. / Down				
Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_5_16_20150610_00004.jpg



This photo is looking downstream on Manzanita Ave.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Manzanita Ave. / Down (cont)				
Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_18			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_19			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Manzanita Ave. / Down (cont)				
Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 99 Bridge / Up				
Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_21			
Action/Comments				
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_5_21_20150812_00021.jpg



View of the channel from under Highway 99 facing upstream.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Hwy 99 Bridge / Up (cont)			
Rating **	A	Issue No. 23	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_23		
Action/Comments			
Inspector Comments: No erosion present.			

No Photos

Rating **	A	Issue No. 24	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_24		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No. 25	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_25		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Hwy 99 Bridge / Down				
Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_26			
Action/Comments				
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_5_26_20150812_00022.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_28			
Action/Comments				
Inspector Comments: No erosion present.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Hwy 99 Bridge / Down (cont)				
Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_29			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

Photo 1 of 1 : CH_2015_NA0060_5_29_20150812_00023.jpg



View of the type of riprap that lines the channel.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Up			
Rating **	A	Issue No.	31
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_31		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_31_20150812_00020.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	32
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_32		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	33
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_33		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Up (cont)			
Rating **	N	Issue No.	34
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_34		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No.	35
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_35		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Esplanade / Down			
Rating **	A	Issue No.	36
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_36		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_36_20150812_00019.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				GPS Lat/Long	No Photos
Esplanade / Down (cont)					
Rating **	A	Issue No.	37		
Issue Type +	Ma	Location *		39.731810 °	
Category	Rivers, Channels & Designated Flood			-121.841870 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0060_5_c_2012_37				
Action/Comments					
Inspector Comments: No shoaling or sedimentation observed.					

Rating **	A	Issue No.	38	GPS Lat/Long	
Issue Type +	Ma	Location *		39.731810 °	No Photos
Category	Rivers, Channels & Designated Flood			-121.841870 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0060_5_c_2012_38				
Action/Comments					
Inspector Comments: No erosion observed.					

Rating **	N	Issue No.	39	GPS Lat/Long	
Issue Type +	Ma	Location *		39.731810 °	No Photos
Category	Rivers, Channels & Designated Flood			-121.841870 °	
Item	Revetments				
DWR ID	DWR_NA0060_5_c_2012_39				
Action/Comments					
Inspector Comments: No revetments present.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Down (cont)			
Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_40		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Hwy 32 / Up			
Rating **	A	Issue No.	41
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_41		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_41_20150812_00017.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	42
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_42		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Hwy 32 / Up (cont)			
Rating **	A	Issue No.	43
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_43		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	A	Issue No.	44
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_44		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No.	45
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_45		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Hwy 32 / Down				
Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_46			
Action/Comments				
Inspector Comments: Moderate vegetation on north bank. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_5_46_20150812_00018.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_48			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_49			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_50			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Mud Creek at River Rd / Up				
Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_51			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_5_51_20150812_00015.jpg



View of Mud Creek at River Road facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View

Mud Creek at River Rd / Up (cont)

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	M	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_54			
Action/Comments				
Inspector Comments: Riprap is covered with vegetation.				

No Photos

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_55			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Mud Creek at River Rd / Down			
Rating **	A	Issue No.	56
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_56		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_5_56_20150812_00016.jpg



View of Mud Creek at River Road facing downstream.

Rating **	A	Issue No.	57
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_57		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	53
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_53		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Mud Creek at River Rd / Down (cont)				
Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_58			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_59			
Action/Comments				
Inspector Comments: Riprap is covered with vegetation.				

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_60			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance

Unit Cover Sheet

2015 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Lindo Channel & Sandy Gulch

Channel Rating	A
Date of Inspection	06/10/2015 - 06/11/2015
DWR Inspector	Michael Pitta
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Diversion Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and small trees. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_1_20150821_00039.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_3		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Diversion Structure / Up (cont)			
Rating **	N	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_4		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Diversion Structure / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_6		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_6_20150821_00040.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Diversion Structure / Down (cont)			
Rating **	A	Issue No. 7	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_7		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 8	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_8		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	N	Issue No. 9	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_9		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Diversion Structure / Down (cont)			
Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_10		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Manzanita Ave / Up			
Rating **	A	Issue No.	11
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_11		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_11_20150821_00041.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	12
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_12		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				GPS Lat/Long	No Photos
Manzanita Ave / Up (cont)					
Rating **	A	Issue No.	13		
Issue Type +	Ma	Location *		39.760390 °	
Category	Rivers, Channels & Designated Flood			-121.801621 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0060_6_c_2012_13				
Action/Comments					
Inspector Comments: No head cutting or horizontal deviation observed.					

				GPS Lat/Long	No Photos
Rating **	N	Issue No.	14		
Issue Type +	Ma	Location *		39.760390 °	
Category	Rivers, Channels & Designated Flood			-121.801621 °	
Item	Revetments				
DWR ID	DWR_NA0060_6_c_2012_14				
Action/Comments					
Inspector Comments: This item does not apply to this inspection.					

				GPS Lat/Long	No Photos
Rating **	A	Issue No.	15		
Issue Type +	Ma	Location *		39.760390 °	
Category	Rivers, Channels & Designated Flood			-121.801621 °	
Item	Encroachments				
DWR ID	DWR_NA0060_6_c_2012_15				
Action/Comments					
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Manzanita Ave / Down			
Rating **	A	Issue No.	16
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_16_20150821_00042.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	17
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	18
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_18		
Action/Comments			
Inspector Comments: Some head cutting or horizontal deviation observed due to high water in past years.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Manzanita Ave / Down (cont)			
Rating **	N	Issue No.	19
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_19		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_20		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Bike Path Bridge at Madrone Ave / Up			
Rating **	A	Issue No.	21
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_21		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_21_20150821_00044.jpg



View of the channel facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				GPS Lat/Long	No Photos
Bike Path Bridge at Madrone Ave / Up (cont)					
Rating **	A	Issue No.	22		
Issue Type +	Ma	Location *		39.755400 °	
Category	Rivers, Channels & Designated Flood			-121.814580 °	
Item	Shoaling / Sedimentation				
DWR ID	DWR_NA0060_6_c_2012_22				
Action/Comments					
Inspector Comments: Minimal shoaling or sedimentation observed.					

Rating **	A	Issue No.	23	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.755400 °	
Category	Rivers, Channels & Designated Flood			-121.814580 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0060_6_c_2012_23				
Action/Comments					
Inspector Comments: No head cutting or horizontal deviation observed.					

Rating **	A	Issue No.	24	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.755400 °	
Category	Rivers, Channels & Designated Flood			-121.814580 °	
Item	Revetments				
DWR ID	DWR_NA0060_6_c_2012_24				
Action/Comments					
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the integrity and capacity of the channel is not affected.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Bike Path Bridge at Madrone Ave / Up (cont)			
Rating **	A	Issue No.	25
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_25		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Bike Path Bridge at Madrone Ave / Down			
Rating **	A	Issue No.	26
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_26		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_26_20150821_00043.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View

Bike Path Bridge at Madrone Ave / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_28			
Action/Comments				
Inspector Comments: There is some minor bank erosion.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_29			
Action/Comments				
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the capacity of the channel is not affected.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Mariposa Ave / Up				
Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				



View of the channel facing upstream.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_32			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_33			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Mariposa Ave / Up (cont)			
Rating **	N	Issue No. 34	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_34		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No. 35	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_35		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Mariposa Ave / Down			
Rating **	A	Issue No. 36	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_36		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_36_20150821_00046.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Mariposa Ave / Down (cont)				
Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_37			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed, but the flow is not impeded.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Mariposa Ave / Down (cont)				
Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_40			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
5th Ave / Up				
Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_41			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2015_NA0060_6_41_20150821_00047.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_42			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed, but doesn't impede the flow of the channel.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
5th Ave / Up (cont)				
Rating **	M	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_43			
Action/Comments				
Inspector Comments: Erosion around bridge footing and south bank of channel.				

Photo 1 of 1 : CH_2015_NA0060_6_43_20150821_00051.jpg



View of the erosion found under the bridge.

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_44			
Action/Comments				
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. Riprap clearly visible				

No Photos

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_45			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
5th Ave / Down			
Rating **	A	Issue No.	46
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_46		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_46_20150821_00048.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	47
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_47		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation present, but the flow is not impeded.			

No Photos

Rating **	M	Issue No.	48
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_48		
Action/Comments			
Inspector Comments: Erosion around bridge footing and south bank of channel.			

Photo 1 of 2 : CH_2015_NA0060_6_48_20150610_00011.jpg



Erosion around bridge footing and south bank of channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
5th Ave / Down (cont)			
Rating **	M	Issue No. 48 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_48		
Action/Comments			
Inspector Comments: Erosion around bridge footing and south bank of channel.			

Photo 2 of 2 : CH_2015_NA0060_6_48_20150610_00012.jpg



Erosion around bridge footing and south bank of channel.

Rating **	A	Issue No. 49	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_49		
Action/Comments			
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No. 50	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_50		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Highway 99 / Up				
Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_91			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				



View of the channel facing upstream.

Rating **	A	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_92			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_93			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Highway 99 / Up (cont)			
Rating **	A	Issue No.	94
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_94		
Action/Comments			
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No.	95
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_95		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Highway 99 / Down			
Rating **	A	Issue No.	96
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_96		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_96_20150821_00050.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Highway 99 / Down (cont)				
Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_97			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_98			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_99			
Action/Comments				
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Highway 99 / Down (cont)			
Rating **	A	Issue No.	100
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_100		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Mangrove Avenue / Up			
Rating **	A	Issue No.	111
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_111		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_111_20150820_00030.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	112
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2015_112		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Mangrove Avenue / Up (cont)				
Rating **	A	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_113			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	114	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_114			
Action/Comments				
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	115	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_115			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Mangrove Avenue / Down			
Rating **	M	Issue No.	116
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.750979 °
Item	Vegetation & Obstructions		-121.844711 °
DWR ID	DWR_NA0060_6_c_2015_116		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation may impede the flow of the channel.			

Photo 1 of 1 : CH_2015_NA0060_6_116_20150820_00029.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	117
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.750979 °
Item	Shoaling / Sedimentation		-121.844711 °
DWR ID	DWR_NA0060_6_c_2015_117		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	118
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.750979 °
Item	Erosion / Bank Caving		-121.844711 °
DWR ID	DWR_NA0060_6_c_2015_118		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Mangrove Avenue / Down (cont)			
Rating **	A	Issue No. 119	GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_119		
Action/Comments			
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No. 120	GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_120		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Esplanade / Up			
Rating **	A	Issue No. 51	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_51		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_51_20150821_00033.jpg



View of the channel facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Up (cont)			
Rating **	A	Issue No.	57
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_57		
Action/Comments			
Inspector Comments: Shoaling present on the upstream side underneath the bike crossing bridge, but it doesn't affect the channel capacity.			

No Photos

Rating **	A	Issue No.	53
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_53		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed. Cracking on south wing wall observed.			

Photo 1 of 1 : CH_2015_NA0060_6_53_20150821_00034.jpg



View of the cracking on south wing wall.

Rating **	N	Issue No.	54
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_54		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Up (cont)			
Rating **	A	Issue No.	55
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_55		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Esplanade / Down			
Rating **	A	Issue No.	56
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_56		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_56_20150821_00031.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	52
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2013_52		
Action/Comments			
Inspector Comments: Minimal shoaling and sedimentation present.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Esplanade / Down (cont)			
Rating **	A	Issue No.	58
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.749458 °
Item	Erosion / Bank Caving		-121.854296 °
DWR ID	DWR_NA0060_6_c_2012_58		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed both there are cracks in the south wing wall.			

Photo 1 of 1 : CH_2015_NA0060_6_58_20150821_00032.jpg



View of cracks on south wing wall.

Rating **	N	Issue No.	59
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.749458 °
Item	Revetments		-121.854296 °
DWR ID	DWR_NA0060_6_c_2012_59		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No.	60
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.749458 °
Item	Encroachments		-121.854296 °
DWR ID	DWR_NA0060_6_c_2012_60		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Holly Avenue / Up			
Rating **	A	Issue No.	101
			GPS Lat/Long
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_101		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_101_20150821_00036.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_102			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_103			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Holly Avenue / Up (cont)			
Rating **	N	Issue No.	104
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_104		
Action/Comments			
Inspector Comments: This item does not apply to this inspection.			

No Photos

Rating **	A	Issue No.	105
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_105		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Holly Avenue / Down			
Rating **	A	Issue No.	106
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_106		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_6_106_20150821_00037.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Holly Avenue / Down (cont)				
Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_107			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				
No Photos				

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_108			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				
No Photos				

Rating **	N	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_109			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				
No Photos				

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Holly Avenue / Down (cont)				
Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_110			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 32 / Up				
Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_61			
Action/Comments				
Inspector Comments: Vegetation exists but does not impede the flow.				

Photo 1 of 1 : CH_2015_NA0060_6_61_20150820_00028.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_63			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				
No Photos				

Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_64			
Action/Comments				
Inspector Comments: Revetment is present but due to vegetation not all of it is visible.				
No Photos				

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_65			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				
No Photos				

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Hwy 32 / Down			
Rating **	A	Issue No. 66	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_66		
Action/Comments			
Inspector Comments: Vegetation exists but does not impede the flow.			

Photo 1 of 1 : CH_2015_NA0060_6_66_20150820_00027.jpg



View of the channel facing downstream.

Rating **	A	Issue No. 67	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_67		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 68	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_68		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Hwy 32 / Down (cont)			
Rating **	A	Issue No.	69
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_69		
Action/Comments			
Inspector Comments: Revetment is present but due to vegetation not all of it is visible.			

No Photos

Rating **	A	Issue No.	70
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_70		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Oak Ave. / Up			
Rating **	M	Issue No.	71
Issue Type +	Ma	Location *	39.735560 °
Category	Rivers, Channels & Designated Flood		-121.890970 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_71		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation.			

Photo 1 of 1 : CH_2015_NA0060_6_71_20150820_00026.jpg



View of the channel facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				
No Photos				

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_73			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				
No Photos				

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			
Action/Comments				
Inspector Comments: No revetments present.				
No Photos				

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_75			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Oak Ave. / Down				
Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_76			
Action/Comments				
Inspector Comments: scattered obstructions and vegetation, but doesn't impede the flow.				

Photo 1 of 1 : CH_2015_NA0060_6_76_20150820_00025.jpg



View of the channel facing downstream.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				No Photos
Oak Ave. / Down (cont)				
Rating **	A	Issue No.	78	No Photos
Issue Type +	Ma	Location *	39.735560 °	
Category	Rivers, Channels & Designated Flood		-121.890970 °	
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_78			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

Rating **	N	Issue No.	79	No Photos
Issue Type +	Ma	Location *	39.735560 °	
Category	Rivers, Channels & Designated Flood		-121.890970 °	
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_79			
Action/Comments				
Inspector Comments: No revetments present.				

Rating **	A	Issue No.	80	No Photos
Issue Type +	Ma	Location *	39.735560 °	
Category	Rivers, Channels & Designated Flood		-121.890970 °	
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_80			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Grape Way / Up				
Rating **	A	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_81			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation, but doesn't impede the flow.				

Photo 1 of 1 : CH_2015_NA0060_6_81_20150820_00024.jpg



View of the channel facing upstream.

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_82			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_83			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Grape Way / Up (cont)				
Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_84			
Action/Comments				
Inspector Comments: Revetments are in place and maintained properly.				

No Photos

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_85			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Grape Way / Down				
Rating **	A	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_86			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation, but doesn't impede the flow of the channel.				

Photo 1 of 1 : CH_2015_NA0060_6_86_20150820_00023.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Grape Way / Down (cont)				
Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_87			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				
No Photos				

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_88			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				
No Photos				

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_89			
Action/Comments				
Inspector Comments: Revetments are in place and maintained properly.				
No Photos				

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Grape Way / Down (cont)			
Rating **	A	Issue No.	90
Issue Type +	Ma	Location *	39.722724 °
Category	Rivers, Channels & Designated Flood		-121.912363 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_90		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			
No Photos			

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

Flood Control Project Maintenance
Unit Cover Sheet
2015 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Little Chico Creek

Channel Rating	M *
Date of Inspection	06/10/2015 - 06/11/2015
DWR Inspector	Michael Pitta
Accompanied By	

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Little Chico Ck Control Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2015_NA0060_12_1_20150610_00001.jpg



This is the upstream side at the Little Chico Control Structure.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_2		
Action/Comments			
Inspector Comments: There is shoaling and sedimentation, the flow is not impeded.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_3		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Little Chico Ck Control Structure / Up (cont)			
Rating **	A	Issue No.	4
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2013_4		
Action/Comments			
Inspector Comments: Unwanted vegetation needs to be removed.			

No Photos

Rating **	A	Issue No.	5
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_5		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Little Chico Ck Control Structure / Down			
Rating **	M	Issue No.	6
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_6		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded. Willow trees should be removed in the future.			

Photo 1 of 2 : CH_2015_NA0060_12_6_20150728_00038.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Little Chico Ck Control Structure / Down (cont)				
Rating **	M	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_6			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded. Willow trees should be removed in the future.				

Photo 2 of 2 : CH_2015_NA0060_12_6_20150610_00002.jpg



This photo is looking downstream from the control structure during 2014 inspection.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_7			
Action/Comments				
Inspector Comments: There is shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Little Chico Ck Control Structure / Down (cont)			
Rating **	A	Issue No.	9
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_9		
Action/Comments			
Inspector Comments: Unwanted vegetation needs to be removed.			

No Photos

Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_10		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Bruce Rd / Up			
Rating **	M	Issue No.	11
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_11		
Action/Comments			
Inspector Comments: The vegetation obstructed the view of the channel. Flow may be impeded in the high water event.			

Photo 1 of 1 : CH_2015_NA0060_12_11_20150728_00039.jpg



Photo of the channel facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Bruce Rd / Up (cont)				
Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed. The vegetation in the channel obstructed the view.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_13			
Action/Comments				
Inspector Comments: No erosion observed. Vegetation obstructed the view.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_14			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Bruce Rd / Up (cont)				
Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_15			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area. The vegetation obstructed the view.				

No Photos

Check Point / View				
Bruce Rd / Down				
Rating **	U	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_16			
Action/Comments				
Inspector Comments: The vegetation obstructed the view of the channel. Flow may be impeded in high water.				

Photo 1 of 1 : CH_2015_NA0060_12_16_20150728_00040.jpg



Photo of the channel from the bridge facing downstream.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed. The vegetation in the channel obstructed the view.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Bruce Rd / Down (cont)			
Rating **	A	Issue No.	18
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c _ 2012_18		
Action/Comments			
Inspector Comments: No erosion observed. Vegetation obstructed the view.			

No Photos

Rating **	N	Issue No.	19
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c _ 2012_19		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c _ 2012_20		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area. The vegetation obstructed the view.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Forest Ave / Up			
Rating **	A	Issue No.	21
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_21		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow does not appear impeded.			

Photo 1 of 1 : CH_2015_NA0060_12_21_20150724_00031.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No.	22
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_22		
Action/Comments			
Inspector Comments: Shoaling or sedimentation present, the flow is not impeded.			

No Photos

Rating **	M	Issue No.	23
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_23		
Action/Comments			
Inspector Comments: Moderate erosion on north bank.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Forest Ave / Up (cont)			
Rating **	N	Issue No.	24
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_24		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No.	25
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_25		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Forest Ave / Down			
Rating **	M	Issue No.	26
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_26		
Action/Comments			
Inspector Comments: Moderate vegetation observed. Flow may be obstructed in high water.			

Photo 1 of 1 : CH_2015_NA0060_12_26_20150724_00033.jpg



View of the channel from the bridge facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Forest Ave / Down (cont)			
Rating **	A	Issue No.	27
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_27		
Action/Comments			
Inspector Comments: Shoaling or sedimentation present, the flow does not appear impeded.			

No Photos

Rating **	A	Issue No.	28
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_28		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	N	Issue No.	29
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_29		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Forest Ave / Down (cont)				
Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Repair site upstream of Hwy 99 / Up				
Rating **	M	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_31			
Action/Comments				
Inspector Comments: Scattered vegetation. The flow does not appear impeded.				

Photo 1 of 2 : CH_2015_NA0060_12_31_20150724_00034.jpg



View of the material used in the erosion repair site.

Photo 2 of 2 : CH_2015_NA0060_12_31_20150724_00035.jpg



View of the upstream side of the erosion repair site .

Rating **	M	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_31			

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View
Repair site upstream of Hwy 99 / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_33			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_34			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Repair site upstream of Hwy 99 / Up (cont)			
Rating **	A	Issue No.	35
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_35		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Repair site upstream of Hwy 99 / Down			
Rating **	M	Issue No.	36
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_36		
Action/Comments			
Inspector Comments: There is vegetation in the channel, the flow may be impeded in high water.			

Photo 1 of 1 : CH_2015_NA0060_12_36_20150724_00037.jpg



View of the downstream side of the erosion repair site.

Rating **	A	Issue No.	37
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_37		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Repair site upstream of Hwy 99 / Down (cont)				
Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_38			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_39			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_40			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Bruce Street / Up				
Rating **	M	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_82			
Action/Comments				
Inspector Comments: There is vegetation in the channel and it appears to potentially impede the flow.				

Photo 1 of 1 : CH_2015_NA0060_12_82_20150724_00017.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_85			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed at this location.				

No Photos

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_84			
Action/Comments				
Inspector Comments: No erosion was observed at this location.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Bruce Street / Up (cont)			
Rating **	N	Issue No.	88
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_88		
Action/Comments			
Inspector Comments: No riprap was observed.			

No Photos

Rating **	N	Issue No.	87
Issue Type +	--	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2015_87		
Action/Comments			
Inspector Comments: No encroachments were observed.			

No Photos

Check Point / View			
Bruce Street / Down			
Rating **	A	Issue No.	89
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_89		
Action/Comments			
Inspector Comments: Channel was free of vegetation.			

Photo 1 of 1 : CH_2015_NA0060_12_89_20150724_00018.jpg



View of the channel from the bridge facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Bruce Street / Down (cont)				
Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_90			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_91			
Action/Comments				
Inspector Comments: No erosion was observed.				

No Photos

Rating **	N	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_92			
Action/Comments				
Inspector Comments: No riprap was observed at this location.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Bruce Street / Down (cont)				
Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_93			
Action/Comments				
Inspector Comments: No encroachments were observed.				

No Photos

Check Point / View				
Boucher St / Up				
Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_41			
Action/Comments				
Inspector Comments: There is vegetation in the channel and overhanging the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2015_NA0060_12_41_20150724_00020.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_42			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Boucher St / Up (cont)			
Rating **	A	Issue No.	43
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_43		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	N	Issue No.	44
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_44		
Action/Comments			
Inspector Comments: There was no riprap observed at this site.			

No Photos

Rating **	A	Issue No.	45
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_45		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Boucher St / Down				
Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_46			
Action/Comments				
Inspector Comments: There is vegetation in the channel, overhanging the channel, and arundo. The flow does appear slightly impeded.				

Photo 1 of 1 : CH_2015_NA0060_12_46_20150724_00019.jpg



View of the channel from the bridge facing downstream.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_48			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Boucher St / Down (cont)			
Rating **	N	Issue No.	49
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_49		
Action/Comments			
Inspector Comments: No riprap observed of this site.			

No Photos

Rating **	A	Issue No.	50
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_50		
Action/Comments			
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Olive St / Up			
Rating **	A	Issue No.	51
Issue Type +	Ma	Location *	39.726792 °
Category	Rivers, Channels & Designated Flood		-121.829713 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_51		
Action/Comments			
Inspector Comments: There is vegetation in the channel, it does not appear to impeded the flow.			

Photo 1 of 1 : CH_2015_NA0060_12_51_20150724_00021.jpg



View of the channel from the bridge facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Olive St / Up (cont)				
Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_53			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_54			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Olive St / Up (cont)				
Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_55			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Olive St / Down				
Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_56			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2015_NA0060_12_56_20150724_00022.jpg



View of the channel from the bridge facing downstream.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_57			
Action/Comments				
Inspector Comments: There is minimal sedimentation in the channel, the flow does not appear impeded.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View

Olive St / Down (cont)

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_58			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_59			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

Rating **	M	Issue No.	60	GPS Lat/Long
Issue Type +	En	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_60			
Action/Comments				
Inspector Comments: There is a structure on the right bank of the channel, no permit found.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Broadway St / Up			
Rating **	A	Issue No. 61	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_61		
Action/Comments			
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.			

Photo 1 of 1 : CH_2015_NA0060_12_61_20150724_00023.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No. 62	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_62		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 63	GPS Lat/Long
Issue Type +	Ob	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_63		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Broadway St / Up (cont)			
Rating **	N	Issue No.	64
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_64		
Action/Comments			
Inspector Comments: No riprap observed.			

No Photos

Rating **	A	Issue No.	65
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_65		
Action/Comments			
Inspector Comments: No encroachments observed at this site.			

No Photos

Check Point / View			
Broadway St / Down			
Rating **	A	Issue No.	66
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_66		
Action/Comments			
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.			

Photo 1 of 1 : CH_2015_NA0060_12_66_20150724_00024.jpg



View of the channel from the bridge facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Broadway St / Down (cont)				
Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_67			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_68			
Action/Comments				
Inspector Comments: No erosion observed at this site.				

No Photos

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_69			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Broadway St / Down (cont)				
Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2013_70			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

Check Point / View				
Ivy Street / Up				
Rating **	A	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2015_94			
Action/Comments				
Inspector Comments: Vegetation is present in the channel. The flow does not appear to be impeded.				

Photo 1 of 1 : CH_2015_NA0060_12_94_20150724_00025.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_95			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed at this location.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Ivy Street / Up (cont)			
Rating **	A	Issue No.	96
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_96		
Action/Comments			
Inspector Comments: No erosion was observed.			

No Photos

Rating **	N	Issue No.	97
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_97		
Action/Comments			
Inspector Comments: No riprap was observed.			

No Photos

Rating **	A	Issue No.	98
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2015_98		
Action/Comments			
Inspector Comments: The channel appeared to be free of encroachments.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Ivy Street / Down			
Rating **	A	Issue No.	99
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_99		
Action/Comments			
Inspector Comments: The channel appeared to be free of any vegetation that would impede the flow.			

Photo 1 of 1 : CH_2015_NA0060_12_99_20150724_00026.jpg



View of the channel from the bridge facing downstream.

Rating **	A	Issue No.	100
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2015_100		
Action/Comments			
Inspector Comments: No shoaling or sedimentation was observed.			

No Photos

Rating **	A	Issue No.	101
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_101		
Action/Comments			
Inspector Comments: No erosion was observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Ivy Street / Down (cont)			
Rating **	N	Issue No.	102
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_102		
Action/Comments			
Inspector Comments: No riprap was observed.			

No Photos

Rating **	A	Issue No.	103
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2015_103		
Action/Comments			
Inspector Comments: The channel appeared free of encroachments.			

No Photos

Check Point / View			
Walnut Street / Up			
Rating **	A	Issue No.	104
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_104		
Action/Comments			
Inspector Comments: The channel appeared to be free of any vegetation that would impede the flow.			

Photo 1 of 1 : CH_2015_NA0060_12_104_20150724_00027.jpg



View of the channel from the bridge facing upstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View

Walnut Street / Up (cont)

Rating **	A	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_105			

No Photos

Action/Comments

Inspector Comments: No shoaling or sedimentation was observed.

Rating **	A	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_106			

No Photos

Action/Comments

Inspector Comments: No erosion was observed.

Rating **	N	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_107			

No Photos

Action/Comments

Inspector Comments: No riprap was observed

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Walnut Street / Up (cont)				
Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_108			
Action/Comments				
Inspector Comments: The channel appeared free of encroachments.				

No Photos

Check Point / View				
Walnut Street / Down				
Rating **	A	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_109			
Action/Comments				
Inspector Comments: The channel appeared free of any vegetation that would impede the flow.				

Photo 1 of 1 : CH_2015_NA0060_12_109_20150724_00028.jpg



View of the channel from the bridge facing downstream.

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_110			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Walnut Street / Down (cont)				
Rating **	A	Issue No.	111	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_111			
Action/Comments				
Inspector Comments: No erosion was observed.				

No Photos

Rating **	N	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_112			
Action/Comments				
Inspector Comments: No riprap was observed.				

No Photos

Rating **	A	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_113			
Action/Comments				
Inspector Comments: The channel appeared free of encroachments.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Lone Pine Avenue / Up			
Rating **	A	Issue No.	71
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.703260 °
Item	Vegetation & Obstructions		-121.868470 °
DWR ID	DWR_NA0060_12_c_2012_71		
Action/Comments			
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.			

Photo 1 of 1 : CH_2015_NA0060_12_71_20150724_00029.jpg



View of the channel from the bridge facing upstream.

Rating **	A	Issue No.	72
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.703260 °
Item	Shoaling / Sedimentation		-121.868470 °
DWR ID	DWR_NA0060_12_c_2012_72		
Action/Comments			
Inspector Comments: No shoaling observed at this site.			

No Photos

Rating **	A	Issue No.	73
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.703260 °
Item	Erosion / Bank Caving		-121.868470 °
DWR ID	DWR_NA0060_12_c_2012_73		
Action/Comments			
Inspector Comments: No erosion observed at this site.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Lone Pine Avenue / Up (cont)				
Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_75			
Action/Comments				
Inspector Comments: No encroachments observed at this site.				

No Photos

Check Point / View				
Lone Pine Avenue / Down				
Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_76			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2015_NA0060_12_76_20150724_00030.jpg



View of the channel facing downstream.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View				
Lone Pine Avenue / Down (cont)				
Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_78			
Action/Comments				
Inspector Comments: No erosion observed at this site.				

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_79			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2015

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	06/10/2015 06/11/2015	Michael Pitta

Check Point / View			
Lone Pine Avenue / Down (cont)			
Rating **	A	Issue No.	80
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_80		
Action/Comments			
Inspector Comments: No encroachments observed at this site.			

No Photos

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--