

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2013 Levee Inspection Results**

Reclamation District No. 0001 Union Island

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2013 Levee Inspection Results

Reclamation District No. 0001 Union Island

Waterway		Bank	Unit Miles
Unit No. 01 Old River		Right	1.15

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	05/09/2013 - 05/09/2013			
DWR Inspector	Maksim Khashchuk			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo	
	Start	End						Start	End		
1				Flood Preparedness & Training	LS	A				6	
								DWR ID: DWR_RD0001_01_s_2013_6			
2				Emergency Supplies & Equipment	LS	A				8	
								DWR ID: DWR_RD0001_01_s_2013_8			
3				Operations & Maintenance Manuals	LS	A				9	
								DWR ID: DWR_RD0001_01_s_2013_9			
4	0.00	0.00	Supplemental	DWR Erosion Survey	WS	U	Inspector Comments: 08/07/2012: The erosion is at the confluence of Old River and one of its tributary. [2012 Site ID:RD0001U01RM31.4]	37.822306 ° -121.375304 °	37.822306 ° -121.375304 °	2 Y	
								DWR ID: DWR_RD0001_01_s_2013_2			
5	0.01	0.01		Encroachments	WSA/W	PI : Pipe	Inspector Comments: Steel irrigation intake pipe up levee slope and through freeboard.	37.822408 ° -121.375714 °	37.822408 ° -121.375714 °	1 Y	
								DWR ID: DWR_RD0001_01_s_2012_1			
6	0.02	0.02		Animal Control	LS	M	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Several burrows present	37.822511 ° -121.375857 °	37.822511 ° -121.375857 °	18 Y	
								DWR ID: DWR_RD0001_01_s_2012_18			
7	0.03	0.03		Animal Control	WS	C	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Burrow evident on water side, burrow appears to have collapsed.	37.822403 ° -121.375937 °	37.822403 ° -121.375937 °	4	
								DWR ID: DWR_RD0001_01_s_2012_4			
8	0.20	0.20		Erosion / Bank Caving	LS	M	E2 : Schedule repair of erosion site prior to the next inspection.	37.820989 ° -121.378174 °	37.820989 ° -121.378174 °	5 Y	
								DWR ID: DWR_RD0001_01_s_2013_5			
9	0.39	0.39		Encroachments	WSA/W	PI : Pipe	Inspector Comments: Irrigation intake through levee crown.	37.819651 ° -121.380467 °	37.819651 ° -121.380467 °	7 Y	
								DWR ID: DWR_RD0001_01_s_2012_7			
10	0.66	0.66		Animal Control	LS	M	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.817249 ° -121.382026 °	37.817249 ° -121.382026 °	15 Y	
								DWR ID: DWR_RD0001_01_s_2012_15			
11	0.67	0.67		Encroachments	LS A/W	PI : Pipe	Inspector Comments: Drainage discharge into Old River. No photo found from previous inspection. 04/26/2011 photo added.	37.817134 ° -121.382099 °	37.817134 ° -121.382099 °	20 Y	
								DWR ID: DWR_RD0001_01_s_2012_20			
12	0.86	0.86		Encroachments	LS A/W	PI : Pipe	Inspector Comments: Irrigation intake through levee freeboard.	37.814566 ° -121.382450 °	37.814566 ° -121.382450 °	10 Y	
								DWR ID: DWR_RD0001_01_s_2012_10			

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
13	0.91	0.91		Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	37.814220 ° -121.383336 °	37.814220 ° -121.383336 °	11 Y
DWR ID: DWR_RD0001_01_s_ 2012_11										
14	1.09	1.09		Slope Stability	LS	M Ma	S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.	37.812021 ° -121.384020 °	37.812021 ° -121.384020 °	3 Y
DWR ID: DWR_RD0001_01_s_ 2013_3										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Front view of the erosion

mkhashch_s_20130225_297.jpg



Levee Mile Report Line	5
Start Levee Mile	0.01
End Levee Mile	0.01
Location	Water Side
Category	
Item	Encroachments

View of irrigation intake pipe on waterside slope.

mkhashch_s_20130225_296.JPG



Levee Mile Report Line	6
Start Levee Mile	0.02
End Levee Mile	0.02
Location	Land Side
Category	
Item	Animal Control

04/26/2011 Animal burrow in levee crown.

mkhashch_s_20130225_304.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

Levee Mile Report Line	6
Start Levee Mile	0.02
End Levee Mile	0.02
Location	Land Side
Category	
Item	Animal Control
04/26/2011 Several burrows present in levee crown and landside slope.	
mkhashch_s_20130225_305.jpg	



Levee Mile Report Line	8
Start Levee Mile	0.20
End Levee Mile	0.20
Location	Land Side
Category	
Item	Erosion / Bank Caving
View of the erosion on the landside levee slope.	
mkhashch_s_20130509_737.JPG	



Levee Mile Report Line	9
Start Levee Mile	0.39
End Levee Mile	0.39
Location	Water Side
Category	
Item	Encroachments
Drainage discharge pipe through levee freeboard.	
mkhashch_s_20130225_299.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

Levee Mile Report Line	10
Start Levee Mile	0.66
End Levee Mile	0.66
Location	Land Side
Category	
Item	Animal Control
Rodent holes on levee slope.	
mkhashch_s_20130225_303.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.67
End Levee Mile	0.67
Location	Land Side
Category	
Item	Encroachments
04/26/2011 Discharge pipe in water side slope.	
mkhashch_s_20130225_306.jpg	



Levee Mile Report Line	12
Start Levee Mile	0.86
End Levee Mile	0.86
Location	Land Side
Category	
Item	Encroachments
View of irrigation intake pipe on waterside.	
mkhashch_s_20130225_300.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Reclamation District No. 0001 Union Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Old River	Right	1.15	05/09/2013 05/09/2013	Maksim Khashchuk

Levee Mile Report Line	12
Start Levee Mile	0.86
End Levee Mile	0.86
Location	Land Side
Category	
Item	Encroachments
View of irrigation pipe on landside.	
mkhashch_s_20130225_301.JPG	



Levee Mile Report Line	13
Start Levee Mile	0.91
End Levee Mile	0.91
Location	Land Side
Category	
Item	Vegetation
View of Elderberries blocking visibility of landside slope and toe.	
mkhashch_s_20130225_302.JPG	



Levee Mile Report Line	14
Start Levee Mile	1.09
End Levee Mile	1.09
Location	Land Side
Category	
Item	Slope Stability
View of the tire tracks on the landside levee slope.	
mkhashch_s_20130509_736.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---