

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Reclamation District No. 0010 Honcut

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles
Unit No. 01 Simmerly Slough	Right	7.68

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/15/2010 - 4/15/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Finlay Williams			

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.
- (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Right	7.68	04/15/2010 04/15/2010	Clay Thomas

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.47	0.47	Earthen Levee	Trim / Thin Trees	WS	C	Thin trees to allow visibility of the ground and room to flood fight.	39.162572 ° -121.601277 °	39.162572 ° -121.601277 °	11
2	0.63	0.63	Earthen Levee	Trim / Thin Trees	WS	C	Thin trees to allow visibility of the ground and room to flood fight.	39.161718 ° -121.598497 °	39.161718 ° -121.598497 °	10
3	4.17	4.17	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	39.205782 ° -121.581283 °	39.205782 ° -121.581283 °	24
4	4.30	4.30	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	39.207727 ° -121.581030 °	39.207727 ° -121.581030 °	23
5	5.44	5.44	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	39.224015 ° -121.578987 °	39.224015 ° -121.578987 °	22
6	5.56	5.56	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	39.225727 ° -121.578797 °	39.225727 ° -121.578797 °	21
7	5.71	5.71	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	39.227892 ° -121.578480 °	39.227892 ° -121.578480 °	20

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> <p>C : Corrected W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles
Unit No. 02 Feather River	Left	11.24

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/15/2010 - 4/15/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Finlay Williams			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector			
Unit No. 02 Feather River				Left	11.24	04/15/2010 04/15/2010	Clay Thomas			
LMIR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	11.19	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.163714 ° -121.609940 °	39.307024 ° -121.617313 °	2 Y
2	0.00	11.19	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.163714 ° -121.609940 °	39.307024 ° -121.617311 °	1 Y
3	1.35	1.35	Earthen Levee	Encroachments	LS	PO	Landscaping	39.182957 ° -121.609800 °	39.182957 ° -121.609800 °	9
4	4.93	4.93	Earthen Levee	Encroachments	LS	C	Debris	39.233245 ° -121.614648 °	39.233245 ° -121.614648 °	40
5	5.15	5.15	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.236373 ° -121.615112 °	39.236373 ° -121.615112 °	32
6	5.42	5.42	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.240148 ° -121.616085 °	39.240148 ° -121.616085 °	33
7	6.07	6.07	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.248942 ° -121.619172 °	39.248942 ° -121.619172 °	34
8	6.27	6.27	Earthen Levee	Encroachments	LS	M	Debris	39.251905 ° -121.619202 °	39.251905 ° -121.619202 °	7
9	6.40	6.40	Earthen Levee	Animal Control	WS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.253667 ° -121.619536 °	39.253667 ° -121.619536 °	16
10	7.10	7.10	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.262316 ° -121.614376 °	39.262316 ° -121.614376 °	18
11	7.59	7.59	Earthen Levee	Encroachments	LS	M	Debris	39.268841 ° -121.611425 °	39.268841 ° -121.611425 °	35
12	8.38	8.38	Earthen Levee	Animal Control	WS	C	Exterminate rodents and backfill and compact or grout burrows.	39.278210 ° -121.608864 °	39.278210 ° -121.608864 °	36
13	9.30	9.30	Earthen Levee	Encroachments	LS	M	Prunings	39.285883 ° -121.600353 °	39.285883 ° -121.600353 °	3 Y
14	9.43	9.43	Earthen Levee	Animal Control	LS	C	Exterminate rodents and backfill and compact or grout burrows.	39.287716 ° -121.600591 °	39.287716 ° -121.600591 °	37
15	9.59	9.59	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	39.289906 ° -121.601758 °	39.289906 ° -121.601758 °	38
16	9.91	9.91	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	39.293100 ° -121.605911 °	39.293100 ° -121.605911 °	39
17	10.74	11.11	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	39.300812 ° -121.617528 °	39.305892 ° -121.617715 °	23

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected
 W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.24	04/15/2010 04/15/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	11.19
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Water side vegetation levee mile 6.69.	
cathom_s_20100520_054.jpg	



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	11.19
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Water side vegetation levee mile 0.00.	
cathom_s_20100520_063.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	11.19
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Land side vegetation levee mile 6.69.	
cathom_s_20100520_055.jpg	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.24	04/15/2010 04/15/2010	Clay Thomas

Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	11.19
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Land side vegetation levee mile 0.00.	
cathom_s_20100520_064.jpg	



Levee Mile Report Line	13
Start Levee Mile	9.30
End Levee Mile	9.30
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Land side levee mile 9.30.	
cathom_s_20100520_056.jpg	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles
Unit No. 03 Honcut Creek	Left	3.01

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/15/2010 - 4/15/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Finlay Williams			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Honcut Creek	Left	3.01	04/15/2010 04/15/2010	Clay Thomas

LMIR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	2.89	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.307868 ° -121.617070 °	39.299152 ° -121.571802 °	3 Y
2	0.00	2.89	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.307869 ° -121.617070 °	39.299152 ° -121.571801 °	1 Y
3	0.17	0.17	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees over roadway to at least 12 feet above ground level.	39.310032 ° -121.616338 °	39.310032 ° -121.616338 °	2
4	1.91	1.91	Earthen Levee	Animal Control	WS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.303247 ° -121.587677 °	39.303247 ° -121.587677 °	4
5	2.81	2.81	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	39.299653 ° -121.573072 °	39.299653 ° -121.573072 °	6

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Honcut Creek	Left	3.01	04/15/2010 04/15/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	2.89
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Land side vegetation levee mile 0.00.	
cathom_s_20100520_057.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	2.89
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Water side vegetation levee mile 0.00.	
cathom_s_20100520_058.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p>
---	---