

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Right	7.65	11/10/2015 11/10/2015	Jai Lor

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	o
DWR ID	DWR_RD0010_01_s_2013_7				
Action/Comments					
Inspector Comments: The O&M manual is located at Tom Schultz's house.					

No Photos

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	o
DWR ID	DWR_RD0010_01_s_2013_8				
Action/Comments					
Inspector Comments: Finlay Williams stated that they are part of the CO-OP with RD 784 which shares flood fight supplies at multiple locations. Also he has a small amount of supplies located at his house within the district.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	o
DWR ID	DWR_RD0010_01_s_2013_9				
Action/Comments					
Inspector Comments: The district has attended the class in the past and plans to attend the Flood Fight class put on by RD 784 and DWR.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Right	7.65	11/10/2015 11/10/2015	Jai Lor

LM Start	3.57	Rating **	A/W	Issue No.	28
LM End	7.64	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			39.197526 °	39.255993 °
				-121.582294 °	-121.574930 °
DWR ID	DWR_RD0010_01_f_2015_28				
Action/Comments					
Add appropriate material and re-grade the levee to bring the crown above the design elevation. Inspector Comments: Crown needs to be re-graded. LMA is in the proces of regrading the levee in correspondence with DWR.					

Photo 1 of 1 : FA_2015_RD0010_163_28_20151113_00024.jpg



View of the crown of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.36	11/10/2015 11/10/2015	Jai Lor

LM Start	0.03	Rating **	A	Issue No.	26
LM End	11.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.164091 °	39.310067 °
				-121.610076 °	-121.616287 °
DWR ID	DWR_RD0010_02_f_2015_26				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Levee has been burned and dragged.					

No Photos

LM Start	0.03	Rating **	A	Issue No.	25
LM End	11.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.164091 °	39.310068 °
				-121.610076 °	-121.616287 °
DWR ID	DWR_RD0010_02_f_2015_25				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Levee has been burned and dragged.					

Photo 1 of 1 : FA_2015_RD0010_164_25_20151113_00020.jpg



View of the vegetation on the waterward side of the levee looking upstream. Fall 2015.

LM Start	0.38	Rating **	M	Issue No.	28
LM End	0.38	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.169231 °	39.169231 °
				-121.610711 °	-121.610711 °
DWR ID	DWR_RD0010_02_f_2015_28				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2015_RD0010_164_28_20151113_00021.jpg



View of the rodent hole on the waterward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.36	11/10/2015 11/10/2015	Jai Lor

LM Start	0.94	Rating **	M	Issue No.	29
LM End	0.94	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.177289 °	39.177289 °	
			-121.609860 °	-121.609860 °	
DWR ID	DWR_RD0010_02_f_2015_29				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	1.13	Rating **	M	Issue No.	30
LM End	1.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.179947 °	39.179947 °	
			-121.610024 °	-121.610024 °	
DWR ID	DWR_RD0010_02_f_2015_30				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	3.65	Rating **	M	Issue No.	68
LM End	3.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.216059 °	39.216059 °	
			-121.610815 °	-121.610815 °	
DWR ID	DWR_RD0010_02_f_2013_68				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.36	11/10/2015 11/10/2015	Jai Lor

LM Start	6.72	Rating **	M	Issue No.	32
LM End	6.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.257859 °	39.257859 °	
			-121.617667 °	-121.617667 °	
DWR ID	DWR_RD0010_02_f_2015_32				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	6.88	Rating **	M	Issue No.	33
LM End	6.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.259843 °	39.259843 °	
			-121.616013 °	-121.616013 °	
DWR ID	DWR_RD0010_02_f_2015_33				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	8.09	Rating **	M	Issue No.	35
LM End	8.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.275179 °	39.275179 °	
			-121.611283 °	-121.611283 °	
DWR ID	DWR_RD0010_02_f_2015_35				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.36	11/10/2015 11/10/2015	Jai Lor

LM Start	9.34	Rating **	M	Issue No.	27
LM End	9.34	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		39.286983 °	39.286983 °	
			-121.600423 °	-121.600423 °	
DWR ID	DWR_RD0010_02_s_2015_27				
Action/Comments					
Add appropriate material and re-grade the levee to bring the crown above the design elevation.					

No Photos

LM Start	9.46	Rating **	C	Issue No.	5
LM End	9.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.288766 °	39.288766 °	
			-121.600875 °	-121.600875 °	
DWR ID	DWR_RD0010_02_f_2012_5				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	9.47	Rating **	C	Issue No.	6
LM End	9.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.288834 °	39.288834 °	
			-121.600898 °	-121.600898 °	
DWR ID	DWR_RD0010_02_f_2012_6				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	11.36	11/10/2015 11/10/2015	Jai Lor

LM Start	9.88	Rating **	C	Issue No.	7
LM End	9.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.293159 °	39.293159 °	
			-121.606011 °	-121.606011 °	
DWR ID	DWR_RD0010_02_f_2012_7				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	10.32	Rating **	M	Issue No.	71
LM End	10.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.297062 °	39.297062 °	
			-121.612336 °	-121.612336 °	
DWR ID	DWR_RD0010_02_f_2013_71				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Blackberries on landward slope should be removed.					

No Photos

LM Start	11.08	Rating **	C	Issue No.	72
LM End	11.08	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.306077 °	39.306077 °	
			-121.617645 °	-121.617645 °	
DWR ID	DWR_RD0010_02_f_2013_72				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Honcut Creek	Left	2.81	11/10/2015 11/10/2015	Jai Lor

LM Start	0.00	Rating **	A	Issue No.	4
LM End	2.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.310069 °	39.298537 °	
			-121.616287 °	-121.569954 °	
DWR ID	DWR_RD0010_03_f_2015_4				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetation has been burned.					

Photo 1 of 1 : FA_2015_RD0010_165_4_20151113_00008.jpg



View of the vegetation on the landward side of the levee looking upstream. Fall 2015.

LM Start	0.00	Rating **	A	Issue No.	6
LM End	2.80	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.310069 °	39.298537 °	
			-121.616287 °	-121.569954 °	
DWR ID	DWR_RD0010_03_f_2015_6				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetation has been burned.					

No Photos

LM Start	1.67	Rating **	M	Issue No.	18
LM End	1.67	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		39.302904 °	39.302904 °	
			-121.588578 °	-121.588578 °	
DWR ID	DWR_RD0010_03_f_2013_18				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible. Inspector Comments: Toe cut at edge of waterward side of levee.					

Photo 1 of 1 : FA_2015_RD0010_165_18_20151030_00004.jpg



This photo was taken from the levee crown facing north looking down the waterward slope at agricultural tilling causing a cut at the levee toe. Fall 2013.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0010 Honcut

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Honcut Creek	Left	2.81	11/10/2015 11/10/2015	Jai Lor

LM Start	1.73	Rating **	C	Issue No.	12
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		39.303317 °	39.303317 °	
			-121.587539 °	-121.587539 °	
DWR ID	DWR_RD0010_03_s_2013_12				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---