

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2013 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

**Sacramento River Basin**

<b>RD0108</b>	Overall LMA Rating	Total LMA Miles						
<b>Reclamation District No. 0108 River Farms</b>	<b>A</b>	<b>20.87</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.73			
Slope Stability	0.01		0.01	0.05%				
Cracking	0.05		0.05	0.24%				
<i>Supplemental</i>								
USACE Erosion Survey	0.01		0.01	0.05%				
<i>LMA Totals:</i>	0.07	0.00	0.07	0.34%	0.73	0.00	0.00	0.00

  

<b>Unit No. 01 Colusa Basin Drain LB</b>	Overall Unit Rating	Total Unit Miles						
<b>RD0108</b>	<b>A</b>	<b>20.59</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.73			
Slope Stability	0.01		0.01	0.05%				
Cracking	0.05		0.05	0.24%				
<i>Supplemental</i>								
USACE Erosion Survey	0.01		0.01	0.05%				
<i>Unit Totals:</i>	0.07	0.00	0.07	0.34%	0.73	0.00	0.00	0.00

  

<b>Unit No. 02 Castle Properties RB</b>	Overall Unit Rating	Total Unit Miles						
<b>RD0108</b>	<b>A</b>	<b>0.28</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2013 Levee Inspection Results**

**Reclamation District No. 0108 River Farms**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2013 Levee Inspection Results**

**Reclamation District No. 0108 River Farms**

Waterway			Bank	Unit Miles
Unit No. 01 Colusa Basin Drain			Left	20.59
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	-		10/04/2013 - 10/04/2013	
DWR Inspector	John Williamson		John Williamson	
Accompanied By	Chad Navarrot RD 108		Chad Navarrot RD 108	

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Colusa Basin Drain						Left	20.59	10/04/2013 10/04/2013	John Williamson	
LMR No.	Levee Mile		Category	Item	Location + Rating	Action/Comment	GPS Latitude/Longitude		Issue No.	Photo
	Start	End					Start	End		
1			Earthen Levee	Operations & Maintenance Manuals	LS A Ma		° °	° °	5	
DWR ID: DWR_RD0108_01_s_2013_5										
2			Earthen Levee	Emergency Supplies & Equipment	LS A Ma		° °	° °	7	
DWR ID: DWR_RD0108_01_s_2013_7										
3			Earthen Levee	Flood Preparedness & Training	LS A Ma		° °	° °	9	
DWR ID: DWR_RD0108_01_s_2013_9										
4	3.86	3.88	Earthen Levee	Cracking	CR M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.843048 ° -121.862460 °	38.843090 ° -121.862807 °	277 Y	
DWR ID: DWR_RD0108_01_f_2013_277										
5	5.56	5.56	Earthen Levee	Animal Control	LS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.848592 ° -121.893017 °	38.848592 ° -121.893017 °	22	
DWR ID: DWR_RD0108_01_s_2012_22										
6	5.57	5.57	Earthen Levee	Animal Control	LS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.848688 ° -121.893349 °	38.848688 ° -121.893349 °	18	
DWR ID: DWR_RD0108_01_s_2012_18										
7	6.93	6.93	Earthen Levee	Animal Control	WS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.864891 ° -121.907285 °	38.864891 ° -121.907285 °	10	
DWR ID: DWR_RD0108_01_s_2012_10										
8	7.63	7.63	Earthen Levee	Animal Control	LS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.873613 ° -121.913853 °	38.873613 ° -121.913853 °	23	
DWR ID: DWR_RD0108_01_s_2012_23										
9	9.28	9.28	Earthen Levee	Slope Stability	WS M Ma	S1 : Repair slope instability.	38.897452 ° -121.914680 °	38.897452 ° -121.914680 °	279 Y	
DWR ID: DWR_RD0108_01_f_2013_279										
10	9.28	9.28	Earthen Levee	Cracking	LS M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.897453 ° -121.914680 °	38.897453 ° -121.914680 °	278 Y	
DWR ID: DWR_RD0108_01_f_2013_278										
11	9.99	9.99	Earthen Levee	Animal Control	WS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.907854 ° -121.914658 °	38.907854 ° -121.914658 °	24	
DWR ID: DWR_RD0108_01_s_2012_24										
12	11.35	11.35	Earthen Levee	Animal Control	LS C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.927354 ° -121.913455 °	38.927354 ° -121.913455 °	25	
DWR ID: DWR_RD0108_01_s_2012_25										
13	11.52	11.52	Earthen Levee	Animal Control	WS C Ma	A1 : Exterminate rodents and backfill and compact or grout burrows.	38.929757 ° -121.912128 °	38.929757 ° -121.912128 °	1	
DWR ID: DWR_RD0108_01_f_2012_1										
14	14.22	14.24	Earthen Levee	Cracking	LS M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.964848 ° -121.920245 °	38.965205 ° -121.920537 °	280 Y	
DWR ID: DWR_RD0108_01_f_2013_280										

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Colusa Basin Drain						Left	20.59	10/04/2013 10/04/2013	John Williamson	

  

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
15	14.54	14.54	Earthen Levee	Cracking	LS	A/W Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.968032 ° -121.924480 °	38.968032 ° -121.924480 °	2 Y
DWR ID: DWR_RD0108_01_f_2012_2										
16	18.26	18.26	Earthen Levee	Encroachments	WS	M En	PR : Prunings	39.006497 ° -121.973158 °	39.006497 ° -121.973158 °	281 Y
DWR ID: DWR_RD0108_01_f_2013_281										
17	18.88	19.60	Earthen Levee	Encroachments	LS	M En	DT : Ditch	39.013245 ° -121.980795 °	39.021302 ° -121.988557 °	6 Y
DWR ID: DWR_RD0108_01_s_2012_6										
18	19.29	19.29	Supplemental	USACE Erosion Survey	WS	M Ma	Inspector Comments: 2011 - Toe scour at the bottom of a steep bank, large sections of the toe are sliding down. Erosion may be due to the upstream bend. 2012: Site is part of the extended inventory, last inspected 2011. [2012 Site ID: CBD_19-2_L]	39.017516 ° -121.986374 °	39.016727 ° -121.985411 °	3
DWR ID:										

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.59	10/04/2013 10/04/2013	John Williamson

Levee Mile Report Line	4
Start Levee Mile	3.86
End Levee Mile	3.88
Location	Crown
Category	Earthen Levee
Item	Cracking

Cracking along the crown of the levee, fall 2013

johngw\_f\_20131007\_960.JPG



Levee Mile Report Line	9
Start Levee Mile	9.28
End Levee Mile	9.28
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

Slope stability with cracking 1-2 inches open and 12 inches deep Fall 2013 The district is monitoring the site.

johngw\_f\_20131007\_962.JPG



Levee Mile Report Line	9
Start Levee Mile	9.28
End Levee Mile	9.28
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

The cracking runs in a horseshoe pattern on the levee slope Fall 2013

johngw\_f\_20131007\_963.JPG



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.59	10/04/2013 10/04/2013	John Williamson

Levee Mile Report Line	10
Start Levee Mile	9.28
End Levee Mile	9.28
Location	Land Side
Category	Earthen Levee
Item	Cracking

Cracking on the landside levee slope Fall 2013

johngw\_f\_20131007\_961.JPG



Levee Mile Report Line	14
Start Levee Mile	14.22
End Levee Mile	14.24
Location	Land Side
Category	Earthen Levee
Item	Cracking

Small cracking along the shoulder of the crown, fall 2013.

johngw\_f\_20131007\_964.JPG



Levee Mile Report Line	14
Start Levee Mile	14.22
End Levee Mile	14.24
Location	Land Side
Category	Earthen Levee
Item	Cracking

It appears to have some slope stability issues with the cracking. Fall 2013

johngw\_f\_20131007\_965.JPG



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.59	10/04/2013 10/04/2013	John Williamson

Levee Mile Report Line	15
Start Levee Mile	14.54
End Levee Mile	14.54
Location	Land Side
Category	Earthen Levee
Item	Cracking

A crack running along the landside shoulder app. 50' long. Fall 2012

johngw\_f\_20130924\_875.jpg



Levee Mile Report Line	16
Start Levee Mile	18.26
End Levee Mile	18.26
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Piles of prunings are at the waterside berm. Fall 2013

johngw\_f\_20131007\_966.JPG



Levee Mile Report Line	17
Start Levee Mile	18.88
End Levee Mile	19.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Agricultural ditch

johngw\_f\_20130924\_878.jpg



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.59	10/04/2013 10/04/2013	John Williamson

Levee Mile Report Line	17
Start Levee Mile	18.88
End Levee Mile	19.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Agricultural ditch along toe of landside. Photo taken fall 2011.

johngw\_f\_20130924\_879.jpg



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2013 Levee Inspection Results**

**Reclamation District No. 0108 River Farms**

Waterway			Bank	Unit Miles
Unit No. 02 Castle Properties			Right	0.28
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	-		09/24/2013 - 09/24/2013	
DWR Inspector	John Williamson		John Williamson	
Accompanied By	Chad Navarrot RD 108		Chad Navarrot RD 108	

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Castle Properties						Right	0.28	09/24/2013 09/24/2013	John Williamson	

  

LMR No.	Levee Mile		Category	Item	Location *	Rating ** +	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.01	0.28	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.799050 ° -121.724623 °	38.796268 ° -121.727943 °	1 Y
DWR ID: DWR_RD0108_02_f_2013_1										
2	0.01	0.01	Earthen Levee	Animal Control	LS A/W Ob	A3	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.798992 ° -121.724643 °	38.798992 ° -121.724643 °	3 Y
DWR ID: DWR_RD0108_02_s_2013_3										
3	0.09	0.09	Earthen Levee	Animal Control	LS A/W Ob	A3	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.798196 ° -121.725660 °	38.798196 ° -121.725660 °	4 Y
DWR ID: DWR_RD0108_02_f_2012_4										

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2013**

**Reclamation District No. 0108 River Farms**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	09/24/2013 09/24/2013	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.01
End Levee Mile	0.28
Location	Land Side
Category	Earthen Levee
Item	Vegetation

The landside levee slope has been burned. Waterside vegetation is below 12 inches. Fall 2013

johngw\_f\_20130930\_937.JPG



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	0.01
Location	Land Side
Category	Earthen Levee
Item	Animal Control

No rodents but holes need to be backfilled. Spring 2013

johngw\_f\_20130917\_118.JPG



Levee Mile Report Line	3
Start Levee Mile	0.09
End Levee Mile	0.09
Location	Land Side
Category	Earthen Levee
Item	Animal Control

A couple of rodent holes on the landside slope. Fall 2012

johngw\_f\_20130917\_119.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement