

**Flood Control Project Maintenance
Levee Inspections**

Fall 2018 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0108	Overall LMA Rating	Total LMA Miles						
Reclamation District No. 0108 River Farms	A	20.92						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.37			
<i>Supplemental</i>								
DWR UCIP Field Study					0.03			
DWR UCIP LMA Responsibility								
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.40	0.00	0.00	0.00
Unit No. 01 Colusa Basin Drain LB	Overall Unit Rating	Total Unit Miles						
RD0108	A	20.64						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.37			
<i>Supplemental</i>								
DWR UCIP Field Study					0.03			
DWR UCIP LMA Responsibility								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.40	0.00	0.00	0.00
Unit No. 02 Castle Properties RB	Overall Unit Rating	Total Unit Miles						
RD0108	A	0.28						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2018 Levee Inspection Results

Reclamation District No. 0108 River Farms

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2018 Levee Inspection Results

Reclamation District No. 0108 River Farms

Waterway			Bank	Unit Miles
Unit No. 01 Colusa Basin Drain			Left	20.64
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/16/2018 - 3/16/2018		10/9/2018 - 10/9/2018	
DWR Inspector	Zach Jojola		Zach Jojola	
Accompanied By	Gary Marler RD0108		Gary Marler RD0108	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0108_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 108 has O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0108_01_s_2013_7				
Comment Code					
Inspector Comment					
RD 108 maintains a stockpile of flood response materials.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD0108_01_s_2013_9				
Comment Code					
Inspector Comment					
RD 108 has written response plans and regular flood response training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	29
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°
				-121.797000°	-121.797000°
DWR ID	17943				
Comment Code					
Inspector Comment					
FS_ID:37608 DS_ID:17943 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 1 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37608_68207.jpg



View of concrete structure visible on waterward side.

LM Start	0.06	Rating **	M	Issue No.	29 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37608_68210.jpg



Dense vegetation on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	29 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°	
				-121.797000°	-121.797000°	
DWR ID	17943					
Comment Code						
Inspector Comment						
FS_ID:37608 DS_ID:17943 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 1 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37608_68208.jpg



View of concrete structure visible on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	30
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °
				-121.797046 °	-121.797046 °
DWR ID	22386				
Comment Code					
Inspector Comment					
FS_ID:37609 DS_ID:22386 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 2 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37609_68211.jpg



Concrete structure located on waterward side.

LM Start	0.06	Rating **	M	Issue No.	30 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37609_68215.jpg



Dense vegetation covers the waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	30 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °	
				-121.797046 °	-121.797046 °	
DWR ID	22386					
Comment Code						
Inspector Comment						
FS_ID:37609 DS_ID:22386 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 2 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37609_68213.jpg



View of concrete structure located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	31
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °
				-121.797081 °	-121.797081 °
DWR ID	22387				
Comment Code					
Inspector Comment					
FS_ID:37610 DS_ID:22387 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 3 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

LM Start	0.06	Rating **	M	Issue No.	31 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_37610_68216.jpg



Concrete structure located on waterward side.

Photo 2 of 3 : UCIP_FA_2018_37610_68219.jpg



Dense vegetation covers waterward side slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	31 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °	
				-121.797081 °	-121.797081 °	
DWR ID	22387					
Comment Code						
Inspector Comment						
FS_ID:37610 DS_ID:22387 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 3 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37610_68217.jpg



Concrete structure located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	32
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°
				-121.797000°	-121.797000°
DWR ID	22388				
Comment Code					
Inspector Comment					
FS_ID:37611 DS_ID:22388 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 4 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

LM Start	0.06	Rating **	M	Issue No.	32 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_37611_68220.jpg



Concrete structure located on waterward side.

Photo 2 of 3 : UCIP_FA_2018_37611_68224.jpg



Waterward slope covered by dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	32 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°	
				-121.797000°	-121.797000°	
DWR ID	22388					
Comment Code						
Inspector Comment						
FS_ID:37611 DS_ID:22388 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 4 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37611_68222.jpg



Concrete structure visible on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.07	Rating **	M	Issue No.	33
LM End	0.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °
				-121.797135 °	-121.797135 °
DWR ID	22389				
Comment Code					
Inspector Comment					
FS_ID:37607 DS_ID:22389 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 5 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

LM Start	0.07	Rating **	M	Issue No.	33 (cont)
LM End	0.07	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_37607_68203.jpg



Concrete structure located on waterward side.

Photo 2 of 3 : UCIP_FA_2018_37607_68206.jpg



Waterward slope covered by dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.07	Rating **	M	Issue No.	33 (cont)	
LM End	0.07	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °	
				-121.797135 °	-121.797135 °	
DWR ID	22389					
Comment Code						
Inspector Comment						
FS_ID:37607 DS_ID:22389 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 5 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37607_68204.jpg



Concrete structure located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	2.91	Rating **	M	Issue No.	34	
LM End	2.91	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.838696 °	38.838696 °	
				-121.845843 °	-121.845843 °	
DWR ID	24875					
Comment Code						
Inspector Comment						
FS_ID:39707 DS_ID:24875 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No signs of pipe visible--need to contact owner to obtain permit number authorizing work. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure. FIELD_STRUCT_DESC: Corrugated metal pipe (CMP) riser on the waterside (WS). Riser is filled with trash and debris. Unable to determine if a crossing exists at this location. This riser was field discovered. FS Date: 3/18/2014						

LM Start	2.91	Rating **	M	Issue No.	34 (cont)
LM End	2.91	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_FA_2018_39707_71682.jpg



View of waterward side.

Photo 2 of 3 : UCIP_FA_2018_39707_71681.jpg



CMP riser located on waterward toe--2/3 filled with soil and trash.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	2.91	Rating **	M	Issue No.	34 (cont)	
LM End	2.91	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.838696 °	38.838696 °	
				-121.845843 °	-121.845843 °	
DWR ID	24875					
Comment Code						
Inspector Comment						
FS_ID:39707 DS_ID:24875 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No signs of pipe visible--need to contact owner to obtain permit number authorizing work. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure. FIELD_STRUCT_DESC: Corrugated metal pipe (CMP) riser on the waterside (WS). Riser is filled with trash and debris. Unable to determine if a crossing exists at this location. This riser was field discovered. FS Date: 3/18/2014						

Photo 3 of 3 : UCIP_FA_2018_39707_71680.jpg



View of waterward slope.

LM Start	9.66	Rating **	M	Issue No.	16
LM End	9.66	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.902691 °	38.902691 °
				-121.914645 °	-121.914645 °
DWR ID	DWR_RD0108_01_f_2016_16				
Comment Code					
ST : Stairway					
Inspector Comment					
Department of Fish and Game staff is using stairway to access their monitoring site. Unable to verify permit.					

Photo 1 of 2 : FA_2018_RD0108_203_16_20181011_00029.jpg



View of stairway look upstream. Fall 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	9.66	Rating **	M	Issue No.	16 (cont)	
LM End	9.66	Issue Type +	En	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Encroachments			38.902691 °	38.902691 °	
				-121.914645 °	-121.914645 °	
DWR ID	DWR_RD0108_01_f_2016_16					
Comment Code						
ST : Stairway						
Inspector Comment						
Department of Fish and Game staff is using stairway to access their monitoring site. Unable to verify permit.						

Photo 2 of 2 : FA_2018_RD0108_203_16_20180904_00002.jpg



View of a steel stairway on WS slope. Fall 2016 inspection.

LM Start	10.77	Rating **	C	Issue No.	21
LM End	10.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.918902 °	38.918902 °
				-121.914589 °	-121.914589 °
DWR ID	DWR_RD0108_01_s_2018_21				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Minor erosion on landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	11.24	Rating **	M	Issue No.	35	
LM End	11.24	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.925662 °	38.925662 °	
				-121.914303 °	-121.914303 °	
DWR ID	24876					
Comment Code						
Inspector Comment						
FS_ID:39717						
DS_ID:24876						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner to determine additional details of crossing.						
FIELD_STRUCT_DESC: Natural gas pipeline of an unknown size or material slightly angled through the levee, at an unknown depth.						
Markers on both sides of the levee. Gas station located across the canal on the landside (LS). This crossing was field discovered.						
FS Date: 3/18/2014						

LM Start	11.24	Rating **	M	Issue No.	35 (cont)
LM End	11.24	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_FA_2018_39717_71705.jpg



View of marker visible on shoulder.

Photo 2 of 3 : UCIP_FA_2018_39717_71704.jpg



Owner contact information listed on marker.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	11.24	Rating **	M	Issue No.	35 (cont)	
LM End	11.24	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.925662 °	38.925662 °	
				-121.914303 °	-121.914303 °	
DWR ID	24876					
Comment Code						
Inspector Comment						
FS_ID:39717						
DS_ID:24876						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner to determine additional details of crossing.						
FIELD_STRUCT_DESC: Natural gas pipeline of an unknown size or material slightly angled through the levee, at an unknown depth.						
Markers on both sides of the levee. Gas station located across the canal on the landside (LS). This crossing was field discovered.						
FS Date: 3/18/2014						

Photo 3 of 3 : UCIP_FA_2018_39717_71703.jpg



Marker visible on waterward side.

LM Start	14.42	Rating **	C	Issue No.	28
LM End	14.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.966547 °	38.966547 °
				-121.922360 °	-121.922360 °
DWR ID	DWR_RD0108_01_f_2017_28				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Small rodent holes on landside slope. Recommend monitoring for future activity.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	14.94	Rating **	M	Issue No.	36	
LM End	14.94	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.971607 °	38.971607 °	
				-121.929499 °	-121.929499 °	
DWR ID	17942					
Comment Code						
Inspector Comment						
FS_ID:37623						
DS_ID:17942						
EP_NO: 3800						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner--marker missing on waterward side.						
FIELD_STRUCT_DESC: 20-inch concrete encased steel natural gas pipeline through the levee, 3 feet below the crown. Crossing appears to be angled through the levee. Small rock revetment on the waterside (WS) slope, unable to locate. Gas well approximately 1000 feet off the landside (LS) toe. (Plans to construct and maintain a 20-inch gas line across the Sacramento River authorized under Permit No. 3800, 1961 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 1991].						
FS Date: 6/10/2014						

LM Start	14.94	Rating **	M	Issue No.	36 (cont)
LM End	14.94	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_FA_2018_37623_68246.jpg



Marker visible on landward side.

Photo 2 of 3 : UCIP_FA_2018_37623_68245.jpg



Contact information for gas line going through levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	14.94	Rating **	M	Issue No.	36 (cont)	
LM End	14.94	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.971607 °	38.971607 °	
				-121.929499 °	-121.929499 °	
DWR ID	17942					
Comment Code						
Inspector Comment						
FS_ID:37623						
DS_ID:17942						
EP_NO: 3800						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner--marker missing on waterward side.						
FIELD_STRUCT_DESC: 20-inch concrete encased steel natural gas pipeline through the levee, 3 feet below the crown. Crossing appears to be angled through the levee. Small rock revetment on the waterside (WS) slope, unable to locate. Gas well approximately 1000 feet off the landside (LS) toe. (Plans to construct and maintain a 20-inch gas line across the Sacramento River authorized under Permit No. 3800, 1961 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 1991].						
FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37623_68244.jpg



View of waterward side. No marker visible on waterward side.

LM Start	18.92	Rating **	M	Issue No.	6
LM End	19.28	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.013160 °	39.017000 °
				-121.980808 °	-121.985364 °
DWR ID	DWR_RD0108_01_s_2012_6				
Comment Code					
DT : Ditch					
Inspector Comment					
Ditch is at the toe of the levee.					

Photo 1 of 1 : FA_2018_RD0108_203_6_20180904_00001.jpg



View of the ditch at the toe of the levee on the landward side looking upstream. Spring 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	19.27	Rating **	A/W	Issue No.	13
LM End	19.35	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.016727 °	39.017516 °
				-121.985411 °	-121.986374 °
DWR ID	DWR_RD0108_01_f _ 2018_13				
Comment Code					
Inspector Comment					
2017 Site ID: CBD 19.2 L					
Status: Eroding					
2017 Field Notes: Access Issues - Could not observe					
Site History: 2011 - Toe scour at the bottom of a steep bank, large sections of the toe are sliding down. Erosion may be due to the upstream bend.					
DWR Inspector Notes: Doesn't appear to be an issue at this time.					
Recommend monitoring.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2018 Levee Inspection Results

Reclamation District No. 0108 River Farms

Waterway			Bank	Unit Miles
Unit No. 02 Castle Properties			Right	0.28
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/13/2018 - 3/13/2018		10/12/2018 - 10/12/2018	
DWR Inspector	Zach Jojola		Zach Jojola	
Accompanied By	Gary Marler RD0108		Gary Marler RD0108	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	10/12/2018 10/12/2018	Zach Jojola

LM Start	0.06	Rating **	C	Issue No.	1
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.796756 °	38.796756 °
				-121.727099 °	-121.727099 °
DWR ID	DWR_RD0108_02_s_2018_1				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree branch on wanterside slope.					

No Photos

LM Start	0.15	Rating **	A	Issue No.	2
LM End	0.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.797784°	38.797784°
				-121.726039°	-121.726039°
DWR ID	DWR_RD0108_02_f_2018_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The LMA maintains the vegetation at a high level.					

Photo 1 of 1 : FA_2018_RD0108_590_2_20181012_00002.jpg



View of the maintained landside slope. Fall 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---